

Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

manuals.plus /

› [LOTOS](#) /

› [LOTOS TIG200ACDC 200A AC/DC Aluminum Tig Welder Instruction Manual](#)

LOTOS TIG200ACDC

LOTOS TIG200ACDC 200A AC/DC Aluminum Tig Welder Instruction Manual

Model: TIG200ACDC

1. INTRODUCTION

This manual provides essential information for the safe and effective operation of your LOTOS TIG200ACDC 200A AC/DC Aluminum Tig Welder. Please read this manual thoroughly before operating the equipment to ensure proper usage and to prevent injury or damage.

2. IMPORTANT SAFETY INFORMATION

WARNING: Welding equipment can be dangerous. Always follow safety precautions to prevent electric shock, fire, and injury.

- Always wear appropriate personal protective equipment (PPE), including welding helmet, gloves, and protective clothing.
- Ensure proper ventilation to avoid inhaling hazardous fumes.
- Connect the equipment to a properly grounded power supply.
- Keep children and unauthorized personnel away from the welding area.
- Do not operate in damp or wet conditions.
- Refer to local safety regulations and standards for welding operations.

This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. Wash hands after handling.

3. PACKAGE CONTENTS

The LOTOS TIG200ACDC welder package typically includes the following items:

- LOTOS TIG200ACDC Power Supply Unit
- TIG Torch
- MMA/Stick Clamp

- Foot Pedal
- Argon Regulator
- 220V/110V Converter Pigtail
- Ground Clamp
- Consumable Set
- Instruction Manual

4. PRODUCT OVERVIEW

The LOTOS TIG200ACDC is a versatile welding machine designed for both TIG and Stick (MMA) welding. It features dual voltage input (110/220V) and AC/DC output, making it suitable for a wide range of materials including aluminum, stainless steel, and mild steel.

4.1. Welder Unit



Figure 1: LOTOS TIG200ACDC Welder Unit. This image displays the overall view of the welding machine, highlighting its compact design and integrated handles for portability.

4.2. Front Panel Controls



Figure 2: Front Panel Controls. This image details the control panel with knobs for amperage, pre-flow, clearance effect, down-slope, and post-flow, along with mode selection switches for AC/DC, TIG/MMA, and power.

- **Amperage Control:** Adjusts the welding current (10-200A).
- **Pre-Flow:** Controls the duration of gas flow before arc ignition.
- **Clearance Effect:** Adjusts the cleaning action for AC TIG welding on aluminum.
- **Downslope:** Controls the time it takes for the welding current to decrease after releasing the torch trigger or foot pedal.
- **Post-Flow:** Controls the duration of gas flow after the arc is extinguished to protect the weld puddle and tungsten.
- **Mode Switches:** Select between AC/DC output and TIG/MMA welding processes.

- **Output Terminals:** Connections for TIG torch, ground clamp, and MMA/Stick clamp.

4.3. Rear Panel Connections



Figure 3: Rear Panel Connections. This image shows the rear of the welder, including the power input, cooling fans, and the argon gas inlet.

- **Power Input:** Connects to the main power supply (110V or 220V).
- **Argon Gas Inlet:** Connection point for the argon gas hose from the regulator.
- **Cooling Fans:** Ensures stable and durable high performance by dissipating heat.
- **Circuit Breaker:** Provides overload protection.

5. SETUP INSTRUCTIONS

Follow these steps to set up your LOTOS TIG200ACDC welder:

5.1. Power Connection



Figure 4: 220V/110V Converter Pigtail. This adapter allows the welder to connect to either 110V or 220V power outlets.

1. Ensure the welder is switched OFF.
2. Connect the main power cable to the welder's power input.
3. Use the provided 220V/110V converter pigtail if connecting to a 110V outlet. The welder automatically detects the voltage.
4. Plug the power cable into a suitable, grounded electrical outlet.

5.2. Gas Connection (TIG Welding)



Figure 5: Argon Regulator. This device is used to control the flow of argon gas from the cylinder to the TIG torch.



Figure 6: Gas Hose. This hose connects the argon regulator to the welder's gas inlet.

1. Attach the argon regulator to your argon gas cylinder.
2. Connect one end of the gas hose to the argon regulator and the other end to the "Ar" gas inlet on the rear of the welder.
3. Ensure all connections are tight to prevent gas leaks.

5.3. Torch and Clamp Connections



Figure 7: TIG Torch and Consumables. This image shows the TIG torch, collets, collet bodies, and ceramic nozzles included with the welder.



Figure 8: Ground Clamp. This clamp provides the electrical return path for the welding circuit and must be securely attached to the workpiece.



Figure 9: MMA/Stick Clamp. This clamp holds the welding electrode for Stick (MMA) welding.

1. Connect the TIG torch or MMA/Stick clamp to the appropriate output terminals on the front panel.
2. Connect the ground clamp to the designated ground terminal on the front panel.

3. Ensure all connections are secure.

5.4. Foot Pedal Connection




Figure 10: Foot Pedal. This accessory provides precise amperage control during TIG welding.

If using the foot pedal for TIG welding, connect it to the designated port on the front panel. The foot pedal allows for variable amperage control during welding.

6. OPERATING MODES

The LOTOS TIG200ACDC supports two primary welding processes:

6.1. TIG Welding (AC/DC)

TIG (Tungsten Inert Gas) welding provides precise control and high-quality welds, especially on thinner materials. The TIG200ACDC offers both AC and DC TIG capabilities:

- **AC TIG:** Ideal for welding aluminum and magnesium alloys. The AC current provides a cleaning action that breaks up aluminum oxide.
- **DC TIG:** Suitable for welding stainless steel, mild steel, copper, and other non-ferrous metals (except aluminum).

Use the mode switches on the front panel to select the desired current type (AC or DC) and the TIG welding process.

6.2. Stick (MMA) Welding (DC)

Stick (Manual Metal Arc) welding is a versatile process for various metals and thicknesses, often used outdoors or on dirty materials. The TIG200ACDC provides DC Stick/MMA welding capability:

- **DC Stick:** Offers easy arc start, a stable welding arc, and is suitable for welding with different kinds of acid or basic electrodes.

Use the mode switches on the front panel to select DC output and the MMA welding process.

7. OPERATING INSTRUCTIONS

Before operating, ensure all safety precautions are observed and the machine is correctly set up for your chosen welding process and material.

7.1. General Operation Steps

1. Turn on the welder using the main power switch.
2. Select the appropriate welding mode (AC/DC, TIG/MMA) using the front panel switches.
3. Adjust the amperage and other parameters (Pre-Flow, Clearance Effect, Downslope, Post-Flow) according to the material thickness and welding requirements.
4. For TIG welding, open the argon gas cylinder valve and set the flow rate using the regulator.
5. Securely attach the ground clamp to the workpiece.
6. Begin welding, maintaining proper technique and safety.
7. After welding, close the argon gas cylinder valve (if applicable) and turn off the welder.

7.2. Video Demonstration: LOTOS TIG200ACDC Welder Overview



Video 1: An overview of the LOTOS TIG200ACDC 200A AC/DC Aluminum Tig Welder, demonstrating its features and components. This video provides a visual guide to the machine's capabilities and setup.

8. MAINTENANCE

Regular maintenance ensures the longevity and optimal performance of your welder.

- **Cleaning:** Periodically clean the exterior of the machine and ensure cooling vents are free from dust and debris. Use compressed air to clear internal components if necessary, ensuring the machine is unplugged.
- **Cable Inspection:** Regularly inspect all cables (power, torch, ground) for damage, cuts, or frayed insulation. Replace damaged cables immediately.
- **Consumables:** Replace TIG torch consumables (tungsten, collets, collet bodies, nozzles) as they wear out to maintain weld quality.
- **Gas System:** Check gas hoses and connections for leaks. Ensure the argon regulator is functioning correctly.
- **Storage:** Store the welder in a clean, dry environment when not in use.

9. TROUBLESHOOTING

This section addresses common issues you might encounter. For more complex problems, contact customer support.

Problem	Possible Cause	Solution
---------	----------------	----------

Problem	Possible Cause	Solution
Welder does not power on.	No power supply; tripped circuit breaker; faulty power cable.	Check power connection; reset circuit breaker; inspect power cable.
No arc in TIG mode.	Incorrect gas flow; faulty tungsten; poor ground connection; wrong mode selected.	Check gas supply and flow rate; replace tungsten; ensure solid ground connection; verify TIG mode is selected.
Poor weld quality.	Incorrect amperage settings; improper gas shielding; contaminated material; worn consumables.	Adjust amperage; check gas flow and purity; clean workpiece; replace consumables.
Amperage display shows 010 or doesn't change.	Foot pedal connected but not in use, or a setting conflict.	If not using the foot pedal, unplug it from the machine. If using the foot pedal, depress it to see the actual amperage output.

10. SPECIFICATIONS

Feature	Detail
Model	TIG200ACDC
Item Model Number	1H-4HPT-NF6E
Manufacturer	Lotos Technology
Input Voltage	110/120 V, 220/240 V (Dual Voltage)
Input Frequency	50/60Hz
TIG Current Output	10-200A (AC/DC)
Stick/MMA Current Output	15-200A (DC)
Power Efficiency	80%
Item Weight	58 pounds
Product Dimensions	28 x 13 x 17 inches
Installation Method	TIG Welding

11. WARRANTY AND SUPPORT

LOTOS Technology offers a comprehensive warranty and customer support for the TIG200ACDC welder:

- **Money-Back Guarantee:** 30-day money-back guarantee.
- **New Replacement Warranty:** 1-year new replacement warranty.
- **Limited Warranty:** Total 3-year limited warranty.
- **Warranty Registration:** To activate your warranty, please submit the warranty registration form on the official LOTOS website.
- **Customer Service:** USA-based customer service is available via phone or email to assist with any inquiries or support needs.

For further assistance, please refer to the contact information provided on the LOTOS Technology website or in your warranty documentation.

