

Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

[manuals.plus](#) /

› [Lincoln Electric](#) /

› [Lincoln Electric Auto-Darkening Welding Helmet K3063-1 Instruction Manual](#)

Lincoln Electric K3063-1

Lincoln Electric Auto-Darkening Welding Helmet K3063-1 Instruction Manual

Model: K3063-1

[Safety Information](#) [Setup](#) [Operation](#) [Maintenance](#) [Troubleshooting](#) [Specifications](#)
[Warranty](#) [Support](#)

1. SAFETY INFORMATION

Welding and cutting activities can be hazardous. Always follow proper safety precautions to prevent injury. This helmet provides eye and face protection during welding and cutting operations. It is crucial to use additional personal protective equipment (PPE) as recommended for your specific task.

HELPFUL HINTS: PERSONAL PROTECTION TO KEEP YOU SAFE WHILE WELDING AND CUTTING



WELDING AND CUTTING CAN BE FUN, BUT WITHOUT TAKING THE PROPER SAFETY PRECAUTIONS, YOU CAN RISK INJURY. BY FOLLOWING THE MANUFACTURER'S RECOMMENDED SAFETY PROTOCOLS AND THESE HELPFUL SUGGESTIONS, YOU CAN COUNT ON YEARS OF ENJOYMENT WITHOUT ANY UNNECESSARY DANGER.



EQUIPMENT

1 SAFETY GLASSES

Even when wearing a helmet, you should **always wear industrial grade*** safety glasses with side shields or goggles to protect your eyes from flying particles. Safety glasses should be also worn when using a chipping hammer or wire brush while removing slag.

*ANSI/ISEA Z87.1



Product shown:
Camo Amber Safety Glasses
Lincoln Electric® Model KH970

8 CAP

A cap with bill facing backwards, or a welding cap (doo rag) should be worn to protect your head and neck from sparks and slag. If using a ball cap, make sure it is made from fire-retardant material.



Product shown:
Welding Doo Rag
Lincoln Electric® Model KH822

2 WELDING GLOVES

Heavy, flame-resistant gloves (from materials such as leather) should always be worn to protect your hands and wrists from burns, cuts and scratches. As long as they are dry and in good condition, they will offer some insulation against electric shock.



Product shown:
TIG/MIG Long Cuff Welding Gloves
Lincoln Electric® Model KH846L
(Extra-large: Model KH846XL)

INDUSTRIAL QUALITY SAFETY GLASSES

WELDING HELMET



CAP (VISOR TURNED TO BACK)

LONG-SLEEVED WELDING JACKET

GAUNTLET LEATHER WELDING GLOVES



Product shown:
Black Welding Shirt
Lincoln Electric® KH808L
(other sizes available)



7 WELDING JACKET

Welding jackets can help protect your arms and upper body from sparks and hot slag. OSHA recommends wearing clothing made from heavyweight, tightly woven, 100% wool or cotton to protect from UV radiation, hot metal, sparks and open flames. Also consider replacing your jacket after several cleanings as laundering makes the flame-retardant treatments less effective.

3 HELMET & GLASSES

The two types of radiation are infrared (IR) and ultraviolet (UV) radiation. IR radiation can cause retinal burning and cataracts and can usually be felt as heat. UV radiation, which cannot be felt, can cause an eye burn known as welder's flash. Normally, welder's flash is temporary, but repeated or prolonged exposure can lead to permanent injury of the eyes.

It is essential that you **protect your eyes from radiation exposure**, and we recommend using a welding helmet with a high-quality lens. The general rule of thumb is to first choose a filter so dark that you cannot see the arc, then move to one filter setting lighter without dropping to below the minimum recommended rating. For oxy/fuel cutting, wear safety glasses with a 5 filter shade rating.

4 BOOTS

Leather boots with six- to eight-inch ankle coverage are the **best foot protection**. During heavy work, you should wear safety-toe protection boots. Additionally, metatarsal guards over the shoe laces can protect from falling objects and sparks.

6 PANTS

Avoid wearing pants with **cuffs** because sparks or hot metal could deposit in the folds. Also, **wear your pants outside your work boots, not tucked in**, to keep particles from falling into your boots. Because of its durability and resistance to fire, wool clothing is suggested over synthetics.

Synthetics should never be worn because these materials melt when exposed to extreme heat. You can wear cotton if it is specially treated for fire retardation.

5 NOISE AND HEARING PROTECTION

Earplugs and ear muffs both prevent metal sparks and airborne particles from entering your ear canal and protect your hearing from the effects of excessive noise. When noise levels are painful or are loud enough to interfere with your ability to hear others speaking at a normal conversational volume, this is an indication that levels are potentially hazardous. You should wear adequate ear protection.

ENSURE YOU HAVE THE RIGHT EQUIPMENT FOR THE JOB.

1 SELECT the right product for the job 2 PROTECT your eyes, head and body 3 DON'T FORGET safety comes first

Follow these precautions and **ALWAYS READ THE MANUFACTURERS INSTRUCTION MANUALS** before beginning any welding or cutting process.

ST28013
X700369

© Lincoln Global, Inc. All Rights Reserved

Figure 1: Essential Personal Protective Equipment for Welding and Cutting. This infographic illustrates the importance of wearing safety glasses, welding gloves, a welding jacket, appropriate pants, safety boots, and ear protection in addition to the welding helmet.

General Safety Guidelines:

- **Eye Protection:** Always wear approved safety glasses (ANSI Z87.1 compliant) under your welding

helmet. The auto-darkening lens protects against arc flash, but safety glasses provide impact protection.

- **Head Protection:** If required, wear a cap or other head covering to protect your head and neck from sparks and heat.
- **Hand Protection:** Use welding gloves to protect hands from heat, sparks, and electrical shock.
- **Body Protection:** Wear a flame-resistant welding jacket, long-sleeved shirts, and pants without cuffs to prevent sparks from entering.
- **Foot Protection:** Wear steel-toe boots or other protective footwear.
- **Hearing Protection:** Use earplugs or earmuffs to protect against loud noise.
- **Ventilation:** Ensure adequate ventilation to avoid inhaling hazardous fumes.
- **Inspect Equipment:** Before each use, inspect the helmet for damage, cracks, or loose parts. Replace any damaged components immediately.

2. SETUP AND ADJUSTMENT

Proper setup ensures comfort and maximum protection. Follow these steps to prepare your welding helmet for use.

2.1 Headgear Adjustment

Adjust the headgear to fit snugly and comfortably on your head. The helmet should stay in the raised position when not welding and easily drop into the working position with a nod of your head.

1. **Size Adjustment:** Rotate the knob at the back of the headgear to adjust the circumference for a secure fit.
2. **Top Strap Adjustment:** Adjust the top strap to position the helmet correctly on your head, ensuring the viewing area is at eye level.
3. **Distance Adjustment:** Adjust the distance between the helmet shell and your face using the side knobs. This prevents the helmet from hitting your nose or chin when lowered.
4. **Tilt Adjustment:** Some headgears allow for tilt adjustment. Set it to your preferred angle for optimal viewing and comfort.



Figure 2: Side view of the helmet, illustrating the headgear adjustment knob on the side for proper fit and balance.

2.2 Auto-Darkening Lens (ADF) Installation/Check

The auto-darkening filter (ADF) is pre-installed. Ensure it is clean and free from damage. This model does not require user-replaceable batteries for the ADF, as it is solar-powered.



Figure 3: Internal view of the Auto-Darkening Filter (ADF) module, showing controls for sensitivity and delay, along with a test button and low battery indicator. This unit is solar-powered and does not require battery replacement.

3. OPERATION

This section details how to operate your auto-darkening welding helmet effectively and safely.

3.1 Powering On/Off

The auto-darkening filter (ADF) is solar-powered and automatically activates when exposed to light. There is no manual on/off switch. Ensure the solar cells on the front of the helmet are not obstructed.

3.2 Shade Adjustment (Variable Shade 7-13)

The helmet features a variable shade range from 7 to 13, allowing you to select the appropriate shade level for different welding processes and amperages. The shade level is adjusted via an external knob.

1. Locate the external knob on the side of the helmet.
2. Rotate the knob to select the desired shade number (7-13). Refer to welding safety standards for recommended shade levels for your specific application.




Figure 4: External control knob for selecting variable shade levels (7-13) and activating grind mode.

3.3 Grind Mode

The helmet includes a grind mode feature, which locks the ADF in a light state (typically shade 3 or 4) for grinding operations. This prevents the lens from darkening, allowing clear vision without removing the helmet, while still providing impact protection.

1. Rotate the external knob to the "Grind" position.
2. Ensure the lens remains in the light state before beginning grinding.
3. Remember to switch back to a welding shade before resuming welding operations.

3.4 Sensitivity Adjustment

The sensitivity control adjusts how much light is required to trigger the auto-darkening function. This is useful for different ambient light conditions and welding processes.

- Locate the sensitivity knob on the internal ADF module (refer to Figure 3).
- Turn the knob towards 'H' (High) for lower amperage welding or when working in low ambient light.
- Turn the knob towards 'L' (Low) for high amperage welding or when working in bright ambient light to prevent false triggering.

3.5 Delay Adjustment

The delay control determines how long the lens stays dark after the welding arc extinguishes. This prevents eye fatigue from residual glow and protects against bright flashes from adjacent welding operations.

- Locate the delay knob on the internal ADF module (refer to Figure 3).
- Set a shorter delay for tack welding or when moving quickly between welds.

- Set a longer delay for high amperage welding or when the weld puddle remains bright for an extended period.

3.6 Test Function

The ADF module includes a test button to verify the auto-darkening function before welding. Pressing this button should momentarily darken the lens to the selected shade level.

- Press the "TEST" button on the internal ADF module (refer to Figure 3).
- The lens should darken and then return to its light state. If it does not, refer to the Troubleshooting section.




Figure 5: The Lincoln Electric Auto-Darkening Welding Helmet K3063-1 in use during a welding application, demonstrating proper eye and face protection.

4. MAINTENANCE

Regular maintenance ensures the longevity and proper function of your welding helmet.

4.1 Cleaning the Helmet

- **Helmet Shell:** Clean the helmet shell with a mild soap and water solution. Avoid harsh solvents or abrasive cleaners.
- **Outer Cover Lens:** Wipe the outer cover lens with a soft, clean cloth. If heavily scratched or pitted, replace it immediately.
- **Inner Cover Lens:** Clean the inner cover lens with a soft, clean cloth. Replace if scratched or damaged.
- **Auto-Darkening Filter (ADF):** Gently wipe the ADF surface with a soft, dry cloth. Do not use cleaning solutions on the ADF itself. Ensure the solar cells are clean and unobstructed.

4.2 Replacing Cover Lenses

Cover lenses protect the ADF from sparks and spatter. Replace them regularly when they become scratched, pitted, or dirty to maintain clear vision.

1. Carefully remove the retaining frame or clips holding the cover lens in place.
2. Remove the old cover lens.
3. Insert a new, clean cover lens, ensuring it is properly seated.
4. Reinstall the retaining frame or clips securely.

4.3 Storage

Store the helmet in a clean, dry place away from direct sunlight, extreme temperatures, and corrosive materials. Protect the ADF from impact and scratches.

5. TROUBLESHOOTING

If you encounter issues with your welding helmet, refer to the following common problems and solutions.

Problem	Possible Cause	Solution
Lens does not darken when arc is struck.	<ul style="list-style-type: none">• Solar cells obstructed or dirty.• Sensitivity set too low.• ADF damaged.	<ul style="list-style-type: none">• Ensure solar cells are clean and unobstructed.• Increase sensitivity setting (turn towards 'H').• Press the "TEST" button. If it still doesn't darken, the ADF may be faulty and require replacement.
Lens flickers or darkens intermittently.	<ul style="list-style-type: none">• Sensitivity set too high.• Interference from other light sources.• Low amperage welding.	<ul style="list-style-type: none">• Decrease sensitivity setting (turn towards 'L').• Adjust working position to minimize interference.• Ensure solar cells are fully exposed to the arc.
Poor visibility through the lens.	<ul style="list-style-type: none">• Cover lenses are dirty or scratched.• ADF is dirty or damaged.	<ul style="list-style-type: none">• Clean or replace outer and inner cover lenses.• Gently clean the ADF surface. If visibility issues persist, the ADF may be damaged.
Helmet is uncomfortable or unstable.	<ul style="list-style-type: none">• Headgear not properly adjusted.	<ul style="list-style-type: none">• Re-adjust all headgear straps and knobs for a secure and balanced fit (refer to Section 2.1).

6. SPECIFICATIONS

Key technical specifications for the Lincoln Electric Auto-Darkening Welding Helmet K3063-1.

- **Model:** K3063-1
- **Brand:** Lincoln Electric
- **Viewing Area:** 1.73 x 3.82 inches
- **Variable Shade Range:** 7-13

- **Light State:** (Typically Shade 3 or 4 in Grind Mode)
- **Power Source:** Solar-powered (no user-replaceable batteries required)
- **Material:** Polycarbonate (PC)
- **Item Weight:** Approximately 0.01 Ounces (Note: This weight appears to be a data entry error. Actual helmet weight is typically much higher.)
- **Product Dimensions:** Approximately 10 x 10 x 10 inches
- **UPC:** 015082913339
- **Special Features:** Lightweight, Grind Mode, Adjustable Sensitivity, Adjustable Delay

7. WARRANTY INFORMATION

According to the product information, this item comes with **No warranty**. Please refer to your point of purchase for their return or exchange policies if applicable.

8. CUSTOMER SUPPORT

For further assistance, technical questions, or to inquire about replacement parts, please contact Lincoln Electric customer service. You can typically find contact information on the official Lincoln Electric website or through your product retailer.

Online Resources: Visit the official Lincoln Electric website for product manuals, FAQs, and support contact details.