



Manuals.plus /

- › GAIN EXPRESS /
- › GAIN EXPRESS Digital Car Window Tint Meter WTM-1100 Instruction Manual

GAIN EXPRESS WTM-1100

GAIN EXPRESS Digital Car Window Tint Meter

MODEL: WTM-1100

Instruction Manual

[Safety Information](#)

[Product Overview](#)
[Troubleshooting](#)

[Setup](#)
[Specifications](#)

[Operating Instructions](#)
[Warranty & Support](#)

[Maintenance](#)

1. Safety Information

Please read this manual carefully before operating the GAIN EXPRESS Digital Car Window Tint Meter WTM-1100. Retain this manual for future reference.

- Do not attempt to disassemble or modify the device. This may void the warranty and cause damage.
- Keep the device away from water and excessive humidity.
- Avoid exposing the device to extreme temperatures or direct sunlight for prolonged periods.
- Use only the specified battery type (AAA alkaline batteries) for power.
- Handle the measuring probes with care to prevent damage to the optical components.
- Ensure proper alignment of the probes during measurement to obtain accurate readings.

2. Product Overview

The GAIN EXPRESS WTM-1100 is a portable digital window tint meter designed for accurately measuring the Visible Light Transmission (VLT) through various transparent or translucent materials, including automotive windows, filmed glass, and other samples. While the product title mentions capabilities for UV IR Rejection and Spectrum Testing, the primary measurement detailed in the specifications is Visible Light Transmission at 550 nanometers. It features a clear LCD display, one-key calibration, and a compact design for ease of use.

Key Features:

- **Accurate Measurement:** Precisely measures Visible Light Transmission (VLT) from 0% to 100%.
- **Versatile Applications:** Suitable for automotive, aerospace, glass products, plastic sheets, and more.

- **Digital Display:** Features a 10mm LCD display for clear reading results.
- **High Resolution:** Provides accurate and reliable readings with high resolution.
- **Portable Design:** Solid structure, small size, and lightweight for easy carrying and use.
- **Continuous Measuring Mode:** Allows for ongoing measurements.
- **Internal Light Source:** Enables use in various lighting conditions, day or night.
- **One-Key Calibration:** Simplifies the calibration process for user convenience.
- **Optional PC Connectivity:** Can be connected to a PC via an optional RS232C cable and software (not included) for expanded functionality.



Figure 2.1: GAIN EXPRESS Digital Car Window Tint Meter WTM-1100. This image shows the main unit of the tint meter, highlighting its compact design and digital display.



Figure 2.2: Labeled components of the WTM-1100 Tint Meter. This image identifies the RS-232 port, display, calibration key, power key, and measuring probes.

3. Setup

3.1 Battery Installation

The WTM-1100 meter is powered by four AAA alkaline batteries. To install or replace batteries:

1. Locate the battery compartment cover on the back of the device.
2. Slide the cover open.
3. Insert four AAA alkaline batteries, ensuring correct polarity (+/-).
4. Close the battery compartment cover securely.



Figure 3.1: Battery compartment. This image shows the open battery compartment on the back of the device, ready for battery insertion.

3.2 Power On and Self-Calibration

After battery installation, the device will perform a self-calibration upon power-on. This ensures accuracy without manual adjustment.

1. Press the **Power** button to turn on the instrument.
2. The instrument will automatically self-calibrate. During this process, the display will show initial values and then settle to 100% VLT (or similar initial values depending on the model variant).
3. Once self-calibration is complete, the device is ready for use.

[Your browser does not support the video tag.](#)

Video 3.1: LS162 Transmission Meter Instruction Guide. This video demonstrates the battery installation, power-on sequence, and automatic self-calibration of a similar transmission meter, showing the display settling to initial values.

4. Operating Instructions

4.1 Taking a Measurement

To measure the light transmission of a sample:

1. Ensure the device is powered on and has completed its self-calibration.
2. Carefully insert the material (e.g., window, film) into the test slot between the transmitter and receiver probes.
3. Ensure the two markings on the probe are properly aligned for accurate results.
4. The measured Visible Light Transmission (VLT) percentage will be displayed instantly on the LCD.



NOTE:

For accurate measurements, ensure the two markings on the probe are properly aligned.

Figure 4.1: Proper probe alignment. This image illustrates how to align the two markings on the measuring probe to ensure accurate readings.

Your browser does not support the video tag.

Video 4.1: Window Tint Meter Operation. This video demonstrates the process of placing a window between the transmitter and receiver to obtain a tint measurement.

4.2 Checking Calibration

To quickly verify the accuracy of the device's calibration:

1. Use the included reference sample (test sheet) if available.
2. Place the receiver probe on top of the test sheet.
3. Compare the value shown on the LCD with the specified value on the test sheet. They should match closely.

Your browser does not support the video tag.

Video 4.2: Calibration Check. This video shows how to verify the meter's accuracy by comparing its reading with a reference sample.

4.3 Data Hold Function

The device features a data hold function to freeze the current reading on the display.

- After taking a measurement, short press the **DATA TRANS** button (or equivalent data hold button) to lock the displayed value.

- The "HOLD" indicator may appear on the screen.
- To release the hold and return to live measurement, short press the button again.



Figure 4.2: One-key calibration. This image highlights the 'CAL' button, which is used for calibration or data hold depending on the model variant.

Your browser does not support the video tag.

Video 4.3: Data Hold Function. This video demonstrates how to use the data hold function to lock a measurement on the display.

4.4 RS232C Connectivity (Optional)

The WTM-1100 can be connected to a PC for data transfer and analysis using an optional RS232C cable and software (not included).

- Locate the RS-232 port on the device.
- Connect the RS232C cable (purchased separately) from the device to your PC.
- Install the appropriate software on your PC to enable data communication.



Figure 4.3: RS232C port. This image shows the RS232C port located on the side of the device for optional PC connectivity.

5. Maintenance

5.1 Cleaning

- Wipe the device exterior with a soft, dry cloth.
- Do not use abrasive cleaners or solvents, as these may damage the casing or display.
- Keep the optical components of the probes clean and free from dust or smudges. Use a soft, lint-free cloth specifically designed for optics if necessary.

5.2 Battery Replacement

When the low battery indicator appears on the display, replace the batteries as described in Section 3.1. Always replace all four batteries at once with new AAA alkaline batteries.

5.3 Storage

Store the device in a dry, cool place, away from direct sunlight and extreme temperatures. The recommended storage environment is -70 to 50 degrees Celsius with less than 80% relative humidity (non-condensing).

6. Troubleshooting

Problem	Possible Cause	Solution
Device does not power on.	Dead or incorrectly installed batteries.	Check battery polarity. Replace with new AAA alkaline batteries.
Inaccurate or inconsistent readings.	Probes not properly aligned. Dirty optical components. Device not calibrated.	Ensure probes are aligned (refer to Figure 4.1). Clean the optical components of the probes. Perform a calibration check (refer to Section 4.2).
Display shows "Low Battery" or similar.	Batteries are low.	Replace all four AAA alkaline batteries.

7. Specifications

Parameter	Value
Model Number	WTM-1100
Measurement Type	Transmission Meter
Resolution	0.1
Accuracy	≤ 2%
Wavelength	550 Nanometers (Visible Light)
Measurement Range	0~100% Light Transmission
Sample Thickness	Less than 18mm / 0.4 inch
Power Source	Battery Powered (4 x AAA alkaline batteries)
Minimum Operating Voltage	1.5 Volts
Upper Temperature Rating	50 Degrees Celsius
Operating Environment	0-50°C, <80% RH (No condensation)
Storage Environment	-70-50°C, <80% RH
Item Weight	100 Grams
Product Dimensions (L x W x H)	25.4 x 5.1 x 20.3 Centimetres
Interface	RS-232C (optional, not included)



Figure 7.1: Specifications. This image provides a visual summary of the key technical specifications for the WTM-1100.



Figure 7.2: Dimensions. This image shows the physical dimensions of the main unit and the probe.

8. Warranty and Support

GAIN EXPRESS products are manufactured to high-quality standards. For warranty information and technical support, please refer to the warranty card included with your product or contact your retailer.

Keep your purchase receipt as proof of purchase.

For further assistance, please visit the GAIN EXPRESS store on Amazon or contact their customer service directly.

Manufacturer: Gain Express Holdings Ltd

Place of Business: To Kwa Wan, Kowloon, 000, HK