

Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

[manuals.plus](#) /

› [Meco](#) /

› [Meco 2250-HZ Auto Digital Clamp Meter User Manual](#)

Meco 2250-HZ AUTO

Meco 2250-HZ Auto Digital Clamp Meter User Manual

Model: 2250-HZ AUTO

1. INTRODUCTION

This manual provides detailed instructions for the safe and effective operation of the Meco 2250-HZ Auto Digital Clamp Meter. This device is designed for measuring various electrical parameters, including AC/DC voltage, AC current, frequency, continuity, and diode testing. Please read this manual thoroughly before use and retain it for future reference.

2. SAFETY INFORMATION

Always observe standard safety precautions when working with electrical circuits. Failure to do so may result in injury or damage to the meter. This meter is designed with over-voltage protection up to 200V DC and AC Peak. However, exercise caution.

- Do not attempt to measure voltages or currents exceeding the specified maximum limits.
- Ensure the test leads are in good condition and properly connected before making measurements.
- Do not operate the meter if it appears damaged or if the battery cover is not securely closed.
- Avoid using the meter in wet environments or in the presence of explosive gases or dust.
- Always disconnect power to the circuit before connecting or disconnecting test leads, especially for current measurements.

3. PRODUCT OVERVIEW

The Meco 2250-HZ Auto Digital Clamp Meter features a robust design for reliable performance. Familiarize yourself with the components shown below.



Figure 1: Front view of the Meco 2250-HZ Auto Digital Clamp Meter. This image displays the clamp jaw at the top, the LCD screen showing '1000', the function dial, and the input terminals at the bottom. The 'SELECT' and 'DATA HOLD' buttons are visible next to the display.

Key Components:

- **Clamp Jaw:** Used for non-contact AC current measurement.
- **LCD Display:** 3½ digit liquid crystal display with a maximum reading of 3999. Shows measurement values, polarity, overrange indication (OL or -OL), and low battery indication.
- **Function Dial:** Rotary switch to select measurement functions (OFF, Volts DC/AC, Hz, ACA 40A/400A/1000A).
- **SELECT Button:** Used to switch between DC and AC voltage modes, or other sub-functions within a dial setting.

- **DATA HOLD Button:** Freezes the current reading on the display. Press again to release.
- **Input Terminals (COM, VΩ):** For connecting test leads for voltage, resistance, continuity, and diode measurements.

4. SETUP

4.1 Battery Installation

The Meco 2250-HZ Auto Digital Clamp Meter requires batteries for operation. Batteries are not included with the product. To install or replace batteries:

1. Ensure the meter is turned OFF.
2. Locate the battery compartment on the back of the meter.
3. Use a screwdriver to open the battery compartment cover.
4. Insert the required batteries, observing correct polarity (+ and -).
5. Replace the battery compartment cover and secure it with the screw.

A low battery indication will appear on the display when the battery voltage is low, signaling the need for replacement.

5. OPERATING INSTRUCTIONS

5.1 General Operation

- Turn the function dial to the desired measurement setting.
- Connect test leads to the appropriate input terminals (COM and VΩ) for voltage, resistance, continuity, or diode tests.
- For current measurements, use the clamp jaw around a single conductor.
- Press the **SELECT** button to toggle between AC/DC modes or other sub-functions if available for the selected range.
- Press the **DATA HOLD** button to freeze the current reading on the display. Press again to release.

5.2 AC/DC Voltage Measurement

1. Set the function dial to the "VOLTS" position.
2. Connect the black test lead to the COM terminal and the red test lead to the VΩ terminal.
3. Press the **SELECT** button to choose between AC or DC voltage measurement. The display will indicate "AC" or "DC".
4. Connect the test leads in parallel to the circuit or component under test.
5. Read the voltage value on the LCD display.

5.3 AC Current Measurement (Clamp)

1. Set the function dial to the desired AC current range (40A, 400A, or 1000A).
2. Open the clamp jaw by pressing the trigger.
3. Enclose only one conductor of the circuit within the clamp jaw. Ensure the jaw is fully closed.
4. Read the AC current value on the LCD display.

5.4 Frequency (Hz) Measurement

1. Set the function dial to the "Hz" position.
2. Connect the black test lead to the COM terminal and the red test lead to the VΩ terminal.

3. Connect the test leads in parallel to the circuit where frequency needs to be measured.
4. Read the frequency value in Hertz (Hz) on the LCD display.

5.5 Audible Continuity Check

1. Set the function dial to the continuity/diode symbol (often shared with resistance).
2. Connect the black test lead to the COM terminal and the red test lead to the VΩ terminal.
3. Touch the test probes across the component or circuit to be tested.
4. If continuity exists (low resistance), the meter will emit an audible beep.

5.6 Diode Test

1. Set the function dial to the continuity/diode symbol.
2. Connect the black test lead to the COM terminal and the red test lead to the VΩ terminal.
3. Connect the red test lead to the anode of the diode and the black test lead to the cathode. The display will show the forward voltage drop.
4. Reverse the test leads. The display should show "OL" (overload) for a good diode.

6. MAINTENANCE

6.1 Cleaning

Wipe the meter's casing with a damp cloth and a mild detergent. Do not use abrasives or solvents. Keep the display clean and dry.

6.2 Battery Replacement

Refer to Section 4.1 for battery installation and replacement instructions. Replace batteries promptly when the low battery indicator appears to ensure accurate readings.

7. TROUBLESHOOTING

Problem	Possible Cause	Solution
Meter does not power on.	Dead or incorrectly installed batteries.	Check battery polarity and replace batteries if necessary.
"OL" or "-OL" displayed.	Overrange condition; measurement exceeds meter's range.	Select a higher range or ensure the measured value is within the meter's capabilities.
Inaccurate readings.	Low battery, poor test lead connection, or incorrect function selection.	Replace batteries, ensure secure connections, verify function dial setting.
No audible beep during continuity test.	Open circuit or high resistance.	Verify the circuit is closed and resistance is low enough for continuity.

8. SPECIFICATIONS

Feature	Detail

Feature	Detail
Display	3¾ digit LCD, max reading 3999
Polarity	Automatic, negative polarity indication
Overrange Indication	"OL" or "-OL" displayed
Zero Adjustment	Automatic
Battery Life	200 hours typical
Over Voltage Protection	200V DC and AC Peak
Audible Continuity Check	Yes
Diode Test	Yes
Low Battery Indication	Yes
Item Weight	600 g (1.32 Pounds)
Product Dimensions	21 x 13 x 6 cm
Material	Plastic
Manufacturer	Meco Instruments

9. WARRANTY AND SUPPORT

For warranty information or technical support, please contact the retailer or the manufacturer, Meco Instruments, directly. Keep your purchase receipt as proof of purchase.

Related Documents - 2250-HZ AUTO



[Klein Tools CL810 Instruction Manual: 600A AC/DC Auto-Ranging TRMS Clamp Meter with Work Light](#)

Instruction manual for the Klein Tools CL810 clamp meter, detailing its features, specifications, and operating procedures for electrical measurements including AC/DC current, voltage, resistance, continuity, frequency, capacitance, diode testing, NCV detection, and work light functionality.



[ANENG ST212 Digital Clamp Meter User Manual](#)

Comprehensive user manual for the ANENG ST212 Digital Clamp Meter, covering safety information, specifications, operation guides, and maintenance for AC/DC current, voltage, resistance, capacitance, and temperature measurements.




[Klein Tools CL220 400A AC Auto-Ranging Digital Clamp Meter Instruction Manual](#)

Comprehensive instruction manual for the Klein Tools CL220, a 400A AC auto-ranging digital clamp meter featuring True RMS measurement technology, non-contact voltage testing, data hold, temperature measurement, and audible continuity. Includes general and electrical specifications, operating instructions, safety warnings, and maintenance details.




[Klein Tools CL390 400A AC/DC Auto-Ranging Digital Clamp Meter Instruction Manual](#)

Comprehensive instruction manual for the Klein Tools CL390 digital clamp meter, detailing its features, specifications, and safe operating procedures for AC/DC current, voltage, resistance, and temperature measurements.



[Sealey MM102 Professional Auto-Ranging Digital Multimeter User Manual and Instructions](#)


Detailed user manual and operating instructions for the Sealey MM102 Professional Auto-Ranging Digital Multimeter, including safety precautions, specifications, and maintenance guides.



[ANENG 683 Touch Meter User Manual: Features, Specs & Operation Guide](#)

Comprehensive user manual for the ANENG 683 digital multimeter. Covers safety, specifications, measurement functions (voltage, current, resistance, etc.), and operational guidance for electrical testing.

Documents - Meco – 2250-HZ AUTO




[\[pdf\] User Manual Specifications Dimension Guide Accessories](#)

9A 05 final comp 2 mecoinst products manual online dt3150 Em306b Digital Clamp Meter Manual |||

Bus-Bar upto 16mm x 65mm Cable upto 43mm Diameter DIGITAL CLAMP METER MODEL : DT3150 1. SPECIFICATIONS 1.1 General Specification Display n 3 digit liquid crystal display LCD with a maximum reading of 3999. Polarity n Automatic, positive implied, negative polarity indication. Overrange n ...

lang:en score:24 filesize: 194.79 K page_count: 8 document date: 2006-09-13




[\[pdf\] User Manual Specifications Dimension Guide Accessories](#)

3150 aboli AUTORANGING DIGITAL CLAMP METER 2250hz auto 3690auto mecoinst products manual online |||

Bus-Bar upto 16mm x 65mm Cable upto 43mm Diameter AUTORANGING DIGITAL CLAMP METER MODEL : DT3150 1. SPECIFICATIONS 1.1 General Specification Display n 3 digit liquid crystal display LCD with a maximum reading of 3999. Polarity n Automatic, positive implied, negative polarity indication. O...

lang:en score:21 filesize: 243.75 K page_count: 10 document date: 2012-10-17



[\[pdf\] Test Report Catalog](#)

Meco Product Catalog 2023 meco product catalog mecoinst |||

Certifications / Approvals ISO 9001:2015 CERTIFICATE C/QA I/SV January 23, 2007

M/s Meco instruments Pvt. Ltd., Plot No.EL-1, MIDC Electronic Zone TTC Industrial Area, Mahape, Navi Mumbai-400710 Fax No. 022-27673310/27673330 Kind Attn. : Shri Kamal Goliya CEO Sub : Approval of MECO Make In...

lang:en **score:17** filesize: 19.52 M page_count: 160 document date: 2023-04-03



[\[pdf\] Test Report Catalog](#)

Meco Products Catalog 2025 Panel and Switchboard Instruments Test Measuring Power Harmonics

Analyzers by Pvt Ltd Mmeco product catalog 2025mecoinst meco |||

60 YEARS INDIA ONE MISSION Reliable Long-Lasting Affordable INDIA

Certifications / Approvals ISO 9001:2015 CERTIFICATE STQC TYPE TEST

REPORT ISO 9001-2015 Certified Company EIL APPROVAL C/QA I/SV January 23, 2007 M/s Meco instruments Pvt. Ltd., Plot No.EL-1, MIDC Electronic Zone TTC Ind...

lang:en **score:16** filesize: 20.95 M page_count: 168 document date: 2025-04-02



[\[pdf\] Catalog](#)

CLAMP METER New Godown metrix aca dca digital clamp meterDigital Power Clamp Meter 3510 PW

8400 Page No 17 to 20 93 3 ACA Digital Metrix @ With 10% Discount Sr Description Model Rs

Catalogmetrix meter4 imimg data4 DC BO MY 419417 meter |||

Quotation 93 Clamp Meter Lutron / Kusum Meco make Model no Make ACA / DCA

ACV / DCV Temp. Rs. Calibration Catalog DM 6046 Lutron 1000 600 -- 2900 900

Page No - 3 DM 6055 C Lutron 1000 600 with 4550 900 Page No - 5 CM 9930 Lutron 2000 1000 6650 900 Page No - 6 CM 9940 Lutron 600 600 3580 900 P...

lang:tl **score:14** filesize: 1.63 M page_count: 21 document date: 2016-06-15

