

[manuals.plus](#) /› [UNI-T](#) /› [UNI-T UT33C Palm Size Digital Handheld Multimeter Instruction Manual](#)

UNI-T UT33C

UNI-T UT33C Digital Handheld Multimeter Instruction Manual

1. INTRODUCTION

This manual provides detailed instructions for the safe and effective operation of the UNI-T UT33C Digital Handheld Multimeter. The UT33C is a compact, battery-powered device designed for measuring DC/AC voltage, DC current, resistance, diode, continuity, and temperature. Please read this manual thoroughly before use to ensure proper functionality and safety.

2. SAFETY INFORMATION

WARNING: To avoid electric shock or personal injury, read and understand all safety information before using this multimeter.

- Always ensure the test leads are correctly inserted into the appropriate input jacks for the measurement being performed.
- Do not exceed the maximum input values specified for each range. Refer to the specifications section.
- Never use the multimeter if it appears damaged or if the test leads are damaged.
- Do not operate the multimeter in explosive gas, vapor, or dusty environments.
- Always turn off the circuit power and discharge all high-voltage capacitors before testing resistance, continuity, or diodes.
- Replace the battery immediately when the low battery indicator appears on the display.
- Ensure the battery cover is securely closed before operation.
- Adhere to local and national safety codes.

3. PRODUCT FEATURES

- Palm-size design for easy portability.
- Measures DC/AC Voltage, DC Current, Resistance.
- Diode and Continuity test functions.
- Temperature measurement in Celsius and Fahrenheit.
- Data Hold function for convenient reading.

- Backlight for clear display in low-light conditions.
- Low battery indication.

4. PRODUCT OVERVIEW AND COMPONENTS

The UNI-T UT33C multimeter features a clear digital display, a central rotary switch for function selection, and input jacks for test leads. Below is an illustration and description of its main components.




Figure 1: Front view of the UNI-T UT33C Digital Multimeter. This image displays the red casing, LCD screen showing '00.0', 'HOLD' button, backlight button, central rotary switch with various measurement functions (voltage, current, resistance, temperature, diode, continuity), and three input jacks at the bottom for test leads.

Key Components:

1. **LCD Display:** Shows measurement readings, units, and function indicators.

2. **HOLD Button:** Freezes the current reading on the display.
3. **Backlight Button (Snowflake/Light Symbol):** Activates or deactivates the display backlight.
4. **Rotary Switch:** Used to select the desired measurement function and range.
5. **10A Input Jack:** For DC current measurements up to 10A.
6. **VΩmACF Input Jack:** For voltage, resistance, milliampere current, capacitance, and frequency measurements. This is the positive (+) input.
7. **COM Input Jack:** Common (negative -) input for all measurements.

5. SETUP

5.1 Battery Installation

1. Ensure the multimeter is turned OFF.
2. Locate the battery compartment on the back of the unit.
3. Use a screwdriver to remove the screw securing the battery cover.
4. Carefully remove the cover.
5. Insert a new 9V battery, observing the correct polarity (+ and -).
6. Replace the battery cover and secure it with the screw.

5.2 Test Lead Connection

1. For most measurements (voltage, resistance, diode, continuity, temperature, and current up to 200mA), connect the black test lead to the **COM** jack and the red test lead to the **VΩmACF** jack.
2. For DC current measurements between 200mA and 10A, connect the black test lead to the **COM** jack and the red test lead to the **10A** jack.

6. OPERATING INSTRUCTIONS

Always select the appropriate function and range using the rotary switch before connecting the test leads to the circuit under test.

6.1 Measuring DC Voltage (V=)

1. Connect the test leads as described in Section 5.2 (COM and VΩmACF).
2. Set the rotary switch to the desired DC Voltage (V=) range (e.g., 200m, 2000m, 20, 200, 500). If the voltage is unknown, start with the highest range (500V) and decrease as necessary.
3. Connect the test leads across the component or circuit to be measured, observing polarity.
4. Read the voltage value on the LCD display.

6.2 Measuring AC Voltage (V~)

1. Connect the test leads as described in Section 5.2 (COM and VΩmACF).
2. Set the rotary switch to the desired AC Voltage (V~) range (e.g., 200, 500). If the voltage is unknown, start with the highest range (500V) and decrease as necessary.
3. Connect the test leads across the component or circuit to be measured. Polarity is not critical for AC voltage.
4. Read the voltage value on the LCD display.

6.3 Measuring DC Current (A=)

1. **For 200mA or less:** Connect the black test lead to COM and the red test lead to VΩmACF.
2. **For 10A:** Connect the black test lead to COM and the red test lead to 10A.
3. Set the rotary switch to the desired DC Current (A=) range (e.g., 20m, 200m, 10A). Start with the highest range if the current is unknown.
4. Open the circuit where current is to be measured and connect the multimeter in series with the load.
5. Read the current value on the LCD display.

6.4 Measuring Resistance (Ω)

1. Ensure the circuit is de-energized and all capacitors are discharged.
2. Connect the test leads as described in Section 5.2 (COM and VΩmACF).
3. Set the rotary switch to the desired Resistance (Ω) range (e.g., 200, 2000, 20k, 200k, 20M). Start with a higher range if the resistance is unknown.
4. Connect the test leads across the component to be measured.
5. Read the resistance value on the LCD display.

6.5 Diode Test

1. Ensure the circuit is de-energized.
2. Connect the test leads as described in Section 5.2 (COM and VΩmACF).
3. Set the rotary switch to the Diode symbol.
4. Connect the red test lead to the anode and the black test lead to the cathode of the diode. A forward voltage drop (typically 0.5V to 0.8V for silicon diodes) will be displayed.
5. Reverse the test leads. The display should show 'OL' (Open Loop) for a good diode.

6.6 Continuity Test

1. Ensure the circuit is de-energized.
2. Connect the test leads as described in Section 5.2 (COM and VΩmACF).
3. Set the rotary switch to the Continuity (buzzer) symbol.
4. Connect the test leads across the component or circuit path.
5. If the resistance is below approximately 50Ω, the buzzer will sound, indicating continuity. The display will also show the resistance value.

6.7 Temperature Measurement (°C/°F)

1. Connect the temperature probe (K-type thermocouple, not included with all models) to the VΩmACF (positive) and COM (negative) jacks, observing polarity.
2. Set the rotary switch to the °C or °F position.
3. Place the tip of the temperature probe on or near the object whose temperature is to be measured.
4. Read the temperature value on the LCD display.

6.8 Data Hold Function

Press the **HOLD** button to freeze the current reading on the display. Press it again to release the hold function and resume live measurements.

6.9 Backlight Function

Press the **Snowflake/Light** button to turn on the display backlight. Press it again to turn off the backlight. This feature is useful in dimly lit environments.

7. MAINTENANCE

7.1 Battery Replacement

When the low battery indicator appears on the display, replace the 9V battery as soon as possible to ensure accurate measurements. Follow the steps outlined in Section 5.1.

7.2 Fuse Replacement

The 10A input jack is protected by a fuse. If the multimeter fails to measure current in the 10A range, the fuse may need replacement. Refer to the specifications for the correct fuse type. Fuse replacement should only be performed by qualified personnel.

1. Ensure the multimeter is turned OFF and test leads are disconnected.
2. Remove the battery cover and battery.
3. Unscrew the case screws and carefully open the multimeter casing.
4. Locate the fuse(s) and replace the blown fuse with one of the identical type and rating.
5. Carefully reassemble the casing, ensuring all screws are tightened.

7.3 Cleaning

Wipe the case with a damp cloth and mild detergent. Do not use abrasives or solvents. Ensure the multimeter is completely dry before use.

8. TROUBLESHOOTING

Problem	Possible Cause	Solution
No display or dim display	Low battery or no battery.	Replace the 9V battery.
'OL' (Overload) displayed	Input value exceeds selected range.	Select a higher range or check if the circuit is open.
Incorrect readings	Incorrect function/range selected, poor test lead connection, or damaged test leads.	Verify function/range, ensure secure connections, inspect/replace test leads.
No current measurement (10A range)	Blown fuse.	Replace the fuse (refer to Section 7.2).

9. SPECIFICATIONS

Parameter	Value
-----------	-------

Parameter	Value
Manufacturer	UNI-T
Model Number	UT33C
Measurement Type	Multimeter
DC Voltage Ranges	200mV, 2000mV, 20V, 200V, 500V
AC Voltage Ranges	200V, 500V
DC Current Ranges	20mA, 200mA, 10A
Resistance Ranges	200Ω, 2000Ω, 20kΩ, 200kΩ, 20MΩ
Diode Test	Yes
Continuity Test	Yes (with buzzer)
Temperature Measurement	Yes (°C, °F)
Data Hold	Yes
Backlight	Yes
Power Source	9V Battery
Item Weight	150 g
Product Dimensions	150 x 100 x 100 cm
Safety Rating	CATI 600V, CATII 300V (UL 61010-1, IEC 61010-2-030)

10. WARRANTY AND SUPPORT

The UNI-T UT33C Digital Handheld Multimeter is designed for reliability and performance. For specific warranty details, please refer to the warranty card included with your product or contact your local UNI-T distributor or retailer.

For technical support, troubleshooting assistance, or service inquiries, please contact the authorized UNI-T service center or your point of purchase. Keep your purchase receipt as proof of purchase for warranty claims.