

Walfront AN8205

AN8205 Digital Multimeter User Manual

Model: AN8205

Brand: Walfront

1. INTRODUCTION

The Walfront AN8205 Digital Multimeter is a portable and compact device designed for measuring various electrical parameters. It is an essential tool for electricians, hobbyists, and anyone working with electrical circuits.

This multimeter is capable of measuring AC & DC voltage, DC current, resistance, and features audible continuity and diode/transistor verification modes. Its user-friendly design includes a 20-position rotary switch for easy selection of measurement functions and ranges.



Figure 1: Walfront AN8205 Digital Multimeter with included test leads.

2. SAFETY INFORMATION

Always observe basic safety precautions when using this multimeter to avoid electric shock or personal injury, and to prevent damage to the meter or the equipment under test.

- Do not apply more than the rated voltage, as marked on the meter, between the terminals or between any terminal and ground.
- Use caution when working with voltages above 30V AC RMS, 42V peak, or 60V DC. Such voltages pose a shock hazard.
- Before changing functions, disconnect the test leads from the circuit under test.
- Do not use the meter if it is damaged or if the test leads are damaged. Inspect the meter and test leads before use.
- Ensure the battery cover is securely closed before operation.
- Always use the correct function and range for measurements.
- Do not exceed the maximum input value of any range.

3. SETUP AND BATTERY INSTALLATION

3.1 Package Contents

Verify that all items are present in the package:

- 1 × Walfront AN8205 Digital Multimeter
- 1 × English Manual
- 2 × Testing Cables (Red and Black)

3.2 Battery Installation

The AN8205 Multimeter requires a 6F22 9V battery (not included). Follow these steps to install the battery:

1. Locate the battery compartment on the back of the multimeter.
2. Open the battery cover by sliding it or unscrewing the retaining screw (if present).
3. Connect a 9V battery to the battery clips, observing the correct polarity (+ and -).
4. Place the battery inside the compartment.
5. Close the battery cover securely.

Note: The multimeter features a low battery voltage indication on its LCD display.

4. OPERATING INSTRUCTIONS

4.1 Overview of Controls and Terminals



Figure 2: Front view of the AN8205 Multimeter.

- **LCD Display:** Shows measurement readings, units, and low battery indicator.
- **Rotary Switch:** Selects the desired measurement function and range.
- **"HOLD" Button:** Freezes the current reading on the display.
- **"BACK LIGHT" Button:** Activates the blue backlight for improved visibility in low light conditions.
- **"COM" Jack (Black):** Common terminal for all measurements. Connect the black test lead here.
- **"VΩmA" Jack (Red):** Input terminal for voltage, resistance, and current measurements up to 200mA. Connect the red test lead here.
- **"10ADC" Jack (Red):** Input terminal for DC current measurements up to 10A. Connect the red test lead here for high current measurements.
- **hFE Sockets:** For transistor (NPN/PNP) testing.

4.2 Measuring DC Voltage (V=)

1. Insert the black test lead into the "COM" jack and the red test lead into the "VΩmA" jack.

2. Set the rotary switch to the desired DC Voltage range (e.g., 200mV, 2V, 20V, 200V, 600V). If the voltage is unknown, start with the highest range and decrease as needed.
3. Connect the test leads across the DC voltage source to be measured.
4. Read the voltage value on the LCD display.

4.3 Measuring AC Voltage (V_{\sim})

1. Insert the black test lead into the "COM" jack and the red test lead into the " $V_{\Omega}mA$ " jack.
2. Set the rotary switch to the desired AC Voltage range (e.g., 200V, 600V).
3. Connect the test leads across the AC voltage source to be measured.
4. Read the voltage value on the LCD display.

4.4 Measuring DC Current ($A_{=}$)

1. **For currents up to 200mA:** Insert the black test lead into the "COM" jack and the red test lead into the " $V_{\Omega}mA$ " jack.
2. **For currents up to 10A:** Insert the black test lead into the "COM" jack and the red test lead into the "10ADC" jack.
3. Set the rotary switch to the desired DC Current range (e.g., 200 μ A, 2mA, 20mA, 200mA, 10A).
4. Disconnect power to the circuit. Open the circuit where you want to measure current.
5. Connect the multimeter in series with the circuit.
6. Apply power to the circuit and read the current value on the LCD display.
7. **CAUTION:** Do not attempt to measure currents exceeding 10A.

4.5 Measuring Resistance (Ω)

1. Insert the black test lead into the "COM" jack and the red test lead into the " $V_{\Omega}mA$ " jack.
2. Set the rotary switch to the desired Resistance range (e.g., 200 Ω , 2k Ω , 20k Ω , 200k Ω , 2M Ω).
3. Ensure the circuit or component is de-energized before measuring resistance.
4. Connect the test leads across the component whose resistance you want to measure.
5. Read the resistance value on the LCD display.

4.6 Continuity Test

1. Insert the black test lead into the "COM" jack and the red test lead into the " $V_{\Omega}mA$ " jack.
2. Set the rotary switch to the continuity symbol (usually a speaker icon).
3. Connect the test leads across the circuit or component.
4. If the resistance is below a certain threshold (typically 50 Ω), the buzzer will sound, indicating continuity.

4.7 Diode Test

1. Insert the black test lead into the "COM" jack and the red test lead into the " $V_{\Omega}mA$ " jack.
2. Set the rotary switch to the diode symbol.
3. Connect the red test lead to the anode and the black test lead to the cathode of the diode. The display will show the forward voltage drop.
4. Reverse the leads. The display should show "OL" (Open Loop) for a good diode.

4.8 Transistor (hFE) Test

1. Set the rotary switch to the hFE position.
2. Identify if the transistor is NPN or PNP.
3. Insert the transistor's emitter, base, and collector leads into the corresponding hFE sockets on the multimeter.
4. The display will show the hFE (DC current gain) value of the transistor.

5. MAINTENANCE

5.1 Cleaning

To clean the multimeter, wipe the case with a damp cloth and mild detergent. Do not use abrasives or solvents. Ensure the meter is off and disconnected from any circuits before cleaning.

5.2 Battery Replacement

When the low battery indicator appears on the display, replace the 9V battery promptly to ensure accurate measurements. Refer to Section 3.2 for battery installation instructions.

5.3 Storage

If the multimeter is not used for an extended period, remove the battery to prevent leakage and damage to the device. Store the multimeter in a cool, dry place, away from direct sunlight and extreme temperatures.

6. TROUBLESHOOTING

Problem	Possible Cause	Solution
No display or dim display	Dead or low battery	Replace the 9V battery.
"OL" (Overload) displayed	Input value exceeds selected range; Open circuit (for continuity/resistance)	Select a higher range; Check test lead connections; Verify circuit continuity.
Inaccurate readings	Incorrect range selected; Poor test lead contact; Battery low	Select appropriate range; Ensure firm contact; Replace battery.
No continuity beep	Open circuit; High resistance	Check circuit for breaks; Ensure resistance is below threshold for beep.

7. SPECIFICATIONS

Parameter	Value
Model Number	AN8205
Material	ABS
Display Type	Digital Display
Maximum Display	1999
Operating Mode	Manual Mode
Battery Type	6F22 9V Battery (Not Included)
DC Voltage Range	200mV - 2-20-200-600V
AC Voltage Range	200mV-600V
DC Current Range	200u-2m-20m-200m-10A

Parameter	Value
Resistance Range	200-2k-20k-200k-2MΩ
Buzzer Test	Yes
Night Light	Blue
Product Dimensions	13.5 × 6.5 × 3 cm / 5.31 × 2.55 × 1.18 inch
Weight	123g (0.12 Kilograms)



Figure 3: Dimensions of the AN8205 Multimeter.

8. WARRANTY AND SUPPORT

Walfront is committed to customer satisfaction. For any issues, questions, or support regarding your AN8205 Digital Multimeter, please contact Walfront customer service.

While specific warranty terms are not detailed in this manual, please refer to the purchase documentation or the official Walfront website for the most up-to-date warranty information.

You can visit the official Walfront store for more information and support: [Walfront Store on Amazon](#).

© 2024 Walfront. All rights reserved.
Manual Version: 1.0