

Reboot RBM-2000

Reboot 200Amp MIG Welder (RBM-2000) User Manual

5-in-1 Welding Machine with CO2 Gas Regulator

1. INTRODUCTION

This manual provides essential information for the safe and effective operation, setup, and maintenance of your Reboot 200Amp MIG Welder, model RBM-2000. This versatile 5-in-1 welding machine supports Gas/Solid Wire MIG (GMAW), Gasless Flux Core MIG (FCAW), Stick/MMA, Spot welding, and Lift TIG processes. Please read this manual thoroughly before using the equipment.



Figure 1: The Reboot 200Amp MIG Welder (RBM-2000) with included CO2 gas regulator and essential accessories.

2. SAFETY INFORMATION

WARNING: Welding can be dangerous. Always follow safety precautions to prevent injury or death.

- **Electric Shock:** Can kill. Do not touch live electrical parts. Wear dry insulating gloves and protective clothing. Ensure the work area is dry.
- **Fumes and Gases:** Can be hazardous to your health. Keep your head out of the fumes. Use ventilation or exhaust to remove fumes from the breathing zone.
- **Arc Rays:** Can injure eyes and burn skin. Wear a welding helmet with a proper shade filter. Wear protective clothing to cover exposed skin.
- **Fire and Explosion:** Welding can cause fire or explosion. Keep flammable materials away from the welding area. Have a fire extinguisher readily available.
- **Hot Parts:** Can cause severe burns. Allow welded materials and equipment to cool before handling.
- **Personal Protective Equipment (PPE):** Always wear appropriate PPE, including a welding helmet, safety glasses, welding gloves, and protective clothing.

3. PRODUCT COMPONENTS

The Reboot 200Amp MIG Welder package typically includes the following items:

- Reboot RBM-2000 Multi-Process Welding Machine
- MIG Welding Torch
- Ground Clamp with Cable
- Electrode Holder with Cable (for Stick/MMA welding)
- CO2 Gas Regulator
- Gas Hose
- Power Adapter (for 120V/240V compatibility)
- Wire Spool (starter roll)
- Consumables (e.g., contact tips, nozzles)



Figure 2: Main components included with the RBM-2000 welding machine.

4. SPECIFICATIONS

Feature	Specification
Model	RBM-2000
Input Voltage	120V / 240V (Auto-sensing)
Output Current	Up to 200 Amps
Welding Processes	MIG (Gas/Solid Wire), Flux Core MIG (Gasless), Stick/MMA, Spot Welding, Lift TIG
Compatible Solid Wire Diameters	0.023" (0.6mm), 0.030" (0.8mm), 0.035" (0.9mm)
Compatible Flux Core Wire Diameters	0.023" (0.6mm), 0.030" (0.8mm), 0.035" (0.9mm)
CO2 Gas Regulator Output Flow	0 - 25 Liters Per Minute (LPM)
Display	Large LED Digital Panel
Portability	Ergonomic carrying handle, folding design
Note	Aluminum welding is not supported.

5. SETUP

5.1 Power Connection

The RBM-2000 welder is designed for both 120V and 240V input. The machine automatically detects the input voltage. Use the provided power adapter if necessary to match your wall outlet. Ensure the power source is capable of supplying the required amperage for welding.

5.2 Gas Regulator Setup (for Gas MIG/TIG)

If performing Gas MIG or Lift TIG welding, connect the CO2 gas regulator to your gas cylinder and then to the welder's gas inlet. The regulator's output flow is adjustable from 0 to 25 LPM, indicated by a ball in the flow tube.




Figure 3: Detailed view of the CO2 Gas Regulator, showing the flow meter, high pressure gauge, and connection points.

5.3 Wire Spool Installation (for MIG/Flux Core)

Open the wire spool compartment on the side of the welder. Place the appropriate wire spool (solid or flux core) onto the spindle, ensuring it unwinds smoothly. Thread the wire through the wire feed mechanism according to the instructions inside the compartment. The machine supports 2-pound rolls of wire.



Figure 4: The internal wire spool compartment, illustrating how to install a wire roll.

5.4 Torch and Ground Clamp Connection

Connect the MIG torch to the designated port on the front panel. Connect the ground clamp cable to the ground terminal and securely attach the clamp to the workpiece or welding table. For Stick/MMA welding, connect the electrode holder to the appropriate terminal.



Figure 5: Example of the welding machine in operation, demonstrating proper setup and use.

6. OPERATING INSTRUCTIONS

6.1 Control Panel Overview

The RBM-2000 features a large LED digital panel for clear data display. It offers a unique design concept with technological elements for ease of use. The control panel allows for mode selection and parameter adjustment.

SYNERGIC CONTROL, EXCLUSIVE DESIGN

new year, new welder



Figure 6: The RBM-2000's digital control panel, showing various welding modes and parameter readouts.

6.2 Welding Modes and Parameter Adjustment

The machine supports multiple welding processes. Use the single-button selector to choose your desired welding mode:

- **MIG (Gas/Solid Wire):** For welding with shielding gas and solid wire.
- **Flux Core MIG (Gasless):** For welding with flux-cored wire without external shielding gas.
- **Stick/MMA:** For manual metal arc welding with coated electrodes.
- **Spot Welding:** For precise spot welds.
- **Lift TIG:** For TIG welding (TIG gun not included) with a lift-arc start.

The digital control system automatically matches recommended current and wire feeding speed based on the selected welding wire diameter and gas material. You can also fine-tune the welding current and other parameters according to your specific welding habits and material requirements.

7. MAINTENANCE

Regular maintenance ensures the longevity and optimal performance of your welding machine.

- **Cleaning:** Periodically clean the machine's exterior and ventilation openings to prevent dust and debris buildup. Use compressed air to clear internal components if accessible.
- **Wire Feed Mechanism:** Inspect and clean the wire feed rollers regularly. Ensure they are free of debris and that the wire feeds smoothly.
- **Consumables:** Replace MIG torch contact tips and nozzles as they wear out to maintain arc stability and weld quality.
- **Cables and Connections:** Check all cables (power, ground, torch) for damage or fraying. Ensure all connections are secure. The internal cables are made of all copper for high efficiency and long service life.
- **Gas Hose:** Inspect the gas hose for any cracks or leaks. The gas hose is designed for strong pressure resistance and firmness.



Figure 7: Close-up view of the internal cable and gas hose connections, highlighting their quality and durability.

8. TROUBLESHOOTING

If you encounter issues with your RBM-2000 welder, refer to the following common problems and solutions:

Problem	Possible Cause	Solution
No Power	Power cord unplugged, circuit breaker tripped, faulty outlet.	Check power connections, reset breaker, try a different outlet.
No Arc	Poor ground connection, wrong welding mode, worn contact tip, incorrect parameters.	Ensure ground clamp is secure, select correct mode, replace contact tip, adjust settings.
Wire Feeding Issues	Wire tangled, wrong drive roller size, tension too loose/tight, clogged liner.	Untangle wire, ensure correct drive roller, adjust tension, clean/replace liner.
Poor Weld Quality	Incorrect voltage/amperage, improper gas flow (MIG), dirty workpiece, wrong wire.	Adjust parameters, check gas flow/regulator, clean workpiece, use correct wire type.
Regulator Flow Issues	Gas cylinder empty, regulator not fully open, hose kinked/leaking.	Check cylinder pressure, open regulator valve fully, inspect hose for damage.

If the problem persists after attempting these solutions, please contact Reboot customer support.

9. WARRANTY AND SUPPORT

For warranty information and customer support, please refer to the documentation included with your purchase or visit the official Reboot website. You can also contact Reboot-USA, the seller, for assistance with your product.

ASIN: B0CY58ZXRB

Date First Available: March 15, 2024