

## Reboot RBC6000D-PRO

# Reboot RBC6000D PRO 8th Generation Plasma Cutter Instruction Manual

Model: RBC6000D-PRO

## 1. INTRODUCTION

This manual provides essential information for the safe and effective operation, setup, and maintenance of your Reboot RBC6000D PRO 8th Generation Plasma Cutter. Please read this manual thoroughly before using the equipment to ensure proper function and safety.

## 2. SAFETY INFORMATION

**Plasma cutting involves high voltage, high temperatures, and intense light. Failure to follow safety precautions can result in serious injury or death.**

- Always wear appropriate personal protective equipment (PPE), including a welding helmet with proper shade, flame-resistant clothing, gloves, and safety shoes.
- Ensure adequate ventilation to remove fumes and gases produced during cutting.
- Never operate the plasma cutter in wet conditions or near flammable materials.
- Ensure the workpiece is properly grounded.
- Do not touch live electrical parts or hot metal.
- Keep children and unauthorized personnel away from the work area.
- Disconnect power before performing any maintenance or changing consumables.

## 3. PACKAGE CONTENTS

Verify that all items are present in the package:

- RBC6000D-PRO Plasma Cutter (120/240V with conversion line)
- Upgrade PT31 Torch
- Earth Ground Clamp
- Air Regulator Set

- Air Hose and Manual
- 14pcs Extra Consumables (tips, electrodes, endcaps)



Image: The Reboot RBC6000D PRO Plasma Cutter shown with all included accessories, such as the plasma torch, ground clamp, air regulator, air hose, and various consumables.

## 4. PRODUCT OVERVIEW

The Reboot RBC6000D PRO is an 8th Generation plasma cutter featuring IGBT inverter technology, dual voltage capability (120V/240V), and a high-frequency touch arc starting mode. It is designed for efficient metal cutting with a maximum clean cut of 3/5 inch and severance cut of 4/5 inch.

### Key Features:

- **Touch Arc Start:** High-frequency starting mode where the torch head touches the metal plate.
- **Large Digital Screen:** Displays real-time parameters including air pressure, post air settings, and current.
- **Air Pressure Sensor:** Integrated sensor indicates appropriate air pressure with a green light, or red for too high/low pressure.
- **Dual Voltage:** Operates on 120V (15-35A) or 240V (15-60A).

- **Post Air Function:** Adjustable cooling time (3-15 seconds, recommended 4-8 seconds) for torch consumables.
- **2T/4T Function:** 2T for semi-automatic cutting, 4T for automatic cutting.



Image: Labeled diagram of the plasma cutter showing the pressure adjust knob, on/off switch, power cable, air regulator, high speed fan, air input, current adjust, current display, 2T/4T/Air Testing button, post air/air pressure display, cutting torch interface, and torch switch socket.



Image: Close-up of the intelligent digital screen display, showing air pressure (PSI), current (Amps), and indicators for Post Air, 2T, 4T, and Air Testing functions.

## 5. SETUP

Follow these steps to set up your plasma cutter:

1. **Unpacking:** Carefully remove the plasma cutter and all accessories from the packaging.
2. **Power Connection:** Connect the power cable to an appropriate 120V or 240V power source. Use the provided conversion line if switching between voltages.
3. **Air Compressor Connection:** An air compressor (minimum 90 PSI, 60 L/min) is required. Connect the air hose from your compressor to the air filter regulator, then connect the regulator to the plasma cutter's air input.



## EASY TO SET UP WITH UPGRADE QUICK CONNECTOR



Image: Illustration showing the quick connector for the air hose, simplifying the connection between the air compressor, air filter regulator, and the plasma cutter.

4. **Torch and Ground Clamp Connection:** Connect the plasma torch to the cutting torch interface and the ground clamp to the designated ground terminal.
5. **Air Regulator Installation:** The plasma cutter has a built-in air pressure sensor. The included air regulator does not require an additional gauge.

# **NOTE: GAS REGULATOR WITHOUT GAUGE**

**MODEL: RBC6000D PRO/ RBC6000DL PRO**



**Upgraded large LED display panel,  
the air pressure value is visible on the panel,  
the machine has a built-in air pressure sensor,  
no need to install an additional  
air pressure regulating gauge.**



Image: The air filter regulator, indicating that it does not require an additional pressure gauge as the machine has a built-in sensor and displays air pressure on its LED panel.

## **6. OPERATING INSTRUCTIONS**

### **6.1 Power On/Off**

- Turn the main power switch to the 'ON' position. The digital screen will light up after approximately four seconds.
- To power off, turn the main switch to 'OFF'. The screen will go off after about six seconds.



The screen lights up after four seconds of startup



Screen goes off 6 seconds after shutdown

Image: Two panels illustrating the digital screen's behavior during startup (lights up after 4 seconds) and shutdown (goes off after 6 seconds).

## 6.2 Adjusting Air Pressure

- The digital screen displays the current air pressure.
- Adjust the air pressure using the regulator until the green light on the screen indicates the pressure is within the normal operating range.
- A red light indicates air pressure is too high or too low.






Image: Four panels showing the digital screen indicating appropriate air pressure (green light), no air connected (E06 error code), air pressure too low, and air pressure too high.

### 6.3 Adjusting Cutting Current

- Use the current adjust knob to set the desired amperage for your cutting task.
- Current range at 120V is 15-35A.
- Current range at 240V is 15-60A.

### 6.4 2T/4T Function

- **2T (Two-Touch):** For semi-automatic cutting. Press and hold the torch trigger to start cutting, release to stop.
- **4T (Four-Touch):** For automatic cutting. Press the trigger once to start, release, and press again to stop. This function is useful for longer cuts as it frees your finger from holding the trigger.



## EAST TO SET UP WITH QUICK CONNECTOR

Just need to prepare air compressor for starting to work,  
set up with 1 minute



Image: An illustration explaining the 2T and 4T functions, showing how they control the cutting process for semi-automatic and automatic operation, respectively.

### 6.5 Post Air Function

- Post air adjusts the cooling time for the torch head after cutting stops, extending consumable lifespan.
- Adjustable range: 3-15 seconds.
- Recommended range: 4-8 seconds.

### 6.6 Cutting Guidelines

- Maximum cutting thickness: 14mm (approx. 3/5 inch) at 35A (120V, 50 PSI).
- Maximum cutting thickness: 20mm (approx. 4/5 inch) at 60A (240V, 60 PSI).

# RBC6000D PRO -PLASMA CUTTER

60Amps Dual Voltage 120/240V  
IGBT Inverter Technology 50/60Hz  
High Frequency



## MAX CUTTING THICKNESS:

120V,35A 14MM @ 50PSI

240V,60A 20MM @ 60PSI

Image: The Reboot RBC6000D PRO Plasma Cutter in use, demonstrating its cutting capabilities on metal, with text indicating maximum cutting thicknesses at different voltages and amperages.

## 7. MAINTENANCE

Regular maintenance ensures optimal performance and extends the life of your plasma cutter.

- **Consumables:** Regularly inspect the torch consumables (tips, electrodes, shield cups) for wear and replace them as needed. Worn consumables can affect cut quality and efficiency.
- **Air Filter Regulator:** Periodically check and drain any accumulated moisture from the air filter regulator. Clean or replace the filter element if it becomes clogged.
- **Cleaning:** Keep the plasma cutter clean and free from dust and debris. Use compressed air to blow out internal components if necessary, ensuring the unit is unplugged.
- **Cables and Connections:** Inspect all cables and connections for damage or loose fittings. Repair or replace any damaged parts immediately.

## 8. TROUBLESHOOTING

This section addresses common issues you might encounter.

### 8.1 Error Codes

- **E06:** Indicates no air connected or insufficient air pressure. Check air compressor connection, air hose, and regulator settings.

### 8.2 Common Issues and Solutions

- **No Arc:**
  - Ensure the ground clamp is securely attached to the workpiece.
  - Check power supply and connections.
  - Verify air pressure is within the recommended range.
  - Inspect torch consumables for wear and replace if necessary.
- **Poor Cut Quality:**
  - Adjust cutting current and air pressure according to material thickness.
  - Replace worn consumables.
  - Ensure proper torch standoff distance from the workpiece.
- **Machine Overheating:**
  - Allow the machine to cool down. The unit has thermal overload protection.
  - Ensure adequate ventilation around the machine.
  - Check for blocked air vents.

## 9. SPECIFICATIONS





Specification	Value
Manufacturer	Reboot-US
Part Number	RBC6000-PRO
Item Model Number	RBC6000D-PRO
Item Weight	14.21 pounds
Product Dimensions	12.4 x 4.53 x 8.66 inches
Power Source	AC
Voltage	120/240 Volts
Cutting Amperage (120V)	15-35A
Cutting Amperage (240V)	15-60A
Max Clean Cut (120V)	14mm (approx. 3/5 inch) @ 35A, 50PSI
Max Clean Cut (240V)	20mm (approx. 4/5 inch) @ 60A, 60PSI
Post Air Adjustment	3-15 seconds (recommended 4-8 seconds)





## 10. WARRANTY AND SUPPORT

Reboot provides a **ONE YEAR AFTER-SALES** warranty for the RBC6000D PRO Plasma Cutter. For technical support, warranty claims, or service inquiries, please contact Reboot customer service through their official channels or the retailer where the product was purchased.

### Related Documents - RBC6000D-PRO

 <p>Operation Manual</p> <p>RBC-5000DL Cutting Machine</p>	<p><a href="#">Reboot RBC-5000DL Cutting Machine Operation Manual</a></p> <p>This operation manual provides detailed instructions for the Reboot RBC-5000DL Cutting Machine, covering its features, installation, operation, maintenance, and troubleshooting. It includes technical parameters, safety precautions, and warranty information.</p>
 <p>Operation Manual</p>	<p><a href="#">Reboot RBM1300 Operation Manual: Your Guide to Advanced Welding</a></p> <p>Discover the capabilities of the Reboot RBM1300 welding machine. This comprehensive manual covers operation, technical specifications, and troubleshooting for MMA, MIG, and LIFT TIG welding modes.</p>
 <p>Operation Manual</p>	<p><a href="#">Reboot RBM2000P Operation Manual: Welding Machine Guide</a></p> <p>Comprehensive operation manual for the Reboot RBM2000P welding machine. Learn about its features, MMA, MIG, and Pulse MIG welding modes, technical specifications, setup, operation, and troubleshooting for efficient welding.</p>
 <p>Operation Manual</p>	<p><a href="#">Reboot RBM1600 Operation Manual: Your Guide to MMA, MIG, and LIFT TIG Welding</a></p> <p>Comprehensive operation manual for the Reboot RBM1600 welding machine. Learn to use MMA, MIG (Gas/Gasless), and LIFT TIG modes with detailed instructions, technical specifications, and troubleshooting tips for optimal performance.</p>

<div><div><div>Operation Manual</div><div>Reboot RBM1300 welding machine</div><div><p>Reboot RBM1300 welding machine manual provides detailed instructions on how to operate and maintain the machine safely and effectively. It covers all aspects of the machine's operation, including safety precautions, setup, and troubleshooting.</p><p>The manual is divided into several sections, including:</p><ul style="list-style-type: none"><li>1. Safety Precautions: This section provides essential information on how to use the machine safely, including warnings, cautions, and first aid instructions.</li><li>2. Setup: This section describes the steps for setting up the machine, including connecting the power cord, gas cylinder, and electrode holder.</li><li>3. Operation: This section provides detailed instructions on how to operate the machine, including selecting the welding mode, adjusting the wire speed, and controlling the arc.</li><li>4. Maintenance: This section provides information on how to maintain the machine, including cleaning, lubrication, and inspection.</li><li>5. Troubleshooting: This section provides a list of common problems and their solutions.</li></ul></div></div><div><div>Part 1: Machine Introduction</div><div></div><div><p>1. Safety Precautions</p><p>The Reboot RBM1300 welding machine is a powerful tool that can be used to weld a variety of materials. It is important to read the manual carefully and follow all safety instructions to avoid injury or damage to the machine.</p><p>2. Setup</p><p>The Reboot RBM1300 welding machine is easy to set up. Simply connect the power cord to a standard AC outlet, attach the gas cylinder, and connect the electrode holder.</p><p>3. Operation</p><p>The Reboot RBM1300 welding machine has three main operating modes: MMA (Manual Metal Arc), MIG Gas, and MIG Gasless. Each mode has its own set of controls and settings.</p><p>4. Maintenance</p><p>The Reboot RBM1300 welding machine requires minimal maintenance. Regular cleaning and inspection of the machine's components will ensure optimal performance.</p><p>5. Troubleshooting</p><p>If you encounter any problems with the Reboot RBM1300 welding machine, consult the troubleshooting section of the manual for solutions.</p></div></div></div>	<p><a href="#">Reboot RBM1300 Welding Machine Operation Manual</a></p> <p>This manual provides detailed instructions for operating the Reboot RBM1300 welding machine, covering its features, setup, different welding modes (MMA, MIG Gas, MIG Gasless, LIFT TIG), technical specifications, safety precautions, and troubleshooting.</p>
<div><div><div>Reboot RBM2100D Recommended Weld Settings Guide</div><div></div></div></div>	<p><a href="#">Reboot RBM2100D Recommended Weld Settings Guide</a></p> <p>A comprehensive guide detailing recommended welding settings for the Reboot RBM2100D multi-process welder. This document covers settings for MIG, TIG, and Stick welding processes, including various electrode types, wire types, and wire diameters, along with control panel descriptions and installation instructions.</p>