

Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

manuals.plus /

› [ZOYI](#) /

› [ZT-Y Digital Multimeter - True RMS, Auto-Ranging, AC/DC Voltage, Current, NCV](#)

ZOYI ZT-Y

ZOYI ZT-Y Digital Multimeter User Manual

Model: ZT-Y

Brand: ZOYI

1. INTRODUCTION

The ZOYI ZT-Y Digital Multimeter is a high-precision, auto-ranging instrument designed for a wide range of electrical measurements. It is suitable for students, electricians, maintenance personnel, and laboratory use. This multimeter features True RMS measurement capabilities, an easy-to-read inverted triple display, a built-in flashlight, and a comfortable rotary dial for quick function selection.

Package Contents:

- ZT-Y Digital Multimeter
- Cloth Bag
- Test Leads
- Temperature Probe



Figure 1: ZT-Y Digital Multimeter and its accessories, including test leads, a temperature probe, and a cloth carrying bag.

2. SAFETY INFORMATION

WARNING: Always exercise extreme caution when working with electricity. Incorrect use of this multimeter can lead to electric shock, injury, or damage to the device or equipment under test.

- This multimeter is designed to meet CAT II 600V safety standards.
- Do not exceed the maximum input values specified for each function.
- Ensure the test leads are properly connected and the function dial is set to the correct range before making any measurements.
- Inspect test leads for damage before each use. Do not use if insulation is cracked or damaged.
- Do not operate the multimeter if it appears damaged or is not functioning properly.
- Always disconnect power to the circuit before connecting or disconnecting test leads, especially when measuring current.
- Avoid touching exposed wires or circuit components while taking measurements.
- Use caution when working with voltages above 30V AC RMS, 42V peak, or 60V DC, as they pose a shock

hazard.

3. PRODUCT OVERVIEW

The ZT-Y multimeter features a robust design with an intuitive layout for ease of use.



Figure 2: Front view of the ZT-Y Digital Multimeter, highlighting the display, function dial, and input terminals.

3.1. Components

1. **LCD Display:** Inverted triple display for clear readings.
2. **Function Dial:** Rotary switch to select measurement modes.
3. **Function Buttons:**
 - **SELECT/V.F.C:** Toggles between AC/DC, selects sub-functions, activates V.F.C mode.
 - **RANGE/REL:** Toggles between auto/manual ranging, activates relative measurement.
 - **MAX/MIN:** Records maximum and minimum values.
 - **HOLD/Light:** Freezes the current reading, long press activates/deactivates backlight.

4. Input Jacks:

- **COM:** Common terminal for all measurements.
- **VΩHz-||-NCV:** Input for Voltage, Resistance, Frequency, Capacitance, Diode, Continuity, and Non-Contact Voltage.
- **mAμA:** Input for milliampere and microampere current measurements.
- **10A MAX:** Input for up to 10A current measurements.

5. **Flashlight:** Located at the top for illuminating the measurement area.

4. SETUP

4.1. Battery Installation

The ZT-Y multimeter is powered by batteries (typically AA or AAA, refer to the battery compartment for specifics). To install or replace batteries:

1. Ensure the multimeter is turned OFF.
2. Locate the battery compartment cover on the back of the unit.
3. Unscrew the retaining screw(s) and remove the cover.
4. Insert new batteries, observing the correct polarity (+/-) as indicated inside the compartment.
5. Replace the cover and secure the screw(s).

4.2. Connecting Test Leads

Always connect the black test lead to the COM jack. Connect the red test lead to the appropriate input jack based on the measurement you intend to make:

- For Voltage, Resistance, Capacitance, Diode, Continuity, Frequency, NCV: Connect red lead to **VΩHz-||-NCV** jack.
- For Current (mA/μA): Connect red lead to **mAμA** jack.
- For Current (10A): Connect red lead to **10A MAX** jack.

5. OPERATING MODES AND MEASUREMENTS

Turn the function dial to the desired measurement mode. The multimeter features auto-ranging, simplifying operation. Press the **RANGE** button to switch to manual ranging if needed.

MULTI-FUNCTION DIGITAL MULTIMETER TRUE RMS 9999 COUNTS



Figure 3: Overview of the multi-function capabilities of the ZT-Y Digital Multimeter.

5.1. AC/DC Voltage Measurement (V~ / V-)

1. Set the function dial to V~ (AC Voltage) or V- (DC Voltage).
2. Connect the test leads in parallel to the circuit or component to be measured.
3. Read the voltage value on the display.

5.2. AC/DC Current Measurement (A~ / A-, mA~ / mA-, μ A~ / μ A-)

1. Set the function dial to the appropriate current range (A, mA, or μ A).
2. **WARNING:** Disconnect power to the circuit. Connect the multimeter in series with the circuit.
3. Apply power and read the current value.

5.3. Resistance Measurement (Ω)

1. Set the function dial to Ω .
2. Ensure the circuit is de-energized before measuring resistance.

3. Connect the test leads across the component.
4. Read the resistance value.

5.4. Continuity Test (•)

1. Set the function dial to •).
2. Connect the test leads across the circuit or component.
3. A continuous beep indicates continuity (low resistance).

5.5. Diode Test (→|)

1. Set the function dial to →|.
2. Connect the red lead to the anode and the black lead to the cathode of the diode.
3. The display shows the forward voltage drop. Reverse the leads to check for open circuit.

5.6. Capacitance Measurement (—||—)

1. Set the function dial to —||—.
2. **WARNING:** Discharge capacitors before testing to avoid damage to the meter.
3. Connect the test leads across the capacitor.
4. Read the capacitance value.

5.7. Non-Contact Voltage (NCV) Detection

The NCV function allows detection of AC voltage without direct contact.

1. Set the function dial to NCV.
2. Move the top of the multimeter close to the conductor.
3. The meter will beep and the NCV indicator will flash, with the frequency increasing as it gets closer to the AC voltage source.



Figure 4: Demonstrating the NCV (Non-Contact Voltage) detection feature, where the multimeter detects AC voltage when brought close to a conductor.

5.8. Temperature Measurement (°C/°F)

Use the included temperature probe for this function.

1. Set the function dial to TEMP.
2. Connect the temperature probe to the VΩHz-||-NCV and COM jacks, observing polarity.
3. Place the probe tip on or near the object whose temperature is to be measured.
4. Read the temperature on the display.

MEASURING TEMPERATURE

RANGE

-20°C~1000°C
-4°F~1832°F

ACCURACY

$\pm (2.5\%+5)$



Figure 5: The ZT-Y multimeter measuring temperature using its dedicated probe, showing a reading of 176°F for a cup of tea.

5.9. Frequency Measurement (Hz)

1. Set the function dial to Hz.
2. Connect the test leads to the signal source.
3. Read the frequency value.

5.10. Square Wave Output

The multimeter can generate a 5KHz square wave output.

1. Set the function dial to the Square Wave Output mode.
2. The output will be available at the V Ω Hz-||-NCV and COM jacks.

5.11. V.F.C Immunity Measurement

This mode is designed for measuring variable frequency voltage.

1. Set the function dial to V.F.C.
2. Connect the test leads to the circuit.
3. The multimeter will display the voltage with improved immunity to frequency variations.

5.12. REL (Relative Value) Measurement

The REL function allows you to store a reading as a reference and display subsequent measurements as a deviation from that reference.

1. Take a measurement.
2. Press the **REL** button (often combined with RANGE). The display will show "0" and subsequent readings will be relative to the stored value.


5.13. True RMS Measurement

The ZT-Y is a True RMS multimeter, meaning it accurately measures the RMS (Root Mean Square) value of AC voltage and current, even for non-sinusoidal waveforms. This provides a more accurate reading compared to average-responding meters when dealing with distorted waveforms common in modern electronics.

TRUE RMS

Electronic loads with frequency changes are non-sine
Only true RMS multimeter can measure the correct value

Both average and true RMS meters can measure the correct value



Only true RMS meters can measure the correct value







Figure 6: Illustration of True RMS capability, demonstrating its accuracy in measuring various waveform types compared to average-responding meters.

6. MAINTENANCE

6.1. Cleaning

Wipe the case with a damp cloth and mild detergent. Do not use abrasives or solvents. Keep the input terminals free of dirt and moisture.

6.2. Battery Replacement

When the battery indicator appears on the display, replace the batteries promptly to ensure accurate readings. Refer to section 4.1 for battery installation instructions.

6.3. Fuse Replacement

If the current measurement function stops working, the fuse may need replacement. This typically requires opening the multimeter case. Refer to the internal diagram or contact customer support for fuse specifications and replacement procedures. Always use a fuse with the correct rating.

WARNING: Disconnect all test leads and turn off the multimeter before opening the case for fuse replacement.

7. TROUBLESHOOTING

Problem	Possible Cause	Solution
No display or dim display	Low batteries; Power OFF.	Replace batteries; Turn on the multimeter.
Incorrect readings	Incorrect function selected; Damaged test leads; Overload.	Select correct function; Check/replace test leads; Ensure measurement is within range.
Current measurement not working	Blown fuse; Incorrect connection.	Replace fuse (refer to 6.3); Ensure multimeter is connected in series.
No continuity beep	Open circuit; Damaged test leads.	Check circuit for breaks; Check/replace test leads.

8. SPECIFICATIONS

Feature	Detail
Model Number	ZT-Y
Display	9999 Counts, Inverted Triple Display
True RMS	Yes
Auto-Ranging	Yes
Safety Level	CAT II 600V

Feature	Detail
AC/DC Voltage	Includes millivolts
AC/DC Current	Includes milliamps and microamps
Temperature Measurement	-20°C ~ 1000°C (-4°F ~ 1832°F) with probe
Resistance Measurement	Yes
Continuity Test	Yes
Diode Test	Yes
Capacitance Measurement	Yes
NCV Measurement	Yes
Square Wave Output	5KHz
V.F.C Immunity Measurement	Yes
REL Absolute Value Measurement	Yes
Data Hold	Yes
Flashlight	Yes
Power Source	Battery Powered (refer to battery compartment for type)
Maximum Operating Voltage	4.5 Volts (DC) (<i>Internal operating voltage, not measurement voltage. Measurement safety rating is CAT II 600V.</i>)
Dimensions	7.48 x 5.12 x 2.76 inches
Weight	1.32 Pounds

9. WARRANTY AND SUPPORT

For warranty information, technical support, or service inquiries, please contact ZOYI customer service through their official website or the retailer where the product was purchased. Keep your purchase receipt as proof of purchase.

Online Resources:

- Visit the [ZOYI Official Store on Amazon](#) for product information and updates.

