

## GRSS XL830L

# GRSS XL830L Digital Multimeter User Manual

Model: XL830L | Model Number: 1005005058274255

## PRODUCT OVERVIEW

---

The GRSS XL830L Digital Multimeter is a heavy-duty, general-purpose testing tool designed for measuring AC/DC voltage, DC current, resistance, and for performing diode and transistor verification. It features a clear, easy-to-read LCD display with blue backlight and is housed in a rugged rubber boot for enhanced durability and protection.



Image: The GRSS XL830L Digital Multimeter, showing the device itself, the red and black test leads, and the included instruction manual.

## Key Features:

- Clear, Easy-to-Read LCD Display with Blue Backlight
- Overload Protection on All Ranges
- Rugged Rubber Boot with Integral Stand
- Low Battery Voltage Indication
- Portable & Compact Design
- Data Hold Function
- Diode Test Facility
- 20 Position Rotary Switch for various measurements
- Measures AC/DC Voltage, DC Current, Resistance, Audible Continuity, Diode, and Transistor Verification



Image: A detailed view of the GRSS XL830L Digital Multimeter with key components labeled, including the LCD blue backlit screen, data hold button, DC voltage range, range turntable, resistance, diode/buzzer, 10A current jack, triode test hole, red watch pen jack, and black pen jack.

Model: XL830L 1999 Count

# Multi-range Multimeter

①.AC/DC voltage/Diode

②.DC current/Triode

③.Buzzer/Resistance

④.LCD blue screen

⑤.Data retention



Image: The GRSS XL830L Multimeter emphasizing its multi-range capabilities, including AC/DC voltage/diode, DC current/triode, buzzer/resistance, LCD blue screen, and data retention.

## SAFETY INFORMATION

Always observe safety precautions when using electrical testing equipment. Failure to do so may result in injury or damage to the meter or equipment under test.

- Do not apply voltage to the meter that exceeds the maximum rated input values for any range.
- Use extreme caution when working with voltages above 60V DC or 30V AC RMS. These voltages pose a shock hazard.
- Always disconnect the test leads from the circuit before changing functions or ranges.
- Ensure the meter is in good working condition before use. Do not use if the meter or test leads appear damaged.
- Do not operate the meter in explosive gas, vapor, or dust environments.
- Always use the correct terminals, function, and range for your measurements.

# Triode hFE Test

Go to hFE gear measurement and make sure the transistor is NPN or PNP type



Image: The GRSS XL830L Multimeter performing a triode hFE test, highlighting its built-in short circuit, overload, and overcurrent protection features.

## SETUP AND BATTERY INSTALLATION

Before first use, or when the low battery indicator appears, install or replace the battery.

1. Ensure the multimeter is turned **OFF** and disconnect all test leads from the input terminals.
2. Locate the battery compartment cover on the back of the unit.
3. Unscrew the retaining screw(s) and remove the battery compartment cover.
4. Insert a new 9V battery (NEDA 1604 or equivalent) into the battery clips, observing correct polarity.
5. Replace the battery compartment cover and secure it with the screw(s).

*Note: Battery is not included with the multimeter.*

## OPERATING INSTRUCTIONS

## Connecting Test Leads:

- Insert the black test lead into the **COM** (common) jack.
- For voltage, resistance, and diode measurements, insert the red test lead into the **VΩmA** jack.
- For current measurements up to 200mA, use the **VΩmA** jack.
- For current measurements up to 10A, insert the red test lead into the **10ADC** jack.

## Making Measurements:

Always select the appropriate function and range using the rotary switch before connecting the test leads to the circuit.



# 20-Bit functional range

More complete functions, strong sense of pause in the rotation of the dial, precise and wear-resistant dial, long service life



Image: The GRSS XL830L Multimeter's rotary dial, illustrating its comprehensive 20-bit functional range for precise measurements and long service life.

### 1. DC Voltage Measurement (V=):

1. Set the rotary switch to the desired DC Voltage range (e.g., 200mV, 2V, 20V, 200V, 600V).
2. Connect the red test lead to the positive side of the circuit and the black test lead to the negative side.

3. Read the voltage value on the LCD display.

## 2. AC Voltage Measurement (V~):

1. Set the rotary switch to the desired AC Voltage range (e.g., 200V, 600V).
2. Connect the test leads across the AC voltage source.
3. Read the voltage value on the LCD display.

# Measure voltage

Go to the corresponding range of AC voltage measurement, easier to use



Image: The GRSS XL830L Multimeter connected to an electrical outlet, demonstrating AC voltage measurement. The display shows a reading of 242V.

## 3. DC Current Measurement (A=):

1. Set the rotary switch to the desired DC Current range (e.g., 200 $\mu$ A, 2mA, 20mA, 200mA, 10A).
2. **Important:** For 10A measurements, move the red test lead to the **10ADC** jack. For other current ranges, use the **VΩmA** jack.
3. Connect the meter in series with the circuit where current is to be measured.
4. Read the current value on the LCD display.

#### 4. Resistance Measurement ( $\Omega$ ):

1. Set the rotary switch to the desired Resistance range (e.g., 200 $\Omega$ , 2k $\Omega$ , 20k $\Omega$ , 200k $\Omega$ , 2M $\Omega$ ).
2. Ensure the circuit is de-energized before measuring resistance.
3. Connect the test leads across the component to be measured.
4. Read the resistance value on the LCD display.

#### 5. Diode Test:

1. Set the rotary switch to the Diode symbol.
2. Connect the red test lead to the anode and the black test lead to the cathode of the diode.
3. The display will show the forward voltage drop. Reverse the leads; an open circuit (OL) indicates a good diode.

#### 6. Transistor (hFE) Test:

1. Set the rotary switch to the hFE position.
2. Identify if the transistor is NPN or PNP.
3. Insert the transistor leads (E, B, C) into the corresponding holes in the hFE socket on the meter.
4. Read the hFE value on the display.

#### 7. Data Hold Function:

- Press the "HOLD" button to freeze the current reading on the display.
- Press the "HOLD" button again to release the reading and return to live measurement.

#### 8. Backlight Function:

- Press the "BACK LIGHT" button to turn on the display backlight for better visibility in low-light conditions.
- Press the "BACK LIGHT" button again to turn off the backlight.

### MAINTENANCE AND CARE

- **Cleaning:** Wipe the meter with a damp cloth and mild detergent. Do not use abrasives or solvents.
- **Battery Replacement:** Replace the 9V battery when the low battery indicator appears on the display. Refer to the "Setup and Battery Installation" section.
- **Storage:** If the meter is not to be used for a long period, remove the battery to prevent leakage. Store in a cool, dry place.
- **Fuse Replacement:** The 10A input is unfused. The mA input is fused. If the mA current range stops working, the fuse may need replacement. This typically requires opening the case and replacing a fast-blow fuse (e.g., F200mA/250V). Consult a qualified technician if unsure.

### TROUBLESHOOTING

Problem	Possible Cause	Solution
No display or dim display	Dead or low battery; Incorrect battery installation.	Replace battery; Check battery polarity.
"OL" (Overload) displayed	Input value exceeds selected range; Open circuit (for resistance/continuity).	Select a higher range; Check circuit connections.
Incorrect readings	Incorrect range selected; Poor test lead connection; Damaged test leads.	Select appropriate range; Ensure firm connections; Inspect and replace damaged leads.

Problem	Possible Cause	Solution
No current measurement (mA range)	Blown fuse.	Replace the internal fuse (F200mA/250V).

## SPECIFICATIONS

Parameter	Value
Model	XL830L
DC Voltage	200mV / 2V / 20V / 200V / 600V
AC Voltage	200V / 600V
DC Current	200µA / 2mA / 20mA / 200mA / 10A
Resistance	200Ω / 2kΩ / 20kΩ / 200kΩ / 2MΩ
Diode Test	Yes
Transistor hFE Test	Yes
Display	LCD with Blue Backlight
Power Supply	9V Battery (NEDA 1604 or 6F22)
Dimensions (Approx.)	142.5mm x 69.2mm x 35.7mm (5.59in x 2.72in x 1.40in)
Weight (Approx.)	10g (0.353 ounces) - <i>Note: This weight seems unusually low for a multimeter, likely referring to a component or packaging. The actual product weight is typically higher.</i>



Image: Technical drawing showing the dimensions of the GRSS XL830L Digital Multimeter: 142.5mm (5.59in) height, 69.2mm (2.72in) width, and 35.7mm (1.40in) depth.

## WARRANTY AND SUPPORT

For warranty information or technical support regarding your GRSS XL830L Digital Multimeter, please refer to the contact information provided with your purchase documentation or visit the official GRSS website. Keep your purchase receipt as proof of purchase for any warranty claims.

For general inquiries, you may also refer to the product page on Amazon: [GRSS XL830L Product Page](#)

