

HITBOX MIG200III

HITBOX MIG200III 6-in-1 Multi-Process Welder Instruction Manual

Model: MIG200III

1. INTRODUCTION

This manual provides comprehensive instructions for the safe and effective operation, setup, maintenance, and troubleshooting of your HITBOX MIG200III 6-in-1 Multi-Process Welder. Please read this manual thoroughly before using the equipment and retain it for future reference.

The HITBOX MIG200III is a versatile welding machine designed for various applications, offering six welding processes: Gas MIG, Gasless Flux Core MIG, Stick (MMA), Lift TIG, Spot Welding, and Spool Gun compatibility. It features synergic control, digital welding technology, and a large LED display for ease of use.



Image 1.1: HITBOX MIG200III Welder and included accessories.

2. SAFETY INFORMATION

WARNING: Welding can be dangerous. Always follow safety precautions to prevent injury or death.

- **Electric Shock Can Kill:** Do not touch live electrical parts. Wear dry welding gloves and protective clothing. Ensure the workpiece is properly grounded.
- **Fumes and Gases Can Be Dangerous:** Keep your head out of the fumes. Use enough ventilation, exhaust at the arc, or both, to keep fumes and gases away from your breathing zone.
- **Arc Rays Can Burn Eyes and Skin:** Wear a welding helmet with a proper shade of filter to protect your face and eyes. Wear appropriate protective clothing to protect your skin.
- **Fire and Explosion Hazard:** Remove all flammables within 35 feet (10 meters) of the welding area. Have a fire extinguisher nearby.
- **Hot Parts Can Cause Severe Burns:** Allow welding equipment to cool before touching.
- **Magnetic Fields:** Pacemaker wearers should consult their doctor before operating.
- Always ensure the machine is connected to a properly rated power supply (110V or 220V) and that the

power cord is in good condition.

3. PRODUCT OVERVIEW

3.1 Key Features

- **6-in-1 Multi-Process Welding:** Supports Gas MIG, Gasless Flux Core MIG, Stick (MMA), Lift TIG, Spot Welding, and Spool Gun (TIG torch and spool gun sold separately).
- **Synergic Control:** Automatically adjusts recommended current and wire feed speed based on selected wire diameter and gas type, simplifying setup.
- **Digital Welding Technology:** Equipped with MCU control and IGBT inverter for improved stability and performance. Includes burn-back adjustment, pre-flow/post-flow, and 2T/4T settings.
- **Large LED Digital Display:** Provides clear and accurate data visibility for easy operation.
- **Dual Voltage Capability:** Operates on both 110V and 220V power supplies.
- **Enhanced Safety:** Features VRD (Voltage Reduction Device), overcurrent, overvoltage, overload, and overheat protection.

7 IN 1 MULTI-PROCESS WELDER



Gas MIG



Flux MIG



Spool Gun
(Extra purchase required)



Lift TIG
(Extra purchase required)



Spot Welding



Single Pulse
MIG



MMA



Note: WP26V TIG torch and spool gun need to be purchased additionally

Image 3.1: Multi-Process Capabilities of the HITBOX MIG200III.

3.2 Components (Typical)

The HITBOX MIG200III typically includes:

- MIG200III Welding Machine
- MIG Torch (with graphene tube enhancement)
- Ground Clamp
- Electrode Holder (for Stick welding)
- Flux Core Wire Spool
- Contact Tips and Nozzles
- Power Cord (110V/220V compatible)

Note: Additional accessories such as a TIG torch, spool gun, and gas regulator are sold separately.

SAFETY & DURABILITY

High Integration MCU, Premium Fan



Image 3.2: Internal components and safety features.

4. SETUP

4.1 Power Connection

1. Ensure the welder is turned off.
2. Connect the power cord to a suitable 110V or 220V AC power outlet. The machine automatically detects the voltage.

3. Verify the power source meets the welder's requirements.

4.2 Wire Installation (MIG/Flux Core)

1. Open the wire feeder compartment.
2. Place the wire spool onto the spool holder, ensuring it rotates freely.
3. Feed the welding wire through the guide tube and into the drive roller mechanism.
4. Close the drive roller tension arm and adjust the tension appropriately for the wire diameter.
5. Connect the MIG torch to the front panel.
6. Press and hold the wire feed button (often integrated with the gas save function) to feed the wire through the torch liner until it exits the contact tip.



Image 4.1: Wire Spool Installation.

4.3 Gas Connection (for Gas MIG)

1. Attach the gas hose from your shielding gas cylinder regulator to the gas inlet connector on the rear of the welder.
2. Ensure all connections are tight to prevent gas leaks.
3. Open the gas cylinder valve and adjust the flow rate on the regulator as required for your welding process.

4.4 Torch and Ground Clamp Connection

1. Connect the MIG torch to the appropriate connector on the front panel.
2. Connect the ground clamp cable to the designated terminal on the front panel. For Flux Core MIG, the ground clamp is typically connected to the positive (+) terminal, and for Gas MIG, it's typically connected to the negative (-) terminal. Refer to the machine's specific polarity markings.
3. Securely attach the ground clamp to the workpiece or welding table, ensuring good electrical contact.

Your browser does not support the video tag.

Video 4.1: Demonstrates connecting the MIG torch, feeding welding wire, and adjusting settings on the digital display.

5. OPERATING INSTRUCTIONS

5.1 Power On and Mode Selection

1. Turn on the welder using the main power switch.
2. Use the control panel to select the desired welding process (MIG, MMA, TIG, etc.).

5.2 Synergic Control (MIG)

The synergic control simplifies MIG welding setup:

1. Select the **SYN** mode on the display.
2. Choose the **Material Type** (e.g., Fe+CO2 for carbon steel with CO2, Fe+MIX for carbon steel with mixed gas, FLUX for flux core, AL+Ar for aluminum with Argon).
3. Select the **Wire Diameter** (e.g., 0.8mm, 0.9mm, 1.0mm).
4. The machine will automatically suggest optimal voltage and wire feed speed. Fine-tune these settings using the voltage and amperage/wire feed speed knobs if necessary.

SYNERGIC MIG WELDING

Great for Beginners

Only 3 Steps to Welding

① Select SYN mode

② Select material

③ Select wire size



Image 5.1: Synergic Control Interface.

5.3 Specific Welding Modes

Gas MIG / Flux Core MIG:

- Select the appropriate MIG mode (Gas or Flux).
- Adjust parameters using synergic control or manually.
- Use 2T/4T function: 2T (Two-Touch) for short welds, 4T (Four-Touch) for longer welds without holding the trigger.
- **Pre-Gas/Post-Gas:** Adjust the duration of gas flow before and after welding to protect the weld puddle.

Stick (MMA) Welding:

- Select MMA mode.
- Connect the electrode holder to the appropriate terminal and the ground clamp to the other.
- Adjust amperage based on electrode type and material thickness.
- Features include Hot Start, Arc Force, and Anti-stick for improved arc stability and performance.

Lift TIG Welding:

- Select TIG mode. *(Requires separate TIG torch, not included).*
- Connect the TIG torch and ground clamp.
- Initiate arc by gently touching the tungsten electrode to the workpiece and lifting slightly.

Spot Welding:

- Select Spot Welding mode.
- Adjust spot welding time as needed.

Spool Gun Welding:

- Connect a compatible spool gun. *(Spool gun sold separately).*
- Ideal for welding aluminum and other soft wires.



Image 5.2: Stick & Lift TIG Welding Parameters.

5.4 Gas Management Functions

- **Gas Save:** Press and hold the knob to feed wire without gas, useful for initial wire feeding or testing.
- **Gas Check:** Use this function to check the proper supply and flow of shielding gas before welding.



Image 5.3: Gas Save and Gas Check Functions.

6. MAINTENANCE

Regular maintenance ensures optimal performance and longevity of your welding machine.

- **Cleaning:** Regularly clean the exterior of the machine with a dry, soft cloth. Ensure ventilation openings are free from dust and debris. Use compressed air to clear internal dust periodically, ensuring the machine is unplugged.
- **Wire Feeder:** Inspect the drive rollers and wire liner for wear or blockages. Clean any metal dust or debris from the wire path. Ensure proper tension on the drive rollers.
- **Torch and Cables:** Check the MIG torch nozzle, contact tip, and diffuser for spatter buildup and wear. Replace worn parts as needed. Inspect all cables (MIG torch, ground clamp, electrode holder, power cord) for cuts, cracks, or loose connections.
- **Storage:** Store the welder in a clean, dry environment, away from excessive dust, moisture, and corrosive materials.

7. TROUBLESHOOTING

This section addresses common issues you might encounter. For problems not listed here, contact customer support.

- **No Power:**
Possible Cause: Power cord not connected, circuit breaker tripped, machine switch off.
Solution: Check connections, reset breaker, ensure power switch is ON.
- **No Arc / Weak Arc:**
Possible Cause: Poor ground connection, incorrect settings, worn contact tip, wrong polarity, wire feed issue.
Solution: Ensure ground clamp has good contact. Verify welding parameters (voltage, amperage, wire speed). Replace contact tip. Check polarity for the selected welding process. Inspect wire feeder for blockages or incorrect tension.
- **Wire Feeding Problems (Wire bunched up, inconsistent feed):**
Possible Cause: Incorrect drive roller tension, clogged liner, wrong drive roller size, spatter in nozzle/tip.
Solution: Adjust drive roller tension. Clean or replace the torch liner. Ensure drive rollers match wire

diameter. Clean nozzle and replace contact tip if necessary.

- **Overheat Protection Activated:**

Possible Cause: Exceeded duty cycle, poor ventilation.

Solution: Allow the machine to cool down. Ensure adequate airflow around the welder. Reduce welding time or current.

- **Inaccurate Amperage Display:**

Possible Cause: Calibration variance.

Solution: While the display provides a guide, experienced users may need to adjust settings based on visual weld quality. This is a known characteristic for some units and does not necessarily indicate a malfunction if welding performance is satisfactory.

8. SPECIFICATIONS

Specification	Value
Brand	HITBOX
Model Number	MIG200III
Item Weight	31.8 pounds
Package Dimensions	20.2 x 15.2 x 12.8 inches
Power Source	AC (110V/220V Dual Voltage)
Included Components	MIG Welder (MIG200III)
Batteries Required?	No

9. WARRANTY AND SUPPORT

For warranty information, technical support, or service inquiries, please contact HITBOX customer service directly. Refer to the product packaging or the official HITBOX website for the most current contact details. Please have your model number (MIG200III) and purchase date available when contacting support.

Related Documents - MIG200III



[HITBOX HBM200 Operation Instruction Manual | MIG, MMA, TIG Welder](#)

Comprehensive operation instruction manual for the HITBOX HBM200 welding machine, covering safety, features, installation, operation, maintenance, and troubleshooting for MIG, MMA, and TIG welding applications.



[HITBOX MIG250DP Professional MIG Welding Machine for Aluminum](#)

Discover the HITBOX MIG250DP, a versatile 5-in-1 MIG welding machine designed for aluminum and other metals. Features include 2T/4T function, synergic control, IGBT inverter, and advanced digital display. Ideal for professional and beginner welders.



[HITBOX SYN MIG200 MIG/MAG Inverter Welder Test Report](#)

This comprehensive test report details the performance and compliance of the HITBOX SYN MIG200 MIG/MAG inverter welder, tested by Dongguan NTEK Testing Service Co., Ltd. against CAN/CSA E60974-1-12 and ANSI/IEC 60974-1 standards.

Dear customer,
HITBOX offers good services. If you have any problem when using our products, please contact us at the first time, our customer service will solve it for you.
Our Email: sales@hitbox.com
WhatsApp: <https://www.whatsapp.com/channel/00299160000000000000>
Twitter: <https://twitter.com/hitboxwelder>
LINE: <https://line.me/tv/channel/00299160000000000000>
Facebook: <https://www.facebook.com/hitboxwelder/>
Website: <http://www.hitbox.com>
Contact

[HITBOX Product Support and Contact Information | Warranty & Service](#)

Get in touch with HITBOX customer support for warranty inquiries and product assistance. Find contact details including email, WhatsApp, WeChat, LINE, and Facebook.



[HZXVOGEN MIG185II Operation Instruction Manual - Welding Machine Guide](#)

Comprehensive operation instruction manual for the HZXVOGEN MIG185II welding machine. Learn about features, applications, parameters, troubleshooting, and safety for this IGBT inverter welder.

