

LVSEDTAL GDZ80x73-2.2

LVSEDTAL GDZ80x73-2.2 Air Cooled Spindle Motor  
Instruction Manual

INTRODUCTION

This manual provides essential information for the safe and efficient installation, operation, and maintenance of your LVSEDTAL GDZ80x73-2.2 Air Cooled Spindle Motor. Please read this manual thoroughly before using the product and retain it for future reference. Proper understanding and adherence to these instructions will ensure optimal performance and longevity of your spindle motor.

PRODUCT FEATURES

- **Durable Construction:** Designed for extended working life and increased stability during operation.
- **Wide Application Range:** Primarily designed for use with CNC machine materials.
- **Efficient Cooling:** Achieves heat dissipation through a convenient axial fan cooling system.
- **Optimized Heat Management:** The shell is cooled by an internal liquid cycle to reduce heat rise caused by high-speed rotation.

TECHNICAL SPECIFICATIONS

The following image provides a detailed technical drawing of the GDZ80x73-2.2 spindle motor, including key dimensions and connection points. Below the image, a table summarizes the main technical parameters.



Figure 1: Technical drawing of the GDZ80x73-2.2 Spindle Motor with dimensions and connection details.

GDZ80x73-2.2 Spindle Motor Parameters

| Parameter | Value |
|-----------|-------|
|-----------|-------|

| Parameter             | Value               |
|-----------------------|---------------------|
| Model                 | GDZ80x73-2.2        |
| Rotational Speed      | 24000 r/min         |
| Frequency             | 400 Hz              |
| Power                 | 2.2 KW              |
| Voltage               | 220 V               |
| Current               | 6 A                 |
| Cooling Method        | Axial Fan Cooling   |
| Collet Type           | ER20                |
| Collet Range          | 1-13 mm             |
| Bearing Configuration | 7005DB*2 + 7002DT*2 |
| Net Weight            | 4.75 kgs            |
| Maximum Torque        | 0.87 Nm             |

Additional specifications:

- **Brand:** LVSEDTAL
- **Application:** Milling
- **Cable Clamp Head:** M22X1.5

## SETUP INSTRUCTIONS

### Safety Precautions

- Ensure the power supply is disconnected before any installation or maintenance.
- Wear appropriate personal protective equipment (PPE), including safety glasses and gloves.
- Verify that the voltage and frequency of the power supply match the spindle motor's specifications (220V, 400Hz).
- Ensure proper grounding of the spindle motor to prevent electrical hazards.
- Keep the work area clean and free of obstructions.

### Installation Steps

1. **Mounting:** Securely mount the spindle motor to your CNC machine using appropriate fasteners. Refer to the technical drawing for mounting dimensions (e.g., 8-Φ7 through holes, 80x95mm flange dimensions).
2. **Electrical Connection:** Connect the power cable to the spindle motor's cable clamp head (M22X1.5). Ensure correct phase connections for 220V operation. Connect the ground wire to a reliable ground point.
3. **Inverter Connection:** Connect the spindle motor to a compatible Variable Frequency Drive (VFD) or inverter. Configure the VFD parameters according to the spindle's specifications (e.g., 400Hz frequency, 2.2KW power, 24000 RPM maximum speed).
4. **Cooling System:** Verify that the axial fan cooling system is unobstructed and functioning correctly. Ensure

adequate airflow around the spindle motor.

5. **Collet Installation:** Insert the ER20 collet and tighten the collet nut. Ensure the collet is clean and free of debris before inserting a tool.

## OPERATING INSTRUCTIONS

---

### Initial Start-up

1. After installation, double-check all electrical connections and mounting security.
2. Power on the VFD/inverter and gradually increase the spindle speed. Observe for any unusual noises, vibrations, or overheating.
3. Allow the spindle to run at a low speed for a few minutes to ensure proper bearing lubrication and break-in.
4. Gradually increase to the desired operating speed, monitoring the spindle's performance.

### Normal Operation

- Always ensure the spindle is running at the appropriate speed for the material and tool being used.
- Avoid sudden changes in speed or direction, as this can stress the bearings and motor.
- Monitor the spindle temperature during extended operation. While the axial fan provides cooling, excessive heat can indicate an issue.
- Ensure the workpiece is securely clamped before starting any milling operation.

## MAINTENANCE

---

### Routine Maintenance

- **Daily:** Inspect the spindle for any visible damage, loose connections, or unusual noises. Clean any dust or debris from the cooling fan vents.
- **Weekly:** Check the collet and collet nut for wear or damage. Ensure they are clean and provide a secure grip on the tool.
- **Monthly:** Verify the tightness of all mounting bolts. Inspect the power cable for any signs of wear or fraying.
- **Bearing Lubrication:** This spindle motor uses sealed bearings (7005DB\*2 + 7002DT\*2) that are typically maintenance-free for their lifespan. Avoid attempting to lubricate sealed bearings unless specifically instructed by the manufacturer.

### Storage

When not in use for extended periods, store the spindle motor in a clean, dry, and temperature-controlled environment. Protect it from dust, moisture, and corrosive substances. It is recommended to rotate the spindle manually every few weeks to prevent bearing seizure.

## TROUBLESHOOTING

---

| Problem | Possible Cause | Solution |
|---------|----------------|----------|
|---------|----------------|----------|

| Problem                    | Possible Cause                                                                                    | Solution                                                                                                                           |
|----------------------------|---------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|
| Spindle does not start     | No power supply; VFD error; wiring issue                                                          | Check power connections; verify VFD status and error codes; inspect wiring for damage or incorrect connections.                    |
| Unusual noise or vibration | Loose mounting; worn bearings; unbalanced tool; VFD parameter mismatch                            | Tighten mounting bolts; inspect bearings (if accessible, otherwise contact support); balance or replace tool; verify VFD settings. |
| Overheating                | Blocked cooling fan; excessive load; prolonged high-speed operation; ambient temperature too high | Clean fan vents; reduce load; operate within recommended parameters; ensure adequate ventilation in the work area.                 |
| Reduced performance/power  | Incorrect VFD settings; worn tool; voltage drop                                                   | Review VFD parameters; replace worn tools; check power supply voltage.                                                             |

## WARRANTY AND SUPPORT

---

For warranty information, technical support, or service inquiries regarding your LVSEDTAL GDZ80x73-2.2 Air Cooled Spindle Motor, please refer to the documentation provided at the time of purchase or contact your vendor directly. Keep your purchase receipt and product serial number handy when contacting support.

Unauthorized disassembly or modification of the spindle motor may void the warranty and could lead to product damage or personal injury.