

## Reboot RBM2500 PRO

# Reboot RBM2500 PRO 8-in-1 Multi-Process Welder Instruction Manual

Model: RBM2500 PRO

## 1. INTRODUCTION

This manual provides essential information for the safe and effective operation, setup, and maintenance of your Reboot RBM2500 PRO 8-in-1 Multi-Process Welder. Please read this manual thoroughly before operating the equipment. Retain this manual for future reference.

## 2. SAFETY INFORMATION

Welding operations can be hazardous. Always follow safety precautions to prevent injury or damage. Failure to comply with safety instructions may result in serious injury or death.

- **Eye Protection:** Always wear a welding helmet with appropriate shade lenses to protect your eyes from arc rays.
- **Body Protection:** Wear flame-resistant clothing, gloves, and safety shoes to protect against sparks, heat, and electric shock.
- **Ventilation:** Ensure adequate ventilation to remove welding fumes and gases from the work area.
- **Electrical Safety:** Never operate the welder in wet conditions. Ensure proper grounding and inspect cables for damage before each use.
- **Fire Prevention:** Keep flammable materials away from the welding area. Have a fire extinguisher readily available.
- **Gas Cylinders:** Handle gas cylinders with care. Secure them to prevent falling.

## 3. PRODUCT OVERVIEW

The Reboot RBM2500 PRO is a versatile 8-in-1 multi-process welding machine designed for various welding applications. It supports Gas MIG, Flux Core, Lift TIG, Stick (MMA), Spot welding, and Spool Gun operations. This unit offers dual voltage flexibility (120V/240V) and a maximum output of 250A.





**Figure 3.2:** The large LED display of the RBM2500 PRO, showing welding parameters and settings for different processes.

### 3.2 Included Components

- Reboot RBM2500 PRO Welder Unit
- MIG Torch
- Ground Clamp
- 300AMP Heavy Duty Copper Electrode Holder
- Power Adapter (for 120V/240V)
- Consumables (e.g., contact tips, nozzles)



**Figure 3.3:** The included Reboot 300ACE heavy-duty copper electrode holder, designed for reliable ARC/Stick welding.

## 4. SETUP

Proper setup is crucial for safe and efficient welding. Follow these steps carefully.

### 4.1 Power Connection

1. Ensure the welder's power switch is in the OFF position.
2. Determine the appropriate voltage for your power source (120V or 240V).
3. Connect the power cord to the welder and then to a suitable grounded electrical outlet. Use the provided adapter if switching between 120V and 240V.
4. Verify that the circuit breaker or fuse rating is sufficient for the welder's maximum current draw.

### 4.2 Ground Clamp Connection

Connect the ground clamp cable to the appropriate terminal on the welder. Securely attach the ground clamp to the workpiece or a clean, bare metal portion of the welding table. A good ground connection is essential for arc stability and safety.

### 4.3 Welding Torch/Holder Connection

- **MIG Torch:** Connect the MIG torch cable to the front panel connector. Ensure it is securely tightened.



- **Electrode Holder (Stick/MMA):** Connect the electrode holder cable to the positive (+) terminal for most applications, or negative (-) depending on electrode type and desired penetration.
- **TIG Torch:** Connect the TIG torch to the appropriate connector. For Lift TIG, a gas connection may also be required if using shielding gas.



## Efficient Connection

Supplied with an allen wrench and cable connection ferrule, assuring efficient connection

**Figure 4.1:** Detail of the electrode holder connection, illustrating the use of an Allen wrench for efficient and secure cable attachment.

### 4.4 Gas Connection (for Gas MIG/TIG)

If performing Gas MIG or TIG welding, connect the gas hose from your shielding gas cylinder regulator to the gas inlet on the rear of the welder. Ensure all connections are tight and leak-free. Set the gas flow rate according to your welding process and material.

## 5. OPERATING MODES

The RBM2500 PRO offers multiple welding processes. Select the desired mode using the control panel and adjust parameters accordingly.

# 8 IN 1 Multi-Process Welder



**Figure 5.1:** Visual representation of the 8-in-1 multi-process capabilities of the RBM2500 PRO welder, including MIG, MMA, Spot, Flux Core, Spool Gun, and Lift TIG.

## 5.1 MIG Welding (Gas MIG / Flux Core)

MIG welding uses a continuously fed wire electrode and, for Gas MIG, an external shielding gas. Flux Core welding uses a self-shielding wire that does not require external gas.

1. Install the appropriate wire spool (solid wire for Gas MIG, flux-cored wire for Flux Core).
2. Feed the wire through the torch liner and out the contact tip.
3. Select 'MIG' mode on the welder.
4. Adjust voltage and wire feed speed according to the material thickness and wire type.
5. For Gas MIG, ensure shielding gas is connected and flowing.

## 5.2 Lift TIG Welding

Lift TIG welding provides precise control and high-quality welds, typically used for thinner materials.

1. Install a tungsten electrode into the TIG torch.
2. Connect shielding gas (typically Argon) and set the flow rate.
3. Select 'Lift TIG' mode.

4. Adjust amperage based on material thickness.
5. Initiate the arc by gently touching the tungsten to the workpiece and lifting slightly.

### 5.3 Stick Welding (MMA/ARC)

Stick welding uses a consumable electrode coated with flux. This process is versatile and suitable for outdoor use and thicker materials.

1. Insert the desired electrode into the 300AMP electrode holder.
2. Select 'Stick' or 'MMA' mode.
3. Adjust amperage according to the electrode type and diameter, and material thickness.
4. Strike the arc by lightly scratching or tapping the electrode on the workpiece.



**Strong bite force not easy to fall off**

**Figure 5.2:** The robust jaw grip of the 300AMP electrode holder, ensuring secure electrode retention during Stick welding operations.

### 5.4 Spot Welding

Spot welding is used for joining overlapping metal sheets at specific points.

1. Select 'Spot' mode.
2. Adjust the spot welding time and power settings.
3. Position the MIG torch over the desired spot on the overlapping sheets.



4. Initiate the weld.

### 5.5 Spool Gun Welding

The spool gun is typically used for welding softer wires like aluminum, as it minimizes wire feeding issues.

1. Connect the spool gun to the designated port on the welder.
2. Load the wire spool into the spool gun.
3. Select 'Spool Gun' mode.
4. Adjust welding parameters as needed for the specific wire and material.

## 6. MAINTENANCE

Regular maintenance ensures the longevity and optimal performance of your welder.

- **Cleaning:** Regularly clean the welder's exterior and ventilation openings to prevent dust and debris buildup. Use compressed air to clear internal components periodically.
- **Cable Inspection:** Inspect all welding cables, power cords, and gas hoses for cuts, abrasions, or loose connections before each use. Replace damaged components immediately.
- **Torch/Holder Maintenance:** Clean MIG torch liners, replace worn contact tips and nozzles. Ensure the electrode holder jaws are clean and provide a strong grip.
- **Wire Feeder:** Keep the wire feeder mechanism clean and free of debris. Check drive rolls for wear and adjust tension as needed.

## 7. TROUBLESHOOTING

This section addresses common issues you might encounter. For problems not listed here, contact customer support.


Problem	Possible Cause	Solution
No Arc	No power, poor ground, incorrect settings, faulty cable.	Check power connection, ensure good ground, verify settings, inspect cables.
Poor Weld Quality	Incorrect parameters, contaminated material, improper technique, insufficient gas.	Adjust voltage/ampereage/wire speed, clean workpiece, review technique, check gas flow.
Wire Feeding Issues (MIG)	Incorrect drive roll tension, clogged liner, wrong contact tip, bent wire.	Adjust drive roll tension, clean/replace liner, use correct contact tip, check wire spool.
Overheating	Exceeding duty cycle, blocked ventilation.	Allow welder to cool, ensure clear ventilation.

## 8. SPECIFICATIONS

Feature	Detail
Model	RBM2500 PRO



Feature	Detail
Input Voltage	120V / 240V (Dual Voltage)
Max Output Current	250 Amps
Welding Processes	Gas MIG, Flux Core, Lift TIG, Stick (MMA), Spot, Spool Gun
Electrode Holder Capacity	1/4 ~ 7/8 inch (with 300AMP holder)
ASIN	B0FBRLC7P9
Date First Available	May 13, 2025



**Figure 8.1:** Dimensions of the 300AMP electrode holder, indicating its length, width, height, and jaw opening.








**LARGE 300-AMP**  
provides durability, 1/4~7/8 inch  
electrode capacity

**Figure 8.2:** The large 300-AMP electrode holder jaw, capable of securely holding electrodes from 1/4 to 7/8 inches.

## 9. WARRANTY AND SUPPORT

For warranty information, technical support, or service inquiries, please contact Reboot customer service. Refer to your purchase documentation for specific warranty terms and contact details.

**Reboot Customer Support:** Please visit the official Reboot website or refer to the contact information provided with your product packaging.

	<p><a href="#">Reboot RBM2100D Recommended Weld Settings Guide</a></p> <p>A comprehensive guide detailing recommended welding settings for the Reboot RBM2100D multi-process welder. This document covers settings for MIG, TIG, and Stick welding processes, including various electrode types, wire types, and wire diameters, along with control panel descriptions and installation instructions.</p>
	<p><a href="#">Reboot RBA1400 &amp; RBA1400D Welding Machine Operation Manual</a></p> <p>Detailed operation manual for Reboot RBA1400 and RBA1400D welding machines. Covers machine introduction, parts, setup, MMA and LIFT TIG modes, technical specifications, troubleshooting, and welding parameters. Includes safety tips and internal component descriptions.</p>
	<p><a href="#">Reboot RBM1600 Operation Manual: Your Guide to MMA, MIG, and LIFT TIG Welding</a></p> <p>Comprehensive operation manual for the Reboot RBM1600 welding machine. Learn to use MMA, MIG (Gas/Gasless), and LIFT TIG modes with detailed instructions, technical specifications, and troubleshooting tips for optimal performance.</p>
	<p><a href="#">Reboot RBM1300 Welding Machine Operation Manual</a></p> <p>This manual provides detailed instructions for operating the Reboot RBM1300 welding machine, covering its features, setup, different welding modes (MMA, MIG Gas, MIG Gasless, LIFT TIG), technical specifications, safety precautions, and troubleshooting.</p>
	<p><a href="#">Reboot RBM1300 Operation Manual: Your Guide to Advanced Welding</a></p> <p>Discover the capabilities of the Reboot RBM1300 welding machine. This comprehensive manual covers operation, technical specifications, and troubleshooting for MMA, MIG, and LIFT TIG welding modes.</p>

