



[Manuals.plus](#) /

> [plplaaoo](#) /

> plplaaoo FS8233 Digital Multimeter User Manual

plplaaoo FS8233

plplaaoo FS8233 Digital Multimeter User Manual

Model: FS8233

1. PRODUCT OVERVIEW

The plplaaoo FS8233 is an ultra-thin, full-screen intelligent automatic digital multimeter designed for electricians, engineers, and technicians. It features intelligent auto-ranging technology for precise detection of voltage, current, resistance, and continuity without manual adjustments. Built with durable ABS and silicone materials, it offers reliable performance in various environments.



Image 1.1: Front view of the plplaaoo FS8233 Digital Multimeter, showcasing its full-screen display.

Key Features:

- **Automatic Testing:** Intelligent auto-ranging for voltage, current, resistance, and continuity.
- **High Accuracy:** Advanced chip ensures $\pm 0.5\%$ DC voltage accuracy.
- **Durable Construction:** Made from premium ABS and wear-resistant silicone for industrial-grade durability.
- **Multifunctional:** Measures AC/DC voltage (up to 600V), current (10A max), resistance (60M Ω), capacitance (60mF), and temperature.
- **Safety Features:** Anti-burn protection and 600V CAT III safety rating.
- **User-Friendly Design:** Large backlit screen for clear readings in low-light conditions.

2. SAFETY INFORMATION

Always adhere to safety precautions when using electrical testing equipment. Failure to do so may result in injury or damage to the device or equipment being tested.

- Ensure the multimeter is in good working condition before use.

- Do not exceed the maximum input values specified for each function.
- Verify the correct function and range are selected before making measurements.
- Use appropriate personal protective equipment (PPE) such as insulated gloves and safety glasses.
- Avoid touching exposed conductors or circuit components during measurements.
- Replace batteries promptly when the low battery indicator appears to ensure accurate readings.
- The device has a 600V CAT III safety rating. Always respect this rating and do not use it in circuits exceeding this category.

3. SETUP

3.1 Battery Installation

The FS8233 multimeter requires two 1.5V AAA batteries (not included) for operation.

1. Locate the battery compartment cover on the back of the multimeter.
2. Use a screwdriver to open the battery compartment.
3. Insert two AAA batteries, ensuring correct polarity (+ and -).
4. Securely close the battery compartment cover.

3.2 Connecting Test Leads

The multimeter comes with two test leads. Connect them to the appropriate input jacks:

- Insert the **black** test lead into the **COM** (common) jack.
- Insert the **red** test lead into the **VHzΩmA** jack for most voltage, resistance, frequency, capacitance, and current measurements (up to 600mA).
- For high current measurements (up to 10A), insert the **red** test lead into the **10A** jack.



Image 3.2: Bottom view of the multimeter, illustrating the input jacks for test lead connection.

4. OPERATING INSTRUCTIONS

The FS8233 features intelligent auto-ranging, simplifying most measurements. Power on the device and it will automatically detect the measurement type.

4.1 Power On/Off

- Press the power button (usually marked with a circle and a vertical line) to turn the multimeter on.
- Press and hold the power button to turn the multimeter off.



Image 4.1: The multimeter display indicating 'AUTO' mode, ready for automatic measurement.


4.2 Automatic Measurement

In auto mode, the multimeter will automatically identify and measure AC/DC voltage, resistance, and continuity. Simply connect the test leads to the circuit or component you wish to measure.

4.3 Specific Measurements

While the device is largely auto-ranging, it supports specific measurements:

- **Voltage (AC/DC):** Connect test leads in parallel to the circuit. The multimeter will automatically detect AC or DC voltage.
- **Current (AC/DC):** Connect test leads in series with the circuit. Ensure the red lead is in the correct current jack (mA or 10A).
- **Resistance:** Connect test leads across the component. Ensure the component is de-energized.
- **Capacitance:** Connect test leads across the capacitor. Ensure the capacitor is discharged before testing.
- **Temperature:** Connect the included temperature probe to the appropriate jacks (usually V Ω mA and COM) and place the probe tip on the object to be measured.



Test Instrument

According to the current input, it can automatically identify and test, saving time and effort.

Image 4.3: An electrician using the FS8233 multimeter to perform tests on an electrical panel, demonstrating practical application.

4.4 Reading the Display

The large backlit screen displays readings clearly. The unit of measurement (V, A, Ω , F, $^{\circ}\text{C}$) will be shown alongside the numerical value. The 'AUTO' indicator confirms auto-ranging is active.



Image 4.4: Close-up view of the multimeter's display, showing a clear numerical reading and measurement units.

5. MAINTENANCE

5.1 Cleaning

To maintain the multimeter's performance and appearance:

- Wipe the casing with a damp cloth and mild detergent. Do not use abrasive cleaners or solvents.
- Ensure no moisture enters the device through the input jacks or seams.

5.2 Battery Replacement

When the low battery indicator appears on the display, replace the batteries as described in Section 3.1. Always use fresh 1.5V AAA batteries.

5.3 Storage

Store the multimeter in a cool, dry place away from direct sunlight and extreme temperatures. If storing for an extended period, remove the batteries to prevent leakage.

6. TROUBLESHOOTING

If you encounter issues with your FS8233 Digital Multimeter, refer to the following common troubleshooting steps:

- **No Display/Device Not Turning On:**
 - Check if the batteries are correctly installed and have sufficient charge. Replace if necessary.
 - Ensure the power button is pressed firmly.
- **Incorrect or Unstable Readings:**
 - Verify that the test leads are securely connected to the correct input jacks.
 - Ensure good contact between the test probes and the circuit/component being measured.
 - Check for damaged test leads and replace if necessary.
 - Ensure the component being measured is within the multimeter's specified range.
- **'OL' or Overload Indication:**
 - This indicates the measured value exceeds the current range. Ensure the red test lead is in the appropriate high-current jack (10A) if measuring high current, or that the voltage/resistance is within the device's maximum limits.

7. SPECIFICATIONS

Parameter	Specification
Model	FS8233
Material	ABS + Silicone
Battery	2 x 1.5V AAA Battery (Not Included)
AC Current Range	6000mA (1mA, $\pm(1.0\% + 8 \text{ digits})$), 10A (0.01A)
DC Current Range	6000mA (1mA, $\pm(1.0\% + 5 \text{ digits})$), 10A (0.01A)
DC Voltage Range	6V (0.001V, $\pm(0.5\% + 3 \text{ digits})$), 60V (0.01V), 600V (0.1V)
Resistance Range	Up to 60M Ω
Capacitance Range	Up to 60mF
Safety Rating	600V CAT III
Included Components	2 Test Leads, 1 Temperature Probe, User Manual