

# **KERN EOB Platform Floor Scales Instruction Manual**

Home » KERN » KERN EOB Platform Floor Scales Instruction Manual



## **Contents**

- 1 KERN EOB Platform Floor Scales 1.1 Product Usage Instructions
- 2 Technical data
- 3 Appliance overview
- 4 Overview of display
- **5 Basic Information (General)**
- 6 Unpacking, Setup and Commissioning
- 7 Adjustment
- 8 Operation
- 9 Menu
- 10 Servicing, maintenance, disposal
- 11 Error messages, troubleshooting guide
- **12 FAQ**
- 13 Documents / Resources
  - 13.1 References
- 14 Related Posts



**KERN EOB Platform Floor Scales** 



## **Specifications**

Model	KERN EOB	KERN EOE
Trademark	KERN (Type)	KERN (Type)
Readability (d)	10 g – 50 g	5 g – 50 g
Weighing range (max)	35 kg – 300 kg	15 kg – 150 kg

#### **Product Usage Instructions**

### 1. Setup

Place the platform/floor scale on a flat and stable surface. Ensure it is connected to a power source within the specified voltage range.

#### 2. Calibration

Before use, calibrate the scale using the recommended adjustment weight provided in the manual. Follow the calibration instructions carefully.

## 3. Weighing

Place the item to be weighed on the center of the scale's platform. Wait for the stabilization time to ensure an accurate reading.

## 4. Power Management

The scale has an auto-off feature to conserve battery life. Make sure to turn off the scale when not in use to prolong the battery operation period.

## 5. Unit Conversion

You can switch between different weighing units as needed. Refer to the manual for instructions on changing the weighing units.

#### **Technical data**

#### **Models KERN EOB**

KERN (Type)	EOB 10K-3B	EOB 30K-2B	EOB 60K-2B	EOB 60K-2LB
	EOB	EOB	EOB	EOB
Trademark	15K5	35K10	60K20	60K20L
Readability (d)	5 g	10 g	20 g	20 g
Weighing range (max)	15 kg	35 kg	60 kg	60 kg
Reproducibility	5 g	10 g	20 g	20 g
Linearity	± 10 g	± 20 g	± 40 g	± 40 g
Recommended adjustment weight, not added (class)	10 kg (M2)	20 kg (M2)	40 kg (M2)	40 kg (M2)
Stabilization time (typical)	3 sec.		1	
Warm-up time	10 min			
Input Voltage	220 V- 240 V, AC	50 Hz		
Power pack secondary voltage	9V, 100 mA	9V, 100 mA		
Battery	4 x 1.5 V AA (= 6	V)		
Battery operation period	60 h			
Auto-Off	3 min			
Weighing Units	kg, lb, pcs			
Ambient temperature	+ 5°C+ 35°C			
Humidity of air	max. 80 % (not co	ondensing)		
Display unit				
(B x D x H) mm	235 x 114 x 51			
Cable length display unit	180 cm	180 cm	180 cm	270 cm
Weighing surface mm	300 x 300 550 x 550			550 x 550
Weight kg (net)	4.2 13.5			13.5

	ЕОВ ЕОВ		ЕОВ	
KERN (Type)	100K-2B	100K-2LB	100K-2XLB	
	EOB	EOB	EOB	
Trademark	150K50	150K-50L	150K50XL	
Readability (d)	50 g	50 g	50 g	
Weighing range (max)	150 kg	150 kg	150 kg	
Reproducibility	50 g	50 g	50 g	
Linearity	± 100 g	± 100 g	± 100 g	
Recommended adjustment weig ht, not added (class)	100 kg (M2)	100 kg (M2)	100 kg (M2)	
Stabilization time (typical)	3 sec.			
Warm-up time	10 min			
Input Voltage	220 V- 240 V, AC 50 Hz			
Power pack secondary voltage	9V, 100 mA	9V, 100 mA		
Battery	4 x 1.5 V AA (= 6 V)			
Battery operation period	60 h			
Auto-Off	3 min			
Weighing Units	kg, lb, pcs			
Ambient temperature	+ 5°C+ 35°C			
Humidity of air	max. 80 % (not condens	ing)		
Display unit				
(B x D x H) mm	235 x 114 x 51			
Cable length display unit	180 cm	270 cm	270 cm	
Weighing surface mm	300 x 300	550 x 550	950 x 500	
Weight kg (net)	4.2	13.5	19.5	

	ЕОВ	ЕОВ	ЕОВ	
KERN (Type)	300K-1B	300K-1LB	300K-1XLB	
	EOB	EOB	EOB	
Trademark	300K100	300K100L	300K100XL	
Readability (d)	100 g	100 g	100 g	
Weighing range (max)	300 kg	300 kg	300 kg	
Reproducibility	100 g	100 g	100 g	
Linearity	± 200 g	± 200 g	± 200 g	
Recommended adjustment weig ht, not added (class)	300 kg (M2)	300 kg (M2)	300 kg (M2)	
Stabilization time (typical)	3 sec.			
Warm-up time	10 min.			
Input Voltage	220 V- 240 V, AC 50 Hz			
Power pack secondary voltage	9V, 100 mA			
Battery (optional)	4 x 1.5 V AA (= 6 V)			
Battery operation period	220 h			
Auto-Off	3 min			
Weighing Units	kg, lb, pcs			
Ambient temperature	+ 10°C+ 35°C			
Humidity of air	max. 80 % (not condensi	ng)		
Display unit				
(B x D x H) mm	235 x 114 x 51			
Cable length display unit	180 cm	270 cm	270 cm	
Weighing surface mm	300 x 300	550 x 550	945 x 505	
Weight kg (net)	4.2	13.5	19.5	

# **Models KERN EOE**

KERN (Type)	EOE 10K-3B	EOE 30K-2B	EOE 60K-2B	EOE 60K-2L B	EOE 100K-2 B
	EOE	EOE	EOE	EOE	EOE
Trademark	10K-3	30K-2	60K-2	60K-2L	100K-2
Readability (d)	5 g	10 g	20 g	20 g	50 g
Weighing range (max)	15 kg	35 kg	60 kg	60 kg	150 kg
Reproducibility	5 g	10 g	20 g	20 g	50 g
Linearity	± 10 g	± 20 g	± 40 g	± 40 g	± 100 g
Recommended adjustment weig ht, not added (class)	10 kg (M3)	20 kg (M2)	40 kg (M2)	40 kg (M2)	100 kg (M2)
Stabilization time (typical)	2.5 sec.				
Warm-up time	10 min.				
Input Voltage	220 V- 240 V,	220 V- 240 V, AC 50 Hz			
Power pack secondary voltage	9V, 100 mA				
Battery (optional)	4 x 1.5 V AA (= 6 V)				
Battery operation period	100 h	100 h			
Auto-Off	3 min				
Weighing Units	kg, lb, pcs				
Ambient temperature	+ 5°C+ 35°	С			
Humidity of air	max. 80 % (no	ot condensing)			
Display unit					
(B x D x H) mm	235 x 114 x 51				
Cable length display unit	180 cm 270 cm 180 cm			180 cm	
Weighing surface mm	300 x 300 550			550 x 550	315 x 305
Weight kg (net)	3.8	3.8	3.8	13	3.8

	EOE 100K-2	EOE 100K-	EOE 300K-1	EOE 300K-1	EOE 300K-
KERN (Type)	LB	2XLB	B	LB	1XLB
	EOE	EOE	EOE	EOE	EOE 300K10
Trademark	150K50L	150K50XL	300K100	300K100L	0XL
Readability (d)	50 g	50 g	100 g	100 g	100 g
Weighing range (max)	150 kg	150 kg	300 kg	300 kg	300 kg
Reproducibility	50 g	50 g	100 g	100 g	100 g
Linearity	± 100 g	± 100 g	± 200 g	± 200 g	± 200 g
Recommended adjustment weig ht, not added (class)	100 kg (M3)	100 kg (M2)	300 kg (M2)	300 kg (M2)	300 kg (M2)
Stabilization time (typical)	3 sec.				
Warm-up time	10 min.				
Input Voltage	220 V- 240 V, AC 50 Hz				
Power pack					
secondary voltage	9V, 100 mA				
Battery (optional)	4 x 1.5 V AA (:	= 6 V)			
Battery operation period	100 h				
Auto-Off	3 min				
Weighing Units	kg, lb, pcs				
Ambient temperature	+ 5°C+ 35°	С			
Humidity of air	max. 80 % (no	ot condensing)			
Display unit					
(B x D x H) mm	235 x 114 x 51				
Cable length display unit	270 cm 180 cm 270 cm				
Weighing surface mm	505 x 505	950 x 500	300 x 300	550 x 550	950 x 500
Weight kg (net)	13,0	18.0	3.8	13.0	18.0

## **Models KERN EOS**

KERN (Type)	EOS 100K-2BXL	EOS 300K-1BXL	
	EOS	EOS	
Trademark	150K50XL	150K50XL	
Readability (d)	50 g	100 g	
Weighing range (max)	150 kg	300 kg	
Reproducibility	50 g	100 g	
Linearity	± 100 g	± 200 g	
Recommended adjustment weig ht, not added (class)	100 kg (M2)	300 kg (M2)	
Stabilization time (typical)	3 sec.		
Warm-up time	10 min.		
Input Voltage	220 V- 240 V, AC 50 Hz		
Power pack secondary voltage	9V, 100 mA		
Battery (optional)	4 x 1.5 V AA (= 6 V)		
Battery operation period	220 h		
Auto-Off	3 min		
Weighing Units	kg, lb, pcs		
Ambient temperature	+ 10°C+ 35°C		
Humidity of air	max. 80 % (not condensing)		
Display unit			
(B x D x H) mm	235 x 114 x 51		
Cable length display unit	270 cm		
Weighing surface mm	900 x 550 900 x 550		
Weight kg (net)	17.0		

# Appliance overview

# Models EOB

Weighing pan, stainless steel



**Models EOE**Weighing pan varnished steel



# **Models EOS**


- Weighing pan, stainless steel
- Anti-slip rubber mat





# Overview of display

# **Example EOB:**



NΩ	Description
	Balance zero display:
1	Should the balance not display exactly zero despite empty scale pan, press the
	TARE button. The balance will be set to zero after a short standby time.
	Stability display:
2	If the display shows the stability display <b>[0]</b> the balance is in a stable status. If the status is instable the [0] display disappears.
3	Stored tare value, see chap. 8.3 "Taring"
	Gross weight display:
4	If the gross weight [Gross] appears in the display, the gross weight of the object and weighing container are displayed.
5	Hold/animal weighing function active, see chap. 8.4
6	Weighing unit [kg   Ib]

## **Keyboard overview**

Button	Function
ON OFF	Turn on/off balance
HOLD	Hold/ animal weighing function
TARE →0←	Tare balance
UNITS	Switch-over weighing unit Back to weighing mode, or to menu

# **Basic Information (General)**

#### 1. Proper use

The balance you purchased is intended to determine the weighing value of material to be weighed. It is intended to be used as a "non-automatic balance", i.e. the material to be weighed is manually and carefully placed in the center of the weighing pan. As soon as a stable weighing value is reached the weighing value can be read.

## 2. Improper Use

• Do not use balance for dynamic add-on weighing procedures, if small amounts of goods to be weighed are removed or added. The "stability compensation" installed in the balance may result in displaying an incorrect measuring value! (Example: Slowly draining fluids from a container on the balance.)

- Do not leave permanent load on the weighing pan. This may damage the measuring system.
- Impacts and overloading exceeding the stated maximum load (max) of the balance, minus a possibly existing tare load, must be strictly avoided. Balance may be damaged by this.
- Never operate balance in explosive environment. The serial version is not explosion-protected.
- The structure of the balance may not be modified. This may lead to incorrect weighing results, safetyrelated faults, and destruction of the balance.
- The balance may only be used according to the described conditions. Other areas of use must be released by KERN in writing.

### 3. Warranty

Warranty claims shall be voided in case

- · Our conditions in the operation manual are ignored
- · The appliance is used outside the described uses
- · The appliance is modified or opened
- Mechanical damage or damage by media, liquids, natural wear and tear
- The appliance is improperly set up or incorrectly electrically connected
- · The measuring system is overloaded

#### 4. Monitoring of Test Resources

In the framework of quality assurance the measuring-related properties of the balance and, if applicable, the testing weight, must be checked regularly. The responsible user must define a suitable interval as well as type and scope of this test. Information is available on KERN's home page (<a href="www.kern-sohn.com">www.kern-sohn.com</a>) with regard to the monitoring of balance test substances and the test weights required for this. In KERN's accredited DKD calibration laboratory test weights and balances may be calibrated (return to the national standard) quickly and at a moderate cost.

#### **Basic Safety Precautions**

#### 1. Pay attention to the instructions in the Operation Manual

Carefully read this operation manual before setup and commissioning, even if you are already familiar with KERN balances.

#### 2. Personnel training

The appliance may only be operated and maintained by trained personnel.

#### Transport and storage

#### 1. Testing upon acceptance

When receiving the appliance, please check packaging immediately, and the appliance itself when unpacking for possible visible damage.

#### 2. Packaging/return transport

- Keep all parts of the original packaging for a possibly required return.
- · Only use original packaging for returning.
- Prior to dispatch disconnect all cables and remove loose/mobile parts.
- Reattach possibly supplied transport securing devices.
- Secure all parts such as the glass wind screen, the weighing pan, the power unit etc. against shifting and damage.

## **Unpacking, Setup and Commissioning**

#### Installation Site, Location of Use

The balances are designed in a way that reliable weighing results are achieved in common conditions of use. You will work accurately and fast, if you select the right location for your balance.

#### Therefore, observe the following for the installation site:

- Place the balance on a firm, level surface;
- Avoid extreme heat as well as temperature fluctuation caused by installing next to a radiator or in the direct sunlight;
- Protect the balance against direct draughts due to open windows and doors;
- · Avoid jarring during weighing;
- · Protect the balance against high humidity, vapours and dust;
- Do not expose the device to extreme dampness for longer periods of time. Non-permitted condensation (condensation of air humidity on the appliance) may occur if a cold appliance is taken to a considerably warmer environment. In this case, acclimatize the disconnected appliance for ca. 2 hours at room temperature.
- Avoid static charge of goods to be weighed or weighing container.

If electro-magnetic fields or static charge occur, or if the power supply is unstable major deviations on the display (incorrect weighing results) are possible. In that case, the location must be changed.

#### Unpacking and placing

- Open package, take out the appliance and accessories. Verify that there has been no damage and that all packing items are present.
- The balance must be installed in a way that the weighing pan is exactly in horizontal position.
- Mount the display unit in a way that facilitates operation and where it is easy to see.

## Scope of delivery / serial accessories

- Platform and display unit, see chap. 2
- · Mains adapter
- 4 x adjustable feet
- Wall fixture (with fixing screws)
- · Operating manual

#### Mains connection

- Select a country-specific power plug and insert it in the power unit.
- Check, whether the voltage acceptance on the scales is set correctly. Do not connect the scales to the power grid unless the information on the scales (sticker) matches the local mains voltage.
- Only use KERN original mains adapter. Using other makes requires consent by KERN.

#### Important:

- Before starting your weighing balance, check the mains cable for damage.
- Ensure that the power unit does not come into contact with liquids.
- Ensure access to power plug at all times.

#### **Battery operation**


- On the rear side of the display unit remove the battery cover and connect 4 x 1.5V mignon cells. Reinsert the battery cover.
- In order to save the battery, the balance switches automatically off after 3 minutes without weighing. Additional switch-off times can be set in the menu (function "A.OFF").
- If the batteries are depleted, the battery symbol is displayed. Switch off balance and replace batteries at once.
- If the balance is not used for a longer time, take out the batteries and store them separately. Leaking battery liquid could damage the balance.

#### **Initial Commissioning**

- In order to obtain exact results with the electronic balances, your balance must have reached the operating temperature (see warming up time chap. During this warming-up time the balance must be connected to the power supply (mains, accumulator or battery).
- The accuracy of the balance depends on the local acceleration of gravity.
- Strictly observe hints in chapter Adjustment.

## **Adjustment**

As the acceleration value due to gravity is not the same at every location on earth, each balance must be coordinated – in compliance with the underlying physical weighing principle – to the existing acceleration due to gravity at its place of location (only if the balance has not already been adjusted to the location in the factory). This adjustment process must be carried out for the first commissioning, after each change of location as well as in case of fluctuating environment temperature. To receive accurate measuring values it is also recommended to adjust the balance periodically in weighing operation. Observe stable environmental conditions. A warming up time (see chapter 1) is required for stabilization.



An error message will be displayed in the event of an adjustment error or incorrect adjustment weight. Remove the adjustment weight and repeat the adjustment process.


Keep the adjustment weight close to the balance. Daily control of the weighing exactness is recommended for quality-relevant applications.

# Operation

Start-up

Start balance by pressing

The balance will carry out a self-test As soon as the weight display appears, the balance is ready for weighing.




Should the balance not display exactly zero despite empty weighing pan, press the will be set to zero after a short standby time.



button. The balance

## **Switching Off**




## **Taring**

Place an empty weighing container, the weight of the weighing container will be displayed.	0.500
Press, the zero display appears. The indicator [NET] is displayed. The tare weight is saved until it is deleted.	0.000
Weigh the material, the net weight will be indicated.  The taring process can be repeated any number of times, e.g. when adding several components for a mixture (adding). The limit is reached when the whole weighing range is exhausted.  After removing the weighing container, the weight of the weighing container appears as negative display.	7.000
The tare weight is saved until it is deleted.	
Unload the balance and press TARE TARE, zero display will appear.	0.000

## Hold function (animal weighing function)

The balance has an integrated animal weighing function (mean value calculation). Using this function it is possible to weigh domestic or small animals exactly (min. load 1% of the max. one), although they do not stand quiet on the weighing pan.



There is no average value calculation in the event of too much movement (heavy display oscillation).

### Determination of the number of pieces


Before it is possible to determine the number of pieces by means of the scales, it is necessary to specify the average piece weight (unit weight), the so-called reference value. In order to do it, one shall place the specific

number of pieces being counted up. By means of the scales, the total mass shall be determined which then will be divided by the number of pieces (the so-called reference pieces). Afterwards, based on the calculated average piece weight, counting up shall be carried out.

The greater the number of reference pieces, the higher the accuracy of counting up.

In the weighing module, by means of button, set "Pcs" unit. The scales is now in the module allowing to determine the number of pieces.	Pcs
Keep pushing button until the display shows "C00000". The value after the comma blinks.  The number of reference pieces may be entered in the way described below:  • HOLD : Increasing the numerical value  • Moving on to the next value after comma  • Confirmation of the entered number of reference pieces	C0000
Enter the number of reference pieces in the way described above. Here, for example 100 pieces. Digit "1" blinks.	(example)
Place the pieces to be counted up on the scales and confirm by means of pushing button. The number of pieces shall be displayed.	20°Pcs

### Menu







to exit the menu. The balance returns automatically into weighing mode.

# Menu overview

UF - I	- 1630 (example)	Internal value not documented	
UF-2	Roff IO .	Auto-Off Automatic shutdown fur Can be set between 1-9	
UF - 3		Display background il Adjustable:	lumination
	Lib on	Background lighting on	
	Lib off	Background lighting off	
	Lie A *	Backlight automatically	off
UF-4		Hold function (animal weighing function) Adjustable:	
	H9 509	Average value is calcul weighing conditions fro	
	H4 54	Average value is calculated for unstable weighing conditions from approx. 5 d	
	H4 10d*	Average value is calculated for unstable weighing conditions from approx. 10 d	
UF-5	2P 0	Auto Zero Adjustable:	
	2P 5	ZP 0 *	Auto Zero: Off
	2P 5	ZP 1	• 0.5 d/s
		ZP 2	• 1 d/s
		ZP 3	• 2 d/s
		ZP 4	• 3 d/s
		ZP 5	• 5 d/s
UF-6	9.79450 *	G-value (value of the acceleration) Adjustable	local gravitational

Factory settings are marked by \*.

## Servicing, maintenance, disposal

#### Cleaning

- Before cleaning, disconnect the appliance from the operating voltage.
- Please do not use aggressive cleaning agents (solvents or similar agents), but a cloth dampened with mild soap suds. Take care that the device is not penetrated by fluids and polish it with a dry soft cloth.
- Loose residue sample/powder can be removed carefully with a brush or manual vacuum cleaner.
- Spilled weighing goods must be removed immediately.

## · Servicing, maintenance

- The appliance may only be opened by trained service technicians who are authorized by KERN.
- Before opening, disconnect from power supply.

## Disposal

Disposal of packaging and appliance must be carried out by operator according to valid national or regional law of the location where the appliance is used.

# Error messages, troubleshooting guide

Error message	Function
hhhhhh	Overload
LLLLLL	Minimum weight under min. value

In case of an error in the program process, briefly turn off the balance and disconnect from power supply. The weighing process must then be restarted from the beginning.

#### Help:

Fault	Possible cause
The displayed weight does not glow.	· The balance is not switched on.
	The mains supply connection has been interrupted ( mains cable not plugged in/faulty).
	· Power supply interrupted.
The displayed weight is permanently changing	· Draught/air movement
	· Table/floor vibrations
	The weighing pan is in contact with foreign matter.
	Electromagnetic fields / static charging (choose differ ent location/switch off interfering device if possible)
	The display of the balance is not at zero
The weighing value is obviously wrong	· Adjustment is no longer correct.
	The balance is on an uneven surface.
	Great fluctuations in temperature.
	Electromagnetic fields / static charging (choose a diff erent location/switch off
	the interfering device if possible)

Should other error messages occur, switch balance off and then on again. If the error message remains inform the manufacturer

## **Declaration of conformity**

The current EC/EU Conformity declaration can be found online in: www.kern-sohn.com/ce

## Ziegelei 1 D-72336 Balingen

• E-Mail: info@kern-sohn.com

• **Phone**: +49-[0]7433- 9933-0

Fax: +49-[0]7433-9933-149Internet: www.kern-sohn.com

FAQ

# Q: How do I change the weighing units on the scale?

A: To change the weighing units, press the designated button on the display unit. Refer to the user manual for specific instructions based on your model.

## Q: What should I do if the scale is not stabilizing correctly?

A: Ensure that the scale is placed on a stable surface and that there are no external factors affecting its accuracy. Recalibrate if needed following the instructions provided.

## **Documents / Resources**



<u>KERN EOB Platform Floor Scales</u> [pdf] Instruction Manual EOB\_B, EOE\_B, EOS\_B, EOB Platform Floor Scales, EOB, Platform Floor Scales, Floor Scales, Scales

## References

- O Your Name as Your Email | Hover Realnames
- User Manual

Manuals+, Privacy Policy

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.