

# INFORMATION NOTE



**N° 10204AERRA**

**Dear Customer,**

With this INFINEON Technologies Information Note we would like to inform you about the following

**MC-ISAR\_AS422 Release Notes Addendum V4.0 affecting products TC3xx**

Infineon Technologies AG  
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0  
Chairman of the Supervisory Board: Dr. Wolfgang Eder  
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider  
Registered Office: Neubiberg  
Commercial Register: München HRB 126492

# INFORMATION NOTE



N° 10204AERRA

## MC-ISAR\_AS422 Release Notes Addendum V4.0 affecting products TC3xx

### ► Products affected:

Please refer to attached affected product list 1\_cip10204.

### ► Detailed Change Information:

**Subject:** MC-ISAR\_AS422 Release Notes Addendum V4.0 affecting products TC3xx.

**Reason:** Update of the Release Note Addendum due to new known issues.

**Description:**

**Old**

- Release Notes Addendum  
**Version 3.0**

**New**

- Release Notes Addendum  
**Version 4.0**  
(for details please refer to  
4\_cip10204 attached).

### ► Product Identification:

Not applicable (no change of product)

### ► Impact of Change:

Assessment in Application required !

### ► Attachments:

|                                    |            |
|------------------------------------|------------|
| Affected product list              | 1_cip10204 |
| Release Notes Addendum Version 4.0 | 4_cip10204 |

### ► Intended start of delivery:

Not applicable

If you have any questions, please do not hesitate to contact your local Sales office.

# MC-ISAR\_AS422\_TC3xx

## Release Notes Addendum

Version: v4.0 Released

Date: 2020-08-06

## About this document

### Scope and purpose

This release notes addendum (RNA) document lists all the issues identified in productive releases of the MC-ISAR\_AS422\_TC3xx product. Issues reported on or before 2020-07-16 are considered in this version, including safety topics / anomalies.

*Note: Issues and safety anomalies known at the time of release are documented in release notes and safety case. Integrators are required to take them into consideration in addition to the issues listed in this document.*

**Table 1 Production Releases (PR) covered**

| HW Devices  | SW Package names   | Release Date | Release quality | Release number |
|---|--|--------------|-----------------|----------------|
| TC39xB<br>TC38x   | MC-ISAR_AS42x_AURIX2G_TC38xA_TC39xB_BASIC_1.10.0.zip<br>MC-ISAR_AS42x_AURIX2G_TC38xA_TC39xB_CD_1.10.0.zip<br>MC-ISAR_AS42x_AURIX2G_TC38xA_TC39xB_COM-E_1.10.0.zip<br>MC-ISAR_AS42x_AURIX2G_TC38xA_TC39xB_DEMO_1.10.0.zip | 2019-03-27   | PR              | 1.10.0         |
| TC39xB<br>TC38x<br>TC37xEXT<br>TC37xPD<br>TC35x                                     | MC-ISAR_AS42x_TC3xx_BASIC_1.30.0.zip<br>MC-ISAR_AS42x_TC3xx_CD_1.30.0.zip<br>MC-ISAR_AS42x_TC3xx_COM-E_1.30.0.zip<br>MC-ISAR_AS42x_TC3xx_DEMO_1.30.0.zip   | 2019-10-24   | PR              | 1.30.0         |
| TC39x<br>TC38x<br>TC37x<br>TC37xEXT<br>TC35x<br>TC36x<br>TC33xEXT<br>TC33x<br>TC32x | MC-ISAR_AS42x_TC3xx_BASIC_1.40.0.zip<br>MC-ISAR_AS42x_TC3xx_CD_1.40.0.zip<br>MC-ISAR_AS42x_TC3xx_COM-E_1.40.0.zip<br>MC-ISAR_AS42x_TC3xx_DEMO_1.40.0.zip   | 2020-05-29   | PR              | 1.40.0         |

**Intended audience**

**Intended audience**

This document is intended for anyone using the MC-ISAR\_AS422\_TC3xx, also referred as MCAL SW.

## Table of contents

|                                   |           |
|-----------------------------------|-----------|
| <b>About this document.....</b>   | <b>1</b>  |
| <b>Table of contents.....</b>     | <b>3</b>  |
| <b>1 Known issues v4.0.....</b>   | <b>5</b>  |
| 1.1 Can_17_McmCan.....            | 5         |
| 1.2 CanTrcv_17_V9251.....         | 5         |
| 1.3 Crc.....                      | 6         |
| 1.4 Dma.....                      | 6         |
| 1.5 Eth_17_GEthMac.....           | 6         |
| 1.6 Fee.....                      | 7         |
| 1.7 Fls_17_Dmu.....               | 7         |
| 1.8 General.....                  | 9         |
| 1.9 Icu_17_Timerlp.....           | 10        |
| 1.10 Mcu.....                     | 11        |
| 1.11 Sent.....                    | 12        |
| 1.12 Smu.....                     | 12        |
| 1.13 Spi.....                     | 13        |
| 1.14 Uart.....                    | 14        |
| 1.15 Wdg_17_Scu.....              | 14        |
| <b>2 Safety topics v4.0 .....</b> | <b>15</b> |
| <b>3 Known issues v3.0.....</b>   | <b>17</b> |
| 3.1 ADC.....                      | 17        |
| 3.2 CAN.....                      | 17        |
| 3.3 CanTrcv_17_V9251.....         | 18        |
| 3.4 CanTrcv_17_W9255.....         | 18        |
| 3.5 DIO.....                      | 19        |
| 3.6 DMA.....                      | 19        |
| 3.7 DSADC.....                    | 20        |
| 3.8 FEE.....                      | 21        |
| 3.9 Flexray.....                  | 23        |
| 3.10 FLS.....                     | 24        |
| 3.11 FLSLoader.....               | 25        |
| 3.12 General.....                 | 25        |
| 3.13 HSSL.....                    | 26        |
| 3.14 I2C.....                     | 27        |
| 3.15 ICU.....                     | 27        |
| 3.16 LIN.....                     | 27        |
| 3.17 MCALLIB.....                 | 28        |
| 3.18 MCU.....                     | 29        |
| 3.19 OCU.....                     | 30        |
| 3.20 PORT.....                    | 31        |
| 3.21 PWM.....                     | 32        |
| 3.22 SENT.....                    | 33        |
| 3.23 SMU.....                     | 33        |
| 3.24 SPI.....                     | 33        |
| 3.25 UART.....                    | 38        |
| 3.26 WDG.....                     | 39        |
| <b>4 Safety topics v3.0 .....</b> | <b>40</b> |
| 4.1 HW safety manual.....         | 40        |

## Table of contents

|           |   |           |
|-----------|---|-----------|
| <b>5</b>  | <b>Known issues v2.0.....</b>                               | <b>41</b> |
| 5.1       | ADC.....  | 41        |
| 5.2       | All Modules .....   | 41        |
| 5.3       | CAN.....  | 42        |
| 5.4       | DIO .....   | 44        |
| 5.5       | Ethernet.....   | 44        |
| 5.6       | FLS.....  | 45        |
| 5.7       | FLS loader.....   | 46        |
| 5.8       | Flexray.....  | 46        |
| 5.9       | General.....  | 47        |
| 5.10      | HSSL.....   | 49        |
| 5.11      | I2C .....   | 49        |
| 5.12      | ICU.....  | 50        |
| 5.13      | MCALLIB.....  | 51        |
| 5.14      | MCU.....  | 51        |
| 5.15      | OCU .....   | 53        |
| 5.16      | PORT .....  | 56        |
| 5.17      | PWM .....   | 56        |
| 5.18      | SMU .....   | 57        |
| 5.19      | SPI .....   | 58        |
| 5.20      | WDG.....  | 59        |
| <b>6</b>  | <b>Safety topics v2.0 .....</b>                             | <b>61</b> |
| 6.1       | HW safety manual.....                                       | 61        |
| <b>7</b>  | <b>Known issues v1.0.....</b>                               | <b>62</b> |
| 7.1       | ADC.....  | 62        |
| 7.2       | CAN.....  | 62        |
| 7.3       | DIO .....   | 62        |
| 7.4       | FLS.....  | 63        |
| 7.5       | General.....  | 64        |
| 7.6       | Ethernet.....   | 64        |
| 7.7       | ICU.....  | 65        |
| 7.8       | LIN .....   | 65        |
| 7.9       | MCALLIB.....  | 65        |
| 7.10      | MCU.....  | 66        |
| 7.11      | PORT .....  | 67        |
| 7.12      | PWM .....   | 67        |
| 7.13      | SPI .....   | 67        |
| 7.14      | UART .....  | 68        |
| 7.15      | WDG.....  | 68        |
| <b>8</b>  | <b>Safety topics v1.0 .....</b>                             | <b>69</b> |
| 8.1       | Safety case.....  | 69        |
| 8.2       | ISO 26262 Argumentation Sheet.....                          | 69        |
| <b>9</b>  | <b>HW Derivative specification .....</b>                    | <b>70</b> |
| 9.1       | Device support details:.....                                | 70        |
| <b>10</b> | <b>Acronyms, abbreviations and integration support.....</b> | <b>72</b> |
|           | <b>Revision History .....</b>                               | <b>73</b> |

## Known issues v4.0

**1 Known issues v4.0****1.1 Can\_17\_McmCan****1.1.1 0000053912-11728**

**Issue description:** Each CAN kernel has a dedicated message RAM shared between the controllers associated with the kernel. The message RAM associated with each kernel has a start and end boundary. The RX and TX hardware object configuration associated with the hardware objects should take care that this message RAM boundary is not exceeded. However in case the message RAM end address of one kernel overlaps with that of another, there is no error message flagged during generation of code. Hence the configuration errors result in an overlap of message RAM boundaries leading to mismatched hardware object configuration.

**Impact:** The user shall not know that an incorrect configuration has been made and the message RAM boundaries have overlapped.

**Work around:** The user shall ensure by checking the generated files the start and end addresses of the message RAM for each kernel.

**Impacted Release(s):** 1.30.0

**1.1.2 0000053912-10616**

**Issue description:** In CAN driver uses references of MCU parameters. The DESTINATION-REF path has an incorrect reference of AUTOSAR for IFX specific parameters. This reference should be AURIX2G.

**Impact:** Incorrect BMD reference path leading to schema violations.

**Work around:** No workaround.

**Impacted Release(s):** 1.30.0

**1.2 CanTrcv\_17\_V9251****1.2.1 0000053912-12336**

**Issue description:** In tresos, option to add new element is not available in CanTrcvWaitTime and CanTrcvTimerType containers.

**Impact:** User is not able to add the elements in CanTrcvWaitTime and CanTrcvTimerType containers.

**Work around:**

While creating tresos project, if the option "Automatically add the minimum number of child elements in lists" is enabled, issue is resolved.

**Impacted Release(s):** 1.40.0

**Known issues v4.0****1.3 Crc****1.3.1 0000053912-8823**

**Issue description:** SMC[SW]:FCE:CRC\_CFG safety measure to be handled by integrator.

**Impact:** No impact to CRC driver. User shall implement the safety measure described in SMC[SW]:FCE:CRC\_CFG.

**Work around:**

Integrator/User shall compare the expected CRC and the calculated CRC provided by CRC driver. If mismatch in CRC results, integrator/user shall take appropriate actions.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

**1.4 Dma****1.4.1 0000053912-12349**

**Issue description:** Incorrect documentation of ASIL level for Dma\_ChInterruptHandler() and Dma\_MEInterruptDispatcher().

**Impact:** No functional impact. ASIL level for Dma\_ChInterruptHandler() and Dma\_MEInterruptDispatcher() should be ASIL B, instead of QM.

**Work around:**

Customer shall treat the ASIL level of Dma\_ChInterruptHandler() and Dma\_MEInterruptDispatcher() as ASIL B.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

**1.5 Eth\_17\_GEthMac****1.5.1 0000053912-11663**

**Issue description:**

As per GETH\_TC.P001, Ethernet frequency operating range changed to 100 - 150 MHz from 150 - 200 MHz.

**Impact:** User can configure wrong operation conditions for Ethernet frequency if > 150 MHz and may impact the Ethernet IP functionality.

**Work around:**

User shall configure Ethernet Frequency only as 150MHz.

**Impacted Release(s):** 1.10.0, 1.30.0



## Known issues v4.0

**1.6 Fee****1.6.1 0000053912-12347****Issue description:**

When NVM block read request is made while QS block erase is ongoing in the hardware and if suspending the ongoing erase fails, then the NVM block read request will be rejected with E\_NOT\_OK along with DET error FEE\_E\_BUSY or Safety error FEE\_SE\_BUSY.

**Impact:** Unintended DET or safety error (FEE\_E\_BUSY\FEE\_SE\_BUSY) is reported.

**Work around:**

Do not use following combination of features together:

1. Both NVM and QS blocks are configured
2. Erase suspend feature is enabled
3. Safety errors or DETs are enabled

OR

Ignore FEE\_E\_BUSY or FEE\_SE\_BUSY in the above scenario based on E\_NOT\_OK returned by Fee\_Read() API.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

**1.7 Fls\_17\_Dmu****1.7.1 0000053912-12506**

**Issue description:** In the Example code presented in the user manual, the call to Fls\_17\_Dmu\_Write () function is incorrect. The parameter pass to this function are not in the correct order.

**Impact:**

If the customer uses the same example mentioned in the user manual, then

1. If DET/Safety is enabled, FLS\_17\_DMU\_E\_PARAM\_ADDRESS DET will be raised.
2. If DET/Safety is disabled then incorrect behavior will occur and may lead to trap.

**Work around:**

Refer to the prototype of API Fls\_17\_Dmu Write() as describe in user manual and pass the parameters in the order described.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

**1.7.2 0000053912-12152****Issue description:**

Due to improper handling of OPER error in interrupt mode , driver may get stuck in busy state.

Pre-condition: FLS is configured in Interrupt mode and DET/Safety is disabled.

**Impact:** Driver will get stuck in busy state.

**Work around:**

User can use one of the following workaround.

Workaround 1: Enable DET/Safety , this will give the timeout DET notification. When user receive timeout notification, he can use Fls\_17\_Dmu\_GetOperStatus to determine if an OPER has occurred. If OPER error has occurred, then user should initiate a system reset to clear the OPER error.

Workaround 2: User should implement a timeout mechanism. When timeout occurs, application should call Fls\_17\_Dmu\_GetOperStatus to determine if an OPER has occurred. If OPER error has occurred, then user should initiate a system reset to clear the OPER error.

**Impacted Release(s):** 1.30.0

**1.7.3 0000053912-12507**

**Issue description:** FLS\_E\_PARAM\_DATA is also reported when the SourceAddressPtr is not word aligned (4 byte aligned). This information is missing in the error handling description of Fls\_17\_Dmu\_Write API.

**Impact:** User may not be able to find out the reason why FLS\_E\_PARAM\_DATA DET is reported even when the SourceAddressPtr passed is not NULL.

**Work around:**

If FLS\_E\_PARAM\_DATA DET is reported, user has to check whether the SourceAddressPtr passed is word-aligned and not NULL.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

**1.7.4 0000053912-12365**

**Issue description:** When configuration parameter FlsIxFeeUse is not enabled and if erase operation fails due to EVER error, runtime error FLS\_17\_DMU\_E\_ERASE\_FAILED is not reported.

**Impact:** Run time error FLS\_17\_DMU\_E\_ERASE\_FAILED is not reported.

**Work around:** User should use the job error notification to mean that erase failed.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

## Known issues v4.0

**1.8 General****1.8.1 0000053912-8815**

**Issue description:** SMC[SW]:SCU:ERU\_CONFIG ESM is not supported by MCAL.

**Impact:**

SMC[SW]:SCU:ERU\_CONFIG ESM is not supported by MCAL and wrongly documented in MCAL User manual. This may cause confusion to integrator.

**Work around:**

Customer shall implement the SMC[SW]:SCU:ERU\_CONFIG ESM if required for their use case.

**Impacted Release(s):** 1.10.0, 1.30.0

**1.8.2 0000053912-12030**

**Issue description:** IRQ configuration not supported for Can\_17\_McmCan, Eth\_17\_GEthMac, I2c, Sent, Adc, Lin\_17\_AscLin and Uart modules.

**Impact:**

1) User cannot configure IRQ configurations for modules like Ethernet, CAN, VADC, I2C and ASCLIN.

Impacted devices are :

TC356\_ADAS - ETH, ASCLIN, I2C, VADC, CAN

TC357\_ADAS - ETH, ASCLIN, I2C, VADC, CAN

TC364\_LQFP - ETH, ASCLIN, I2C, VADC, CAN

TC364\_TQFP - ETH, ASCLIN, I2C, VADC, CAN

TC365 - ETH, ASCLIN, I2C, VADC, CAN

TC366 - ETH, ASCLIN, I2C, VADC, CAN

TC367 - ETH, ASCLIN, I2C, VADC, CAN

TC375 - ETH, ASCLIN, VADC, CAN

TC377 - ETH, ASCLIN, VADC, CAN

TC375\_ED - ETH, ASCLIN, VADC, CAN

TC377\_ED - ETH, ASCLIN, VADC, CAN

TC377\_ED\_EX - ETH, ASCLIN, VADC, CAN

TC387 - ETH, ASCLIN, I2C, VADC, CAN

TC389 - ETH, ASCLIN, I2C, VADC, CAN

TC397 - ETH, ASCLIN, I2C, VADC, CAN

**Known issues v4.0**

TC397\_ADAS - ETH,ASCLIN,I2C,VADC,CAN

TC399 - ETH,ASCLIN,I2C,VADC,CAN

2) For TC374\_ED, additional SENT IRQ connections provided which do not exist in the device.

3) For TC32x and TC33x devices, SENT IRQ connections increased to support 0 - 9 available SRNs.

**Work around:**

- 1) User cannot use interrupt modes for missing modules.
- 2) User shall not configure Sent interrupt connections > 9
- 3) User can only use the SRNs as provided in the configuration.

**Impacted Release(s):** 1.10.0, 1.30.0**1.9 Icu\_17\_TimerIp****1.9.1 0000053912-12024****Issue description:** Configuration missing for Tim Channels in TC375, TC375\_ED and TC374\_ED variants.**Impact:**

User cannot configure the below TIM channels :

- 1) TIM4\_CH1 and TIM4\_CH7 for TC374\_ED variant
- 2) TIM5\_CH0, TIM5\_CH1, TIM5\_CH2, TIM5\_CH3 for TC375, TC375\_ED and TC374\_ED variants.

User also cannot configure the above missing TIM channels input as previous TIM channel's input.

**Work around:**

User shall ensure to achieve ICU driver functionality with the TIM channels as provided/available in the configuration.

**Impacted Release(s):** 1.30.0

## Known issues v4.0

**1.10      Mcu****1.10.1      0000053912-12344**

**Issue description:** Incorrect Tresos description for McuClockReferencePointFrequency2

**Impact:**

No functional impact.

Tresos description for McuClockReferencePointFrequency2 (fPLL2) should be calculated as :

$f_{PLL2} = ((N+1) * f_{OSC}) / ((P+1) * (K3 + 1) * 1, 6)$  if McuPll2DivSelect= MCU\_K3\_DIV\_FACTOR\_NOT\_BYPASSED\_SELO  
OR

$f_{PLL2} = ((N+1) * f_{OSC}) / ((P+1) * (K3 + 1))$  if McuPll2DivSelect= MCU\_K3\_DIV\_FACTOR\_BYPASSED\_SEL1

**Work around:**

User shall configure the McuClockReferencePointFrequency2 as per the above equation.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

**1.10.2      0000053912-11679**

**Issue description:** Mcu plugin issue for TC375, TC375\_ED and TC374\_ED derivatives.

**Impact:**

Code generation failure occurs since error is reported for MCU plugin. This applies for TC375, TC375\_ED and TC374\_ED derivatives.

**Work around:**

Customer cannot use Mcu plugin configuration for TC375, TC375\_ED and TC374\_ED derivatives.

**Impacted Release(s):** 1.30.0

**1.10.3      0000053912-11550**

**Issue description:** DCO Input frequency range increased to 10 - 40 MHz from 16 - 40 MHz.

**Impact:**

For all A2G variants, DCO Input frequency range increased from 16 - 40 MHz to 10 - 40 MHz . But MCU code generation plugin only supports in the range of 16 - 40 MHz.

**Work around:**

User needs to configure DCO Input frequency in the provided range of 16 - 40 MHz only.

**Impacted Release(s):** 1.10.0, 1.30.0

**Known issues v4.0****1.10.4 0000053912-11663**

**Issue description:** As per GETH\_TC.P001, Ethernet frequency operating range changed to 100 - 150 MHz from 150 - 200 MHz.

**Impact:**

User can configure wrong operation conditions for Ethernet frequency if > 150 MHz and may impact the Ethernet IP functionality.

**Work around:**

User shall configure Ethernet Frequency only as 150MHz.

**Impacted Release(s):** 1.10.0, 1.30.0

**1.11 Sent****1.11.1 0000053912-12426**

**Issue description:** In TC387, 20 SENT channels are bonded out(0-14, 17/18, 20-22).However in TC387 properties file, SENT Channels 0 to 19 are considered.

Holes present in sent channels are not considered in TC387 properties file.

**Impact:**

In TC387, few SENT channels (20,21,22) are not selectable in MCAL though provided in the hardware. SENT channels (15,16,19) are listed as configurable channels which should not be selected by the user.

**Work around:**

Use only the SENT channels (0-14, 17/18).

**Impacted Release(s):** 1.40.0

**1.12 Smu****1.12.1 0000053912-12189**

**Issue description:** Smu\_SetAlarmAction() does not support disable of FSP action.

**Impact:**

User cannot disable FSP action at runtime using Smu\_SetAlarmAction() API.

**Work around:**

Users shall configure the FSP action during SMU initialization and not change the FSP action at runtime.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

## Known issues v4.0

**1.13 Spi****1.13.1 0000053912-10645**

**Issue description:** Calling Spi\_Cancel() cancels the successive job of ongoing sequence being transmitted and updates the sequence status to cancelled. However updating the QSPI HW unit status to IDLE only happens once the ongoing job transmission is completed. So calling Spi\_GetHwUnitStatus or Spi\_GetStatus immediately after Spi\_Cancel will return SPI\_BUSY due to ongoing job.

**Impact:**

Calling Spi\_GetHwUnitStatus or Spi\_GetStatus immediately after Spi\_Cancel in case of only single sequence/last sequence will return SPI\_BUSY.

**Work around:**

User must call Spi\_GetHwUnitStatus or Spi\_GetStatus and wait until the API returns SPI\_IDLE.

**Impacted Release(s):** 1.10.0,1.30.0

**1.13.2 0000053912-12064**

**Issue description:** Trap occurs in SPI when DMA error interrupts occur on multiple channels across cores.

**Impact:**

If DMA move engine error occurs simultaneously on multiple SPI channels, a trap would occur in SPI driver if DMA interrupt error is less than any of the SPI interrupts.

**Work around:**

Interrupt priority of DMA and SPI shall be of order : DmaError > QspiError > Tx > Rx > PT2.

**Impacted Release(s):** 1.10.0, 1.30.0

**1.13.3 0000053912-12218**

**Issue description:** SPI\_E\_UNINIT DET reported from Spi\_MainFunction\_Handling.

**Impact:**

DET reported when Spi\_MainFunction\_Handling is called when SPI module is not initialized.

**Work around:**

SPI\_E\_UNIT DET when reported from Spi\_MainFunction\_Handling to be ignored by the application software.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

## Known issues v4.0

**1.14 Uart****1.14.1 0000053912-12037**

**Issue description:** If CTS pin is not used for handshaking in UART, NONE option is missed in BMD files.

**Impact:**

User need to select one of the pin from the list.

**Work around:**

If UartCTSEnable option is disabled, any pin selected will not have impact on the generated code.

**Impacted Release(s):** 1.10.0,1.30.0

**1.15 Wdg\_17\_Scu****1.15.1 0000053912-12307**

**Issue description:** Incorrect information provided in WDG UM.

**Impact:**

In WDG UM, "system WDT" is mentioned in Hardware-software mapping chapter. The "system WDT" peripheral does not exist and should be renamed as "Safety WDT".

**Work around:** User shall interpret "system WDT" as "Safety WDT".

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0



## Safety topics v4.0

## 2 Safety topics v4.0

### 2.1.1 0000053912-8814

**Issue description:** ESM[SW]:DMA:ERROR\_HANDLING description insufficient.

**Impact:**

User manual information is incomplete.

**Work around:**

Customer to use the workaround as mentioned below:

About handling DMA errors when using of SPI and DMA drivers together  
(Ref:ESM[SW]:DMA:ERROR\_HANDLING):

Limitation:

The below limitation is applicable if SPI uses the DMA driver for asynchronous transmission:

Whenever the DMA channel used by SPI driver encounters an error, the DMA driver notifies the error along with the channel information to the SPI driver. However, due to the limitation in the error notification interface from SPI to the application, the SPI driver notifies the same error to the application without the DMA channel information.

Workaround:

The application shall supervise the DMA RP Error Interrupt Service Request. The application shall read the DMA move engine error registers ERRSR0 and ERRSR1 before invoking the interrupt handler provided by DMA. This is to determine the error cause and the DMA channel number which caused the RP error. The sequence is as below:

- Move engine error occurs in hardware
- RP ISR is triggered
- Application reads the error flags in ERRSRm for determining the error cause and ERRSRm.LEC for determining the DMA channel number that caused the error.
- Call Dma\_MEInterruptDispatcher
- On return from Dma\_MEInterruptDispatcher, Application shall take necessary action.

**Impacted Release(s):** 1.10.0, 1.30.0

**2.1.2      0000053912-8816**

**Issue description:** Clarity to achieve SMC[SW]:SMU:CONFIG is incomplete in SW User Manual.

**Impact:**

In SW User Manual, documentation clarity to achieve SMC[SW]:SMU:CONFIG is incomplete. AoU to be added, see AoU text in Workaround.

**Work around:**

AoU: Customer shall ensure to enable 'SmuStdbbyEnable' in SMU driver configuration to achieve SMC[SW]:SMU:CONFIG ESM.

**Impacted Release(s):** 1.10.0, 1.30.0, 1.40.0

## Known issues v3.0

### 3 Known issues v3.0

#### 3.1 ADC

##### 3.1.1 0000053912-9946

**Issue description:** HSPDM Input Trigger configuration support given for unsupported devices in ADC.

**Impact:** HSPDM module is not available in the following devices i.e. TC38x devices, TC37x devices and TC36x devices, hence trigger of HSPDM is not possible from the unsupported devices if configured.

**Work around:**

User should not configure the HSPDM as a trigger source from the following HSPDM unsupported devices. i.e. TC38x devices, TC37x devices and TC36x devices.

**Impacted Release(s):** 1.10.0, 1.30.0

#### 3.2 CAN

##### 3.2.1 0000053912-10694

**Issue description:** When Can module is initialized again from the same core, the DET CAN\_17\_MCMCAN\_E\_TRANSITION is not reported.

**Impact:** Unnecessary re-initialization sequence retriggered.

**Work around:**

The user shall ensure that Can\_17\_McmCan\_Init is called only once from the same core.

**Impacted Release(s):** 1.10.0, 1.30.0

##### 3.2.2 0000053912-10858

**Issue description:** CAN11 RX selection value is missed in AURIX2G\_TC366.properties file.

**Impact:** There is an additional option of CAN11\_RXDA which is made unavailable in the current configuration. Hence the user is able to use only CAN11\_RXDB.

**Work around:**

The user shall use the CAN11\_RXDB when using controller 1 of kernel 1.

**Impacted Release(s):** 1.30.0

##### 3.2.3 0000053912-10749

**Issue description:** Main Function Period is generated incorrectly in bswmd arxml file.

**Impact:** In case of polling function the period configured is not generated in the bswmd arxml as configured and only the default value of 5ms.

**Work around:**

In case polling is used and the user shall not be able to configure any value other than 5ms. The user shall use the default value of 5ms for polling functions.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.2.4 0000053912-9738

**Issue description:** In the Can\_17\_McmCan\_SetControllerMode API, the return value of the API is determined based on whether the transition to a requested state occurs or not. When a request is made for a state transition to CANIF\_CS\_STARTED and the transition does not take place successfully due to a timeout condition, the global state variable still gets updated to STARTED. Hence in the next call when the system tries to recover by calling the API again, it triggers a DET to indicate that the CanSM is already in STARTED state.

**Impact:** The subsequent attempts to transition to the STARTED state by calling the API returns CAN\_NOT\_OK and DET.

**Work around:**

No workaround.

Hint: Timeout event should be avoided. One possible way to achieve this is to configure a high value for the parameter CanTimeoutDuration.

**Impacted Release(s):** 1.10.0, 1.30.0

## 3.3 CanTrcv\_17\_V9251

### 3.3.1.1 0000053912-10559

**Issue description:** CanTrcv module multiplicity was 0-1. According to the AUTOSAR requirement, the module multiplicity value should be 0-.\*.

**Impact:** Multiple CanTrcv modules cannot be added in the configuration.

**Work around:** Multiple CanTrcv modules should not be in the configuration.

**Impacted Release(s):** 1.30.0

## 3.4 CanTrcv\_17\_W9255

### 3.4.1 0000053912-10560

**Issue description:** CanTrcv module multiplicity was 0-1. According to the AUTOSAR requirement, the module multiplicity value should be 0-.\*.

**Impact:** Multiple CanTrcv modules cannot be added in the configuration.

**Work around:**

**Known issues v3.0**

Multiple CanTrcv modules should not be in the configuration.

**Impacted Release(s):** 1.30.0

### 3.5 DIO

#### 3.5.1 0000053912-10461

**Issue description:** Plausibility check for input parameter "Level" is not done for Dio\_WriteChannel() API.

**Impact:** For Dio\_WriteChannel(), a wrong "Level" value will always result in setting the port pin as STD\_HIGH.

**Work around:**

For Dio\_WriteChannel(), user shall pass only as STD\_LOW or STD\_HIGH as the input parameter for "Level".

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.6 DMA

#### 3.6.1 0000053912-9369

**Issue description:** Mismatches in parameters in their names and dependencies.

**Impact:** The names and dependency mismatches can result in incorrect interpretation of parameters.

**Work around:**

The following parameter names are mentioned incorrectly in User Manual: DmaInitDeInitApiMode, DmaChDeInitApiConfiguration, DmaGetVersionInfoApiConfiguration and DmaResourcePartitionErrorNotifRoutine. They are to be read as DmaInitApiMode, DmaDeinitApiConfiguration, DmaVersionInfoApi and DmaMoveEngineErrorNotifRoutine respectively.

**Impacted Release(s):** 1.30.0

#### 3.6.2 0000053912-10804

**Issue description:** Trap will occur if DMA clock is not enabled and Dma\_MEStatusClear() is invoked before Dma\_Init().

**Impact:** Invoking Dma\_MEStatusClear() API before Dma\_Init() will result in a trap if the DMA clock is not enabled.

**Work around:**

Dma\_MEStatusClear() shall be invoked after Dma\_Init() is done for the respective cores.

**Impacted Release(s):** 1.10.0, 1.30.0

#### 3.6.3 0000053912-9819

**Issue description:** Dma\_ChInit() has a wrong error DET\_DMA\_E\_DATA\_TRANSFER\_IN\_PROGRESS indicated in UM.

**Known issues v3.0**

**Impact:** No functional impact. Customer may mistakenly consider DET DMA\_E\_DATA\_TRANSFER\_IN\_PROGRESS to be raised by Dma\_ChInit() API.

**Work around:**

The user shall ignore the error DET DMA\_E\_DATA\_TRANSFER\_IN\_PROGRESS for Dma\_ChInit() API.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.7 DSADC

#### 3.7.1 0000053912-9745

**Issue description:** Mismatch in Property file variables for the XDM and BMD.

**Impact:** When user uses the BMD for configuration and XDM for generation then Generator will raise an Error for the variable mismatch.

The following parameters cannot be configured only for non-tresos tool user:-

DsadcComModeVoltNegAEnable, DsadcComModeVoltNegBEnable, DsadcComModeVoltNegCEnable,  
DsadcComModeVoltNegDEnable,  
DsadcComModeVoltPosAEnable, DsadcComModeVoltPosBEnable, DsadcComModeVoltPosCEnable, DsadcCom  
ModeVoltPosDEnable, DsadcInputPinSelection

DsadcTriggerSelect.

**Work around:**

Limitation:

Users who do not use Tresos tool, should avoid configuring following parameters:

DsadcComModeVoltNegAEnable, DsadcComModeVoltNegBEnable, DsadcComModeVoltNegCEnable,  
DsadcComModeVoltNegDEnable,  
DsadcComModeVoltPosAEnable, DsadcComModeVoltPosBEnable, DsadcComModeVoltPosCEnable, DsadcCom  
ModeVoltPosDEnable, DsadcInputPinSelection

DsadcTriggerSelect.

**Impacted Release(s):** 1.30.0

#### 3.7.2 0000053912-10628

**Issue description:** Comparator event selection for lower and upper boundary is not working.

**Impact:** Comparator event will be generated for all the events even though user wants the events only for inside boundary or outside boundary.

**Work around:**

Based on the converted results, user has to identify whether the result is inside the boundary or outside the boundary in every comparator event.

## 3.8 FEE

### 3.8.1 0000053912-10899

**Issue description:** Un-configured blocks management while handling word-line failures during write operation may result in out of bound array access.

**Impact:** During the mentioned scenario, if out of bound array access happens to be in a reserved memory area, it results in a trap.

**Work around:**

Use same block configuration for both boot and run time application configurations. This ensures that there are no un-configured blocks.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.8.2 0000053912-10903

**Issue description:** Occurrence of Program verify error during QS hardening results in a word-line skip for the write operation of the block, which triggered GC.

**Impact:** Unintended word-line skips resulting in unusable word-lines until next GC happens.

**Work around:**

No workaround required as driver recovers during next GC cycle.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.8.3 0000053912-10284

**Issue description:** As part of FEE double sector algorithm garbage collection (GC) happens. During GC, erase operation could weaken the data in QS region because of the 'erase disturbs'. In order to secure the QS data, FEE driver performs check and hardening periodically. Due to an error in the software implementation of FEE driver, hardening check is not performed for all pages. This issue is observed only when user configures both NVM and QS data blocks.

**Impact:** This may result in not performing the hardening operation for a page where hardening is actually required and thereby leading to data loss in the QS region.

**Work around:**

Avoid using configuration where both NVM and QS data blocks are configured.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.8.4 0000053912-10964

**Issue description:** Possibilities of Data blocks corruption leading to trap under certain scenarios while handling word-line failures during write operation.

**Impact:** Data flash content may be corrupted leading to data loss of user blocks and may result in a trap.

**Work around:** None.

Customers are requested to contact Field Application Engineers for support in case this issue impacts their use case. Field application engineers can support customer to analyse and understand the impact in customer specific environment.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.8.5 0000053912-10661

**Issue description:** Due to an error in the software implementation of FEE driver, when a pending user write request is cancelled by Fee\_Cancel()/ Fee\_17\_CancelAll() API, followed by either user write request or user read request and then followed by user write request, driver may write unintended data.

API call sequences:

Fee\_Write() → Fee\_Cancel() → Fee\_Read() → Fee\_Write() or Fee\_Write() → Fee\_Cancel() → Fee\_Write()

**Impact:** In the scenario mentioned in the description, the data flash content may be corrupted leading to

- Data loss of user blocks and/or
- Trap (DAE/DSE)

Work around:

Do not use Fee\_Cancel()/ Fee\_17\_CancelAll() API for canceling pending write operation.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.8.6 0000053912-11133

**Issue description:** Multiple instances of QS cannot be erased by single call to Fee\_17\_EraseQuasiStaticData API when 256 QS instances are requested for erasure or if the QS block instances order is not maintained as specified in the user manual even after export and import of the configuration in Tresos.

**Impact:** Multiple instances of QS cannot be erased by single call to Fee\_17\_EraseQuasiStaticData API when 256 QS instances are requested for erasure or if the QS block instances order is not maintained as specified in the user manual even after export and import of the configuration in Tresos.

In the scenario mentioned above, the driver state will be stuck in 'busy' or incorrect QS block state may be reported by Fee\_17\_GetQuasiStaticBlockInfo respectively.

**Work around:**



**Known issues v3.0**

In this scenario, Fee\_17\_EraseQuasiStaticData API shall be called for each instance rather than the total number of instances.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.9 Flexray

#### 3.9.1 0000053912-9999

**Issue description:** The Fr\_17\_Eray\_ReconfigLPdu() API does not report the development error FR\_E\_INV\_CHNL\_IDX for negative values of the input parameter Fr\_ChnlIdx.

**Impact:** When negative values of Fr\_ChnlIdx parameter are passed to the Fr\_17\_Eray\_ReconfigLPdu() API, the API does not report the development error FR\_E\_INV\_CHNL\_IDX and results in incorrect configuration of the channel index value for the LPdu.

**Work around:**

The application should use the defined enum literals of type Fr\_ChannelType for the input parameter Fr\_ChnlIdx, or use positive values.

**Impacted Release(s):** 1.10.0, 1.30.0

#### 3.9.2 0000053912-9310

**Issue description:** During the execution of Fr\_17\_Eray\_SetWakeupChannel() API, if there is a hardware error detected during the change of controller's POCState to POC:ready, the API returns E\_OK (irrespective of the DEM configuration) instead of E\_NOT\_OK.

**Impact:** In case an hardware error is detected by Fr\_17\_Eray\_SetWakeupChannel() API during the change of controller's POCState to POC:ready, this error condition is not recognized by the upper layer SW by checking the return value because E\_OK is returned.

**Work around:**

The DEM event for FR controller hardware error needs to be configured and a check whether this production error is reported needs to be performed in order to examine the hardware error detected by Fr\_17\_Eray\_SetWakeupChannel() API.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.10 FLS

#### 3.10.1 0000053912-10907

**Issue description:** FSI in the NVM subsystem executes erase, program and verify operations on all flash memories. The FSI performs flash commands by the CPU (Host command sequence interpreter) and HSM (HSM command sequence interpreter- Only for DFLASH1) in time slices. Time out values in Flash drivers are calculated for the case that only one operation is executed uninterrupted by the time slicing ( Issue applicable for both FLS and FlsLoader).

**Impact:** Unintended time out DET may be raised when operations on DFLASH0 and DFLASH1 are performed in parallel.

**Work around:**

Ensure operations on DFLASH0 and DFLASH1 are not happening in parallel.

**Impacted Release(s):** 1.10.0, 1.30.0

#### 3.10.2 0000053912-7586

**Issue description:** Reporting of unintended timeouts may be observed for the lower range of supported values of FlsCallCycle parameter.

**Impact:** Reporting of unintended timeouts by the FLS driver will be observed while the actual write/erase operation is still going on in the hardware.

**Work around:**

It is to be ensured that the scheduling frequency of FLS operations using the Fls\_17\_Dmu\_MainFunction() API is done at a rate greater than or equal to 200us. This can be done by configuring the parameter 'FlsCallcycle' to a value greater than or equal to 200. Timeouts may be observed for the values less than 200, if configured for FlsCallCycle.

**Impacted Release(s):** 1.10.0, 1.30.0

#### 3.10.3 0000053912-10182

**Issue description:** Operation Error(OPER) will be notified as sequence error(SQER) for erase resume(Fls\_17\_Dmu\_ResumeErase()) and hardening(Fls\_17\_Dmu\_IsHardening()) operations.

**Impact:** 1) Hardening: There will not be any impact from the user perspective for the hardening operation(Fls\_17\_Dmu\_IsHardeningRequired()) as this API is used only by Infineon FEE, so this will be taken care by Infineon FEE.

2) Resume Erase(Fls\_17\_Dmu\_ResumeErase()): Resume erase will be impacted and an OPER(operation error) will be notified as SQER(sequence error).

**Work around:**

**Known issues v3.0**

If a user repeatedly gets a sequence error(SQER) while resuming an erase using the Fls\_17\_Dmu\_ResumeErase() API, then a system reset is recommended.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.11 FLSLoader

#### 3.11.1 0000053912-10907

**Issue description:** FSI in the NVM subsystem executes erase, program and verify operations on all flash memories. The FSI performs flash commands by the CPU (Host command sequence interpreter) and HSM (HSM command sequence interpreter- Only for DFLASH1) in time slices. Time out values in Flash drivers are calculated for the case that only one operation is executed uninterrupted by the time slicing ( Issue applicable for both FLS and FlsLoader).

**Impact:** Unintended time out DET may be raised when operations on DFLASH0 and DFLASH1 are performed in parallel.

**Work around:**

Ensure operations on DFLASH0 and DFLASH1 are not happening in parallel.

**Impacted Release(s):** 1.10.0, 1.30.0

#### 3.11.2 0000053912-10733

**Issue description:** If there are interrupts during PFLASH write operation or if the Safety watchdog counter frequency divider is not set to 16384, then the Safety watchdog timeout may happen.

**Impact:** Safety alarms may be triggered during PFLASH write operation if the Safety ENDINIT is disabled more than the Safety watchdog timeout period. This may happen if there are interrupts during PFLASH write operation or if the Safety watchdog counter frequency divider is not set to 16384.

**Work around:**

Application shall ensure PFLASH write operation is not interrupted and the Safety watchdog counter frequency divider is set to 16384.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.12 General

#### 3.12.1 0000053912-10718

**Issue description:** OS wrapper calls made for register writes in CAT1 interrupt context.

**Impact:** In CAT1 interrupt context, call to OS wrapper for register writes are made (e.g: ADC, SPI). It is inconsistent across MCAL modules.

**Known issues v3.0****Work around:**

At integration level, user shall take care of handling OS wrappers being called in CAT1 interrupt context.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.12.2 0000053912-9253

**Issue description:** Impact on MCAL for Errata CPU\_TC.H019.

**Impact:** If the lock (like Semaphore or Spinlock) and resource being protected are placed in different memory modules (e.g: DSPR, PSPR, LMU), correct sequence of execution (read and write instruction sequence) to the lock and resource is not ensured and leads to inconsistent data. being read/written to the lock and resource.

**Work around:**

User shall ensure that:

- The lock (address of which is passed to the Mcal\_GetSpinlock() API) and the resource to be protected shall be placed in the same memory module.
- The lock used shall be placed in the non-cached memory section.

**Impacted Release(s):** 1.10.0, 1.30.0

## 3.13 HSSL

### 3.13.1 0000053912-10086

**Issue description:** Structures/Unions are not recommended to be passed directly as function arguments. This will occupy lot of space on stack and inefficient. This is a violation of ECR\_206.

**Impact:** Windriver compiler bug TCDIAB-14541 (structure members are incorrectly accessed) has an impact.

**Work around:**

HSSL is a demo module. If customer see an impact due to this, then required code changes can be made to fix the issue.

**Impacted Release(s):** 1.30.0

### 3.13.2 0000053912-10882

**Issue description:** Running HSSL module in user mode results in trap as registers with SV-write are written directly.

**Impact:** HSSL module cannot be run in user mode.

**Work around:**

As HSSL is demo code, customer can update the code to support user mode.

**Impacted Release(s):** 1.30.0

## Known issues v3.0

**3.14 I2C****3.14.1 0000053912-10934**

**Issue description:** Running I2C module in user mode results in trap as GPCTL(Write-SV mode) register is written directly.

**Impact:** I2C module cannot be run in user mode.

**Work around:**

As I2C is demo code, customer can update the code to support user mode.

**Impacted Release(s):** 1.30.0

**3.15 ICU****3.15.1 0000053912-10719**

**Issue description:** Unavailable port pin PORT23\_PIN0 in TC377\_ED\_EX used for TIM channel configuration.

**Impact:** Customer may select PORT23\_PIN0 for TIM channel configuration which does not exist and ICU functionality will not work for that pin.

**Work around:**

Customer shall not select PORT23\_PIN0 TIM channel in ICU configuration.

**Impacted Release(s):** 1.30.0

**3.16 LIN****3.16.1 0000053912-10001**

**Issue description:** Wakeup related call back LinIf\_WakeupConfirmation to be guarded with Wakeup Enable is ON else implicit declaration of call back function warning is reported.

**Impact:** Compiler warning is reported.

**Work around:**

A dummy declaration of LinIf\_WakeupConfirmation must be defined in LinIf when LIN\_GLOBAL\_CHANNEL\_WAKEUP\_SUPPORT is STD\_OFF.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.16.2 0000053912-10316**

**Issue description:** When DET is OFF and channel state is not in LIN\_CH\_SLEEP, if Lin\_17\_AscLin\_Wakeup and Lin\_17\_AscLin\_WakeupInternal APIs are called the return value will be E\_OK indicating the wakeup has occurred.

**Impact:** Upper layer assumes that the wakeup has occurred successfully and may process channel accordingly though actual wakeup has not occurred on the bus.

**Known issues v3.0****Work around:**

All sequences should be tested with DET ON.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.16.3 0000053912-10315

**Issue description:** When LIN\_17\_ASCLIN\_GLOBAL\_CHANNEL\_WAKEUP\_SUPPORT is ON and channel wakeup is enabled or disabled, EcuM\_CheckWakeup is been called in both cases. EcuM\_CheckWakeup should not be called when channel wakeup is disabled.

**Impact:** If false or unintended wakeup is detected for a LIN channel for which wakeup is disable during configuration, the LIN driver will not validate this scenario and the LIN driver will invoke EcuM\_CheckWakeup().

Note: if this error scenario happens, application will get a wrong information from driver instead of error notification.

**Work around:** No workaround for the issue. Users to ensure that the false wakeup or unintended wakeup is not happening in the system.

**Impacted Release(s):** 1.10.0, 1.30.0

## 3.17 MCALLIB

### 3.17.1 0000053912-10568

**Issue description:** Wrong STM tick used for delay operations if SYSCLK is selected as the clock source.

**Impact:** Mcal\_DelayTickResolution() API will provide a higher STM tick resolution, and result in slower timeout than desired. Below are the impacted MCAL drivers using Mcal\_DelayTickResolution() API:

- CanTrcv\_17\_V9251
- CanTrcv\_17\_W9255
- Can\_17\_McmCan
- Eth\_17\_GEthMac
- FlsLoader
- Fls\_17\_Dmu
- Fr\_17\_Eray
- Lin\_17\_AscLin
- McalLib
- Mcu
- Uart
- Wdg\_17\_Scu

**Work around:**

User shall not use SYSCLK as the input clock source. They shall use the back-up clock or oscillator as the clock sources.

## 3.18 MCU

### 3.18.1 0000053912-9801

**Issue description:** Mcu code generation fails when default Tresos naming convention is not followed for configuration containers and parameters.

**Impact:** If the name of configuration containers and parameters listed below are changed from default Tresos names, Mcu code generation will fail.

McuEruAllocationConf

McuGtmAllocationConf

McuCcu6ModuleAllocationConf

McuGpt12ModuleAllocationConf

GtmTomGlobalConf

GtmTomChannelConf

GtmAtomGlobalConf

GtmAtomChannelConf

**Work around:**

The short name for following containers and their respective sub-containers shall follow the syntax <Container\_Name>\_<i> where <i> is an integer:

McuEruAllocationConf

McuGtmAllocationConf

McuCcu6ModuleAllocationConf

McuGpt12ModuleAllocationConf

GtmTomGlobalConf

GtmTomChannelConf

GtmAtomGlobalConf

GtmAtomChannelConf

Note: The above naming convention is by default followed in Tresos, when new containers are added or when project is created.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.18.2 0000053912-10172

**Issue description:** RAM redundancy handling may result in trap during standby entry of Mcu\_SetMode() API.

**Impact:** If Standby mode is used and customer has application data in the first 64 bytes of configured Standby RAM, a trap may occur. The driver assumes valid RAM addresses are present in the first 64 bytes and tries to de-reference these addresses.

**Known issues v3.0****Work around:**

If Standby mode shall be used, customer shall reserve the first 64 bytes of the configured Standby RAM and not use it.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.18.3 0000053912-9132**

**Issue description:** Mcu\_SetMode() activates the Standby mode even when a write to PMSWCR3 register fails (DEM failure reported).

**Impact:** If wake-up timer is used as a wake-up source and during execution of Mcu\_SetMode() to Standby mode, if PMSWCR3 write fails because of a hardware failure, the system may not wake-up from Standby at all even when wake-up timer has triggered the system for wake-up.

**Work around:**

The user shall not use wake-up timer as the only wake-up source.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.18.4 0000053912-9412**

**Issue description:** A compilation error is reported when McuInitClockApi configuration parameter is set FALSE.

**Impact:** A compilation error will be reported when the configuration parameter McuInitClockApi is switched OFF.

**Work around:**

The user shall not set the McuInitClockApi configuration parameter to False.

**Impacted Release(s):** 1.30.0

**3.19 OCU****3.19.1 0000053912-6153**

**Issue description:** Data Inconsistency when Ocu\_Init is called by multiple cores with different configuration pointer.

**Impact:** The operation of the Ocu driver cannot be guaranteed, if Ocu\_Init is invoked concurrently from multiple cores with different configuration pointer, it leads to data inconsistency.

**Work around:**

User shall ensure the configuration pointer passed for Ocu initialization(Ocu\_Init() API) should be the same across all the configured cores.

**Impacted Release(s):** 1.30.0



## Known issues v3.0

**3.20 PORT****3.20.1 0000053912-9809**

**Issue description:** Variation point for certain Autosar and IFX parameters not configurable.

**Impact:** The following parameters can not be configured:

PortPinDirectionChangeable

PortPinInputPullResistor

PortPinOutputPadDriveStrength

PortPinOutputPinDriveMode

PortPinInputPadLevel

PortPinEnableAnalogInputOnly

PortPinEmergencyStop

PortPinControllerSelect

PortLVDSRxEnController

PortLVDSRxPathEnable

PortLVDSRxTerminationMode

PortLVDSMode

PortLVDSPadSupply

PortLV DSTxEnController

PortLV DSTxPathEnable

**Known issues v3.0**

PortLVDSTxPowerDownPullDown.

**Work around:**

Customer should not configure certain parameters for variation point support.

**Impacted Release(s):** 1.10.0

### 3.21 PWM

#### 3.21.1 0000053912-10918

**Issue description:** GHS Compiler warning in PWM for following configurations:

PWM\_17\_GTMCCU6\_DE\_INIT\_API = STD\_ON, PWM\_17\_GTMCCU6\_SET\_OUTPUT\_TO\_IDLE\_API = STD\_OFF and PWM\_17\_GTMCCU6\_DUTY\_SHIFT\_IN\_TICKS = STD\_OFF.

**Impact:** Compiler warning in GHS will occur when PWM\_17\_GTMCCU6\_DE\_INIT\_API = STD\_ON, PWM\_17\_GTMCCU6\_SET\_OUTPUT\_TO\_IDLE\_API = STD\_OFF and PWM\_17\_GTMCCU6\_DUTY\_SHIFT\_IN\_TICKS = STD\_OFF.

**Work around:**

To avoid the compiler warning, customer can use any one of the below workarounds:

1) Enable PWM\_17\_GTMCCU6\_SET\_OUTPUT\_TO\_IDLE\_API = STD\_ON and PWM\_17\_GTMCCU6\_DUTY\_SHIFT\_IN\_TICKS = STD\_ON

2) Customer shall configure at-least 1 CCU6 channel if PWM\_17\_GTMCCU6\_DE\_INIT\_API = STD\_ON, PWM\_17\_GTMCCU6\_SET\_OUTPUT\_TO\_IDLE\_API = STD\_OFF and PWM\_17\_GTMCCU6\_DUTY\_SHIFT\_IN\_TICKS = STD\_OFF.

**Impacted Release(s):** 1.30.0

#### 3.21.2 0000053912-11145

**Issue description:** For PWM shifted channels when PwmHandleShiftByOffset is TRUE, the configuration error check unnecessarily restricts the user to configure the channels in the order and also the channels to be configured in the same module(TGC/AGC) eventhough check is not required.

**Impact:** User is unnecessarily forced to order the PWM TOM/ATOM channels only within a TOM/ATOM module when PwmHandleShiftByOffset=TRUE.

**Work around:**

User shall ensure PWM TOM/ATOM channels are ordered in the same respective TOM/ATOM module when PwmHandleShiftByOffset=TRUE.

**Impacted Release(s):** 1.30.0

## Known issues v3.0

**3.22 SENT****3.22.1 0000053912-10695**

**Issue description:** Deinit API throws compilation error when SentDevErrorDetect is off and SentMulticoreErrorDetect is ON.

**Impact:** DET off configuration gives compilation error.

**Work around:**

SentDevErrorDetect and SentMultiCoreErrorDetect should be ON.

**Impacted Release(s):** 1.30.0

**3.23 SMU****3.23.1 0000053912-8818**

**Issue description:** 'A2GT-REQ\_AoU\_SW-15' in MCAL user manual is not inline with 'ESM[SW]:SMU:ALIVE\_ALARM\_TEST' AoU in safety manual.

**Impact:** Information related to frequency of the "SMU Alive Test" execution is not mentioned. This may lead to incorrect deployment of the safety measure.

**Work around:**

A2GT-REQ\_AoU\_SW-15 to be read as "The integrated system shall execute the "SMU Alive Test" provided in MCAL software at least once per driving cycle and take the appropriate actions depending on the result."

**Impacted Release(s):** 1.10.0, 1.30.0

**3.23.2 0000053912-10578**

**Issue description:** The Smu\_LockConfigRegs() API is non-reentrant and can be invoked from only one core at a time but it is incorrectly documented to be Re-entrant in both SAS and User Manual.

**Impact:** The Smu\_LockConfigRegs() API does not support reentrancy. Treating the API as reentrant or calling it simultaneously from multiple cores can lead to inconsistent results. In some cases, second invocation may return E\_OK but in others, it may return with E\_NOT\_OK and DET or Safety error, if enabled.

**Work around:**

User shall treat the Smu\_LockConfigRegs() API in a non-reentrant manner.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24 SPI****3.24.1 0000053912-9099**

**Issue description:** Spi\_Deinit not resetting all the registers which are initialized as part of Spi\_Init.

**Known issues v3.0**

**Impact:** Impact analysis done and no functional impact.

**Work around:** No work around required as there is no functional impact.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.2 0000053912-8936**

**Issue description:** In Multicore scenario, few SPI hardware channels mapped to Core 0 which are using only synchronous and few other hardware channels mapped to Core 1 which are always asynchronous. Calling any runtime API results in FALSE UNINIT DET.

**Impact:** The mentioned DET will be observed for all the runtime API until all cores are successfully initialized.

**Work around:**

User must ensure that all cores initializations are done before invoking any runtime API from any core.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.3 0000053912-9102**

**Issue description:** Multiple DEMs are reported on any HW error occurred during asynchronous transmission.

**Impact:** To handle each DEM, repetitive corrective actions may be triggered by application in quick successions.

**Work around:**

Ignore the successive DEM which are reported with the same EVENT ID: SPI\_E\_HARDWARE\_ERROR.

Note: Applicable only for Asynchronous Transmission.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.4 0000053912-9108**

**Issue description:** While Spi\_Controlloopback API is executing and second thread invokes the Spi\_Asynctransmit API then there is a possibility of data getting corrupted since the loopback will be enabled/disabled when data transfer is in progress.

**Impact:** Data transmission over the SPI interface to the other end may not be guaranteed.

**Work around:**

When Spi\_ControlLoopBack API is invoked, upper layer must ensure that no other thread is allowed to start a new sequence on the same HW until Spi\_ControlLoopBack API has completed its execution.

**Impacted Release(s):** 1.30.0

**3.24.5 0000053912-8951**

**Issue description:** Clearing of PT2F is missing when interrupts are enabled.

**Impact:** Trap observed while switching from interrupt mode to polling mode in LEVEL-2 configuration.

**Work around:**

At runtime, user must avoid switching between interrupt to polling mode.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.6 0000053912-9831**

**Issue description:** Issue with 8-bit IB channel buffer access for Synchronous configuration, resulting in invalid generation of SPI\_SYNC\_IB\_BUFFER\_SIZE\_COREx macro size.

**Impact:** IB transmission (TX) and Reception (RX) buffers will be corrupted. Functionality cannot be guaranteed.

**Work around:**

1. Ensure that the number of IB buffers are multiple of 4 bytes in case of 8-bit channel data width.
2. Use asynchronous transmission mode instead of synchronous if #1 is not feasible.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.7 0000053912-9901**

**Issue description:** SpiMaxChannel, SpiMaxJob, SpiMaxSequence Post-build variant value should be set to false.

**Impact:** Values for these configuration parameters are not allowed to change across variants.

**Work around:**

Customers to ensure that value of these configuration parameters (i.e. SpiMaxChannel, SpiMaxJob, SpiMaxSequence) can not be changed.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.8 0000053912-9100**

**Issue description:** CS\_VIA\_GPIO is not de-asserted when error occurs during synchronous transmission.

**Impact:** Slave will not be de-asserted and successive communication to different slave devices will also be impacted.

**Work around:**

1. DEM is reported when there any error during transmission. Use must de-assert the CS line while handling the DEM.
2. Use HW driven CS instead of GPIO.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.24.9 0000053912-9371

**Issue description:** Spi\_SyncTransmit() API is exiting before Trailing Delay is over and updating the state as IDLE even though Hardware is busy.

**Impact:** 1. API Spi\_GetHWUnitStatus() will return SPI\_BUSY  
2. API Spi\_ControlLoopBack() will return E\_NOT\_OK  
though Spi\_SyncTransmit() API returns E\_OK indicating the transmission completion.

**Work around:**

After Spi\_SyncTransmit() API returns E\_OK, user must call Spi\_GetHWUnitStatus() API and wait until it returns SPI\_IDLE.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.24.10 0000053912-9720

**Issue description:** Spi\_Cancel API should cancel the sequence only if the sequence is in pending state.

**Impact:** Updates the sequence status to SPI\_SEQ\_CANCELED even though the sequence transmission is not on-going.

**Work around:**

User must invoke Spi\_Cancel() only when Spi\_GetSequenceResult() API returns SPI\_SEQ\_PENDING.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.24.11 0000053912-9087

**Issue description:** Spi\_SyncTransmit() is returning E\_OK if HW error is encountered by reporting a DEM.

**Impact:** If DEM reporting is disabled, User assumes that the transmission is successful since the API returns E\_OK.

**Work around:**

User can call Spi\_GetSequenceResult() API to get the sequence status though Spi\_SyncTransmit() API returns E\_OK.

**Impacted Release(s):** 1.10.0, 1.30.0

### 3.24.12 0000053912-9890

**Issue description:** IB channel offset overflows when more than one channel configured with 65535 data elements.

**Impact:** IB buffer is corrupted.

**Work around:**

**Known issues v3.0**

User must ensure the sum of all IB channel buffers size allocated for a core must not cross 65535 bytes.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.13 0000053912-10039**

**Issue description:** Incorrect EB, IB channel validation with respect to 8190(max data elements allowed per asynchronous job) during configuration code generation.

**Impact:** Incorrect errors will be reported.

**Work around:**

User must ensure the number of data elements per asynchronous job must not cross 8190 data elements.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.14 0000053912-10068**

**Issue description:** SPI\_E\_PARAM\_SEQ DET/SE not raised if Spi\_AsyncTransmit() is called for a Synchronous sequence.

**Impact:** Functional behavior is not guaranteed.

**Work around:**

User must have a configuration where configuration parameters both SpiDevErrorDetect and SpiMulticoreCheckEnable must be set to TRUE.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.15 0000053912-10935**

**Issue description:** Spi\_GetJobResult doesn't report DET when called with a Job not allocated to that CPU core.

**Impact:** Incorrect job result will be returned even though Job is not configured for the core.

**Work around:**

User must ensure that the JobID passed to the Spi\_GetJobResult() API is assigned to core on which the Spi\_GetJobResult() API is invoked.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.16 0000053912-9101**

**Issue description:** Incorrect behavior of Spi\_GetHwUnitStatus() API.

**Impact:** Spi\_GetHwUnitStatus() may return SPI\_IDLE intermittently, even though HW unit is in busy state.

**Work around:**

Avoid using this API.

**Known issues v3.0**

Note: This is an optional API.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.17 0000053912-9103**

**Issue description:** Spi\_SyncTransmit and Spi\_AsyncTransmit behave different if error is encountered during transmission. If an error occurs during Sync transmission, all the jobs related to same sequence is marked as SPI\_JOB\_FAILED. In case of AsyncTransmit all the jobs apart from the one failed is marked as SPI\_JOB\_OK, only job that failed is marked as SPI\_JOB\_FAILED. Status of the jobs to be retained as Queued / pending.

**Impact:** Calling Spi\_GetJobResult on a Job(not actually transmitted but belongs to failed sequence) returns SPI\_JOB\_OK in case of Asynchronous communication where as it returns SPI\_JOB\_FAILED incase of synchronous communication.

**Work around:**

If the Spi\_GetJobResult API returns SPI\_JOB\_FAILED, user must ignore the status of successive jobs.

**Impacted Release(s):** 1.10.0, 1.30.0

**3.24.18 0000053912-10645**

**Issue description:** Calling Spi\_Cancel() cancels the successive job of ongoing sequence being transmitted and updates the sequence status to cancelled. However updating the QSPI HW unit status to IDLE only happens once the ongoing job transmission is completed. So calling Spi\_GetHwUnitStatus or Spi\_GetStatus immediately after Spi\_Cancel will return SPI\_BUSY due to ongoing job.

**Impact:** Calling Spi\_GetHwUnitStatus or Spi\_GetStatus immediately after Spi\_Cancel in case of only single sequence/last sequence will return SPI\_BUSY.

**Work around:**

User must call Spi\_GetHwUnitStatus or Spi\_GetStatus and wait untill the API returns SPI\_IDLE.

**Impacted Release(s):** 1.0.0, 1.10.0, 1.20.0, 1.30.0, 1.40.0

**3.25 UART****3.25.1 0000053912-10629**

**Issue description:** UART driver does not support fast frequencies.

**Impact:** Clock mismatch possible in baud rate regeneration for fast frequencies. This will lead to incorrect data communication.

**Work around:**

The user should always select UartCsrClksel as ASLINS in tresos to take reference for the baud rate generation.



### 3.25.2 0000053912-10808

**Issue description:** Incorrect CTS select line SELECT\_CTS\_A\_PORT14\_PIN9 is given for ASCLIN0 Kernel it should be None.

**Impact:** If SELECT\_CTS\_A\_PORT14\_PIN9 used for ASCLIN0 then Handshaking mechanism may not work .

**Work around:**

a) ASCLIN0: Avoid using this configuration.

b) For the rest: User can choose different AscLin kernal(ASCLIN1/ASCLIN2/ASCLIN3) to enable Handshaking mechanism.

**Impacted Release(s):** 1.30.0

## 3.26 WDG

### 3.26.1 0000053912-9891

**Issue description:** Wrong maximum limit for WDG Slow Refresh time configuration parameters, when STM timer is selected.

**Impact:** The WDG Slow refresh time configuration for STM timer can only be a maximum of 4.294 seconds. For Slow refresh times > 4.294 secs for STM timer, arithmetic overflow will occur and incorrect timer values would be configured.

**Work around:**

Customer can use one of the workarounds:

- Configure GTM timer instead of STM timer

- If STM timer is used, maximum refresh time for SLOW mode shall be 4.294 seconds.

**Impacted Release(s):** 1.10.0, 1.30.0

## 4 Safety topics v3.0

This section lists safety anomalies and safety related updates related to production releases and maintenance releases.

### 4.1 HW safety manual

#### 4.1.1 0000053912-9009

**Issue description:** Impact analysis of AURIX TC3xx Safety Manual 1.05 to existing production releases.

**Impact:** Additional information related to AoU is documented in 0000053912-8818. No other impacts.

**Work around:** See issue description of 0000053912-8818.

**Impacted Release(s):** 1.10.0, 1.30.0.

## 5 Known issues v2.0

### 5.1 ADC

#### 5.1.1 0000053912-7242

**Issue description:** AdcChannelLowLimit description in MCAL UM is confusing.

**Impact:** UM description for AdcChannelLowLimit parameter is wrong. I.e. Value has to be greater than or equal to AdcChannelLowLimit. However no functional impact.

**Work around:**

UM description for AdcChannelLowLimit parameter should be read as follows:

Parameter defines the lower limit used for limit checking.

1. This parameter is configurable only if AdcChannelLimitCheck is set to TRUE, and AdcChannelRangeSelect is not equal to 'ADC\_RANGE\_OVER\_HIGH'.
2. AdcChannelLowLimit value has to be less than or equal to AdcChannelHighLimit.

The default and maximum value of this parameter is added based on the 12-bit ADC converters value supported by the hardware.

**Impacted Release(s):** Impacted Release(s): Impacted Release(s): 1.10.0.

#### 5.1.2 0000053912-7580

**Issue description:** Config pointer passed in Adc\_InitCheck API is not used for checking the correct initialization of ADC driver.

**Impact:** Validation of the input Config pointer isn't considered and Adc\_InitCheck API will return E\_OK incorrectly.

Work around: None.

**Impacted Release(s):** Impacted Release(s): Impacted Release(s): 1.10.0.

### 5.2 All Modules

#### 5.2.1 0000053912-7100

**Issue description:** In <Mod>\_Bswmd.arxml signed values are not supported for enum data types.

**Impact:** Signed values can't be used for enum data type.

**Work around:** Customer to use only unsigned values for enum data types.

**Impacted Release(s):** Impacted Release(s): Impacted Release(s): 1.10.0.

## Known issues v2.0

**5.2.2 0000053912-8516**

**Issue description:** RTE generation issues possible due to invalid / missing information in BswMD ARXML.

**Impact:** Customer cannot generate RTE with Mentor RTE tool because of the invalid/missing information used in BSWMD ARXML. Impacted drivers are DSADC, MCU, ADC, PWM, ICU, WDG, GPT, OCU, HSSL, I2C, SPI, CanTrcv\_17\_V9251 and CanTrcv\_17\_W9255.

**Work around:** No workaround available.

**Impacted Release(s):** 1.10.0.

**5.3 CAN****5.3.1 0000053912-7284**

**Issue description:** Duplication of SWPDU ID on triggering CAN\_Write() from same dedicated HTH (INTERRUPT and POLLING).

**Impact:** When Can\_Write is triggered at the end of transmission, a notification is provided to upper layer for successful transmission. In this scenario where message is successfully transmitted on bus and notification is delayed due to other higher priority interrupts and in mean time a Can\_Write request is provided on the same HTH, previous PDU id will be overwritten by the new request due to which two notifications will be obtained for last message being transmitted.

**Work around:** Successive Can\_Write on a same dedicated HTH has to trigger only after successful notification is obtained to upper layer.

**Impacted Release(s):** 1.10.0.

**5.3.2 0000053912-7285**

**Issue description:** Unexpected acceptance of Can\_17\_McmCan\_Write during execution of Can\_17\_McmCan\_ActivateIcom.

**Impact:** When Icom is enabled / disabled using the API Can\_17\_McmCan\_SetIcomConfiguration, controller is initialized and filters are re-configured during which messages should not be accepted for transmission. Since the controller is re-initialized, behavior of the hardware will not be predictable and is undefined in this state, so possibility of message not getting transmitted is high.

**Work around:** Controller needs to be in stopped state by using Can\_17\_McmCan\_SetControllerMode API and Can\_17\_McmCan\_SetIcomConfiguration API to be used for enabling / disabling Icom. Application to make sure that messages are requested to be transmitted only after successful Icom enable / disable.

**Impacted Release(s):** 1.10.0.

**5.3.3 0000053912-7295**

**Issue description:** Clearing of Busoff interrupt flag is missed in certain conditions.

**Known issues v2.0**

**Impact:** In Case of Icom feature is enabled through configuration, Icom( Can\_17\_McmCan\_SetIcomConfiguration ) is not enabled and busoff reporting is disabled (CanIcomWakeOnBusOff), bus-off interrupt flag (IR.BO) will not be cleared leading to not getting successive bus-off interrupt.

**Work around:** Disable complete Icom feature by setting the value of CanPublicIcomSupport to FALSE.

**Impacted Release(s):** 1.10.0.

**5.3.4 0000053912-7299**

**Issue description:** Unintended bitwise access, missing timeout monitoring and global variable update sequence is not as expected in CAN Driver.

**Impact:**

#a. Can\_Write API: BAR register updated bit-wise, we have a remote chance to update rest of the bits though transmission is completed in background if we do a bit-wise update. This may lead to a retransmission of same message twice. However this is a very remote possibility.

#b. Can\_17\_McmCan\_SetIcomConfiguration: It has been observed that in this function when clearing / setting INIT, CCE bits timeout is not implemented. These needs to be added to make sure that the bits are SET / clear as intended and then proceed with functionality. No Impact to user is observed but this is the recommended practice.

#c, #d. Can\_17\_McmCan\_SetIcomConfiguration: Certain global variables / update of global variables sequences were not proper due to which Can\_Write and Can\_17\_McmCan\_SetIcomConfiguration API had certain race around condition leading to un-predictable software behavior.

**Work around:**

- None for impact #a
- None for impact #b
- Workaround for #c & #d. Controller needs to be in stopped state by using Can\_17\_McmCan\_SetControllerMode API and Can\_17\_McmCan\_SetIcomConfiguration API to be used for enabling / disabling Icom. Application to make sure that messages are requested to be transmitted only after successful Icom enable / disable.

**Impacted Release(s):** 1.10.0.

**5.3.5 0000053912-7620**

**Issue description:** CAN RX message indications not received after resuming from RXfull and CAN controller mode put to stop.

**Impact:** If interrupts are disabled and more and more messages are received setting the FIFO to full, however in this case, watermark / full interrupt bits would be SET in interrupt register. When CAN controller is put to STOP and then to START mode though CAN controller as such is reset, IR bits would remain SET and is not cleared by ISR due to watermark check in ISR code. In this condition user will experience that no further RX ISR will be triggered and controller will be held in stand-still state.

**Known issues v2.0**

**Work around:** Can\_17\_McmCan\_SetControllerMode API to move to STOP / START state to be performed only when no pending interrupts are to be processed.

**Impacted Release(s):** 1.0.0.

**5.3.6 0000053912-7535**

**Issue description:** A2GT-PRQ-4559 deviated for mixed mode implementation.

**Impact:** If watermark interrupt is missed due to messages getting received when processing the RX interrupt, upper layer may be notified with callback on reception of message.

**Work around:** When polling mode / Mixed mode is not used Can\_17\_McmCan\_MainFunction\_Read should not be called from the scheduler.

**Impacted Release(s):** 1.10.0, 1.30.0.

**5.4 DIO****5.4.1 0000053912-8827**

**Issue description:** P22.6 and P22.7 cannot be configured in TC37x and TC35x devices.

**Impact:** For DIO module, customer will not be able to configure the available port pins 22.6 and 22.7.

**Work around:** No workaround available. Customer can use the patch: "MC-ISAR\_AS42x\_TC3xx\_1.30.0\_Patch\_1.zip".

**Impacted Release(s):** 1.30.0

**5.5 Ethernet****5.5.1 0000053912-4810**

**Issue description:** Transmission is failing intermittently in 10Mbps mode.

**Impact:** Ethernet packet transmission fails in RGMII/10 Mbps mode intermittently. This behavior is observed only when the global time stamp through the parameter 'EthGlobalTimeSupport' is enabled.

Hint - If the time stamp feature is not enabled or the RGMII is not configured in 10 Mbps, then this issue is not observed.

**Work around:** Disable time stamp feature through the parameter 'EthGlobalTimeSupport'.

**Impacted Release(s):** 1.10.0, 1.30.0.

**5.5.2 0000053912-8281**

**Issue description:** VLAN packet transmission with data size of 1500 is not supported.

**Impact:** VLAN tagged packet with data size of 1500 cannot be transmitted using ETHERNET driver.

**Known issues v2.0**

**Work around:** No workaround available.

**Impacted Release(s):** 1.10.0, 1.30.0.

**5.5.1 0000053912-7079**

**Issue description:** Variation Point not supported.

**Impact:** Variation point support is not available for customers to use.

**Work around:** None

**Impacted Release(s):** 1.10.0.

**5.6 FLS****5.6.1 0000053912-7407**

**Issue description:** FLS driver status and Job Result not set when FLS\_17\_DMU\_E\_TIMEOUT DET/SE is raised by Fls\_17\_Dmu\_MainFunction.

**Impact:** Unintended timeout DET may be reported.

**Work around:** To avoid unintended timeout DET, the user has to ensure that calling frequency of Fls\_17\_Dmu\_MainFunction is greater than or equal to 200 us. (Configuration parameter - FlsCallCycle).

**Impacted Release(s):** **Impacted Release(s):** **Impacted Release(s):** 1.10.0.

**5.6.2 0000053912-8037**

**Issue description:** During Flash prog/erase operation, if the flash hardware remains busy, operation error is not handled.

**Impact:** Operation error is not detected and reported, but the timeout DET is reported.

**Work around:** During runtime the timeout DET will be reported, in which case a system reset must be applied.

**Impacted Release(s):** 1.10.0.

**5.6.3 0000053912-8330**

**Issue description:** Compile time error name if FLs\_InitCheck not selected is not named correctly.

**Impact:** Compilation / linker error may occur when FlsInitCheck parameter in configuration is enabled.

**Work around:** User has to ensure that the configuration parameter FlsInitCheck is enabled if an Fls\_17\_Dmu\_InitCheck call is being made in the code.

**Impacted Release(s):** 1.10.0, 1.30.0.

## 5.7 FLS loader

### 5.7.1 0000053912-7697

**Issue description:** FlsLoader\_Write() is failing for DFlash when Executed with McuFSIFrequency at 20MHz.

**Impact:** For FSI frequencies other than 100 MHz, unintended timeout for write or erase operation may occur.

**Work around:** To avoid unintended timeouts, FSI frequency shall be configured at 100MHz.

**Impacted Release(s):** 1.10.0.

### 5.7.2 0000053912-8081

**Issue description:** Possibility of incorrect program flow while checking busy status.

**Impact:** Checking of the busy status, if done too early might reflect a wrong status and cause incorrect program flow.

**Work around:** Delay to be added after program and erase command sequence as per HW UM (v1.2.0 onwards).

**Impacted Release(s):** 1.10.0.

### 5.7.3 0000053912-8089

**Issue description:** During Flash prog/erase operation, if the flash hardware remains busy, operation error is not handled.

**Impact:** Operation error is not detected and reported, but the timeout DET is reported.

**Work around:** During runtime the timeout DET will be reported, in which case a system reset must be applied.

**Impacted Release(s):** 1.10.0.

## 5.8 Flexray

### 5.8.1 0000053912-8320

**Issue description:** Potential issue in macro "FR\_17\_ERAY\_MSG\_BUFF\_COUNT\_MAX\_0".

**Impact:** The pre-compile macro FR\_17\_ERAY\_MSG\_BUFF\_COUNT\_MAX\_0/

FR\_17\_ERAY\_MSG\_BUFF\_COUNT\_MAX\_1 generated in Fr\_17\_Eray\_Cfg.h considers the LPdu count only in the present configuration and not the maximum value across all post-build configurations.

**Work around:** By configuring the variant which is having maximum number of configured LPdus as the last one, the macro FR\_17\_ERAY\_MSG\_BUFF\_COUNT\_MAX\_0/FR\_17\_ERAY\_MSG\_BUFF\_COUNT\_MAX\_1 will be generated with max number of LPdu count. However user has to verify this manually by checking the macro value.

**Impacted Release(s):** **Impacted Release(s):** **Impacted Release(s):** 1.10.0, 1.30.0.



## Known issues v2.0

**5.9 General****5.9.1 0000053912-7985**

**Issue description:** RSM tool not reporting all functions for a module.

**Impact:** Functions with higher complexity may exist, higher than the release criteria.

**Work around:** User can run code complexity tool, other than RSM tool for recheck.

**Impacted Release(s):** 1.10.0

**5.9.2 0000053912-8948**

**Issue description:** Resource properties issues in TC37x.

**Impact:**Impact on PWM or OCU modules:

TC375 device: Customer is not allowed to configure GTM TOUT configurations for port pins PORT21\_PIN6, PORT21\_PIN7 and PORT11\_PIN6.

TC377 device: Customer is not allowed to configure GTM TOUT configurations for port pins PORT21\_PIN6 and PORT21\_PIN7.

TC377\_ED device: Customer is not allowed to configure GTM TOUT configurations for port pins PORT21\_PIN6 and PORT21\_PIN7.

TC377\_ED\_EX device: Customer is not allowed to configure GTM TOUT configurations for port pins PORT21\_PIN6 and PORT21\_PIN7. Customer should not configure the PORT23\_PIN0 TOUT as this pin does not exist on this device.

TC375\_ED device: Customer is not allowed to configure GTM TOUT configurations for port pins PORT21\_PIN6, PORT11\_PIN6 and PORT21\_PIN7.

Impact on LIN and UART module:

TC377\_ED\_EX: Customer cannot configure the ASCLIN RX line for any of the following pins:

SELECT\_C\_PORT1\_PIN8, SELECT\_E\_PORT13\_PIN11, SELECT\_E\_PORT33\_PIN6, SELECT\_H\_PORT13\_PIN12, SELECT\_B\_PORT34\_PIN02, SELECT\_D\_PORT14\_PIN15, SELECT\_B\_PORT01\_PIN0, SELECT\_D\_PORT10\_PIN9, SELECT\_A\_PORT14\_PIN15, SELECT\_B\_PORT01\_PIN8, SELECT\_D\_PORT13\_PIN11

Impact on PORT module:

TC377\_ED:

- P22.6 and P22.7 cannot be used

- P40.10 PCSR feature cannot be used

**Known issues v2.0**

- Port22 and Port23 PCSR pins cannot be configured
- User will not be able to use PDISC support for P40.4, P40.10, P40.11, P40.12
- User will not be able to select Port23 pin 5 fast pin

## TC377\_ED\_EX:

- The complete functionality of P23.0 pin cannot be used.

## TC377\_ED\_EX:

- User will not be able to use Pin channel support for P22.6 and P22.7
- User will not be able to use the P22.6 and P22.7 pin for PCSR functionality
- Analog pin support for Port40 pin 4,10,11,12 added, user will not be able use this pins for DISC configuration

## TC375\_ED:

- P23.2, 23.3, 23.4 PCSR feature cannot be used

## Impact on Dio Module:

TC377\_ED\_EX: The complete functionality of P23.0 pin cannot be used.

T356\_ADAS: P14.6 and P15.6 cannot be used

TC377\_ED, TC377, TC377\_ED\_EX: P22.6 and P22.7 cannot be used

Impact on Eth Module:

TC375, TC375\_ED: User will not be able to configure 10 Mbps speed in RMII mode.

Impact on SENT module:

TC375 and TC375\_ED: P32.5 and P32.7 pins cannot be configured

Impact on CAN module:

TC377\_ED\_EX: selects the incorrectly mapped CANxx\_RXDC pin for the controller with address 0xF0218100, the CAN controller receive functionality will not work as expected. For this device and controller any of the other available options must be used.

**Work around:** No workaround available.

Customer can use the patch: "MC-ISAR\_AS42x\_TC3xx\_1.30.0\_Patch\_1.zip" available in MyInfineon.

**Impacted Release(s):** 1.30.0

## Known issues v2.0

**5.10 HSSL****5.10.1 0000053912-8559**

**Issue description:** Wrong Memmap section used.

**Impact:** No functional impact is seen, however there are two behaviors as captured below

1. Instead of storing the initialized const variable in flash it utilizes the RAM space to store.
2. Single RAM variable is initialized though it can be kept as cleared RAM variable.

**Work around:** No workaround available.

**Impacted Release(s):** 1.30.0.

**5.11 I2C****5.11.1 0000053912-7409**

**Issue description:** Async Read/Write operation is not working after I2c\_AsyncRead API is called with data size more than 4 bytes.

**Impact:** I2C\_AsyncRead() service cannot be used to read more than 4 bytes of data from the slave device.

**Work around:** For reading the data from the slave, application shall use API I2c\_SyncRead().

**Impacted Release(s):** 1.10.0.

**5.11.2 0000053912-9027**

**Issue description:** I2C configure parameter "I2cFastModeSclLowLength" is incorrectly generated.

**Impact:** I2C configure parameter "I2cFastModeSclLowLength" is generated as bit21~bit28, but according to the user manual it should be in bit24~bit31.

**Work around:** No workaround. As I2C is demo code, customer to configure the parameter as per hardware user manual.

**Impacted Release(s):** 1.10.0, 1.30.0.

**5.11.3 0000053912-7801**

**Issue description:** Memory mapping naming for configuration is incorrect.

**Impact:** Since I2C is not multicore, all memory sections names should be defined with core scope as LOCAL. But I2C implementation violates this rule.

**Work around:** Memory mapping for configuration data has to be changed in files(I2c\_PBcfg.c and I2c\_PBcfg.h) as follows:

**Known issues v2.0**

1. From "I2C\_START\_SEC\_CONFIG\_DATA\_QM\_GLOBAL\_UNSPECIFIED" to "I2C\_START\_SEC\_CONFIG\_DATA\_QM\_LOCAL\_UNSPECIFIED".
2. From "I2C\_STOP\_SEC\_CONFIG\_DATA\_QM\_GLOBAL\_UNSPECIFIED" to "I2C\_STOP\_SEC\_CONFIG\_DATA\_QM\_LOCAL\_UNSPECIFIED".

**Impacted Release(s):** 1.10.0.

## 5.12 ICU

### 5.12.1 0000053912-8327

**Issue description:** Invalid configuration check if variation point is enabled.

**Impact:** The configuration tool may wrongly restrict configuration across variation point configurations for below pre-compile configuration parameters:

- IcuGetInputStateApi
- IcuGetDutyCycleValuesApi
- IcuGetTimeElapsedApi
- IcuEnableWakeupApi
- IcuEdgeDetectApi

Below error may be thrown due to difference of ICU modes across valid variation point configurations:

- For edge detect/signal measurement:
  - IcuGetInputStateApi will be forced to be set to false in a variation where no channels are associated but is required to be set to true for another variant where channels are associated.
- For duty cycle measurement:
  - IcuGetDutyCycleValuesApi will be forced to be set to false in a variation where no channels are associated but is required to be set to true for another variant where channels are associated.
- For signal measurement (non dutycycle):
  - IcuGetTimeElapsedApi will be forced to be set to false in a variation where no channels are associated but is required to be set to true for another variant where channels are associated.
- For edge detection only:
  - IcuEnableWakeupApi and IcuEdgeDetectApi will be forced to be set to false in a variation where no channels are associated but is required to be set to true for another variant where channels are associated.

**Known issues v2.0**

**Work around:** For variation point configuration, if any of the below configuration parameters is set to True, then at least one ICU channel must be associated for that ICU mode across variation point configurations :

- IcuGetInputStateApi
- IcuGetDutyCycleValuesApi
- IcuGetTimeElapsedApi
- IcuEnableWakeupApi
- IcuEdgeDetectApi

**Impacted Release(s):** 1.10.0, 1.30.0.

**5.12.2 0000053912-8361**

**Issue description:** Post-Build Variant Multiplicity needs to be changed to TRUE for Edge Detect, Signal Measurement and Time Stamp Containers.

**Impact:** Below ICU configuration containers do not support variation point:

- IcuSignalEdgeDetection
- IcuSignalMeasurement
- IcuTimestampMeasurement
- IcuWakeup.

**Work around:** No workaround available.

**Impacted Release(s):** 1.10.0, 1.30.0.

**5.13 MCALLIB****5.13.1 0000053912-8083**

**Issue description:** McalLib ARXML file issue results in RTE generation issue with Mentor RTE tool..

**Impact:** Customer cannot generate RTE with Mentor RTE tool because of the invalid reference types used in BSWMD ARXML.

**Work around:** None.

**Impacted Release(s):** 1.10.0.

**5.14 MCU****5.14.1 0000053912-7423**

**Issue description:** Tresos allows invalid FSI2 Div Update in CCUCON0 Register.

**Known issues v2.0**

**Impact:** Incorrect divider values generated in Mcu\_PBCfg.c for FSI and FSI2 clocks if SRI frequency is less than PLL0 frequency.

**Work around:** SRI frequency should be equal to PLL0 frequency.

Note: No workaround possible if SRI frequency is less than PLL0 frequency.

**Impacted Release(s):** 1.10.0.

**5.14.2 0000053912-7774**

**Issue description:** Code Sequence issue in Mcu\_17\_Gtm\_AtomChannelShadowTransfer.

**Impact:**

From MCAL perspective,

- No impact during driver initialization, only for runtime APIs
- Only ADC driver calls Mcu\_17\_Gtm\_AtomChannelShadowTransfer() in Adc\_EnableHardwareTrigger() and Adc\_StartGroupConversion() at runtime. If User calls the above mentioned ADC APIs in a re-entrant manner, deadlock may occur and Spinlock might never be acquired by the re-entrant API.

From MCU GTM library's perspective, if Mcu\_17\_Gtm\_AtomChannelShadowTransfer() is called in a re-entrant manner, deadlock may occur and Spinlock might never be acquired by the re-entrant API.

**Work around:** User can use any one of the workarounds:

1. The APIs Adc\_EnableHardwareTrigger(), Adc\_StartGroupConversion() or Mcu\_17\_Gtm\_AtomChannelShadowTransfer() should be treated as non-re-entrant APIs.
2. User shall disable interrupts before invoking APIs Adc\_EnableHardwareTrigger(), Adc\_StartGroupConversion() or Mcu\_17\_Gtm\_AtomChannelShadowTransfer().

**Impacted Release(s):** 1.10.0.

**5.14.3 0000053912-8072**

**Issue description:** Selecting external input for oscillator source will generate wrong OSCVAL value.

**Impact:** To detect malfunction of oscillator, oscillator watchdog monitors the actual incoming clock frequency Fosc. The expected input frequency of Fosc is selected through OSCCON.OSCVAL. If the Oscillator mode is selected as External Input Clock mode, OSCVAL is wrongly configured as 0. This may cause SMU Oscillator watchdog alarms even though there is no malfunction of oscillator.

**Work around:** SMU Oscillator watchdog alarms should not be enabled if Oscillator mode is selected as External Input Clock mode. If customer needs this safety measure, there are no other workarounds.

**Impacted Release(s):** 1.10.0.

## Known issues v2.0

**5.14.4 0000053912-7108**

**Issue description:** fSource2 is mapped to wrong Tresos Parameter in User manual.

**Impact:** The configuration parameter McuClockReferencePointFrequency2 has a typo error in the UM description and may lead to confusion for customer.

**Work around:** McuClockReferencePointFrequency2 to be treated as fSOURCE2.

**Impacted Release(s):** 1.10.0, 1.30.0

**5.14.5 0000053912-8800**

**Issue description:** Generation error when MSC frequency is set to 0 while source frequency is not disabled.

**Impact:** Configuration generation error will occur when McuMscClockSourceSelection != MSC\_CLOCK\_SOURCE\_DISABLED\_SELO and McuMscFrequency = 0.

**Work around:** Customer shall configure one of the workarounds:

- 1) If MSC clock is used, then McuMscFrequency shall be > 0 if McuMscClockSourceSelection != MSC\_CLOCK\_SOURCE\_DISABLED\_SELO
- 2) If MSC clock is not used, McuMscClockSourceSelection shall be set to MSC\_CLOCK\_SOURCE\_DISABLED\_SELO.

**Impacted Release(s):** 1.10.0, 1.30.0

**5.15 OCU****5.15.1 0000053912-9015**

**Issue description:** BSWMD - Module Dependency Section is incorrect.

**Impact:** The BSW-MODULE-DEPENDENCY for Mcu interfaces are missing in the BSWMD file. The missing interfaces are:

Mcu\_17\_Gtm\_AtomChEndisCtrlUpdate  
Mcu\_17\_Gtm\_AtomChEndisStatUpdate  
Mcu\_17\_Gtm\_AtomChInitCheck  
Mcu\_17\_Gtm\_AtomChOutEnCtrlUpdate  
Mcu\_17\_Gtm\_AtomChOutEnStatUpdate  
Mcu\_17\_Gtm\_AtomChUpdateEnDis  
Mcu\_17\_Gtm\_AtomChannelDeInit  
Mcu\_17\_Gtm\_AtomChannelDisable  
Mcu\_17\_Gtm\_AtomChannelShadowTransfer  
Mcu\_17\_Gtm\_TomChInitCheck  
Mcu\_17\_Gtm\_TomChUpdateEnDis  
Mcu\_17\_Gtm\_TomChannelDisable  
Mcu\_17\_Gtm\_TomChannelShadowTransfer.

**Work around:** User shall modify the generated ARXML file by adding the following missed sections:

- 1) Under <SHORT-NAME>McuDependency</SHORT-NAME> tag, add missed Mcu Timer APIs entries under <REQUIRED-ENTRYS> tag:

## Known issues v2.0

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChEndisCtrlUpdate</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChEndisStatUpdate</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChInitCheck</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChOutEnCtrlUpdate</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChOutEnStatUpdate</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChUpdateEnDis</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChannelDeInit</BSW-MODULE-ENTRY-REF>



## Known issues v2.0

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChannelDisable</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_AtomChannelShadowTransfer</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_TomChInitCheck</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_TomChUpdateEnDis</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_TomChannelDisable</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Mcu/BswModuleEntrys/Mcu\_17\_Gtm\_TomChannelShadowTransfer</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

2) Under <SHORT-NAME>McalLibDependency</SHORT-NAME> tag, add below entry:

<BSW-MODULE-DEPENDENCY>

<SHORT-NAME>McalSafetyErrorDependency</SHORT-NAME>

**Known issues v2.0**

<TARGET-MODULE-ID>255</TARGET-MODULE-ID>

<REQUIRED-ENTRYS>

<BSW-MODULE-ENTRY-REF-CONDITIONAL>

<BSW-MODULE-ENTRY-REF DEST="BSW-MODULE-ENTRY">/AUTOSAR\_Stub/BswModuleEntrys/Mcal\_ReportSafetyError</BSW-MODULE-ENTRY-REF>

</BSW-MODULE-ENTRY-REF-CONDITIONAL>

</REQUIRED-ENTRYS>

</BSW-MODULE-DEPENDENCY>

**Impacted Release(s):** 1.30.0.

## 5.16 PORT

### 5.16.1 0000053912-7526

**Issue description:** PortPinMode configuration for Port 40 and Port41 is not available for customers who do not use Tresos as the configuration tool.

**Impact:** Tresos tool does not export the PortPinMode container information in the AUTOSAR format arxml file for Ports 40 and 41 only. Customers who are using any other configuration tool apart from Tresos, this information will be missing.

**Work around:** After importing the generated arxml file, customer shall manually add the Port 40 and Port 41 configurations in the AUTOSAR configuration tool.

**Impacted Release(s):** 1.10.0.

### 5.16.2 0000053912-7344

**Issue description:** Port\_SetPinDirection range check is missing for Direction input parameter.

**Impact:** Range check is not done for input parameter Direction and no error shall be reported if wrong values are passed. If wrong value is passed, the direction will be made as Input.

**Work around:** User shall ensure PORT\_PIN\_IN (0) or PORT\_PIN\_OUT (0x80) is passed for the input parameter Direction in Port\_SetPinDirection API.

Note: for 1.30.0, this limitation is documented in UM.

**Impacted Release(s):** 1.10.0.

## 5.17 PWM

### 5.17.1 0000053912-7131

**Issue description:** TOM\_CH\_IRQ\_NOTIFY Register is not cleared after Pwm\_DelInit.

**Known issues v2.0**

**Impact:** Spurious Interrupt might occur while Pwm\_17\_GtmCcu6\_Deinit for the active PWM channels, before they are de-initialized. However no functional impact.

**Work around:** User should ignore the spurious PWM interrupts after invocation of Pwm\_17\_GtmCcu6\_Deinit.

**Impacted Release(s):** 1.10.0.

**5.17.2 0000053912-8454**

**Issue description:** Glitch in Pwm\_Init if default TOUT is used for other TOM/ATOM channels.

**Impact:** Initialization of one of the GTM PWM channels may trigger a glitch on the output pins of other TOUTSEL/S. The scenario occurs when the affected TOUTSEL/s holds a default value (HW reset value) such that the channel under initialization is driving the affected TOUTSEL (in turn the port pin also). Hence, during the initialization phase a glitch is observed on such channels.

**Work around:** In order to avoid such a glitch on the port pins, the user may follow one of the following workarounds:

- To set the port pins used by the PWM channels as input during the initialization phase of the PWM driver. After completion of the initialization, the port pin's ALT mode can be restored to PWM.
- To set the port pins used for PWM channels as "Output Low" or "Output High" during the initialization phase of the PWM driver. After completion of the initialization, the port pin's ALT mode can be restored to PWM.

**Impacted Release(s):** 1.10.0, 1.30.0.

**5.18 SMU****5.18.1 0000053912-7759**

**Issue description:** Smu\_RegisterMonitor() returns E\_OK even when fault is detected in a safety flip-flop protected register.

**Impact:** UM Description of Smu\_RegisterMonitor() API is ambiguous with respect to return value and output parameter RegMonResult. However no functional impact.

**Work around:** Description of Smu\_RegisterMonitor() API should be read as follows:

The purpose of the Smu\_RegisterMonitor() API is to provide the initialization, execution and termination of the Safety Flip Flop tests to be executed for different modules as enabled in input parameter RegMonPtr.

The prerequisites for Register monitor test shall be taken care by the user as mentioned in the HW UM before invoking the Smu\_RegisterMonitor() API.

The API returns E\_OK only if the test execution was completed successfully irrespective of SFF failures.

The parameter RegMonResult is populated based on the result of SFF tests run for the enabled modules after checking the RMEF.

RegMonResult needs to be checked only when Smu\_RegisterMonitor() returns E\_OK.

## 5.18.2 0000053912-8463

**Issue description:** Register Monitor Test Timeout for different IOM frequency.

**Impact:** For IOM Frequency < 1MHz, Smu\_RegisterMonitor() API may report a DEM failure because the IOM register monitor test status has not completed within the desired time. The timeout value was derived based on Safety Manual 1.04.

**Work around:** Customer shall ensure IOM frequency  $\geq$  1MHz if IOM Functional block is configured for Register monitoring test in Smu\_RegisterMonitor() API.

**Impacted Release(s):** 1.10.0, 1.30.0.

## 5.19 SPI

### 5.19.1 0000053912-7235

**Issue description:** Implementation of Spi\_ControlLoopBack is not robust.

**Impact:**

a. Spi\_kernelLoopBackState variable is not partitioned across cores, so if ASIL partition is done for variables allocated to cores this variable cannot be partitioned since it is allocated to single core.

b. Loopback mode can be enabled / disabled when transmission is in progress.

**Work around:**

a. None

b. Spi\_ControlLoopBack API shall not be invoked while transmission is in progress.

Note: Application to make sure that the Spi\_ControlLoopBack API to be called for enabling / disabling the loopback on 'sequence end notification', when complete transmission of sequence is done.

**Impacted Release(s):** 1.10.0.

### 5.19.2 0000053912-7669

**Issue description:** Calling SchM\_Exit\_Spi\_Queue\_Update() twice when SPI\_SEQ\_PENDING in Async\_Transmit causing error in OS.

**Impact:** Un-predictable behavior. However this can be observed when DET is enabled and DET will be reported if such scenario occurs.

**Work around:** Spi\_GetSequenceResult API to be used to check the status of sequence 'is not in SPI\_SEQ\_PENDING' before calling successive transmit of same sequence.

**Impacted Release(s):** 1.10.0.

### 5.19.3 0000053912-9038

**Issue description:** For GetStatus() API, SPI\_E\_UNINIT DET reporting is not documented in User manual.

**Impact:** If customers enable the DET and call GetStatus() API, then SPI\_E\_UNINIT DET will be reported, though it is not documented in the user manual.

**Work around:** Customers to note that SPI\_E\_UNINIT DET will be reported in the scenario mentioned. No action is required to be taken as its expected behaviour.

**Impacted Release(s):** 1.10.0, 1.30.0.

### 5.19.4 0000053912-8519

**Issue description:** Parameter SPI\_INIT\_CHECK\_API in Tresos does not influence the code.

**Impact:** Spi\_Initcheck() API is always enabled irrespective of corresponding APIs on-off configuration. However no functional impact.

**Work around:** No workaround available.

**Impacted Release(s):** 1.10.0, 1.30.0.

### 5.19.5 0000053912-9020

**Issue description:** Reserved bit DMA ADICR is written with 1 instead of 0. This is not as per HW User manual recommendation.

**Impact:** Reserved bit23 of DMA ADICR register is written with value "1". No impact is seen in MCAL.

**Work around:** None.

**Impacted Release(s):** 1.10.0, 1.30.0.

## 5.20 WDG

### 5.20.1 0000053912-7168

**Issue description:** No "DISABLE" action in "Mcu\_17\_Gtm\_TomChannelDeInit."

**Impact:** The impact is only if Wdg is configured with the GTM timer. The impacted APIs are Wdg\_17\_Scu\_Init(), Wdg\_17\_Scu\_SetMode() and Wdg\_17\_Scu\_SetTriggerCondition(). The first interrupt of the window period will be serviced earlier than the configured interval. The subsequent GTM interrupts for the window shall be serviced within the proper configured interval. However no functional impact foreseen but timing violations can be seen for the first window period.

**Work around:** No workaround for Wdg\_17\_Scu\_Init(). User shall disable the GTM timer by calling Mcu\_17\_Gtm\_TomChannelDisable() before invoking Wdg\_17\_Scu\_SetTriggerCondition() or Wdg\_17\_Scu\_SetMode() API.

**Impacted Release(s):** 1.10.0.

## Known issues v2.0

**5.20.2 0000053912-8790**

**Issue description:** Issue in Wdg driver leading to safety error.

**Impact:** Undesired Safety error shall be reported with Error Id WDG\_17\_SCU\_E\_DRIVER\_STATE in the WDG ISR if Wdg\_17\_Scu\_SetTriggerCondition() API is pre-empted by the ISR after Wdg\_17\_Scu\_DriverState is set to BUSY in the Wdg\_17\_Scu\_SetTriggerCondition() API.

**Work around:** Customer shall disable WDG trigger interrupts before calling Wdg\_17\_Scu\_SetTriggerCondition() API.

**Impacted Release(s):** 1.10.0, 1.30.0.

## 6 Safety topics v2.0

This section lists safety anomalies and safety related updates related to production releases and maintenance releases.

### 6.1 HW safety manual

#### 6.1.1 0000053912-8506

**Issue description:** Impact analysis of AURIX TC3xx Safety Manual 1.02/1.03 to MCAL 1.10.0 production release.

**Impact:** No functional or safety impact to product 1.10.0.

**Work around:** None.

**Impacted Release(s):** 1.10.0.

## 7 Known issues v1.0

### 7.1 ADC

#### 7.1.1 0000053912-6063

**Issue description:** Safety Error ADC\_SE\_PARAM\_KERNEL is not reported when non available kernel (Within 0-11) is passed as parameter for interrupt handlers.

**Impact:** No safety error is reported if non-existent kernel ID is passed to ADC ISR routines. ISR exits without any adverse effect.

**Work around:** User shall ensure that plausible values are passed to the ADC ISR routines.

**Impacted Release(s):** 1.10.0

### 7.2 CAN

#### 7.2.1 0000053912-7064

**Issue description:** CAN messages are lost if Can\_17\_McmCan\_Write() API is invoked for a HTH in re-entrant mode.

**Impact:** Can\_17\_McmCan\_Write() API behaves as non-reentrant for the re-entrant HTH.

**Work around:** Can\_17\_McmCan\_Write() shall not be invoked for a HTH in the re-entrant mode.

**Impacted Release(s):** 1.10.0

#### 7.2.2 0000053912-6838

**Issue description:** CAN driver provides wrong transmit confirmation to CanIf module.

**Impact:** If the Can\_17\_McmCan\_Write() API is invoked for a HTH before receiving the transmit confirmation of the previous pending transmit request for the same HTH, the CAN driver may give incorrect transmit notifications.

**Work around:** Invoke Can\_17\_McmCan\_Write() for a HTH only after receiving the transmit confirmation for the pending request for a HTH.

**Impacted Release(s):** 1.10.0

#### 7.2.3 0000053912-6701

**Issue description:** CAN-FD controller cannot use external oscillator as the clock source.

**Impact:** If the CAN-FD controller is configured to use external oscillator as clock source, then code generator gives an error. Hence CAN-FD controllers cannot use external oscillator as the clock source.

**Work around:** The CAN-FD controller shall be configured to a clock source other than external oscillator.

**Impacted Release(s):** 1.10.0

### 7.3 DIO

#### 7.3.1 0000053912-6170

**Issue description:** Dio\_FlipChannel() API may return incorrect pin level.

**Impact:** Based on the strength of the pin driver and load capacitance, there may be a delay in flipping the channel. Hence, a wrong pin level may be returned by Dio\_FlipChannel().



**Known issues v1.0**

**Work around:** After Dio\_FlipChannel(), user should call Dio\_ReadChannel() API to ensure that the flipping of channel was successful.

Note: Time required to flip the channel is based on the high output load.

**Impacted Release(s):** 1.10.0

## **7.4 FLS**

### **7.4.1 0000053912-6598**

**Issue description:** Fls\_17\_Dmu\_Cancel function should reset the internal variables when a job is cancelled. But, currently Fls\_17\_Dmu\_Cancel API does not reset the internal variables when the ongoing job is either an erase or a blank check.

**Impact:** There is no functional impact. The next request that follows the cancel will set the variables according to the requested job.

**Work around:** None.

**Impacted Release(s):** 1.10.0

### **7.4.2 0000053912-7034**

**Issue description:** FLS status gets set to the initialized in Fls\_17\_Dmu\_Init() even if an operational error (OPER) is present.

**Impact:** FLS status is set to initialized even if an operational error (OPER) is present when Fls\_17\_Dmu\_Init() executes.

**Work around:** If during FLS initialization (Fls\_17\_Dmu\_Init) an illegal state notification is received, then the user should perform a system reset.

**Impacted Release(s):** 1.10.0

### **7.4.3 0000053912-6912**

**Issue description:** Runtime Errors for timeout are not reported in Fls\_17\_Dmu\_Erase() and Fls\_17\_Dmu\_Write().

**Impact:** User is not notified of a run time error.

**Work around:** As the run time error is not reported, the user has to check the return value of the called function. If a run time error occurs, then the return value of the called function will be E\_NOT\_OK.

**Impacted Release(s):** 1.10.0

### **7.4.4 0000053912-6993**

**Issue description:** In FLS standalone mode (without Infineon FEE), ECC errors are not cleared before triggering the write operations on DFLASH (in erase check).

**Impact:** ECC error is not detected in such a scenario but, PVER error will be detected in case the write/program operation fails. Additionally, if SAFETY or DET is enabled, the above mentioned write will be verified by matching the written data with the data in the source buffer and in case a difference is detected, the write operation fails with FLS\_17\_DMU\_E\_VERIFY\_WRITE\_FAILED DET/SAFETY error.

**Work around:** Not required.

**Impacted Release(s):** 1.10.0

## 7.4.5 0000053912-6543

**Issue description:** Range for the parameter FlsWaitStateRead is incorrectly documented in the user manual due to a typographical error.

**Impact:** Wrong information in the user manual. Code is correct.

**Work around:** Correct range for the parameter FlsWaitStateRead is  
FLS\_17\_DMU\_WAIT\_STATE\_READACCESS0 - FLS\_17\_DMU\_WAIT\_STATE\_READACCESS255.

**Impacted Release(s):** 1.10.0

## 7.5 General

### 7.5.1 0000053912-6784

**Issue description:** ARXML file cannot be used with Mentor RTE generator.

**Impact:** Customer cannot generate RTE with Mentor RTE tool because of the invalid reference type used in BSWMD ARXML for 'void' datatype. Impacted drivers are MCU, MCALLIB, FLSLOADER, HSSL, CanTrcv\_17\_V9251 and CanTrcv\_17\_W9255.

**Work around:** User shall modify the generated ARXML file by replacing the following

<BASE-TYPE-REF DEST="SW-BASE-

TYPE"/>/AUTOSAR\_Platform/ImplementationDataTypes/BaseTypes/void</BASE-TYPE-REF> with

<IMPLEMENTATION-DATA-TYPE-REF DEST="IMPLEMENTATION-DATA-

TYPE"/>/AUTOSAR\_Platform/ImplementationDataTypes/BaseTypes/void</IMPLEMENTATION-DATA-TYPE-REF>.

**Impacted Release(s):** 1.10.0

### 7.5.2 0000053912-7071

**Issue description:** Negative value check of Enum parameters is missing.

**Impact:** The driver does comparison checks against enum values considering it as a 32-bit unsigned integer. If user passes a negative value, the comparison fails and results in a wrong control flow. The impacted MCAL drivers are MCU, ICU, OCU and DMA.

**Work around:** Customer shall pass enum values as 32-bit unsigned integer.

**Impacted Release(s):** 1.10.0

## 7.6 Ethernet

### 7.6.1 0000053912-6166

**Issue description:** If a frame exceeding the configured buffer size is received further frames cannot be received.

**Impact:** Ethernet driver stops receiving the frames.

**Work around:** User of the ETH driver must ensure that the EthCtrlRxBufLenByte parameter is configured with maximum packet size, including the header, as expected in the ETH bus. While configuring EthCtrlRxBufLenByte, the user shall consider broadcast frames also. If the maximum receive packet length is not known during the configuration, user shall configure the EthCtrlRxBufLenByte parameter to 1522.

**Impacted Release(s):** 1.10.0

## Known issues v1.0

**7.7 ICU****7.7.1 0000053912-6486**

**Issue description:** GPT12 getInput state for multi-edge detection returning incorrect value. Input state for a GPT12 multi-edge detection channel returns incorrect value.

**Impact:** Icu\_17\_TimerIp\_GetInputState() provides an invalid input state for multi-edge detection channel if notification is not enabled for the respective channel.

**Work around:** Channel notification shall be enabled for multi-edge detection channels to ensure that the channel status is read correctly.

**Impacted Release(s):** 1.10.0

**7.7.2 0000053912-6189**

**Issue description:** Icu\_17\_TimerIp\_SetActivationCondition is not setting the detect condition correctly (for ERU), when pre-empted by Enable Edge Detection API.

**Impact:** Icu\_17\_TimerIp\_SetActivationCondition will have a corrupted active edge configuration if pre-empted by Icu\_17\_TimerIp\_EnableEdgeDetection for that channel. This is applicable only if ERU is configured for that channel in edge detection mode.

**Work around:** User shall ensure Icu\_17\_TimerIp\_SetActivationCondition is executed in critical section.

**Impacted Release(s):** 1.10.0

**7.7.3 0000053912-6173**

**Issue description:** Icu\_17\_TimerIp\_SetActivationCondition not clearing the channel status (for CCU6 and GPT12), if notification is not enabled.

**Impact:** Icu\_17\_TimerIp\_SetActivationCondition returns a wrong channel status if invoked with disabled notifications for that channel. This applies only to GPT12 and CCU6.

**Work around:** Ensure Icu\_17\_TimerIp\_EnableNotification is called before Icu\_17\_TimerIp\_SetActivationCondition for channels associated with GPT12 and CCU6.

**Impacted Release(s):** 1.10.0

**7.8 LIN****7.8.1 0000053912-6547**

**Issue description:** Incorrect reference path to McuClockReferencePointConfig in LIN BMD file.

**Impact:** Code generation for LIN module fails due to error in reference path to MCU module.

**Work around:** User has to manually update the LIN BMD file and correct the path as "/AURIX2G/EcucDefs/Mcu/McuModuleConfiguration/McuClockSettingConfig/McuClockReferencePointConfig" for the parameter "LinSysClockRef".

**Impacted Release(s):** 1.10.0

**7.9 MCALLIB****7.9.1 0000053912-7192**

**Issue description:** Incoherent memory read across cores.

**Known issues v1.0**

**Impact:** If the LockAddress parameter passed to Mcal\_ReleaseSpinlock() is placed in DLMU/DSPR, the value may not be written into the memory but stored in store buffer. Hence, reading from other cores will read the incoherent memory and may timeout to acquire the spinlock even though the acquired core has released it.

**Work around:**

User can choose one of the below:

- Place the variable in LMU
- Invoke DSYNC() after calling Mcal\_ReleaseSpinlock().

**Impacted Release(s):** 1.10.0

## **7.10 MCU**

### **7.10.1 0000053912-6712**

**Issue description:** Divider for EXTCLK1 is not generated correctly in Mcu\_PBCfg.c.

**Impact:** Correct frequency for EXTCLK1 is not generated.

**Work around:** fOut should not be selected for EXTCLK1 in the configuration tool.

**Impacted Release(s):** 1.10.0

### **7.10.2 0000053912-6737**

**Issue description:** Wrong ERU EIFR mask generation.

**Impact:** ERU HW is paired with two ERU channels. If customer selects only one of the ERU pair, a spurious interrupt is issued if an interrupt occurs on the other channel.

**Work around:** Always ensure both the channels of pairs are allocated/used. Currently only ICU driver uses ERU unit for interrupts.

**Impacted Release(s):** 1.10.0

### **7.10.3 0000053912-7108**

**Issue description:** fSource2 is mapped to the wrong Tresos Parameter in MCAL UM.

**Impact:** The configuration parameter McuClockReferencePointFrequency2 has a typographical error in the basic UM description for MCU driver and may confuse customers. No functional impact.

**Work around:** Customer should treat McuClockReferencePointFrequency2 as fSource2.

**Impacted Release(s):** 1.10.0

### **7.10.4 0000053912-6028**

**Issue description:** InitCheck() for ICU or GPT returns E\_NOT\_OK if GPT Timer3 and Timer6 have different pre-scalar values.

**Impact:** Gpt\_InitCheck() API or Icu\_17\_Timerlp\_InitCheck() API fails if customer configures GPT Timer3 and Timer6 with different pre-scalar values.

**Work around:** User can choose one of the below:

- Customer shall configure GPT Timer3 and Timer6 to have the same pre-scalar value.
- Customer shall configure any one of the GPT timers - either Timer3 or Timer6.

**Impacted Release(s):** 1.10.0

## Known issues v1.0

**7.11 PORT****7.11.1 0000053912-6762**

**Issue description:** Variation option missing for AUTOSAR parameters.

**Impact:** Customer cannot configure the AUTOSAR Port parameters PortPinDirectionChangeable as Post Build Variation point.

**Work around:** No workaround available.

**Impacted Release(s):** 1.10.0

**7.11.2 0000053912-7344**

**Issue description:** Range check missing for parameter Direction in Port\_SetPinDirection().

**Impact:** Range check is not done for input parameter Direction and no error is reported if wrong values are passed. If a wrong value is passed, the pin Direction will be wrongly configured as Input.

**Work around:** User shall ensure that 0 or 0x80 is passed as the input parameter Direction for Port\_SetPinDirection() API.

**Impacted Release(s):** 1.10.0

**7.12 PWM****7.12.1 0000053912-6549**

**Issue description:** Link error when compiling the MCAL in Pwm\_17\_GtmCcu6.

**Impact:** Linker error for Pwm\_IPolarity could occur for certain combinations of PWM configurations.

**Work around:** To avoid linker error, enable configuration for any one of the following features:

- PwmDeInitApi
- PwmNotificationSupported
- PwmSetOutputToldle

**Impacted Release(s):** 1.10.0

**7.12.2 0000053912-6387**

**Issue description:** Pwm\_InitCheck() may incorrectly return E\_NOT\_OK for some CCU6 channel combinations.

**Impact:** Pwm\_InitCheck() incorrectly returns E\_NOT\_OK if T13 for CCU60 or T12 for CCU61 is configured.

**Work around:** User shall not configure T13 for CCU60 or T12 for CCU61.

**Impacted Release(s):** 1.10.0

**7.13 SPI****7.13.1 0000053912-6783**

**Issue description:** The SPI driver does not consider the interrupt enable status for spurious interrupt check.

**Impact:** If any SPI spurious interrupts are triggered in the controller, then the SPI driver will not report safety error SPI\_E\_SAFETY\_SPURIOUS\_INTERRUPT and behavior from SPI driver will be undefined.

**Work around:** User shall ensure that SPI interrupts are checked to be enabled before invoking the SPI interrupt handler.

## Known issues v1.0

Impacted Release(s): 1.10.0

**7.14      UART****7.14.1      0000053912-6703**

**Issue description:** Over Sampling parameter (UartChanBaudOverSampling) does not cover the complete range supported by the HW.

**Impact:** Though the possible range for oversampling field in BITCON register is 3 to 15, the values allowed to be configured in the UART driver configuration tool is 8 to 16. Hence, user cannot configure the oversampling values in the range 3 to 7 and also the value 16 is invalid.

**Work around:**

1. User shall not configure value 16 for UartChanBaudOverSampling.
2. There is no work around to configure the range from 3 to 7.

Impacted Release(s): 1.10.0

**7.15      WDG****7.15.1      0000053912-6684**

**Issue description:** DET major version check has an incorrect dependency on "WdgSafetyEnable" parameter.

**Impact:** Unintended DET check for AUTOSAR major version happens if configuration parameter WdgDevErrorDetect is OFF but WdgSafetyEnable is ON. It should be dependent only when WdgDevErrorDetect is ON.

**Work around:** If DET is not used in the user environment, user shall include dummy Det.h file with the macro DET\_AR\_RELEASE\_MAJOR\_VERSION defined as 4.

Impacted Release(s): 1.10.0

## 8 Safety topics v1.0

This section lists safety anomalies related to production releases and maintenance releases.

### 8.1 Safety case

#### 8.1.1 0000053912-7283

**Issue description:** Incorrect ISO 26262 part number mentioned in 1.10.0 safety case, section 5.3.3.

**Impact:** It's a typographical error. No functional or safety impact.

**Work around:** Name of the figure 6 in section 5.3.3 is mentioned as 'Goal: fulfillment of system development requirements according to ISO 26262 Part 6'. Integrators to consider it as 'Goal: fulfillment of system development requirements according to ISO 26262 Part 4'.

**Impacted Release(s):** 1.10.0

### 8.2 ISO 26262 Argumentation Sheet

#### 8.2.1 0000053912-7228

**Issue description:** Method 'error guessing' was incorrectly marked as 'applicable' for unit testing in ISO26262 clauses argumentation sheet (Part 6, Table 11, method 1d).

**Impact:** Error guessing is not mandatory for ASIL B. In addition, unit test cases for boundary value and equivalence class cover all necessary test cases in the context of unit testing. Hence, there is no functional or safety impact.

**Work around:** In safety case for 1.10.0, in 'TC3xx\_SW\_MCAL\_ISO26262\_Argumentation.xlsx' document, Part 6, Table 11, Method 1d is marked as 'YES'. It must be treated as 'NO'.

**Impacted Release(s):** 1.10.0

## 9 HW Derivative specification

This section explains the hardware derivatives supported and their respective property files. Customers must ensure that relevant range checks are implemented and tested as per applicable HW documentation.

### 9.1 Device support details:

**Table 1 Umbrella Device Support TC35xAB/TC37xAA/TC37xED AB/TC38x AD and AE/TC39x BC and BD**

| AURIX Umbrella device              | Name displayed in Tresos Tool | Tresos Property File          |
|------------------------------------|-------------------------------|-------------------------------|
| SAK-TC356TA-64F300S                | TC356_ADAS                    | AURIX2G_TC356_ADAS.properties |
| SAK-TC357TT-64F300S                | TC357_ADAS                    | AURIX2G_TC357_ADAS.properties |
| SAL-TC370TP-96F300                 | TC377                         | AURIX2G_TC377.properties      |
| SAL-TC375TP-96F300W                | TC375                         | AURIX2G_TC375.properties      |
| SAL-TC377TP-96F300S                | TC377                         | AURIX2G_TC377.properties      |
| SAL-TC377DP-96F300S                | TC377                         | AURIX2G_TC377.properties      |
| SAL-TC375TE-96F300W                | TC375_ED                      | AURIX2G_TC375_ED.properties   |
| SAL-TC377TX-96F300S                | TC377_ED_EX                   | AURIX2G_TC377_ED.properties   |
| SAL-TC377TE-96F300S                | TC377_ED                      | AURIX2G_TC377_ED.properties   |
| SAL-TC387QP-160F300S               | TC387                         | AURIX2G_TC387.properties      |
| SAK-TC389QP-160F300S               | TC389                         | AURIX2G_TC389.properties      |
| SAK-TC397XE-256F300S               | TC397                         | AURIX2G_TC397.properties      |
| SAK-TC397XT-256F300S <sup>3)</sup> | TC397_ADAS                    | AURIX2G_TC397_ADAS.properties |
| SAK-TC399XE-256F300S               | TC399                         | AURIX2G_TC399.properties      |

**Table 2 Marking option device Support for TC35xAB/TC37xAA/TC37xED AA/TC38x AD and AE/TC39x BC and BD<sup>1)</sup>**

| AURIX Marking option device | Name displayed in Tresos Tool | Tresos Property File          |
|-----------------------------|-------------------------------|-------------------------------|
| SAK-TC356TH-64F300S         | TC356_ADAS                    | AURIX2G_TC356_ADAS.properties |
| SAK-TC357TA-64F300S         | TC357_ADAS                    | AURIX2G_TC357_ADAS.properties |
| SAK-TC357TH-64F300S         | TC357_ADAS                    | AURIX2G_TC357_ADAS.properties |
| SAK-TC375TP-96F300W         | TC375                         | AURIX2G_TC375.properties      |
| SAK-TC377TP-96F300S         | TC377                         | AURIX2G_TC377.properties      |
| SAK-TC377DP-96F300S         | TC377                         | AURIX2G_TC377.properties      |
| SAK-TC375TE-96F300W         | TC375_ED                      | AURIX2G_TC375_ED.properties   |
| SAK-TC375DP-96F300W         | TC375                         | AURIX2G_TC375.properties      |
| SAL-TC375DP-96F300W         | TC375                         | AURIX2G_TC375.properties      |
| SAK-TC377TX-96F300S         | TC377_ED_EX                   | AURIX2G_TC377_ED.properties   |
| SAK-TC377TX-64F300S         | TC377_ED_EX                   | AURIX2G_TC377_ED.properties   |
| SAL-TC380QP-160F300         | TC389                         | AURIX2G_TC389.properties      |
| SAK-TC387QP-160F300S        | TC387                         | AURIX2G_TC387.properties      |
| SAL-TC387TP-128F300S        | TC387                         | AURIX2G_TC387.properties      |
| SAK-TC387TP-128F300S        | TC387                         | AURIX2G_TC387.properties      |
| SAL-TC387TP-160F300S        | TC387                         | AURIX2G_TC387.properties      |
| SAK-TC387TP-160F300S        | TC387                         | AURIX2G_TC387.properties      |
| SAK-TC387QN-160F300S        | TC387                         | AURIX2G_TC387.properties      |
| SAL-TC389QP-160F300S        | TC389                         | AURIX2G_TC389.properties      |



|                      |            |                               |
|----------------------|------------|-------------------------------|
| SAK-TC389QN-160F300S | TC389      | AURIX2G_TC389.properties      |
| SAL-TC397XP-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAK-TC397XP-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAK-TC397XX-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAK-TC397QP-192F300S | TC397      | AURIX2G_TC397.properties      |
| SAK-TC397QP-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAK-TC397XZ-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAL-TC397XE-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAK-TC397XM-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAL-TC397QP-192F300S | TC397      | AURIX2G_TC397.properties      |
| SAL-TC397QP-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAL-TC397XZ-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAL-TC397XX-256F300S | TC397      | AURIX2G_TC397.properties      |
| SAK-TC397XA-256F300S | TC397_ADAS | AURIX2G_TC397_ADAS.properties |
| SAK-TC397QA-160F300S | TC397_ADAS | AURIX2G_TC397_ADAS.properties |
| SAL-TC399XX-256F300S | TC399      | AURIX2G_TC399.properties      |
| SAL-TC399XP-256F300S | TC399      | AURIX2G_TC399.properties      |
| SAK-TC399XP-256F300S | TC399      | AURIX2G_TC399.properties      |
| SAK-TC399XX-256F300S | TC399      | AURIX2G_TC399.properties      |
| SAL-TC399XE-256F300S | TC399      | AURIX2G_TC399.properties      |

**Note:**

<sup>1)</sup> For TC38x, TC39x, TC37x, TC37xEXT, TC35x marking option device support, range check has to be imposed by user, and not in the MCAL code.

## 10 Acronyms, abbreviations and integration support

Please refer to AURIX 2G HW user manual and MC-ISAR\_AS422\_TC3xx user manual. In case of any queries or support required to implement the work around, contact field application engineers.

## Revision History

## Revision History

| Date       | Version | Description  |
|------------|---------|--|
| 2019-07-22 | v1.0    | Reviewed and released for issues reported post first production release until Jun. 21 <sup>st</sup> 2019.  |
| 2020-01-21 | v2.0    | <ul style="list-style-type: none"><li>• Updated for issues reported from 22<sup>nd</sup> Jun. 2019 to 20<sup>th</sup> Nov. 2019.</li><li>• Chapter 'HW Derivative specification' updated as per latest HW documentation.</li><li>• Updated the file name in line with product name.</li><li>• Issue from RNA v1.0, 0000053912-7344 was updated to enhance the descriptions. Issue 0000053912-7530 was deleted as it had same information as in 0000053912-7697.</li><li>• Chapter name for JIRA 0000053912-6166 changed from GETH to Ethernet to ensure consistency of driver names.</li></ul> |
| 2020-04-30 | v3.0    | <ul style="list-style-type: none"><li>• Updated for issues reported until 9<sup>th</sup> Apr. 2020.</li><li>• Chapter 'HW Derivative specification' updated as per latest HW documentation.</li></ul>  |
| 2020-08-06 | v4.0    | <ul style="list-style-type: none"><li>• Updated for issues reported until 16<sup>th</sup> Jul. 2020.</li><li>• Issue from RNA v3.0, 0000053912-10645 was updated and added to RNA v4.0 to correct the 'Impacted Releases'.</li></ul>   |

#### Trademarks

All referenced product or service names and trademarks are the property of their respective owners.

**Edition 2020-08-06**

#### Published by

**Infineon Technologies AG**  
**81726 Munich, Germany**

**© 2020 Infineon Technologies AG.**  
**All Rights Reserved.**

**Do you have a question about this document?**

**Email: [erratum@infineon.com](mailto:erratum@infineon.com)**

#### Document reference

**Z8F69729595**

#### IMPORTANT NOTICE

The information given in this document shall in no event be regarded as a guarantee of conditions or characteristics ("Beschaffenheitsgarantie").

With respect to any examples, hints or any typical values stated herein and/or any information regarding the application of the product, Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind, including without limitation warranties of non-infringement of intellectual property rights of any third party.

In addition, any information given in this document is subject to customer's compliance with its obligations stated in this document and any applicable legal requirements, norms and standards concerning customer's products and any use of the product of Infineon Technologies in customer's applications.

The data contained in this document is exclusively intended for technically trained staff. It is the responsibility of customer's technical departments to evaluate the suitability of the product for the intended application and the completeness of the product information given in this document with respect to such application.

For further information on the product, technology delivery terms and conditions and prices please contact your nearest Infineon Technologies office ([www.infineon.com](http://www.infineon.com)).

#### WARNINGS

Due to technical requirements products may contain dangerous substances. For information on the types in question please contact your nearest Infineon Technologies office.

Except as otherwise explicitly approved by Infineon Technologies in a written document signed by authorized representatives of Infineon Technologies, Infineon Technologies' products may not be used in any applications where a failure of the product or any consequences of the use thereof can reasonably be expected to result in personal injury.

## AFFECTED MPNS

SAK-TC356TA-64F300S AB  
SAK-TC356TD-48F300S AB  
SAK-TC356TH-64F300S AB  
SAK-TC357TA-64F300S AB  
SAK-TC357TC-64F300S AB  
SAK-TC357TH-64F300S AB  
SAK-TC367DP-48F200S AA  
SAK-TC367DP-48F300S AA  
SAK-TC367DP-64F300S AA  
SAK-TC367V0-64F300S AA  
SAK-TC367VB-32F200S AA  
SAK-TC375TI-96F300W AA  
SAK-TC375TP-96F300W AA  
SAK-TC377DP-96F300S AA  
SAK-TC377TP-96F300S AA  
SAK-TC377TX-64F300S AB  
SAK-TC377TX-96F300S AB  
SAK-TC387QP-160F300S AD  
SAK-TC387QP-160F300S AE  
SAK-TC387TP-128F300S AD  
SAK-TC387TP-128F300S AE  
SAK-TC387TP-128F300S AE  
SAK-TC387TP-160F300S AD  
SAK-TC387TP-160F300S AE  
SAK-TC389QP-160F300S AD  
SAK-TC389QP-160F300S AE  
SAK-TC397QA-160F300S BC  
SAK-TC397QA-160F300S BD  
SAK-TC397QP-192F300S BC  
SAK-TC397QP-192F300S BD  
SAK-TC397QP-256F300S BC  
SAK-TC397QP-256F300S BD  
SAK-TC397TT-256F300S BC  
SAK-TC397XA-256F300S BC  
SAK-TC397XA-256F300S BD  
SAK-TC397XP-256F300S BC  
SAK-TC397XP-256F300S BD  
SAK-TC397XX-256F300S BC  
SAK-TC397XX-256F300S BD  
SAK-TC397XZ-256F300S BC  
SAK-TC397XZ-256F300S BD  
SAK-TC399XP-256F300S BC  
SAK-TC399XX-256F300S BC  
SAK-TC399XX-256F300S BD  
SAL-TC367DP-64F300S AA  
SAL-TC375TI-96F300W AA

SAL-TC375TP-96F300W AA  
SAL-TC377DP-96F300S AA  
SAL-TC377TP-96F300S AA  
SAL-TC377TX-96F300S AB  
SAL-TC387QP-160F300S AD  
SAL-TC387QP-160F300S AE  
SAL-TC387TP-128F300S AD  
SAL-TC387TP-128F300S AE  
SAL-TC387TP-160F300S AD  
SAL-TC387TP-160F300S AE  
SAL-TC389QP-160F300S AD  
SAL-TC389QP-160F300S AE  
SAL-TC397XP-256F300S BC  
SAL-TC397XP-256F300S BD  
SAL-TC399XP-256F300S BC  
SAL-TC399XP-256F300S BD  
SAL-TC399XX-256F300S BC  
SAL-TC399XX-256F300S BD  
SP003833202  
SP005424938  
SP004818890  
SP003803252  
SP003803256  
SP003803258  
SP005351244  
SP004577246  
SP001694656  
SP005411327  
SP005411324  
SP005428961  
SP001724106  
SP004987108  
SP001694648  
SP005353025  
SP004950416  
SP002921224  
SP005351247  
SP002921230  
SP005351248  
SP005425390  
SP002921232  
SP005351249  
SP002921222  
SP005351252  
SP002739588  
SP005351257  
SP002739602

SP005351258  
SP002739604  
SP005351259  
SP002739608  
SP002739594  
SP005351382  
SP002739600  
SP005351385  
SP002725526  
SP005351387  
SP002739606  
SP005351388  
SP002725524  
SP002725518  
SP005351395  
SP001724120  
SP005428963  
SP001724110  
SP004987116  
SP001724092  
SP004950414  
SP002921220  
SP005351250  
SP003021930  
SP005398494  
SP002921234  
SP005411061  
SP002921216  
SP005351253  
SP002725522  
SP005351392  
SP002725520  
SP005351397  
SP002725508  
SP005351398  
TC356TA64F300SABKXUMA1  
TC356TD48F300SABKXUMA1  
TC356TH64F300SABKXUMA1  
TC357TA64F300SABKXUMA1  
TC357TC64F300SABKXUMA1  
TC357TH64F300SABKXUMA1  
TC367DP48F200SAAKXUMA1  
TC367DP48F300SAAKXUMA1  
TC367DP64F300SAAKXUMA1  
TC367V064F300SAAKXUMA1  
TC367VB32F200SAAKXUMA1  
TC375TI96F300WAAKXUMA1

TC375TP96F300WAAKXUMA1  
TC377DP96F300SAAKXUMA1  
TC377TP96F300SAAKXUMA1  
TC377TX64F300SABKXUMA1  
TC377TX96F300SABKXUMA1  
TC387QP160F300SADKXUMA1  
TC387QP160F300SAEKXUMA1  
TC387TP128F300SADKXUMA1  
TC387TP128F300SAEKXUMA1  
TC387TP128F300SAEKXUMA1  
TC387TP160F300SADKXUMA1  
TC387TP160F300SAEKXUMA1  
TC389QP160F300SADKXUMA1  
TC389QP160F300SAEKXUMA1  
TC397QA160F300SBCKXUMA1  
TC397QA160F300SBDKXUMA1  
TC397QP192F300SBCKXUMA1  
TC397QP192F300SBDKXUMA1  
TC397QP256F300SBCKXUMA1  
TC397QP256F300SBDKXUMA1  
TC397TT256F300SBCKXUMA1  
TC397XA256F300SBCKXUMA1  
TC397XA256F300SBDKXUMA1  
TC397XP256F300SBCKXUMA1  
TC397XP256F300SBDKXUMA1  
TC397XX256F300SBCKXUMA1  
TC397XX256F300SBDKXUMA1  
TC397XZ256F300SBCKXUMA1  
TC397XZ256F300SBDKXUMA1  
TC399XP256F300SBCKXUMA1  
TC399XX256F300SBCKXUMA1  
TC399XX256F300SBDKXUMA1  
TC367DP64F300SAALXUMA1  
TC375TI96F300WAALXUMA1  
TC375TP96F300WAALXUMA1  
TC377DP96F300SAALXUMA1  
TC377TP96F300SAALXUMA1  
TC377TX96F300SABLXUMA1  
TC387QP160F300SADLXUMA1  
TC387QP160F300SAELXUMA1  
TC387TP128F300SADLXUMA1  
TC387TP128F300SAELXUMA1  
TC387TP160F300SADLXUMA1  
TC387TP160F300SAELXUMA1  
TC389QP160F300SADLXUMA1  
TC389QP160F300SAELXUMA1  
TC397XP256F300SBCLXUMA1



TC397XP256F300SBDLXUMA1

TC399XP256F300SBCLXUMA1

TC399XP256F300SBDLXUMA1

TC399XX256F300SBCLXUMA1

TC399XX256F300SBDLXUMA1