COLOR LASERJET ENTERPRISE M750 PRINTER SERIES Firmware Readme

Product Name(s): HP Color LaserJet M750n • HP Color LaserJet M750dn • HP Color

LaserJet M750xh

Model Number(s): D3L08A, D3L09A, D3L10A

This document contains information for the firmware revision number:

Firmware Datecode: 20210317

Firmware Revision: 2309046_000284

HP Fleet Bundle Version Designation: FutureSmart Bundle Version 3.9.7

Description

- -What is included in the Firmware bundle?
- -Who needs this firmware?
- -Determining the current version level of your firmware

<u>Enhancements and Fixes provided with this firmware revision</u> <u>Enhancements and Fixes provided with the previous revision(s)</u>

Installation Instructions

- Additional Information to know
- Using the Embedded Web Server
- Using the Walk up USB port
- Web letadmin

System Requirements

Technical Assistance

Customer Support

Internet

Additional Information

Legal Statements

- Trademark Notices
- -- OPEN-SOURCE SOFTWARE LICENSE AGREEMENTS (In English)
- License and Copyright

Description

This Readme file provides specific installation instructions and other information you should know before you perform a firmware update for your HP LaserJet Series printer or MFP. Installation instructions are provided for Single and Multiple Printer Updates.

This document provides specific update, installation and troubleshooting information. For additional information on the device features, refer to the online user guide found on the Windows Printing System Installer CD-ROM that came with your printer or at hp.com.

What is included in a Firmware bundle?

The HP LaserJet printer firmware update file available from the HP web site contains firmware for the printer, embedded JetDirect (if applicable), HP paper handling accessories used with the device in one convenient download file. When the Remote Firmware Upgrade file is sent to the HP LaserJet Printer or MFP firmware for the engine and all connected accessories are upgraded.

Who needs this firmware?

Similar to Hewlett Packard providing improved software for your HP LaserJet Printer or MFP, Hewlett Packard provides firmware updates for your printer periodically through its supported lifecycle. A firmware update may be necessary if it is determined that you may benefit from the resolution of any issue that is documented below. These updates are available on the HP support web site.

Determining the current version level of your firmware

To determine the current level of firmware installed on the device:

Go to the printer's or MFP's control panel.

- 1. Go to the printer's control panel.
- 2. Press the **Home** or **OK** button.
- 3. Scroll down to the **Administration** menu and press **OK**.
- 4. On the **Reports** menu press the **OK** button.
- 5. On the Configuration/Status Pages menu press OK.
- 6. Scroll down to the **Configuration page** option and press **OK**. Scroll back up to the top to the **Print** option and press **OK**.

On the printed Configuration page look in the section marked "Device Information" for the Firmware Datecode and Firmware Revision. The Firmware Datecode and Firmware Revision will look something like this:

Firmware Datecode: 20130730

Firmware Revision: 2301104_394918

IMPORTANT NOTE:

This firmware file requires an interactive update method. You CANNOT update these Product(s)/Model(s) using the traditional FTP, LPR or Port 9100 methods of upgrading. Please use one of the following methods listed below to update the firmware of this device.

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20210317

Firmware Revision: 2309046 000284

HP Fleet Release Designation: FutureSmart Bundle Version 3.9.7

For information on HP Security Bulletins addressed by firmware releases, please visit: https://support.hp.com/security-bulletins

To initiate a subscription to receive future HP Security Bulletin alerts via email, visit: https://www.hp.com/qo/alerts

ENHANCEMENT:

Base:

No New Updates.

Security/Authentication:

No New Updates.

Embedded JetDirect:

No New Updates.

FIXES:

Base:

- ➤ HP Webservices will stop working and the printer will lose its connection to HP Connected on the web. You may see an error "Could not communicate with HP Connected, or Unable to contact HP Connected" when you try to enable HP Web Services.
- ➤ Third party solutions created in 2021 will not be able to load on the device through the solution installer page.

Security/Authentication:

No New Updates.

Embedded JetDirect:

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20210317
	Firmware Revision: 2309046_000284

Embedded JetDirect:	JDI23900047
DC Controller:	4.104
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.9.7
MD5 checksum for .bdl file	0fb06db78a39bcaa502b2a94aa4c9ca7

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20191213

Firmware Revision: 2309025_582102

HP Fleet Release Designation: FutureSmart Bundle Version 3.9.6

For information on HP Security Bulletins addressed by firmware releases, please visit: https://support.hp.com/security-bulletins

To initiate a subscription to receive future HP Security Bulletin alerts via email, visit: https://www.hp.com/qo/alerts

ENHANCEMENT:

$\mathbf{p}_{\mathbf{r}}$	0	\sim	•
ഥര	ıo	ᆫ	

No New Updates.

Security/Authentication:

No New Updates.

Embedded JetDirect:

No New Updates.

FIXES:

Base:

➤ 49.4A.04 error may occur intermittently when printing from certain types of customized applications.

Security/Authentication:

Embedded JetDirect:

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20191213 Firmware Revision: 2309025_582102
Embedded JetDirect:	JDI23900042
DC Controller:	4.104
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.9.6
MD5 checksum for .bdl file	4763325c4b06badc546861351ae16b20

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20190711

Firmware Revision: 2309021_581902

HP Fleet Release Designation: FutureSmart Bundle Version 3.9.5

ENHANCEMENTS:

Base:

No New Updates.

Security/Authentication:

Added an updated digital signature verification for aftermarket solution bundles during installation. Currently installed solutions are not affected. Customers and resellers should work with solution providers for an updated signature-compliant version of their software.

Embedded JetDirect:

FIXES:

Base:

- > Some SmartCard solutions may fail to communicate with the card reader properly causing the authentication dialog window to not appear.
- > The control panel may freeze/lockup when using a spinner list on the 4-line display models.

Security/Authentication:

CVE-2019-6334 - Solution application signature checking may allow potential execution of arbitrary code.

Embedded JetDirect:

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

DEVICE TIRMIVAKE KEVISION	
COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20190711
The CLY (All Colored	Firmware Revision: 2309021_581902
Embedded JetDirect:	JDI23900041
DC Controller:	4.104
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.9.5
MD5 checksum for .bdl file	9bf8a0350dea9ee09057be6d8bfbce07

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20190118

Firmware Revision: 2309010 581423

HP Fleet Release Designation: FutureSmart Bundle Version 3.9.4

ENHANCEMENTS:

n	
Kasa	•
Duse	•

Security/Authentication:

New security check will prevent installation of non-compliant aftermarket solution bundles. Currently installed solutions are unaffected. Please work with solution providers for an updated signature-compliant version of their software.

Embedded JetDirect:

No New Updates.

FIXES:

Base:

No New Updates.

Security/Authentication:

No New Updates.

Embedded JetDirect:

> TLS 1.0 and Multicast IPV4 settings do not get backed up and restored properly.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20190118 Firmware Revision: 2309010_581423
Embedded JetDirect:	JDI23900041
DC Controller:	4.104
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.9.4
MD5 checksum for .bdl file	e7550a39a42ce647efd50377c8100274

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20180605

Firmware Revision: 2308974_579776

HP Fleet Release Designation: FutureSmart Bundle Version 3.9.2

ENHANCEMENTS:

Base:

No New Updates.

Security/Authentication:

Added a feature to prevent Cross-site Request Forgery (CSRF) exploits. This guards against a malicious exploit where unauthorized commands are sent to the EWS using the logged-on administrator credentials.

Embedded JetDirect:

No New Updates.

FIXES:

Base:

- ➤ Under certain conditions 49.38.07 error is seen after receiving a fax job.
- Secure Erase feature does not work properly after replacing the device's Hard Disk Drive (HDD).

Security/Authentication:

- > CVE-2018-5923: Insecure Solution DLL Signature Validation.
- CVE-2015-9251: ¡Query before version 1.12.0 and 3.0.0 may be vulnerable to Cross-site Scripting (XSS) attacks.

Embedded JetDirect:

- > Cisco "ARP Proxy" feature is causing devices to decline the DHCP offer.
- Syslog Priority setting is not filtering properly.
- Device loses network connection after re-negotiating the link speed.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20180605 Firmware Revision: 2308974_579776
Embedded JetDirect:	JDI23900022
DC Controller:	4.104
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.9.2
MD5 checksum for .bdl file	5444e337d8764ccf10c574437b02ebc9

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20180301

Firmware Revision: 2308955_579089

HP Fleet Release Designation: FutureSmart Bundle Version 3.9.1

ENHANCEMENTS:

Base:

No New Updates.

Security/Authentication:

No New Updates.

Embedded JetDirect:

No New Updates.

FIXES:

Base:

- > When printing from Mac OS High Sierra, error "undefinedresult, OFFENDING COMMAND" is seen.
- > Unable to print certain PDF files from USB.

Security/Authentication:

No New Updates

> By default, the IPP queue was disabled and it was enabled only for CUPS client. This change includes enabling IPP queue by default, which improves IPP/IPPS performance significantly.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20180301
THE CESTATA SO SCIES	Firmware Revision: 2308955_579089
Embedded JetDirect:	JDI23900015
DC Controller:	4.104
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.9.1
MD5 checksum for .bdl file	dd583f2c723fcb5d05aad8f51e546feb

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20171213

Firmware Revision: 2308937_578501

HP Fleet Release Designation: FutureSmart Bundle Version 3.9

ENHANCEMENTS:

Base:

- The Backup and Restore feature has been expanded to include JDI settings.

 Additionally, this feature has been expanded to allow creating a backup file and restoring that file to another device of the same model and firmware version as the backup file.
- Added support for "Any Size/Any Type" in cassette trays.
- > This feature increases the number of allowed PIN users in the device's local address book; from 1000 to 2000.
- Optimized JPEG decompression library improves performance of print jobs with JPEG compressed images
- A new option has been added to delete the temporary jobs after 3 days.
- Error code "42.B0.01" will not be displayed in the event log for end customers.
- Added new feature to allow PCL 6 to suppress blank pages. Previously this feature was only available with PCL5, now this functionality is also available with PCL6.
- Changes in power management to meet new Blue Angel regulations.

Security/Authentication:

- Users now have the ability to disable printing from Help.
- Added two new features to improve the private and usability of retrieving stored jobs from the "Retrieve from Device Memory" application. Administrators can define what users first see when entering the "Retrieve from Device Memory" application. The default behavior has not changed, but administrators have a new setting in the embedded web server under "Security" [Tab] -> "Protect Stored Data" [Menu] -> "Managed Stored Jobs" [Section] called "Behavior when users are authenticated. If "Assist users to their jobs" is selected, users entering the application will immediately see their jobs provided a folder exists by their username (default behavior in the print driver when sending jobs) but can navigate back to the list of folders with jobs. Administrators will also note a new permission that is not activated by default in the embedded web server under "Security" [Tab] -> "Access Control" [Menu] -> "Sign In and Permission Policies" [Section] -> "Open from Device Memory application" [Control Panel Permission] for "Other Users' Jobs and Folders". If removing the permissions (e.g. for "Guest" and "Device User") a regular user will only be able to see their or guest jobs. If at the folder view they will only be able to see folders with at least one of their own jobs or a guest job within it except for the special folders like "Untitled" & "Stored Faxes". These two features can be used together to optimize the privacy & usability when users retrieve their stored jobs.
- Allow for nested group behavior on the EWS: Security>Access Control>Windows Setup. Nested AD groups may be configured to inherit parent permissions.
- > Allows for authentication at devices using AD credentials instead of local device credentials via Web Jet admin.
- This firmware provides compatible HP and 3rd party solution software the ability to establish HTTPs communications through the Jetdirect networking interface. The protocol and encryption parameters for these solutions are now configured using the Jetdirect networking settings, allowing access to updated Jetdirect protocols and encryption. This option is available to HP and 3rd party solutions using the HttpWebRequest Class connection methods.
- This firmware addresses the following security issues: CVE-2005-4900– SHA-1 is not collision resistant, allowing for context-dependent spoofing attacks. Cipher suites containing the SHA-1 hashing algorithm can now be disabled by setting Encryption Strength to "High" within the "Mgmt. Protocols" page under the EWS Networking tab. These cipher suites will remain enabled/active if Encryption Strength is set to either "Medium" or "Low". Note: For devices with Encryption Strength set to "High", after installing this firmware the Encryption Strength setting will be changed to "Medium" to allow continued access to SHA-1 cipher suites.

Embedded JetDirect:

No New Updates.

FIXES:

Base:

- You may see a 49.00.FF error while performing a Direct TIFF print job.
- > Setting Legacy resolution to 300 x 300 would not be retained after a power cycle.
- Print job size of 400mb or more not getting stored on the device disk memory.
- Disk resident fonts are not persistent after a power cycle.
- Paper type is displayed incorrectly on control panel when using Chinese.
- > Wrong translation of control panel buttons in Czech.
- Certain PDFs were not printed correctly, text on PDF was getting printed as blocks.
- Improved Barcode scanning.
- > Improvement in print performance of certain PDF files.
- You may see an Access Denied warning when trying to accesses the EWS even prior to entering in a Password.
- Under certain circumstances an SNMP GET request might receive a slow response which exceeds all client retries and timeouts. Sometimes the printer would never respond. This fix ensures that these circumstances do not prevent timely SNMP responses.
- Intermixing of pages is seen when printing mopy jobs.
- Embedded EPrint setting intermittently shows state as "Not Supported" instead of "Enabled/Disabled" via WJA.
- Using the Pages per Sheet N-Up printing feature provided with any version of the UPD PCL6 driver will give incorrect printed output.
- You may see improvements printing certain fonts.
- ➤ 49.38.07 error is seen when printing certain jobs with "reverse page order" setting enabled on a device without finisher.
- > PS Error seen when printing certain documents greater than 40 pages.
- Added a Web Service object for the "Security" -> "Web Scan Auto Capture Jobs: Enable Remote User Auto Capture" feature which will allow Web Jet admin to fleet manage this setting with XTP Tickets where reservation less scanning for Network TWAIN is required.
- ➤ 49.4A.04 is seen when printing certain PDF files containing excessive numbers of XObjects on one or more pages
- Error 49.4A.04 is seen when reprinting certain jobs from Corel Draw.
- > The PCL commands to call barcode fonts does not work when using asterisks
- ➤ 49.38.07 error is seen when printing certain PDF jobs in duplex.
- Improves a Print Quality issue wherein streaks and lines are seen due to excessive calibrations.
- Color mismatch while printing certain PDF documents and selecting the CMYK profile in driver.
- Device stops responding to SNMP requests when we go to Device tab in WJA.
- USB volume name is not getting displayed correctly in Korean and other 2 byte languages.
- Missing graphics on pages when printing certain PCL5 jobs.
- Improvements in small job print performance.

Display brightness value is getting reset to default on a power cycle.

Security/Authentication:

- Resolved issue where aftermarket authentication agents utilizing the OXPd protocol could inadvertently remove guest permissions to tabs (e.g. the Information tab) on the EWS page.
- > "This firmware addresses the following security issue:
- CVE-2016-2183 3DES TLS/SSL Birthday Attacks on 64-bit Block Ciphers (SWEET32) Vulnerability."
- Re-added web services (removed in FS 3.8) to allow HP Jet Advantage Security Manager to manage the state of the Information tab in the embedded web server.
- > Resolved redundant authentication prompts when accessing certain types of logs.
- ➤ This firmware addresses the following security issue: CVE-2017-2750 Insecure Solution DLL Signature Validation.
- Added support for G&D FIPS-201 SIPR smartcards that are provisioned without encipherment certificates.
- When logging into the Embedded Web Server using Windows authentication, you may not be able to see all the tabs or options that you have been granted access to.
- This firmware addresses the following security issues:

 CVE-2017-13077: Reinstallation of the pairwise encryption key (PTK-TK) in the 4way handshake. CVE-2017-13078: Reinstallation of the group key (GTK) in the 4way handshake. CVE-2017-13079: Reinstallation of the integrity group key (IGTK)
 in the 4-way handshake. CVE-2017-13080: Reinstallation of the group key (GTK)
 in the group key handshake. CVE-2017-13081: Reinstallation of the integrity
 group key (IGTK) in the group key handshake.
- > This firmware disables the "TFTP Configuration File" setting to prevent unauthorized device resets.

Embedded JetDirect:

- Fixed "IP Address/Subnet is out of range. Check the field. IP=x.x.x.x Mask=x.x.x.x" error given when an IP address was entered with zero for the host number in the Access Control List.
- Buffers expanded to hold large DNS responses (70+ records). Previously only about 7 or 8 records were accepted.
- Trying to connect via the FTP may fail with certain applications.
- Fixed an issue where Windows Authentication would hang the printer.
- Product was generating Certificate Signing Requests with version number other than zero. RFC 2986 requires a version number of zero.
- Product was generating Certificate Signing Requests with version number other than zero. RFC 2986 requires a version number of zero.
- Printer crashes with 81.09.00 Embedded Jetdirect Error message when user sets Admin password from Telnet.

- Under certain circumstances during initial power-on, the DCHP Discover message is sent without a hostname (option 81). This fix ensures that option 81 is always present when applicable.
- The password input for "Import Certificate and Private Key" has been expanded beyond 16 characters.
- Default name when saving a CSR (Certificate Signing Request) is no longer "certificate.cer".
- Under certain circumstances the certificate validity check performed during the IKE portion of IPsec was done with the local printer time and not UTC time.
- ➤ If a Jetdirect 2900w in installed and two different wired networks are connected to the printer (one on the JD 2900w and one on the Jetdirect Inside connection), then it was possible (under certain circumstances) for the entire printer to become unresponsive.
- This fix prevents the printer from resetting the connection during an intervention event (paper out, paper jam, etc.) when printing using the LPD protocol. Previously, the connection would be reset after the TCP Idle Timeout had expired. Now it will wait indefinitely.
- The firmware had trouble parsing a long list of "additional records" in a DNS SRV response packet. This fix prevents the problems which were causing the device to crash with a 49.38.07 error code.
- Do not respond to pings during the DHCP process (after DHCP Discover).
- ➤ Retry 802.1x EAP Start process if unsolicited Request Identity is received after connecting to unsecured network.
- ➤ IPP attribute "printer state" is not returning the correct state when printing a port 9100 job.
- Updates to HTTPS communications for embedded aftermarket solutions.
- Some SSL requests from embedded solutions would fail due to corruption of the destination URL.
- > Printer is showing offline after registering to Google Cloud Print.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20171213 Firmware Revision: 2308937_578501
Embedded JetDirect:	JDI23900012
DC Controller:	4.104
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.9
MD5 checksum for .bdl file	2df62a16567595c6f2d594bc438cfae9

Enhancements and Fixes provided with this Firmware revision

The fellowing way for all and the endead and are supplied to the first constant of the f
The following new functionality or features are provided by this firmware release:
· · · · · · · · · · · · · · · · · · ·
Firmware Datecode: 20170922
I IIIIWalo Dalooda. 2017 0022

Firmware Revision: 2308216_001085

HP Fleet Release Designation: FutureSmart Bundle Version 3.8.0.3

FN	JH	ΔΙ	NC	FA	۸FP	NTS	•

Security	y/Authentication:
----------	-------------------

No New Updates.

Base:

No New Updates.

Embedded JetDirect:

No New Updates.

FIXES:

Security/Authentication:

- > This firmware addresses the following security issues: CVE-2017-11103 Heimdal before 7.4 allows remote attackers to impersonate services with Orpheus' Lyre attacks.
- This firmware addresses the following security issues: CVE-2017-9765 Integer overflow in SOAP (Simple Object Access Protocol) function allows execution of arbitrary code or Denial of Service, aka Devil's Ivy attack.

Base:

No New Updates.

Embedded JetDirect:

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION	
HP CLJ M750 Series	Firmware Datecode: 20170922 Firmware Revision: 2308216_001085	
Embedded JetDirect:	JDI23e80129	
DC Controller:	4.104	
Optional Trays:	3.103	
HP Fleet Release Designation	FutureSmart Bundle Version 3.8.0.3	

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20170613

Firmware Revision: 2308214_000931

HP Fleet Release Designation: FutureSmart Bundle Version 3.8.0.2

ENHANCEMENTS:

Security/Authentication:

> No New Updates.

Base:

No New Updates.

Embedded JetDirect:

No New Updates.

FIXES:

Security/Authentication:

➤ This firmware addresses the following security issue: CVE-2017-2743 - Cross Site Scripting (XSS) Vulnerability.

Base:

> Improves a Print Quality issue wherein streaks and lines are seen due to excessive calibrations.

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION	
HP CLJ M750 Series	Firmware Datecode: 20170613 Firmware Revision: 2308214_000931	
Embedded JetDirect:	JDI23e80125	
DC Controller:	4.104	
Optional Trays:	3.103	
HP Fleet Release Designation	FutureSmart Bundle Version 3.8.0.2	

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20160820 Firmware Revision: 2308209 000581

HP Fleet Release Designation: FutureSmart Bundle Version 3.8

ENHANCEMENTS:

Security/Authentication:

No New Updates.

Base:

- Introduced a secure pull print job purge feature where when using a pull print solution and there is a condition on the device that requires user intervention, a job purge mode will be tied to the inactivity timeout. Job purge is limited to up to 3 jobs in the current print queue. To enable, select "Cancel Print Jobs after Unattended Error" in the devices EWS Security General tab.
- Upgraded the font library to UFST 7.3.1. The focus areas are Error handling for TrueType fonts and OpenType CFF fonts.
- > Media type "HP EcoSMARTLite" has been renamed to "HP EcoFFICIENT".
- ➤ Role-Based Access to EWS provides ability to limit access to EWS items via defined roles. Note: If configured using 3.7.4, feature changes in next fleet release may cause some access controls to be lost. See white paper for details.
- Added functionality to allow users to cancel A3 jobs on A4 printers, mainly targeted for Pull printing customers.

No New Updates.

FIXES:

Security/Authentication:

- > 33.05.17 Security Alert seen when base filename used to package and zip files for solution bundling is too long.
- You may see a 33.05.18 error when using select Solution Providers software on Firmware bundle 3.7.
- EWS Session Id HttpOnly attribute in HttpCookie class set to true.

Base:

- You may see devices intermittently stop responding in complex print environments.
- > Improvement in print performance of certain PDF files.
- Resolves an issue where HP device with PaperCut solutions may result in users being unable to Authenticate or Pull Print. Within the PaperCut Administration Console the HP device is unable to be configured or the embedded device status reports the following error "Error: The server sent HTTP status code 400: BadRequest".
- ➤ EPrint error "Could not communicate with HPConnected.com. Some internal error happened, try again." is seen after upgrading firmware to FS 3.5.1 or later versions.
- ➤ A 49.38.07 error may be seen when printing PDF files using LPR.
- > Improvement in print performance while printing certain PDFs using PS driver.
- > PCLXL error is seen while printing PDFs with watermark.
- When PJL JOB START specifies a specific page to begin printing on (e.g. PAGE 20), the device correctly begins printing on the specified page. However, unsolicited PJL USTATUS PAGE responses would begin counting from Page 1 (Page 2 when printing duplex) instead of the specified JOB START page (e.g. PAGE 20). This has been corrected so PJL USTATUS returns PAGE counts beginning at the specific START PAGE.
- An indication that direct Tiff printing was supported with the Retrieve from USB feature was missing from control panel screen seen after opening the application on the control panel.
- Not able to change Tray Registration settings while EWS is in certain languages.
- Equitrac Authentication Agent sign-in agent is missing.

- If stop hard key is pressed while the device is in sign-in page of any application, the device does not recover and we are not able to access any application on home screen after that.
- PDF bar code not printed correctly.

- > Functionality of the TCP MSS settings in Telnet has been restored.
- Fixed a situation where bad network packets (invalid checksum) could be accepted and processed as if they were good.
- Resolved memory leaks (and possible device lockup) in DNS mapping logic when handling uncommon IPv4/IPv6 scenarios.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20160820 Firmware Revision: 2308209_000581
Embedded JetDirect:	JDI23e80125
DC Controller:	4.103
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.8

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20160225

Firmware Revision: 2307851 000051

HP Fleet Release Designation: FutureSmart Bundle Version 3.7.01

ENHANCEMENTS:

Security/Authentication:

No New Updates.

Base:

No New Updates.

Embedded JetDirect:

FIXES:

Security/Authentication:

This firmware addresses the following security issue: CVE-2016-2244

Base:

No New Updates.

Embedded JetDirect:

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION	
LID CLI M750 Socion	Firmware Datecode: 20160225	
HP CLJ M750 Series	Firmware Revision: 2307851_000051	
Embedded JetDirect:	JDI23701070	
DC Controller:	4.103	
Optional Trays:	3.103	
HP Fleet Release Designation	FutureSmart Bundle Version 3.7.01	

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20160225

Firmware Revision: 2307851_000051

HP Fleet Release Designation: FutureSmart Bundle Version 3.7.01

ENHANCEMENTS:

Security/Authentication:

Base:

No New Updates.

Fm	hed	Ы	ച	1	طt	Πi	rect:
	Dea	u	eч		еı	וט	reci.

FIXES:

Security/Authentication:

This firmware addresses the following security issue: CVE-2016-2244

Base:

No New Updates.

Embedded JetDirect:

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION	
HP CLJ M750 Series	Firmware Datecode: 20160225	
	Firmware Revision: 2307851_000051	
Embedded JetDirect:	JDI23701070	
DC Controller:	4.103	
Optional Trays:	3.103	
HP Fleet Release Designation	FutureSmart Bundle Version 3.7.01	

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20160102

Firmware Revision: 2307781_551203

HP Fleet Release Designation: FutureSmart Bundle Version 3.7

ENHANCEMENTS:

Security/Authentication:

- Whitelisting ensures only authentic, HP firmware code that has not been tampered with is loaded into memory. If an anomaly is detected, the device reboots to a secure, offline state.
- Runtime Intrusion Detection checks for anomalies in system memory during complex firmware and memory operations. In the event an anomaly is detected, the device automatically reboots. If the Auto-recover feature is disabled, or the anomaly occurs twice within 30 minutes, the device reboots to a secure, offline state.

Base:

- The device now has the capability to directly print TIFF files from the walk up USB port.
- Added support for printing TIFF files.
- ▶ IPP Job Mandatory attributes and Page Overrides are supported in Airprint 1.5 phase 2.
- Additional support added for Code 128, Code 3of9, OCR-A, and OCR-B.
- When No Media Type is specified in the job and Tray 1 is loaded and configured (ex: letter, cardstock), a prompt with the default media type is seen in the mount (default: plain). If we press "OK" then the tray will be seeded to the job size and type. If the user decides to not accept this change and selects the modify button and change the tray1 type and press ok, the mount comes back. What this means is that the user will not be able to use what is loaded and configured in Tray1 with the current job. This requirement provides the capability wherein an "Options" button is displayed instead of "OK" in the mount and once user presses Option button, he should be able to see two listings for Tray1, one with the current tray settings and one with the Job settings. Once user selects Tray1 with Job settings, Job size and Job type will be seeded in Tray1 and Job will get printed from Tray1. If user selects any other listing it will be treated as override of Job to tray settings.

Embedded JetDirect:

No New Updates.

FIXES:

Security/Authentication:

Home Screen Sign-In configuration (deny guest access) lost after firmware upgrade.

Base:

- Issue with enlarged text when printing specific PDF documents with General Office quality level selected.
- PCL XL error page is printed intermittently after retrieving the encrypted stored lobs.
- ➤ 49.4A.04 error is seen when printing certain PDF documents using PS driver or Direct Print.
- ➤ 49.4A.04 error is seen when printing certain Microsoft Word documents using the Print feature in the EWS.
- Printing certain PDF files using the Print Feature in the EWS may result in a blank page being printed.
- Report pages are still able to be printed when Access Control has been locked down for those menu items.
- Slow printing observed when using direct PDF for scanned documents.
- Improvement in print performance of certain PDF files.
- Configuration page not printed in few localization languages (Croatian, Romanian, Slovak, Slovenian, Catalan, Indonesian, Thai).
- Improved small job performance.
- While retrieving stored jobs, device hangs intermittently and control panel submenus are not accessible.
- Device hangs in "processing" state intermittently.
- When printing specific PDF documents via Unix, users can get a message regarding an Invalid Font, Failed reading start X ref number.
- Added the ability to support more characters when defining user defined paper types via the embedded web server.
- Troubleshooting tab localization is wrong in German Language.
- Improved remote control-panel allowing access to remote operators while the initial language and date/time wizard is open for new device installations as well as some error messages.
- Unable to receive toner cartridge low alert email from when toner threshold value is reached.
- You may see a delay in accepting data in the middle of a job or between jobs when using the Equitrac solution.
- HPAC15.0 does not read proximity card correctly when waking from sleep mode with OXPd1.7
- Keyboard layout setting is changed from "English (UK)" to "Japanese (Romaji)" after upgrading FW from 3.2.7 to 3.4.
- Accentuated characters missing with universal font on 3.4.
- Slow printing of specific PDF files.
- Slow performance on PPT files.
- > The Esc E command is not resetting the PCL5 print environment when used with the Paper Type command.
- Lines on page may not print when using certain PS or PDF print files.
- Adding a WJA Template has the potential to produce a 46.23.1C error.

- You may see the devices intermittently stop responding to SNMPv3 queries after 2-3 weeks of up-time.
- SNMP Value for hrMemorySize (OID 0.1.3.6.1.2.1.25.2.2.0) is reporting incorrect Memory Size.
- Arabic words on Win Forms have separated letters only.
- > A 49.38.07 may be seen on the control panel for no apparent reason.
- Firror 81.04.00 is seen while printing a few pages after upgrading the firmware from FS 3.2.7 to FS 3.4 or FS 3.4.1.

- > Telnet setting "Bonjour RCNFG" reverts to zero after power cycling the printer.
- Intermittent system hang seen on several or all devices on the same subnet at around the same time, devices are not even pingable.
- > Upgrading from FS 3.4 will cause Bonjour protocol to be enabled even if it was previously disabled.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION	
LID CLI M750 Code	Firmware Datecode: 20160102	
HP CLJ M750 Series	Firmware Revision: 2307781_551203	
Embedded JetDirect:	JDI23700069	
DC Controller:	4.103	
Optional Trays:	3.103	
HP Fleet Release Designation	FutureSmart Bundle Version 3.7	

Enhancements and Fixes provided with this Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20150609

Firmware Revision: 2305090 000473

HP Fleet Release Designation: FutureSmart Bundle Version 3.5.1

ENHANCEMENTS:

Security/Authentication:

No New Updates.

Base:

No New Updates.

No New Updates.

FIXES:

Security/Authentication:

No New Updates.

Base:

- After rebooting the printer, some customers may notice a significant drop in the percent life remaining in their High Yield Black Original LaserJet Toner (X) Cartridges.
- > Added OID support for Cartridge Serial Number.

Embedded JetDirect:

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20150609
	Firmware Revision: 2305090_000473
Embedded JetDirect:	JDI23500067
DC Controller:	4.103
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.5.1
_	

Enhancements and Fixes provided with this Previous Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20150417

Firmware Revision: 2305081_000144

HP Fleet Release Designation: FutureSmart Bundle Version 3.5

ENHANCEMENTS:

Security/Authentication:

This firmware addresses the following security issues: CVE-2014-3566 – SSLv3 POODLE (Padding Oracle on Downgraded Legacy Encryption) Vulnerability.

Base:

- Added the ability to view the "ProductNumber" and "LookAndFeelId" attributes in the products via OXPd Solution Installer and the Jedi Embedded SDK.
- > The device can now communicate secure stored job options to the printer driver.
- Added Native printer support for "Google Cloud Print". For setup and registration instructions, go to www.google.com/cloudprint/learn/

Embedded JetDirect:

No New Updates.

FIXES:

Security/Authentication:

- Email FROM field does not reflect Authenticated user address when GuestUserOverrride is set as default.
- A smartcard middleware crash can occur with cards containing an "empty certificates" buffer when used with the NIPRNET Smartcard Authentication Solution for US Government.
- ➤ A device hang can occur during smart card sign in if an invalid OCSP URL is configured under Security -> Certificate Management of the device EWS.
- Device enters protected mode on the 6th failed logon attempt, instead of on the 5th failed logon. This issue only affects LDAP & Windows authentication.

Base:

- Error 33.02.01 is observed when upgrading the firmware from FS3.0 to FS 3.4.
- ➤ Devices crashes with Error 49.38.07 while processing a duplex PS job with custom media size.
- > Error "Unregistered Offending Command: ImageMask" is seen while printing certain Jobs using a PS driver.
- Print Jobs are slow when driver Status Notification is turned ON.
- The time stamp does not show local time when EWS Job log is exported to CSV or Text file.
- > Communication failure is reported while using WJA to configure the device.

- ➤ Error 49.2A.01 is observed while printing certain word documents using discrete driver.
- > Error 49.4a.04 is seen when printing multiple copies of certain PDF documents.
- Printing an A4 document may display a prompt on the printer's control panel to load paper in the MP tray.
- > When performing an Encrypted stored job via PC, the "Date Stored" time on the device is incorrect.

> DHCP DISCOVER packets now include Tag 77 containing model and serial number information for the printer/mfp.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20150417
	Firmware Revision: 2305081_000144
Embedded JetDirect:	JDI23500064
DC Controller:	4.103
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.5
_	

Enhancements and Fixes provided with this Previous Firmware revision

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20150218

Firmware Revision: 2304070_439660

HP Fleet Release Designation: FutureSmart Bundle Version 3.4.1

ENHANCEMENTS:

Security/Authentication:

No New Updates.

Base:

No New Updates.

Embedded JetDirect:

FIXES:

Security/Authentication:

No New Updates.

Base:

➤ End users prevented from authenticating to the device for some period of time following a digital send or pull print operation performed by a prior authenticated user. Some customers report an inability to login until the device has been power-cycled.

Embedded JetDirect:

No New Updates.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION	
HP CLJ M750 Series	Firmware Datecode: 20150218	
	Firmware Revision: 2304070_439660	
Embedded JetDirect:	JDI23400008	
DC Controller:	4.103	
Optional Trays:	3.103	
HP Fleet Release Designation	FutureSmart Bundle Version 3.4.1	

FIXES AND ENHANCEMENTS PROVIDED WITH PREVIOUS FIRMWARE REVISIONS:

NOTE: ALL IMPROVEMENTS WITH PREVIOUS REVISIONS OF FIRMWARE ARE INCLUDED WITHIN THE MOST CURRENT REVISIONS

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20141212

Firmware Revision: 2304061_439474

HP Fleet Release Designation: FutureSmart Bundle Version 3.4

ENHANCEMENTS:

Security/Authentication:

- Ability for administrators to configure product EWS for LDAP or Windows Authentication Sign In for product tabs.
- > Support added for extensibility solutions to use Windows and LDAP authentication.
- ➤ AirPrint 1.3 Authentication is now supported.
- Simplified Account Lockout is a feature to protect administrator and user accounts and PIN protected stored jobs from brute force hacking attempts. The feature is built into the interface with no configuration necessary. After 5 failed authentication attempts, the system enters "Protected Mode" and inserts small fixed delays to impede continued password guessing. (Note: Identical passwords are treated as a single attempt.) After the user successfully authenticates, or the device idle timeout expires, the "attempt counter" is reset.
- Provides improved logging performance for syslog security event logging when printing multiple small print jobs.
- LaserJet Single Function Devices now support embedded Windows and LDAP Authentication.

Base:

- Ability for administrators to configure an email alert for print, copy, send or fax jobs that may be still processing or stuck after a given threshold.
- Ability for administrators or optionally help desk to remotely control device if authorized from embedded web server.
- Added PDF 1.7 support for direct printing.
- Device settings can now be backed up and stored on the device before a firmware upgrade is performed.
- > Hebrew and Arabic languages are now available on the device control panel.

Embedded JetDirect:

> The default network interface used for outbound connections has been changed to prioritize the Embedded Jetdirect followed by EIO, the 2700W and finally the 2800W. This priority is settable on the Networking tabs of EWS.

FIXES:

Security/Authentication:

No New Updates.

Base:

- ➤ 49.38.07 error seen when printing duplex jobs containing Thai fonts.
- > If "ability to modify tray size and type" settings is locked for a user, Tray 1 "Use Requested Tray First" capability is lost. The printer cannot pick paper

- automatically from Tray 1, even when loaded with correct paper size, and user gets prompted to load paper into Tray 2 to complete the job.
- > Errors in PCL which did not allow customer files to print, have been turned to warnings.
- Unable to read Barcode printed on configuration page.
- > Registration to eprint outside HP network does not work.
- Duplex printing with Alternative Letterhead mode enabled, gives the wrong image orientation.
- Multi-prompt authentication screens with an "Information" page that contain only "Label" controls and OK and Cancel buttons, appear blank on the small screen devices.
- When trying to retrieve all Encrypt jobs, the device doesn't print till the printer display resets back to home screen.
- When a device with an empty tray, has been discovered in WJA, it does not send "Paper Out" alert, even after subscribing for it.
- > Long print jobs may be terminated with an error if printing is stalled waiting for a user interaction such as loading paper.
- > "Personal Jobs" with Encrypted job (With Password) are not getting stored via IPP driver.
- > The Form Length and the Font number PCL values are reset to default after printing some documents and rebooting the device.
- Some improvements in printing back to back small one-two page jobs.

- Network settings, e.g. static IP address, configuration method, etc. intermittently reset to default values.
- Very long Postscript jobs sometimes do not print.
- A delay may occur between print jobs when CCC logging is enabled.
- A number of ports between 1033 and 1044 report as Open/Filtered.
- Network configuration is reset to DHCP after a firmware upgrade.
- Current 32K TCP buffers cause excessive delay on long latency/high bandwidth transfers.

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION	
HP CLJ M750 Series	Firmware Datecode: 20141212	
	Firmware Revision: 2304061_439474	
Embedded JetDirect:	JDI23400008	
DC Controller:	4.103	
Optional Trays:	3.103	
HP Fleet Release Designation	FutureSmart Bundle Version 3.4	

FIXES AND ENHANCEMENTS PROVIDED WITH PREVIOUS FIRMWARE REVISIONS:

NOTE: ALL IMPROVEMENTS WITH PREVIOUS REVISIONS OF FIRMWARE ARE INCLUDED WITHIN THE MOST CURRENT REVISIONS

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20140731

Firmware Revision: 2302963_436077

HP Fleet Release Designation: FutureSmart Bundle Version 3.2.7

ENHANCEMENTS:

Security/Authentication:

No New Updates

Base:

If a job is still being processed and has not completed, an email alert can be sent out notifying administrators that there may be a stuck job. This can be helpful if troubleshooting situations where fax, send or print jobs are hung but if the time is set too low may generate false-positives. It is recommended to be used as a diagnostic technique when troubleshooting stuck jobs where the device is not frozen only

Embedded JetDirect:

No New Updates

FIXES:

Security/Authentication:

- This firmware address the following security issue: CVE-2014-0224 SSL/TLS MITM vulnerability
- Some control panel authentication screens on single function devices were not displaying complete informational text.
- > Device embedded web server can now be configured to use Windows or LDAP sign in (if configured on the device) instead of the EWS administrator password.

This functionality excludes the Web Services and Networking tabs of the EWS, which still require the device admin password.

Base:

- > Device is not reporting the custom device name
- When printing Mixed Letter/Legal jobs sent by HP-UX OS, if the number of copies is not specified for a particular papersize, it takes the number of copies of the previous set.
- Paper load prompt not consistent between FutureSmart products
- > The message within Web JetAdmin "Intervention Needed" is not cleared even after intervention was cleared from the device.
- You may see a 49.38.13 error using Autosend when not configuring a site proxy with credentials.

Embedded JetDirect:

 Manually configured hostnames are intermittently being reset to factory default values (NPIxxxxx)

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20140731
	Firmware Revision: 2302963_436077
Embedded JetDirect:	JDI23260006
DC Controller:	4.103
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.2.7

FIXES AND ENHANCEMENTS PROVIDED WITH PREVIOUS FIRMWARE REVISIONS:

NOTE: ALL IMPROVEMENTS WITH PREVIOUS REVISIONS OF FIRMWARE ARE INCLUDED WITHIN THE MOST CURRENT REVISIONS

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20140529

Firmware Revision: 2302908 435021

HP Fleet Release Designation: FutureSmart Bundle Version 3.2.5

ENHANCEMENTS:

Security/Authentication:

No New Updates

Base:

- > The Job Cancel button behavior has changed to prompt a user to either resume or cancel the job, which is now also tied to the inactivity timeout. We also have the ability to remove the Job Cancel button (red x) from the CP of the device.
- Now have the ability to support up to 28 characters for Custom Media types.

Embedded JetDirect:

No New Updates

FIXES:

Security/Authentication:

No New Updates

Base:

- > The Web Services tab may be missing.
- > Sending Personal Private Stored Jobs with Encryption does not keep copy count.
- > Certain character may get flipped or mirrored in some documents.
- Safecom users may get accidentally signed out shortly after the device wake up from A1W using the proximity USB card reader.
- You may see a 49.4A.04 error when printing certain Websites or PDF files.
- Fix to prevent certain 49.38.14 error which are not able to be cleared.
- > Retrieving all Personal jobs may result in the print all option not working until the device is rebooted.

Embedded JetDirect:

- The printer will randomly become unresponsive due to excessive printer queries.
- > Network interface not using low power mode

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
-----------	------------------

HP CLJ M750 Series	Firmware Datecode: 20140529 Firmware Revision: 2302908_435021
Embedded JetDirect:	JDI23250001
DC Controller:	4.103
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.2.5

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20140324

Firmware Revision: 2302786_433728

HP Fleet Release Designation: FutureSmart Bundle Version 3.2.3

ENHANCEMENTS:

Security/Authentication:

- Security Self Test enabled through the embedded web server EWS->Security Tab->Self Test page
- > Support added for HP Smartcard US Government SIPRNet Solution

Base:

- New setting to configure job timeout for "Permanent Jobs" for Job Retention.
- Added the ability to allow an administrator to change the Service PIN on their device.

Embedded JetDirect:

No New Updates

FIXES:

Security/Authentication:

No New Updates

Base:

- If a cold reset is performed when a solution is loaded, the EWS->Security->Access Control page still showed Solution entries which no longer exist.
- You may see a 49.4A.04 error when printing certain web pages or PDF files.

- When installing some CCID card readers you may see the following error -"Invalid USB device is attached. Please remove it."
- > The Embedded Web Server exported view of the Job Log does not match what is on screen.
- > May fail to wake from sleep when device is setup to wake (turn on) on a wake schedule.
- When stapling is requested within the print driver you may see the first page separated from the remaining job which is stapled.
- General Stored Job Settings menu missing on the 4-line products

- > When exporting the Jetdirect Identity certificate, the password is incorrect
- > The link speed reported over SNMP is incorrect for 1000T
- > IPP should not be reporting an error on exiting priority-mode job during printing

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20140324
	Firmware Revision: 2302786_433728
Embedded JetDirect:	JDI23230013
DC Controller:	4.100
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.2.3

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20140129

Firmware Revision: 2302600_430595

HP Fleet Release Designation: FutureSmart Bundle Version 3.2.2

ENHANCEMENTS:

Security/Authentication:

No New Updates

Base:

> New setting to configure job timeout for "Permanent Jobs" for Job Retention.

Embedded JetDirect:

No New Updates

FIXES:

Security/Authentication:

No New Updates

Base:

No New Updates

Embedded JetDirect:

No New Updates

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20140129

Firmware Revision: 2302600_430595

HP Fleet Release Designation: FutureSmart Bundle Version 3.2.2

ENHANCEMENTS:

Security/Authentication:

No New Updates

Base:

> Added the ability to allow an administrator to change the Service PIN on their device.

Embedded JetDirect:

No New Updates

FIXES:

Security/Authentication:

No New Updates

Base:

- You may see "Invalid USB device is attached. Please remove it" when using certain USB Card Readers.
- You may see a 49.4A.04 error when printing certain PDF files.
- You may see an extra blank page printed after sending raw PCL code to the printer.
- The EWS exported view of the Job Log does not match what is on screen.
- > Job Status menu is not able to be locked down in the Security/Access Control
- Menus with in the General Stored Job settings are missing.

Embedded JetDirect:

No New Updates

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20140129
	Firmware Revision: 2302600_430595
Embedded JetDirect:	JDI23230004
DC Controller:	4.100
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.2.2

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20131122

Firmware Revision: 2302243_421972

HP Fleet Release Designation: FutureSmart Bundle Version 3.2

ENHANCEMENTS:

Security/Authentication:

Job Data encryption using AES-256 has been added on devices with Solid State mass storage (SSD). The default is AES-128.

- Secure storage of all externally exposed passwords has been updated to industry standard SHA-256 hashing and AES-256 encryption.
- HP US Government Smartcard Authentication is now available as a configurable sign in method for non-MFP print devices. This capability requires the installation of the HP USB Smartcard reader.
- Windows and smart card authentication are now available on single-function printers

Base:

- The Generate Debug Data feature is now available in the products Embedded Web Server.
- The maximum number of Stored Jobs has been increased to 300 to be compatible with the older Legacy devices.
- > A Partial Clean can now be initiated from the products Embedded Web Server.
- Added additional SNMP values to conform to the Standard Printer and Host Resource MIBs.
- Time zones for Russia have been changed to reflect the time zones used in this country.
- > The Optimize speed energy usage values were provided so Web Jet Admin can configure these values.
- > Error messages and codes have been improved
- The "Resend Upgrade" message will appear on the device if no firmware is on Backup/Repository partition.
- A reduction in the firmware bdl file sizes has been provided in this release. For some products this can be as high as a 50% reduction in size.
- An image preview of a Stored Job will be provided on the control panel before printing the Stored Job.
- This firmware release provides the ability to switch FutureSmart levels. It is only supported on device that ship with FutureSmart Level 2. Documentation is available on www.hp.com to learn more about this feature. Steps to perform the level switching are provided in this readme file.

Embedded JetDirect:

- Now able to enable/disable wireless direct print through a web service call
- Added support for NFC and Tap to Print

FIXES:

Security/Authentication:

In the Embedded Web Serve when setting/clearing the admin password using the wizard (Networking>Settings>Wizard), the changes do not show up under the admin password under Security>General.

Base:

- You may see the device power cycles during a pull print process.
- When using AirPrint the printer may drop out of the available printer list.
- An ePrint document sent to the printer will always prompt to load paper despite the correct paper size being available in other Trays
- Printer hangs when using Parallel to USB cable
- Encrypted job storage jobs (from driver settings) do not delete after power cycle
- Color usage control via group permissions may not work correctly
- Web Services will not return the correct state for the Toner Collection Unit (TCU) when it is low.
- e-Print not be able to communicate with HPePrintCenter.com, Registration process timeout. Please try again.
- Device is displaying copy screen in the presence of a FIH device with no credits and it does not change the credit state when a credit is added.
- A Stored Job image preview may be inverted when previewed.
- email address of printer is missing from Control Panel
- An "Out of Space" message or a blank firmware revision string may be seen when loading a firmware image after a attempt with a corrupted image.
- An intermittent 49.38.07 may occur when upgrading Firmware via WJA when DSS is installed.
- You may see a 41.3 unexpected paper size error when sending a print job with the settings Any Size and a specific Media type.
- > Display brightness value not retained after reboot.

Embedded JetDirect:

- WJA cannot configure "Use Stateless DHCP when Manually Configured"
- > TCP acknowledgements are delayed or not sent
- Print and other TCP connections may be interrupted by Auto-Off
- > The counter Job-media-sheets is reported incorrectly

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20131122
	Firmware Revision: 2302243_421972
Embedded JetDirect:	JDI23200024
DC Controller:	4.96
Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.2

FIXES AND ENHANCEMENTS PROVIDED WITH PREVIOUS FIRMWARE REVISIONS:

NOTE: ALL IMPROVEMENTS WITH PREVIOUS REVISIONS OF FIRMWARE ARE INCLUDED WITHIN THE MOST CURRENT REVISIONS

The following new functionality or features are provided by this firmware release:

Firmware Datecode: 20130730

Firmware Revision: 2301104_394918

ENHANCEMENTS:

Base:

No New Updates - Original Release

Security/Authentication:

No New Updates - Original Release

Embedded JetDirect:

No New Updates - Original Release

FIXES:

Base:

No New Updates - Original Release

Security/Authentication:

> No New Updates - Original Release

Embedded letDirect:

No New Updates - Original

Current firmware revisions included in this firmware bundle:

DEVICE FIRMWARE REVISION

COMPONENT	FIRMWARE VERSION
HP CLJ M750 Series	Firmware Datecode: 20130730
	Firmware Revision: 2301104_394918
Embedded JetDirect:	JDI23100010
DC Controller:	4.96

Optional Trays:	3.103
HP Fleet Release Designation	FutureSmart Bundle Version 3.1

Installation Instructions

NOTE: Please be aware that an update in some circumstance may require ten minutes or more to complete.

You can send the firmware update to a device at any time; the device will wait for all I/O channels to become idle before cycling power.

Please print a configuration page prior to performing any firmware update. To print the configuration page:

- 1. Go to the printer's control panel.
- 2. Press the **Home** or **OK** button.
- 3. Scroll down to the **Administration** menu and press **OK**.
- 4. On the **Reports** menu press the **OK** button.
- 5. On the Configuration/Status Pages menu press OK.
- 6. Scroll down to the **Configuration page** option and press **OK**.
- 7. Scroll back up to the top to the **Print** option and press **OK**.

On the printed Configuration page look in the section marked "Device Information" for the Firmware Datecode and Firmware Revision. The Firmware Datecode and Firmware Revision will look something like this:

Firmware Datecode: 20130730

Firmware Revision: 2301104 394918

The elapsed time for an update depends on the I/O transfer time as well as the time that it takes for the printer to reinitialize. The I/O transfer time depend on the speed of the host computer sending the update and the I/O method (USB or network).

The re-initialization time will depend on the specific hardware configuration of the printer, such as the number of EIO devices installed, the presence of external paper handling devices, and the amount of memory installed. Finally, any print jobs ahead of the firmware job in the queue will be printed before the update is processed.

NOTE: When the update process has completed the LaserJet will need to be rebooted. Once the printer is back online, print a Configuration Page and verify that the new firmware has been installed.

Additional information to know

The firmware file will be in the following file format "xxxxxxx.bdl" where "xxx" indicates the firmware file name and the ".bdl" is the files extension.

This file requires an interactive update method. You cannot update the printer using the traditional FTP, LPR or Port 9100 methods of upgrading. Please use one of the following methods listed below to update the firmware of this device.

How to perform firmware upgrades.

Embedded Web Server: (control panel is at a Ready screen)

Please visit the following link to a view video on this firmware upgrade method explained below.

YouTube:

http://youtu.be/Gv6OprEg7Es

Brightcove:

http://link.brightcove.com/services/player/bcpid1190528646001?bctid=REFIDBC3707096437001

NOTE: Please be aware that an update in some circumstance may require ten minutes or more to complete.

After uncompressing the file you will see a xxxxxxx.bdl file.

- 1. Open an Internet Browser Window.
- 2. Enter the IP address in the URL line.
- 3. Select the **Firmware Upgrade** link from within the **Troubleshooting tab**.
- 4. Browse to the location that the firmware upgrade file was downloaded to, and then select the firmware file. Select the Install button to perform the upgrade.

NOTE: Do not close the Browser Window or interrupt communication until the Embedded Web Server displays the Confirmation Page.

 Select **Restart Now** from the EWS confirmation page, or turn the product off and then on again using the power switch. The printer will not automatically reboot.

Once the printer or MFP is back online, print a Configuration Page and verify that the new firmware has been installed.

Walk-up USB thumb drive: (Standard control panel menu)

Please visit the following link to view a video on this firmware upgrade method explained below.

YouTube:

http://youtu.be/IOsm1Z-dbJU

Brightcove:

http://link.brightcove.com/services/player/bcpid1190528646001?bctid=REFIDBC3707191411001

After uncompressing the file you will see a xxxxxxx.bdl file.

1. Copy the xxxxxxx.bdl file to a portable USB flash memory storage device (thumb drive).

NOTE: USB Flash Drives that are not in a Fat32 format or having a CD formatted partition may not be recognized by the printer. You may need to try a different USB flash drive.

- 2. Turn the printer ON.
- 3. Press the **Home** or **OK** button
- 4. Press the **Down** arrow to highlight **Device Maintenance**, and then press **OK**.
- 5. Press the **Down** arrow to highlight **USB Firmware Upgrade**, and then press **OK**
- 6. Insert the portable USB storage device with the xxxxxxx.bdl file on it into the USB port on the front of the product, and then press **OK**.
- 7. Press the **Down** arrow to highlight the xxxxxxx.bdl file, and then press **OK**.

NOTE: If there is more than one xxxxxxx.bdl file on the storage device, make sure that you select the correct file for this product.

8. A prompt to upgrade an older, newer, or reinstall the same version appears. Press the **Down** arrow button to highlight the desired option, and then press **OK**. When the upgrade is complete, the printer will reboot automatically.

NOTE: The upgrade process may take 10 or more minutes to complete. Please do not interrupt the updating process.

Once the printer or MFP is back online, print a Configuration Page and verify that the new firmware has been installed.

Pre-Boot walk-up USB thumb drive: (control panel Pre-Boot menu)

NOTE: Only to be used if the printer is not able to boot to READY

After uncompressing the file you will see a xxxxxxx.bdl file.

1. Copy the xxxxxxx.bdl file to a portable USB flash memory storage device (thumb drive) in the root directory.

NOTE: USB Flash Drives that are not in a Fat32 format or having a CD formatted partition may not be recognized by the printer. You may need to try a different USB flash drive.

- 2. Turn the printer ON.
- 3. Press the **Stop** button when the Ready, Data and Attention LEDs illuminate solid.
- 4. Press the **Down** button to highlight **Administrator**, and then press **OK**.
- 5. Press the **Down** button to highlight **Download**, and then press **OK**.
- 6. Insert the portable USB storage device with the xxxxxxx.bdl file on it.

NOTE: Please make sure the firmware file is located in the root directory of the flash drive. If you have more than one .bdl file on your USB flash drive, select the file you want loaded and press OK.

Please be patient since this may take up to 10 minutes to reboot.

- 7. Press the **Down** button to highlight **USB Thumbdrive**, and then press **OK**.
- 8. Press the **Down** button to highlight the xxxxxxx.bdl file, and then press **OK**.

NOTE: If you have more than one .bdl file on your USB Thumb drive, select the file you want loaded and press **OK**.

Please be patient since this may take up to 10 minutes to reboot.

- 9. When the message **Complete** appears on the control panel display, press the **Back** button 3 times.
- 10. When the message **Continue** appears on the control panel display, press **OK**.
- 11. The printer will continue to boot to the Ready state.

Once the printer or MFP is back online, print a Configuration Page and verify that the new firmware has been installed.

Web Jetadmin (Supported with version 10.3 SR4 or newer)

Please visit <u>www.hp.com</u> and type "Web Jet Admin" in the "Search" Box to find more information about new releases of Web Jetadmin and the release note information for those releases.

Upgrading Firmware:

- 1. Start Web Jetadmin 10.3 SR4 or newer
- 2. From the "Device Management" section, select "All Devices" (or the appropriate device group). An "All Devices" list will appear in the center window.
- 3. Find your device in the list, or type the IP address of the device in the Quick Device Discovery section in the lower-left of the screen (this will highlight your device in the device list). You can sort the device list by clicking on a column name at the top.
- 4. If your device list is sorted my model number, you may select multiple devices with the same model number by Control-Click or Shift-Click.
- 5. Right-click on the device and select "Upgrade firmware...".
- 6. An Upgrade Firmware window will appear. Select "Device firmware" and click "Next"
- 7. A list of available firmware will appear. If the correct version is listed, click "Next", and the upgrade process will start.

NOTE: If the correct firmware version does not appear within the list, you will need to manually upload it into WJA. New firmware may be available on an FTP site prior to appearing on hp.com. The instructions below allow you to upload a firmware file from your local PC to WJA 10.3 SR4 or newer

<u>Uploading new firmware files into WJA:</u>

- 1. Click on "Firmware/Firmware Repository" in the "Device Management" pane
- 2. A "Firmware Repository" window will appear in the center of the screen
- 3. Click on "Upload" in the upper-right of the window
- 4. Browse to the .bdl file on your local PC
- 5. Click "Upload"
- 6. Once the .bdl file is uploaded, go back to step 2 in the first section and complete steps 2 through 6.

NOTE: Do not turn printer off during the update process! When the update process is complete, the printer will automatically reboot. If the firmware update process fails, Web JetAdmin will provide notification with a page (screen) of information regarding the reason(s) for failure. A link will be provided to attempt the process again.

System Requirements

The Firmware upgrade process requires a network or USB port connection.

Technical Assistance

Some of the services below are provided for the United States only. Similar services to those listed below are available in other countries. See your printer's user guide or call your local authorized HP dealer.

Customer Support

See your printer's user guide or call your local authorized HP dealer.

Internet

An anonymous FTP library service is available worldwide for around-the-clock-access to drivers and technical support information for HP peripheral and computer products. Please note that paths may change without notice. Access the Internet or FTP address and use the menus to locate the software or support of your choice.

URL for HP LaserJet Enterprise M750 MFP Series Support:

URL for Support:

http://www.hp.com/go/support

URL for Access HP: http://www.hp.com

FTP address: ftp.hp.com

Login: anonymous

Password: your Internet email address

Additional Information

Refer to your printer's user guide for additional methods of obtaining software and support information, such as printer driver distribution centers other online services, fax services, and other online support.

Legal Statements

Trademark Notices

MS-DOS, Windows, Windows 2000, Excel 2000, Microsoft Office, Windows Server 2003, Outlook, PScript and Internet Explorer are registered trademarks of Microsoft Corporation in the United States and/or other countries.

PostScript is a registered trademark of Adobe Systems Incorporated.

Quark and QuarkXpress are trademarks of Quark Inc.

Mac, Macintosh and Safari are registered trademarks of Apple Computer, Inc.

The Adobe logo, Acrobat, the Adobe PDF logo, Distiller, and Reader are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States and/or other countries.

Novell is a registered trademark of Novell, Inc., in the United States and other countries. Netscape Navigator, is a registered trademark of Netscape Communications Corporation in the United States and other countries.

OPEN-SOURCE SOFTWARE LICENSE AGREEMENTS (In English) can be found here:

ftp://ftp.hp.com/pub/softlib/software12/licenses/OpenSourceLicenses.pdf

License and Copyright

© Copyright 2013 Hewlett-Packard Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein