



Wireless Gecko™ EFR32FG28 Errata



This document contains information on the EFR32FG28 errata. The latest available revision of this device is revision A.

Errata that have been resolved remain documented and can be referenced for previous revisions of this device.

The device data sheet explains how to identify the chip revision, either from the package marking or electronically.

Errata effective date: June, 2025.

1. Errata Summary

The following table lists all the known and unresolved errata for the EFR32FG28.

Table 1.1. Errata Overview

Designator	Title/Problem	Workaround Exists	Exists on Revision
			A
LCD_E301	LOADBUSY Status Goes Inactive Early With Prescaled Clock	Yes	X
SE_E302	DPA Countermeasure Unavailable for Some Operations	Yes	X
USART_E304	PRS Transmit Unavailable in Synchronous Secondary Mode	No	X

2. Current Errata Descriptions

2.1 LCD_E301 — LOADBUSHY Status Goes Inactive Early With Prescaled Clock

Description of Errata
The LCD_STATUS_LOADBUSY bit erroneously reports completion of writes to the LCD_BACTRL, LCD_AREGA, LCD_AREGB, and LCD_SEGDn registers before synchronization is complete when LCD_CTRL_PRESCALE > 3.
Affected Conditions / Impacts
If LOADBUSHY is used to gate consecutive writes to one of the affected registers, only the data associated with the last write is guaranteed to be latched into the register.
Workaround
For each write to one of the affected registers, insert a delay equal to $\text{LCD_CTRL_PRESCALE} \div f_{\text{LCDCLK}}$ after LOADBUSHY transitions from 1 to 0 before issuing the next write to the same register. Note: LOADBUSHY reports when data written from the PCLK register domain into the LCD controller's low-frequency clock domain has been synchronized. It does not indicate when data written into one of the affected registers is actually driven on the LCD controller pins. In cases where writes to these registers, such as LCD_SEGDn, are intended to have the change in pin state be observable on the connected display, LOADBUSHY should not be used to gate consecutive writes. Instead, the CPU should issue the register write and wait to issue the next write until a display update event or frame counter update event occurs as reported by the LCD_IF register DISPLAY or FC flag bits. Interrupts associated with these flags can and should be enabled in such cases to minimize energy use by keeping the CPU in a low-energy mode (e.g., EM2) between such consecutive register writes.
Resolution
There is currently no resolution for this issue.

2.2 SE_E302 – DPA Countermeasure Unavailable for Some Operations

Description of Errata
Differential power analysis (DPA) countermeasures for ECDH on Curve25519, ECDH on Curve448, and EdDSA signing on Curve25519 are unavailable due to a lack of hardware support on all Series 2 devices with a Hardware Secure Engine (HSE).
Affected Conditions / Impacts
A successful DPA attack may be possible if the impacted algorithms are implemented in a customer's product. However, a DPA attack is not an easy/straightforward attack as it requires specific equipment, many traces, physical access to the device, and some control over device operation. If a successful DPA attack occurs, an attacker may be able to gain access to confidential information, such as private keys or encrypted communications between devices.
Workaround
No fix is available to provide the affected DPA countermeasures on Series 2 devices. Refer to Security Advisory A-00000534 for mitigation recommendations, which include refreshing key pairs or using a key pair only once to reduce the risk of a successful DPA attack.
Resolution
There is currently no resolution for this issue.

2.3 USART_E304 — PRS Transmit Unavailable in Synchronous Secondary Mode

Description of Errata
When the USART is configured for synchronous secondary operation, the transmit output (MISO) is not driven if the signal is routed to a pin using the PRS producer (e.g., SOURCESEL = 0x20 and SIGSEL = 0x4 for USART0).
Affected Conditions / Impacts
Systems cannot operate the USART in synchronous secondary mode if the PRS is used to route the transmit output to the RX (MISO) pin. Operation is not affected in main mode when the transmit output is routed to the TX (MOSI) pin using the PRS producer nor is operation affected in any mode when the GPIO_USARTn_RXROUTE and GPIO_USARTn_TXROUTE registers are used.
Workaround
There is currently no workaround for this issue.
Resolution
There is currently no resolution for this issue.

3. Revision History

Revision 0.2

June, 2025

- Added [SE_E302](#).
- Added [USART_E304](#).

Revision 0.1

February, 2023

- Initial release.

Simplicity Studio

One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



IoT Portfolio
www.silabs.com/iot



SW/HW
www.silabs.com/simplicity



Quality
www.silabs.com/quality



Support & Community
www.silabs.com/community

Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice to the product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Without prior notification, Silicon Labs may update product firmware during the manufacturing process for security or reliability reasons. Such changes will not alter the specifications or the performance of the product. Silicon Labs shall have no liability for the consequences of use of the information supplied in this document. This document does not imply or expressly grant any license to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any FDA Class III devices, applications for which FDA premarket approval is required or Life Support Systems without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons. Silicon Labs disclaims all express and implied warranties and shall not be responsible or liable for any injuries or damages related to use of a Silicon Labs product in such unauthorized applications.

Trademark Information

Silicon Laboratories Inc., Silicon Laboratories®, Silicon Labs®, SiLabs® and the Silicon Labs logo®, Bluegiga®, Bluegiga Logo®, EFM®, EFM32®, EFR, Ember®, Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Redpine Signals®, WiSeConnect, n-Link, EZLink®, EZRadio®, EZRadioPRO®, Gecko®, Gecko OS, Gecko OS Studio, Precision32®, Simplicity Studio®, Telegesis, the Telegesis Logo®, USBXpress®, Zentri, the Zentri logo and Zentri DMS, Z-Wave®, and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. Wi-Fi is a registered trademark of the Wi-Fi Alliance. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc.
400 West Cesar Chavez
Austin, TX 78701
USA

www.silabs.com