

4. Rotary Switch:

A rotary switch is used to select measurement function and range switch.

5. Display:


3½ digit (1999), decimal point, minus polarity, overrange and LO BAT indicators.

6. V.O. -Ω- Input Connector:

High input for all voltage, diode, continuity, measurement will accept banana plugs.

7. COM Input Connector:

Low input for all voltage, resistance, diode, continuity, measurement will accept banana plugs.



-5-

The meter is completely portable, LCD, 3½ digit clamp meter. It has rugged design, is easy to hold in operator's hand and convenient to use.

1. Safety Information

- 1.1 Read the following safety information carefully before attempting to operate or service the meter.
- 1.2 To avoid damages to the instrument do not exceed the maximum limits of the input values shown in the technical specifications tables.
- 1.3 Never measure current while the test leads are inserted into the input jacks.
- 1.4 Do not use the meter or test leads if they look damaged. Use extreme caution when working around bare conductors or bus bars.
- 1.5 Caution when working with voltages above 60VDC or 30VAC RMS. Such voltages pose a shock hazard.

2. Operating Features

AC Current	0.01A to 400A
AC Voltage	TV to 450V
DC Voltage	TV to 800V

The meter display is a liquid crystal assembly providing a readability display in all light conditions. The decimal point is automatically positioned, and the polarity sign (minus) is lighted for negative DC

-1-

4.1 AC Current Measurement

1. Make sure that "Data Hold" switch is not pressed.
2. Set the range switch to 2, 20A, 200A or 400A.

Press the trigger to open the transformer jaws and clamp one conductor only. It is impossible to make measurements when two or three conductors are clamped at the same time.

4.2 AC Voltage Measurement

1. Connect the black test lead to the COM jack and the red test lead to the V-Ω- jack.
2. Set the range switch to AC450V or DC800V.
3. Touch the tips of the test leads to the circuit under test.
4. Read the display.

4.3 Diode/Continuity measurement

1. Connect the black test lead to the COM jack and the red test lead to the V-Ω- jack.
2. Set the range switch to "1" -Ω-.
3. Diode measurement the meter will show the approx. forward voltage of the diode. If the lead connection is reversed, only figure "1" displayed.
4. Continuity measurement The beeper sounds below about 75Ω (K78 night buzzer).

4.4 Resistance Measurement

1. Connect the black test lead to the COM jack and the red test lead to the VΩ-Ω- jack.
2. Set the rotary switch at desired Ω position and test

-6-

measurement plus is undertaken if no sign appears, so that the display is direct reading in units selected at the rotary switch. Overrange measurements are indicated by blanking all but the MSD decimal point, and polarity sign (if negative). In addition the display includes a low battery indication. If low battery is indicated, operator should replace the used battery with new one.

3. Specifications

The following Specifications assume a one year calibration cycle and an operating temperature of 54°F to 62°F (10°C to 26°C) at relative humidity up to 80% unless otherwise noted.

3.1 AC Current (Average sensing, calibrated to rms of sine wave)

Range	Resolution	Accuracy (50Hz - 60Hz)
20A	10mA	± (2% of reading +5 digits)
200A	100mA	± (2.5% of reading +5 digits)
400A	1A	± (3% of reading +5 digits)

(Overload protection: 400A on all ranges)

3.2 AC Voltage (Average sensing, calibrated to rms of sine wave)

Range	Resolution	Accuracy (50Hz - 500Hz)
450V	TV	± (2% reading +4 digits)

Input impedance: 9MΩ

Overload protection: 450V AC/DC on all ranges.

-2-

leads across the resistor under measurement.

NOTE:

1. If the resistance being measured exceeds the maximum value of the range selected or the input connected, an overrange indication "1" will be displayed.

2. When checking in-circuit resistances, be sure circuit under test has all power removed and that all capacitors have been discharged fully.

4.5 How to Use Data Hold Function

On all ranges, you can hold a reading on the display using Data Hold function.

1. While making measurement, press the Data Hold switch. The last reading remains held on the display, with a Hold symbol (an arrow mark) shown on the display.
2. Press the Data Hold switch again to exit from Data Hold function.

-7-

Digital Clamp - on Multimeter MODEL 87



Instruction Manual

Reading Rate: 3 reading/sec

Polarity: Automatic, indicated minus, assumed plus
Overload indication: Blanking of all digits, except MSD, decimal point and sign

Power requirements: 1.5V x 2

Battery indication: Display indicates when approximately 20% of battery life remains

Display: LCD, 3½ digit (1999 count)

Data hold: All function and ranges with this feature

Dimension: 190 x 63 x 28mm (L x W x H)

approx

Weight: 145 grams (including battery, approx)

3.9 Accessories

Instruction manual

Test leads

AAA 1.5V x 2

4. Operation and Resolution

1. Transformer Jaws:
Pick up the AC current flowing through the conductor.
2. Trigger:
Press the lever to open the transformer jaws. When the lever is released, the jaws will close again.
3. Data Hold Switch:
A push switch, (push on, do not pull to select function). All function and ranges with this feature.

-8-