


Σ -7-Series AC Servo Drive Linear Servomotor Product Manual

Model: SGLG/SGLF/SGLT



Basic Information on Servomotors	1
Capacity Selection	2
Specifications, Ratings, and External Dimensions of SGLG Servomotors	3
Specifications, Ratings, and External Dimensions of SGLF Servomotors	4
Specifications, Ratings, and External Dimensions of SGLT Servomotors	5
Equipment Design Precautions	6
Servomotor Installation	7
Connecting Linear Encoders	8
Connections between Servomotors and SERVOPACKs	9
Maintenance and Inspection	10

Copyright © 2014 YASKAWA ELECTRIC CORPORATION

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form, or by any means, mechanical, electronic, photocopying, recording, or otherwise, without the prior written permission of Yaskawa. No patent liability is assumed with respect to the use of the information contained herein. Moreover, because Yaskawa is constantly striving to improve its high-quality products, the information contained in this manual is subject to change without notice. Every precaution has been taken in the preparation of this manual. Nevertheless, Yaskawa assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of the information contained in this publication.

About this Manual

This manual provides information required to select, install, connect, and maintain Linear Servomotors for Σ -7-Series AC Servo Drives.

Read and understand this manual to ensure correct usage of the Σ -7-Series AC Servo Drives.

Keep this manual in a safe place so that it can be referred to whenever necessary.

Outline of Manual


The contents of the chapters of this manual are described in the following table.

Refer to these chapters as required.

Chapter	Chapter Title	Contents
1	Basic Information on Servomotors	Provides basic information on Linear Servomotors, including Servomotor part names and combinations with SERVOPACKs.
2	Capacity Selection	Describes calculation methods to use when selecting Servomotor capacities.
3	Specifications, Ratings, and External Dimensions of SGLG Servomotors	Describes how to interpret the model numbers of SGLG Servomotors and gives their specifications, ratings, and external dimensions.
4	Specifications, Ratings, and External Dimensions of SGLF Servomotors	Describes how to interpret the model numbers of SGLF Servomotors and gives their specifications, ratings, and external dimensions.
5	Specifications, Ratings, and External Dimensions of SGLT Servomotors	Describes how to interpret the model numbers of SGLT Servomotors and gives their specifications, ratings, and external dimensions.
6	Equipment Design Precautions	Provides precautions for equipment design.
7	Servomotor Installation	Describes the installation conditions, procedures, and precautions for Servomotors.
8	Connecting Linear Encoders	Describes the conditions and procedures for mounting linear encoders.
9	Connections between Servomotors and SERVOPACKs	Describes the cables that are used to connect the Servomotors and SERVOPACKs. It also provides information on peripheral devices and provides related precautions.
10	Maintenance and Inspection	Describes the maintenance, inspection, and disposal of a Servomotor.

Related Documents

The relationships between the documents that are related to the Servo Drives are shown in the following figure. The numbers in the figure correspond to the numbers in the table on the following pages. Refer to these documents as required.



Classification	Document Name	Document No.	Description
① Machine Controller and Servo Drive General Catalog	Machine Controller and AC Servo Drive Solutions Catalog	KAEP S800001 22	Describes the features and application examples for combinations of MP3000-Series Machine Controllers and Σ -7-Series AC Servo Drives.
② MP3300 Catalog	Machine Controller MP3300	KAEP C880725 03	Provides detailed information on MP3300 Machine Controllers, including features and specifications.
③ Σ -7-Series Catalog	AC Servo Drives Σ -7 Series	KAEP S800001 23	Provides detailed information on Σ -7-Series AC Servo Drives, including features and specifications.
④ Built-in Function Manuals	Σ -7-Series AC Servo Drive Σ -7C SERVOPACK Motion Control User's Manual	SIEP S800002 03	Provides detailed information on the specifications, system configuration, and application methods of the Motion Control Function Modules (SVD, SVC4, and SVR4) for Σ -7-Series Σ -7C SERVOPACKs.
	Machine Controller MP3000 Series Communications User's Manual	SIEP C880725 12	Provides detailed information on the specifications, system configuration, and communications connection methods for the Ethernet communications that are used with MP3000-Series Machine Controllers and Σ -7-Series Σ -7C SERVOPACKs.
⑤ Option Module User's Manuals	Machine Controller MP2000 Series Communication Module User's Manual	SIEP C880700 04	Provide detailed information on the specifications and communications methods for the Communications Modules that can be mounted to MP3000-Series Machine Controllers and Σ -7-Series Σ -7C SERVOPACKs.
	Machine Controller MP2000 Series 262IF-01 FL-net Communication Module User's Manual	SIEP C880700 36	
	Machine Controller MP2000 Series 263IF-01 EtherNet/IP Communication Module User's Manual	SIEP C880700 39	
	Machine Controller MP2000 Series I/O Module User's Manual	SIEP C880700 34	Provide detailed information on the specifications and communications methods for the I/O Modules that can be mounted to MP3000-Series Machine Controllers and Σ -7-Series Σ -7C SERVOPACKs.
	Machine Controller MP2000 Series Analog Input/Analog Output Module AI-01/AO-01 User's Manual	SIEP C880700 26	
	Machine Controller MP2000 Series Counter Module CNTR-01 User's Manual	SIEP C880700 27	

Continued on next page.

Continued from previous page.

Classification	Document Name	Document No.	Description
⑥ Enclosed Documents	Σ-7-Series AC Servo Drive Σ-7S and Σ-7W SERVOPACK Safety Precautions	TOMP C710828 00	Provides detailed information for the safe usage of Σ-7-Series SERVOPACKs.
	Σ-V-Series/Σ-V-Series for Large-Capacity Models/ Σ-7-Series Safety Precautions Option Module	TOBP C720829 00	Provides detailed information for the safe usage of Option Modules.
	Σ-V-Series/Σ-V-Series for Large-Capacity Models/ Σ-7-Series Installation Guide Command Option Module	TOBP C720829 01	Provides detailed procedures for installing the Command Option Module in a SERVOPACK.
	Σ-V-Series/Σ-V-Series for Large-Capacity Models/ Σ-7-Series Installation Guide Fully-closed Module	TOBP C720829 03	Provides detailed procedures for installing the Fully-closed Module in a SERVOPACK.
	Σ-V-Series/Σ-V-Series for Large-Capacity Models/ Σ-7-Series Installation Guide Safety Module	TOBP C720829 06	Provides detailed procedures for installing the Safety Module in a SERVOPACK.
	Σ-V-Series/Σ-V-Series for Large-Capacity Models/ Σ-7-Series Installation Guide INDEXER Module	TOBP C720829 02	Provides detailed procedures for installing the INDEXER Module in a SERVOPACK.
	Σ-V-Series/Σ-V-Series for Large-Capacity Models/ Σ-7-Series Installation Guide DeviceNet Module	TOBP C720829 07	Provides detailed procedures for installing the DeviceNet Module in a SERVOPACK.
⑦ Σ-7-Series Σ-7C SERVOPACK Product Manual	Σ-7-Series AC Servo Drive Σ-7C SERVOPACK Product Manual	SIEP S800002 04	Provides detailed information on selecting Σ-7-Series Σ-7C SERVOPACKs; installing, connecting, setting, testing in trial operation, and tuning Servo Drives; writing, monitoring, and maintaining programs; and other information.
⑧ Σ-7-Series Σ-7C SERVOPACK Troubleshooting Manual	Σ-7-Series AC Servo Drive Σ-7C SERVOPACK Troubleshooting Manual	SIEP S800002 07	Provides detailed troubleshooting information for Σ-7-Series Σ-7C SERVOPACKs.

Continued on next page.

Continued from previous page.

Classification	Document Name	Document No.	Description
⑨ Σ-7-Series Σ-7S/Σ-7W SERVOPACK Product Manuals	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with MECHATROLINK-III Communications References Product Manual	SIEP S800001 28	Provide detailed information on selecting Σ-7-Series SERVO-PACKs and information on installing, connecting, setting, performing trial operation for, tuning, monitoring, and maintaining the Servo Drives.
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with MECHATROLINK-II Communications References Product Manual	SIEP S800001 27	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with Analog Voltage/Pulse Train References Product Manual	SIEP S800001 26	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK Command Option Attachable Type with INDEXER Module Product Manual	SIEP S800001 64	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK Command Option Attachable Type with DeviceNet Module Product Manual	SIEP S800001 70	
	Σ-7-Series AC Servo Drive Σ-7W SERVOPACK with MECHATROLINK-III Communications References Product Manual	SIEP S800001 29	
⑩ Σ-7-Series Σ-7S/Σ-7W SERVOPACK with Hardware Option Specifications Product Manuals	Σ-7-Series AC Servo Drive Σ-7S/Σ-7W SERVOPACK with Hardware Option Specifica- tions Dynamic Brake Product Manual	SIEP S800001 73	Provide detailed information on Hardware Options for Σ-7-Series SERVOPACKs.
	Σ-7-Series AC Servo Drive Σ-7W/Σ-7C SERVOPACK with Hardware Option Specifica- tions HWBB Function Product Manual	SIEP S800001 72	

Continued on next page.

Continued from previous page.

Classification	Document Name	Document No.	Description
⑩ Σ-7-Series Σ-7S/Σ-7W SERVOPACK FT/EX Product Manuals	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Index- ing Application Product Manual	SIEP S800001 84	Provide detailed information on the FT/EX Option for Σ-7-Series SERVOPACKs.
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Track- ing Application Product Manual	SIEP S800001 89	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Application with Special Motor, SGM7D Motor Product Manual	SIEP S800001 91	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Press and Injection Molding Application Product Manual	SIEP S800001 94	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Transfer and Alignment Application Product Manual	SIEP S800001 95	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Torque/Force Assistance for Conveyance Application Product Manual	SIEP S800002 09	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Cutting Application Feed Shaft Motor Product Manual	SIEP S800002 10	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Three-Point Latching for Conveyance Application Product Manual	SIEP S800002 17	
	Σ-7-Series AC Servo Drive Σ-7S SERVOPACK with FT/EX Specification for Semi-/Fully-Closed Loop Control Online Switching for Conveyance Application Product Manual	SIEP S800002 27	
	Σ-7-Series AC Servo Drive Σ-7W SERVOPACK with FT/EX Specification for Gantry Applications Product Manual	SIEP S800002 29	

Continued on next page.

Continued from previous page.

Classification	Document Name	Document No.	Description
⑫ Option Module User's Manual	AC Servo Drives Σ -V Series/ Σ -V Series for Large-Capacity Models/ Σ -7 Series User's Manual Safety Module	SIEP C720829 06	Provides details information required for the design and mainte- nance of a Safety Module.
⑬ Enclosed Documents	AC Servo Drive Rotary Servomotor Safety Precautions	TOBP C230260 00	Provides detailed information for the safe usage of Rotary Servomo- tors and Direct Drive Servomotors.
	AC Servomotor Linear Σ Series Safety Precautions	TOBP C230800 00	Provides detailed information for the safe usage of Linear Servomo- tors.
⑭ Σ -7-Series Servomotor Product Manuals	Σ -7-Series AC Servo Drive Rotary Servomotor Product Manual	SIEP S800001 36	Provide detailed information on selecting, installing, and connecting the Σ -7-Series Servomotors.
	Σ -7-Series AC Servo Drive Linear Servomotor Product Manual	This manual (SIEP S800001 37)	
	Σ -7-Series AC Servo Drive Direct Drive Servomotor Product Manual	SIEP S800001 38	
⑮ Σ -7-Series Peripheral Device Selection Manual	Σ -7-Series AC Servo Drive Peripheral Device Selection Manual	SIEP S800001 32	Provides the following information in detail for Σ -7-Series Servo Sys- tems. • Cables: Models, dimensions, wir- ing materials, connector models, and connection specifications • Peripheral devices: Models, specifications, diagrams, and selection (calculation) methods
⑯ Σ -7-Series MECHATROLINK Communications Command Manuals	Σ -7-Series AC Servo Drive MECHATROLINK-II Communications Command Manual	SIEP S800001 30	Provides detailed information on the MECHATROLINK-II communi- cations commands that are used for a Σ -7-Series Servo System.
	Σ -7-Series AC Servo Drive MECHATROLINK-III Communications Standard Servo Profile Command Manual	SIEP S800001 31	Provides detailed information on the MECHATROLINK-III communi- cations standard servo profile com- mands that are used for a Σ -7- Series Servo System.

Continued on next page.

Continued from previous page.

Classification	Document Name	Document No.	Description
⑰ Programming Manuals	Machine Controller MP3000 Series Ladder Programming Manual	SIEP C880725 13	Provides detailed information on the ladder programming specifications and instructions for MP3000-Series Machine Controllers and Σ -7-Series Σ -7C SERVOPACKs.
	Machine Controller MP3000 Series Motion Programming Manual	SIEP C880725 14	Provides detailed information on the motion programming and sequence programming specifications and instructions for MP3000-Series Machine Controllers and Σ -7-Series Σ -7C SERVOPACKs.
⑱ Σ -7-Series Operation Interface Operating Manuals	Machine Controller MP2000/MP3000 Series Engineering Tool MPE720 Version 7 User's Manual	SIEP C880761 03	Describes in detail how to operate MPE720 version 7.
	Σ -7-Series AC Servo Drive Digital Operator Operating Manual	SIEP S800001 33	Describes the operating procedures for a Digital Operator for a Σ -7-Series Servo System.
	AC Servo Drive Engineering Tool SigmaWin+ Operation Manual	SIET S800001 34	Provides detailed operating procedures for the SigmaWin+ Engineering Tool for a Σ -7-Series Servo System.
⑲ Distributed I/O Module User's Manual	MECHATROLINK-III Compatible I/O Module User's Manual	SIEP C880781 04	Describes the functions, specifications, operating methods, and MECHATROLINK-III communications for the Remote I/O Modules for MP2000/MP3000-Series Machine Controllers.

Using This Manual

◆ Technical Terms Used in This Manual

The following terms are used in this manual.

Term	Meaning
Servomotor	A Σ -7-Series Linear Servomotor.
SERVOPACK	A Σ -7-Series Servo Amplifier.
Servo Drive	The combination of a Servomotor and SERVOPACK.
Main Circuit Cable	One of the cables that connect to the main circuit terminals, including the Main Circuit Power Supply Cable, Control Power Supply Cable, and Servomotor Main Circuit Cable.

◆ Trademarks

- MECHATROLINK is a trademark of the MECHATROLINK Members Association.
- QR code is a trademark of Denso Wave Inc.
- Other product names and company names are the trademarks or registered trademarks of the respective company. "TM" and the ® mark do not appear with product or company names in this manual.

◆ Visual Aids

The following aids are used to indicate certain types of information for easier reference.



Indicates precautions or restrictions that must be observed.
Also indicates alarm displays and other precautions that will not result in machine damage.



Indicates definitions of difficult terms or terms that have not been previously explained in this manual.

Example Indicates operating or setting examples.

Information Indicates supplemental information to deepen understanding or useful information.

Safety Precautions

◆ Safety Information

To prevent personal injury and equipment damage in advance, the following signal words are used to indicate safety precautions in this document. The signal words are used to classify the hazards and the degree of damage or injury that may occur if a product is used incorrectly. Information marked as shown below is important for safety. Always read this information and heed the precautions that are provided.



DANGER

- Indicates precautions that, if not heeded, are likely to result in loss of life, serious injury, or fire.



WARNING

- Indicates precautions that, if not heeded, could result in loss of life, serious injury, or fire.



CAUTION

- Indicates precautions that, if not heeded, could result in relatively serious or minor injury, or in fire.

NOTICE

- Indicates precautions that, if not heeded, could result in property damage.

◆ Safety Precautions That Must Always Be Observed

■ General Precautions



DANGER

- Read and understand this manual to ensure the safe usage of the product.
- Keep this manual in a safe, convenient place so that it can be referred to whenever necessary. Make sure that it is delivered to the final user of the product.
- Do not remove covers, cables, connectors, or optional devices while power is being supplied to the SERVOPACK.
There is a risk of electric shock, operational failure of the product, or burning.



WARNING

- Connect the ground terminals on the SERVOPACK and Servomotor to ground poles according to local electrical codes (100 Ω or less for a SERVOPACK with a 100-VAC or 200-VAC power supply, and 10 Ω or less for a SERVOPACK with a 400-VAC power supply).
There is a risk of electric shock or fire.
- Do not attempt to disassemble, repair, or modify the product.
There is a risk of fire or failure.
The warranty is void for the product if you disassemble, repair, or modify it.



CAUTION

- The SERVOPACK heat sinks, regenerative resistors, External Dynamic Brake Resistors, Servomotors, and other components can be very hot while power is ON or soon after the power is turned OFF. Implement safety measures, such as installing covers, so that hands and parts such as cables do not come into contact with hot components.
There is a risk of burn injury.
- Do not damage, pull on, apply excessive force to, place heavy objects on, or pinch cables.
There is a risk of failure, damage, or electric shock.
- Do not use the product in an environment that is subject to water, corrosive gases, or flammable gases, or near flammable materials.
There is a risk of electric shock or fire.

NOTICE

- Do not attempt to use a SERVOPACK or Servomotor that is damaged or that has missing parts.
- Install external emergency stop circuits that shut OFF the power supply and stops operation immediately when an error occurs.
- Always use a Servomotor and SERVOPACK in one of the specified combinations.
- Do not touch a SERVOPACK or Servomotor with wet hands.
There is a risk of product failure.

■ Storage Precautions



CAUTION

- Store the Magnetic Way of a Linear Servomotor in the package that was used for delivery.
- Do not place an excessive load on the product during storage. (Follow all instructions on the packages.)
There is a risk of injury or damage.

NOTICE

- Do not install or store the product in any of the following locations.
 - Locations that are subject to direct sunlight
 - Locations that are subject to ambient temperatures that exceed product specifications
 - Locations that are subject to relative humidities that exceed product specifications
 - Locations that are subject to condensation as the result of extreme changes in temperature
 - Locations that are subject to corrosive or flammable gases
 - Locations that are near flammable materials
 - Locations that are subject to dust, salts, or iron powder
 - Locations that are subject to water, oil, or chemicals
 - Locations that are subject to vibration or shock that exceeds product specifications
 - Locations that are subject to radiation

If you store or install the product in any of the above locations, the product may fail or be damaged.
- Although machined surfaces are covered with an anticorrosive coating, rust can develop due to storage conditions or the length of storage. If you store the product for more than six months, reapply an anticorrosive coating to machined surfaces, particularly the core.
- Consult with your Yaskawa representative if you have stored products for an extended period of time.

■ Transportation Precautions



CAUTION

- Transport the product in a way that is suitable to the mass of the product.
- Do not hold onto the cables attached to the Moving Coil when you move a Linear Servomotor.
There is a risk of disconnection, damage, or injury.
- Make sure that the eyebolts are securely attached to the Linear Servomotor with no looseness before you use them to move the Linear Servomotor.
There is a risk of injury or damage.
- Do not use the eyebolts on a SERVOPACK or Servomotor to move the machine.
There is a risk of damage or injury.
- When you handle a SERVOPACK or Servomotor, be careful of sharp parts, such as the corners.
There is a risk of injury.
- Do not hold onto the magnet protective cover when you move a Magnetic Way.
There is a risk of injury from the edges of the cover. There is also a risk of deforming the cover.
- Do not place an excessive load on the product during transportation. (Follow all instructions on the packages.)
There is a risk of injury or damage.

NOTICE

- A SERVOPACK or Servomotor is a precision device. Do not drop it or subject it to strong shock.
There is a risk of failure or damage.
- Do not subject connectors to shock.
There is a risk of faulty connections or damage.
- If disinfectants or insecticides must be used to treat packing materials such as wooden frames, plywood, or pallets, the packing materials must be treated before the product is packaged, and methods other than fumigation must be used.
Example: Heat treatment, where materials are kiln-dried to a core temperature of 56°C for 30 minutes or more.
If the electronic products, which include stand-alone products and products installed in machines, are packed with fumigated wooden materials, the electrical components may be greatly damaged by the gases or fumes resulting from the fumigation process. In particular, disinfectants containing halogen, which includes chlorine, fluorine, bromine, or iodine can contribute to the erosion of the capacitors.
- Do not overtighten the eyebolts on a SERVOPACK or Servomotor.
If you use a tool to overtighten the eyebolts, the tapped holes may be damaged.

■ Installation Precautions



DANGER

- The Magnetic Way of a Linear Servomotor uses a strong permanent magnet. To ensure safety and prevent accidents, observe the following precautions when you install the Linear Servomotor.

If you have a heart pacemaker or any other electronic medical device, do not go near the location of or near a machine where the Magnetic Way of a Linear Servomotor is being used. The influence of the magnetism may cause the medical device to malfunction or fail.



CAUTION

- Make sure that there are no magnetic substances, such as pieces of iron, near the worksite before you unpack or install the Magnetic Way.
There is a risk of injury or damage to the magnets in the Magnetic Way due to the magnetic attraction of the Magnetic Way.
- Securely mount the Servomotor to the machine.
If the Servomotor is not mounted securely, it may come off the machine during operation.
- Use all of the mounting screw holes on the Linear Servomotor to mount the Servomotor to the machine.
There is a risk of damage or injury if the Servomotor is not mounted correctly.
- Do not use the mounting screw holes on a Linear Servomotor for any other purpose.
There is a risk of damage or injury if the Servomotor is not mounted correctly.
- The Magnetic Way of a Linear Servomotor uses a strong permanent magnet. To ensure safety and prevent accidents, observe the following precautions when you install the Linear Servomotor.
 - Do not bring magnetic substances (including Moving Coils and tools) near the Magnetic Way. There is a risk of serious injury (such as pinching your hand) due to the large magnetic attraction exerted by the magnetic side of the Magnetic Way. Pay sufficient attention to the worksite and surrounding area to prevent magnetic substances from approaching the Magnetic Way.
 - Use only nonmagnetic tools for all work.
- Install the Servomotor or SERVOPACK in a way that will support the mass given in technical documents.
- Install SERVOPACKs, Servomotors, regenerative resistors, and External Dynamic Brake Resistors on nonflammable materials.
Installation directly onto or near flammable materials may result in fire.
- Do not step on or place a heavy object on the product.
There is a risk of failure, damage, or injury.
- Do not allow any foreign matter to enter the SERVOPACK or Servomotor.
There is a risk of failure or fire.
- When you remove the dummy plates for reducing magnetic force from the Magnetic Way of an SGLF Linear Motor, be careful of the magnetic attraction of the Magnetic Way. Do not place the dummy plates close to the Magnetic Way after you remove them.
There is a risk of injury, damage to the magnets in the Magnetic Way, or damage to the magnet protective cover.
- Implement safety measures, such as installing a cover so that the Linear Servomotor cannot be touched accidentally during operation.

NOTICE

- Do not install or store the product in any of the following locations.
 - Locations that are subject to direct sunlight
 - Locations that are subject to ambient temperatures that exceed product specifications
 - Locations that are subject to relative humidities that exceed product specifications
 - Locations that are subject to condensation as the result of extreme changes in temperature
 - Locations that are subject to corrosive or flammable gases
 - Locations that are near flammable materials
 - Locations that are subject to dust, salts, or iron powder
 - Locations that are subject to water, oil, or chemicals
 - Locations that are subject to vibration or shock that exceeds product specifications
 - Locations that are subject to radiationIf you store or install the product in any of the above locations, the product may fail or be damaged.
- The Magnetic Way of a Linear Servomotor uses a strong permanent magnet. To ensure safety and prevent accidents, observe the following precautions when you install the Linear Servomotor.

Do not work on a Magnetic Way with electronic devices (such as clocks, calculators, or computers) or magnetic storage media (such as IC cards or magnetic cards) on your person or bring such devices or media near a Magnetic Way.

The influence of the magnetism may cause the device or media to malfunction or fail.
- Use the product in an environment that is appropriate for the product specifications.

If you use the product in an environment that exceeds product specifications, the product may fail or be damaged.
- A SERVOPACK or Servomotor is a precision device. Do not drop it or subject it to strong shock.

There is a risk of failure or damage.
- In an application where the Servomotor would be subjected to large quantities of water or oil, implement measures to protect the Servomotor from large quantities of liquid, such as installing covers to protect against water and oil.
- In an environment that contains magnetic substances, such as iron cuttings or powder, implement measures to prevent the magnetic substances from adhering to or entering the product. Be particularly careful not to let foreign matter, such as metals, enter the gaps between a Magnetic Way and Moving Coil.

If foreign material adheres in the gaps between a Moving Coil and Magnetic Way, operation may stop or burning may occur.

■ Wiring Precautions



DANGER

- Do not change any wiring while power is being supplied.

There is a risk of electric shock or injury.



WARNING

- Wiring and inspections must be performed only by qualified engineers.

There is a risk of electric shock or product failure.



CAUTION

- Observe the precautions and instructions for wiring and trial operation precisely as described in this document.
Failures caused by incorrect wiring or incorrect voltage application in the brake circuit may cause the SERVOPACK to fail, damage the equipment, or cause an accident resulting in death or injury.
- Check the wiring to be sure it has been performed correctly.
Connectors and pin layouts are sometimes different for different models. Always confirm the pin layouts in technical documents for your model before operation.
There is a risk of failure or malfunction.
- Connect wires to power supply terminals and motor connection terminals securely with the specified methods and tightening torque.
Insufficient tightening may cause wires and terminal blocks to generate heat due to faulty contact, possibly resulting in fire.
- Use shielded twisted-pair cables or screened unshielded multi-twisted-pair cables for I/O Signal Cables and Encoder Cables.
- The maximum wiring length is 3 m for I/O Signal Cables, and 50 m for Encoder Cables or Servo-motor Main Circuit Cables.
- Observe the following precautions when wiring the SERVOPACK's main circuit terminals.
 - Turn ON the power supply to the SERVOPACK only after all wiring, including the main circuit terminals, has been completed.
 - If a connector is used for the main circuit terminals, remove the main circuit connector from the SERVOPACK before you wire it.
 - Insert only one wire per insertion hole in the main circuit terminals.
 - When you insert a wire, make sure that the conductor wire (e.g., whiskers) does not come into contact with adjacent wires.

NOTICE

- Whenever possible, use the Cables specified by Yaskawa.
If you use any other cables, confirm the rated current and application environment of your model and use the wiring materials specified by Yaskawa or equivalent materials.
- Securely tighten cable connector screws and lock mechanisms.
Insufficient tightening may result in cable connectors falling off during operation.
- Do not bundle power lines (e.g., the Main Circuit Cable) and low-current lines (e.g., the I/O Signal Cables or Encoder Cables) together or run them through the same duct. If you do not place power lines and low-current lines in separate ducts, separate them by at least 30 cm.
If the cables are too close to each other, malfunctions may occur due to noise affecting the low-current lines.
- For a motor with a built-in temperature sensor, use the temperature sensor to protect the motor from overheating.
- Secure the cable from the Moving Coil of the Linear Servomotor so that it moves together with the Moving Coil.
There is a risk of cable disconnection.

■ Operation Precautions



WARNING

- Before starting operation with a machine connected, change the settings of the switches and parameters to match the machine.
Unexpected machine operation, failure, or personal injury may occur if operation is started before appropriate settings are made.
- Do not radically change the settings of the parameters.
There is a risk of unstable operation, machine damage, or injury.
- Install limit switches or stoppers at the ends of the moving parts of the machine to prevent unexpected accidents.
There is a risk of machine damage or injury.
- Forcing the motor to stop for overtravel is disabled when the Jog, Origin Search, or Easy FFT utility function is executed. Take necessary precautions.
There is a risk of machine damage or injury.
- When an alarm occurs, the Servomotor will coast to a stop or stop with the dynamic brake according to the SERVOPACK Option specifications and settings. The coasting distance will change with the moment of inertia of the load and the resistance of the External Dynamic Brake Resistor. Check the coasting distance during trial operation and implement suitable safety measures on the machine.
- Do not enter the machine's range of motion during operation.
There is a risk of injury.
- Do not touch the moving parts of the Servomotor or machine during operation.
There is a risk of injury.



CAUTION

- Always turn OFF the servo before you turn OFF the power supply. If you turn OFF the main circuit power supply or control power supply during operation before you turn OFF the servo, the Servomotor will stop as follows:
 - If you turn OFF the main circuit power supply during operation without turning OFF the servo, the Servomotor will stop abruptly with the dynamic brake.
 - If you turn OFF the control power supply without turning OFF the servo, the stopping method that is used by the Servomotor depends on the model of the SERVOPACK. For details, refer to the manual for the SERVOPACK.
- Linear Servomotors do not have holding brakes. If the load mass is large or the speed is high, the coasting distance will increase even if you perform a rapid stop with a dynamic brake. Install safety devices (external brakes or stoppers) so that the ends of the moving parts of the machine will not strike anything.

NOTICE

- Always measure the vibration of the Servomotor with the Servomotor mounted to the machine and confirm that the vibration is within the allowable value.
If the vibration is too large, the Servomotor will be damaged quickly and bolts may become loose.
- When you adjust the gain during system commissioning, use a measuring instrument to monitor the torque waveform and speed waveform and confirm that there is no vibration.
If a high gain causes vibration, the Servomotor will be damaged quickly.
- If a high gain causes vibration, the Servomotor will be damaged quickly. An alarm or warning may occur if communications are performed with the host controller while the SigmaWin+ or Digital Operator is operating.
If an alarm or warning occurs, it may interrupt the current process and stop the system.

■ Maintenance and Inspection Precautions



DANGER

- Do not change any wiring while power is being supplied.
There is a risk of electric shock or injury.



WARNING

- Wiring and inspections must be performed only by qualified engineers.
There is a risk of electric shock or product failure.
- If you replace a Linear Servomotor, secure the machine before you replace the Servomotor.
There is a risk of injury or equipment damage if the equipment falls.



CAUTION

- Wait for at least six minutes after turning OFF the power supply (with a SERVOPACK for a 100-VAC power supply input, wait for at least nine minutes) and then make sure that the CHARGE indicator is not lit before starting wiring or inspection work. Do not touch the power supply terminals while the CHARGE lamp is lit because high voltage may still remain in the SERVOPACK even after turning OFF the power supply.
There is a risk of electric shock.

■ Troubleshooting Precautions



WARNING

- The product may suddenly start to operate when the power supply is recovered after a momentary power interruption. Design the machine to ensure human safety when operation restarts.
There is a risk of injury.



CAUTION

- When an alarm occurs, remove the cause of the alarm and ensure safety. Then reset the alarm or turn the power supply OFF and ON again to restart operation.
There is a risk of injury or machine damage.
- If the Servo ON signal is input to the SERVOPACK and an alarm is reset, the Servomotor may suddenly restart operation. Confirm that the servo is OFF and ensure safety before you reset an alarm.
There is a risk of injury or machine damage.
- If there is the possibility that an external force (including gravity) may move the current position and create a hazardous situation when power is interrupted or an error occurs, install an external braking mechanism that ensures safety.

■ Disposal Precautions



CAUTION

- When you dispose of a Linear Servomotor, heat the Magnetic Way to 300°C or higher for one hour to demagnetize it.
There is a risk of injury from the strong magnetic attraction.

- Correctly discard the product as stipulated by regional, local, and municipal laws and regulations. Be sure to include these contents in all labelling and warning notifications on the final product as necessary.



■ General Precautions

- Figures provided in this document are typical examples or conceptual representations. There may be differences between them and actual wiring, circuits, and products.
- The products shown in illustrations in this document are sometimes shown without covers or protective guards. Always replace all covers and protective guards before you use the product.
- If you need a new copy of this document because it has been lost or damaged, contact your nearest Yaskawa representative or one of the offices listed on the back of this document.
- This document is subject to change without notice for product improvements, specifications changes, and improvements to the manual itself.
We will update the document number of the document and issue revisions when changes are made.
- Any and all quality guarantees provided by Yaskawa are null and void if the customer modifies the product in any way. Yaskawa disavows any responsibility for damages or losses that are caused by modified products.

Warranty

◆ Details of Warranty

■ Warranty Period

The warranty period for a product that was purchased (hereinafter called the “delivered product”) is one year from the time of delivery to the location specified by the customer or 18 months from the time of shipment from the Yaskawa factory, whichever is sooner.

■ Warranty Scope

Yaskawa shall replace or repair a defective product free of charge if a defect attributable to Yaskawa occurs during the above warranty period.

This warranty does not cover defects caused by the delivered product reaching the end of its service life and replacement of parts that require replacement or that have a limited service life.

This warranty does not cover failures that result from any of the following causes.

- Improper handling, abuse, or use in unsuitable conditions or in environments not described in product catalogs or manuals, or in any separately agreed-upon specifications
- Causes not attributable to the delivered product itself
- Modifications or repairs not performed by Yaskawa
- Use of the delivered product in a manner in which it was not originally intended
- Causes that were not foreseeable with the scientific and technological understanding at the time of shipment from Yaskawa
- Events for which Yaskawa is not responsible, such as natural or human-made disasters

◆ Limitations of Liability

- Yaskawa shall in no event be responsible for any damage or loss of opportunity to the customer that arises due to failure of the delivered product.
- Yaskawa shall not be responsible for any programs (including parameter settings) or the results of program execution of the programs provided by the user or by a third party for use with programmable Yaskawa products.
- The information described in product catalogs or manuals is provided for the purpose of the customer purchasing the appropriate product for the intended application. The use thereof does not guarantee that there are no infringements of intellectual property rights or other proprietary rights of Yaskawa or third parties, nor does it construe a license.
- Yaskawa shall not be responsible for any damage arising from infringements of intellectual property rights or other proprietary rights of third parties as a result of using the information described in catalogs or manuals.

◆ Suitability for Use

- It is the customer's responsibility to confirm conformity with any standards, codes, or regulations that apply if the Yaskawa product is used in combination with any other products.
- The customer must confirm that the Yaskawa product is suitable for the systems, machines, and equipment used by the customer.
- Consult with Yaskawa to determine whether use in the following applications is acceptable. If use in the application is acceptable, use the product with extra allowance in ratings and specifications, and provide safety measures to minimize hazards in the event of failure.
 - Outdoor use, use involving potential chemical contamination or electrical interference, or use in conditions or environments not described in product catalogs or manuals
 - Nuclear energy control systems, combustion systems, railroad systems, aviation systems, vehicle systems, medical equipment, amusement machines, and installations subject to separate industry or government regulations
 - Systems, machines, and equipment that may present a risk to life or property
 - Systems that require a high degree of reliability, such as systems that supply gas, water, or electricity, or systems that operate continuously 24 hours a day
 - Other systems that require a similar high degree of safety
- Never use the product for an application involving serious risk to life or property without first ensuring that the system is designed to secure the required level of safety with risk warnings and redundancy, and that the Yaskawa product is properly rated and installed.
- The circuit examples and other application examples described in product catalogs and manuals are for reference. Check the functionality and safety of the actual devices and equipment to be used before using the product.
- Read and understand all use prohibitions and precautions, and operate the Yaskawa product correctly to prevent accidental harm to third parties.

◆ Specifications Change

The names, specifications, appearance, and accessories of products in product catalogs and manuals may be changed at any time based on improvements and other reasons. The next editions of the revised catalogs or manuals will be published with updated code numbers. Consult with your Yaskawa representative to confirm the actual specifications before purchasing a product.

Compliance with UL Standards, EU Directives, and Other Safety Standards

Certification marks for the standards for which the product has been certified by certification bodies are shown on nameplate. Products that do not have the marks are not certified for the standards.

◆ North American Safety Standards (UL)



Product	Model	UL Standards (UL File No.)
SERVOPACKs	• SGD7S • SGD7W	UL 61800-5-1 (E147823) CSA C22.2 No.274
Rotary Servomotors	• SGM7M • SGM7A • SGM7J • SGM7P • SGM7G • SGMMV	UL 1004-1 UL 1004-6 (E165827)
Direct Drive Servomotors	• SGM7E • SGM7F-□□A, -□□B, -□□C, and -□□D (Small-Capacity Servomotors with Cores) • SGMCV • SGMCS-□□B, -□□C, -□□D, and -□□E (Small-Capacity, Coreless Servomotors)	UL 1004-1 UL 1004-6 (E165827)
Linear Servomotors	• SGLGW* • SGLFW* • SGLFW2 • SGLTW*	UL 1004-1 UL 1004-6 (E165827)

* Only products with derating specifications are in compliance with the UL Standards. Estimates are available for those products. Contact your Yaskawa representative for details.

◆ EU Directives



Product	Model	EU Directives	Harmonized Standards
SERVOPACKs	SGD7S	Machinery Directive 2006/42/EC	EN ISO13849-1: 2015
	- SGD7S - SGD7W	EMC Directive 2014/30/EU	EN 55011 group 1, class A EN 61000-6-2 EN 61000-6-4 EN 61800-3 (Category C2, Second environment)
		Low Voltage Directive 2014/35/EU	EN 50178 EN 61800-5-1
		RoHS Directive 2011/65/EU	EN 50581
Rotary Servomotors	SGMMV	EMC Directive 2004/108/EC	EN 55011 group 1, class A EN 61000-6-2 EN 61800-3 (Category C2, Second environment)
		Low Voltage Directive 2006/95/EC	EN 60034-1 EN 60034-5
		RoHS Directive 2011/65/EU	EN 50581
	- SGM7M - SGM7J - SGM7A - SGM7P - SGM7G	EMC Directive 2014/30/EU	EN 55011 group 1, class A EN 61000-6-2 EN 61000-6-4 EN 61800-3 (Category C2, Second environment)
		Low Voltage Directive 2014/35/EU	EN 60034-1 EN 60034-5
		RoHS Directive 2011/65/EU	EN 50581
Direct Drive Servomotors	- SGM7E - SGM7F - SGM7CV - SGMCS-□□B, -□□C, -□□D, and -□□E (Small-Capacity, Coreless Servomotors)*¹	EMC Directive 2014/30/EU	EN 55011 group 1, class A EN 61000-6-2 EN 61000-6-4 EN 61800-3 (Category C2, Second environment)
		Low Voltage Directive 2014/35/EU	EN 60034-1 EN 60034-5
		RoHS Directive 2011/65/EU	EN 50581
Linear Servomotors	- SGLG*² - SGLF*² - SGLF□2 - SGLT*²	EMC Directive 2014/30/EU	EN 55011 group 1, class A EN 61000-6-2 EN 61000-6-4 EN 61800-3 (Category C2, Second environment)
		Low Voltage Directive 2014/35/EU	EN 60034-1
		RoHS Directive 2011/65/EU	EN 50581

*1. Only models with “-E” at the end of model numbers are in compliance with the standards. Estimates are available for those models. Contact your Yaskawa representative for details.

*2. For Moving Coils, only models with “-E” at the end of model numbers are in compliance with the standards.

Note: 1. We declared the CE Marking based on the harmonized standards in the above table.

2. These products are for industrial use. In home environments, these products may cause electromagnetic interference and additional noise reduction measures may be necessary.

◆ Safety Standards



Product	Model	Safety Standards	Standards
SERVOPACKs	SGD7S	Safety of Machinery	EN ISO13849-1: 2015 IEC 60204-1
		Functional Safety	IEC 61508 series IEC 62061 IEC 61800-5-2
		EMC	IEC 61326-3-1

■ Safety Parameters

Item	Standards	Performance Level	
Safety Integrity Level	IEC 61508	SIL3	
	IEC 62061	SILCL3	
Mission Time	IEC 61508	10 years	20 years
Probability of Dangerous Failure per Hour	IEC 61508 IEC 62061	PFH = 4.04×10^{-9} [1/h] (4.04% of SIL3)	PFH = 4.05×10^{-9} [1/h] (4.05% of SIL3)
Performance Level	EN ISO 13849-1	PLe (Category 3)	
Mean Time to Dangerous Failure of Each Channel	EN ISO 13849-1	MTTFd: High	
Average Diagnostic Coverage	EN ISO 13849-1	DCavg: Medium	
Stop Category	IEC 60204-1	Stop category 0	
Safety Function	IEC 61800-5-2	STO	
Hardware Fault Tolerance	IEC 61508	HFT = 1	
Subsystem	IEC 61508	B	

Contents

About this Manual	iii
Outline of Manual	iii
Related Documents	iv
Using This Manual	xi
Safety Precautions	xii
Warranty	xxi
Compliance with UL Standards, EU Directives, and Other Safety Standards. . .	xxiii

1

Basic Information on Servomotors

1.1	Servomotor Part Names	1-2
1.1.1	SGLG Servomotors	1-2
1.1.2	SGLF Servomotors	1-2
1.1.3	SGLT Servomotors	1-2
1.2	Interpreting the Nameplates.	1-3
1.2.1	Moving Coils	1-3
1.2.2	Magnetic Ways	1-3
1.3	Outline of Model Designations.	1-4
1.3.1	Servomotors	1-4
1.3.2	SERVOPACKs	1-4
1.4	Combinations of Servomotors and SERVOPACKs.	1-5

2

Capacity Selection

2.1	Selecting the Servomotor Capacity	2-2
------------	--	------------

3

Specifications, Ratings, and External Dimensions of SGLG Servomotors

3.1	Model Designations	3-2
3.1.1	Moving Coil	3-2
3.1.2	Magnetic Way	3-3
3.1.3	Precautions on Moving Coils with Polarity Sensors (Hall Sensors)	3-4
3.2	Ratings and Specifications	3-5
3.2.1	Specifications: With Standard-Force Magnetic Way	3-5
3.2.2	Ratings: With Standard-Force Magnetic Way	3-6
3.2.3	Force-Motor Speed Characteristics	3-7
3.2.4	Servomotor Overload Protection Characteristics	3-8
3.2.5	Specifications: With High-Force Magnetic Way	3-9
3.2.6	Ratings: With High-Force Magnetic Way	3-9
3.2.7	Force-Motor Speed Characteristics	3-10
3.2.8	Servomotor Overload Protection Characteristics	3-11

3.3	External Dimensions	3-12
3.3.1	SGLGW-30	3-12
3.3.2	SGLGW-40	3-15
3.3.3	SGLGW-60	3-19
3.3.4	SGLGW-90	3-23
3.4	Selecting Cables	3-25
3.4.1	Cable Configurations	3-25

4

Specifications, Ratings, and External Dimensions of SGLF Servomotors

4.1	Model Designations	4-3
4.1.1	SGLFW2 Models	4-3
4.1.2	SGLFW Models	4-4
4.1.3	Precautions on Moving Coils with Polarity Sensors (Hall Sensors)	4-5
4.2	Ratings and Specifications: SGLFW2 Models	4-6
4.2.1	Specifications	4-6
4.2.2	Ratings: Self-Cooled Models	4-7
4.2.3	Force-Motor Speed Characteristics: Self-Cooled Models	4-9
4.2.4	Ratings: Water-Cooled Models	4-10
4.2.5	Force-Motor Speed Characteristics: Water-Cooled Models	4-11
4.2.6	Servomotor Overload Protection Characteristics	4-12
4.3	Ratings and Specifications: SGLFW Models	4-13
4.3.1	Specifications	4-13
4.3.2	Ratings	4-14
4.3.3	Force-Motor Speed Characteristics	4-15
4.3.4	Servomotor Overload Protection Characteristics	4-16
4.4	External Dimensions	4-17
4.4.1	SGLFW2-30	4-17
4.4.2	SGLFW2-45	4-22
4.4.3	SGLFW2-90: Self-Cooled Models	4-25
4.4.4	SGLFW2-90: Water-Cooled Models	4-28
4.4.5	SGLFW2-90: Self-Cooled and Water-Cooled Models	4-30
4.4.6	SGLFW2-1D	4-31
4.4.7	SGLFW-20	4-34
4.4.8	SGLFW-35	4-36
4.4.9	SGLFW-50	4-39
4.4.10	SGLFW-1Z	4-42
4.5	Selecting Cables	4-45
4.5.1	Cable Configurations	4-45
4.5.2	Linear Servomotor Main Circuit Cables	4-46

5

Specifications, Ratings, and External Dimensions of SGLT Servomotors

5.1	Model Designations	5-2
5.1.1	Moving Coil	5-2
5.1.2	Magnetic Way	5-3
5.1.3	Precautions on Moving Coils with Polarity Sensors (Hall Sensor)	5-4

5.2	Ratings and Specifications	5-5
5.2.1	Specifications	5-5
5.2.2	Ratings	5-6
5.2.3	Force-Motor Speed Characteristics	5-7
5.2.4	Servomotor Overload Protection Characteristics	5-9
5.3	External Dimensions	5-10
5.3.1	SGLTW-20: Standard Models	5-10
5.3.2	SGLTW-35: Standard Models	5-13
5.3.3	SGLTW-35□□□□H□: High-efficiency Models	5-16
5.3.4	SGLTW-40: Standard Models	5-18
5.3.5	SGLTW-50: High-efficiency Models	5-21
5.3.6	SGLTW-80: Standard Models	5-23
5.4	Selecting Cables	5-26
5.4.1	Cable Configurations	5-26
5.4.2	Linear Servomotor Main Circuit Cables	5-27

6

Equipment Design Precautions

6.1	Influence of Magnetic Attraction	6-2
6.1.1	SGLF Servomotors	6-2
6.1.2	SGLT Servomotors	6-3
6.2	Influence of Magnetic Way Leakage Flux	6-4
6.2.1	SGLG Servomotors	6-4
6.2.2	SGLF Servomotors	6-4
6.2.3	SGLT Servomotors	6-5
6.3	Special Precautions for SGLT Servomotors	6-6
6.4	Precautions for Water-Cooled Models	6-7

7

Servomotor Installation

7.1	Installation Conditions	7-2
7.1.1	Installation Environment	7-2
7.1.2	Installation Orientation	7-2
7.2	Installation Procedure	7-3
7.2.1	SGLG Servomotors (Coreless Models)	7-3
7.2.2	SGLF Servomotors (Models with F-type Iron Cores)	7-5
7.2.3	SGLT Servomotors (Models with T-type Iron Cores)	7-10
7.3	Servomotor Temperature Increase	7-16

8

Connecting Linear Encoders

8.1	Installation Conditions for Linear Encoders	8-2
8.1.1	SGLG Servomotors	8-2
8.1.2	SGLF Servomotors	8-3
8.1.3	SGLT Servomotors	8-3
8.2	Mounting Linear Encoders	8-4
8.2.1	Linear Encoders from Heidenhain Corporation	8-4
8.2.2	Linear Encoders from RSF Elektronik GmbH	8-4
8.2.3	Linear Encoders from Renishaw PLC	8-4
8.2.4	Linear Encoders from RLS d.o.o.	8-4
8.2.5	Absolute Linear Encoders from Mitutoyo Corporation	8-5
8.2.6	Linear Encoders from Magnescale Co., Ltd.	8-5
8.3	Adjusting Linear Encoders	8-6

9

Connections between Servomotors and SERVOPACKs

9.1	Selecting Cables	9-2
9.1.1	Linear Encoder Cables	9-2
9.1.2	Serial Converter Unit Cables	9-2
9.1.3	Sensor Cables	9-3
9.1.4	Serial Converter Units	9-4
9.2	Wiring Servomotors and SERVOPACKs	9-7
9.2.1	Wiring Precautions	9-7
9.2.2	Wiring Procedure	9-10

10

Maintenance and Inspection

10.1	Periodic Inspections	10-2
10.1.1	Linear Servomotor Inspections	10-2
10.1.2	Linear Encoder Inspections	10-3
10.2	Disposing of Servomotors	10-4

Revision History

Basic Information on Servomotors

1

This chapter provides basic information on Linear Servomotors, including Servomotor part names and combinations with SERVOPACKs.


1.1	Servomotor Part Names	1-2
1.1.1	SGLG Servomotors	1-2
1.1.2	SGLF Servomotors	1-2
1.1.3	SGLT Servomotors	1-2
1.2	Interpreting the Nameplates	1-3
1.2.1	Moving Coils	1-3
1.2.2	Magnetic Ways	1-3
1.3	Outline of Model Designations	1-4
1.3.1	Servomotors	1-4
1.3.2	SERVOPACKs	1-4
1.4	Combinations of Servomotors and SERVOPACKs . .	1-5

1.1

Servomotor Part Names


1.1.1

SGLG Servomotors




1.1.2

SGLF Servomotors



1.1.3

SGLT Servomotors




1.2

Interpreting the Nameplates

The following basic information is provided on the nameplate.

1.2.1


Moving Coils




1.2.2

Magnetic Ways

◆ SGLG Servomotors



◆ SGLF, SGLT, and SGLF□2 Servomotors



1.3 Outline of Model Designations

1.3.1 Servomotors

This section outlines the model numbers of Σ -7-Series Servomotors. For details, refer to the chapter for your type of Servomotor.

SGL

□

□

-

30

A

050

C

P

□

Series

1st digit

2nd digit

3rd digit on

Series

Σ -7-Series Servomotors

2nd digit

Moving Coil/Magnetic Way

1st digit

Servomotor Type

Code	Specifications	Reference
G	Coreless models	Chapter 3
F	Models with F-type iron core	Chapter 4
T	Models with T-type iron core	Chapter 5

Code	Specification
W	Moving Coil
W2	
M	Magnetic Way
M2	

3rd digit on

The specifications for the 3rd digit on depend on the Servomotor type.

1.3.2 SERVOPACKs

This section outlines the model numbers of Σ -7-Series SERVOPACKs. For details, refer to the manual for your SERVOPACK.

- Σ-7-Series Σ-7S SERVOPACK with Analog Voltage/Pulse Train References Product Manual
(Manual No.: SIEP S800001 26)

Σ-7-Series Σ-7S SERVOPACK with MECHATROLINK-II Communications References Product Manual
(Manual No.: SIEP S800001 27)

Σ-7-Series Σ-7S SERVOPACK with MECHATROLINK-III Communications References Product Manual
(Manual No.: SIEP S800001 28)

Σ-7-Series Σ-7W SERVOPACK with MECHATROLINK-III Communications References Product Manual
(Manual No.: SIEP S800001 29)

SGD7□

-

R70

A

00

A

000

000

B

Series

1st+2nd+3rd digits

4th digit

5th+6th digits

7th digit

8th+9th+10th digits

11th+12th+13th digits

14th digit

Series

Σ -7-Series SERVOPACKs

1st+2nd+3rd digits

Maximum Applicable Motor Capacity

7th digit

Design Revision Order

Code	Specification
SGD7S	Single-Axis SERVOPACKs
SGD7W	Two-Axis SERVOPACKs
SGD7C	Two-Axis SERVOPACKs with Built-in Controllers

0.05 kW to 15 kW

4th digit

Power Supply Voltage

• 200 VAC

5th+6th digits

Interface

• Analog voltage/pulse train reference

• MECHATROLINK-II communications reference

• MECHATROLINK-III communications reference

• Command Option attachable type

8th+9th+10th digits

Hardware Options Specification

11th+12th+13th digits

FT/EX Specification

14th digit

BTO Specification

1.4

Combinations of Servomotors and SERVOPACKs

Linear Servomotor Model		Rated Force N	Instantaneous Maximum Force N	SERVOPACK Model	
				SGD7S-□□□□	SGD7W-□□□□ SGD7C-□□□□
SGLG (Coreless Models), Used with Standard-Force Magnetic Way	SGLGW-30A050C	12.5	40	R70A or R70F	1R6A
	SGLGW-30A080C	25	80	R90A or R90F	
	SGLGW-40A140C	47	140		
	SGLGW-40A253C	93	280	1R6A or 2R1F	
	SGLGW-40A365C	140	420	2R8A or 2R8F	2R8A
	SGLGW-60A140C	70	220	1R6A or 2R1F	1R6A
	SGLGW-60A253C	140	440	2R8A or 2R8F	2R8A
	SGLGW-60A365C	210	660	5R5A	
	SGLGW-90A200C	325	1300	120A	—
	SGLGW-90A370C	550	2200	180A	
	SGLGW-90A535C	750	3000	200A	
SGLG (Coreless Models), Used with High-Force Magnetic Way	SGLGW-40A140C	57	230	1R6A or 2R1F	1R6A
	SGLGW-40A253C	114	460	2R8A or 2R8F	2R8A
	SGLGW-40A365C	171	690	3R8A	5R5A
	SGLGW-60A140C	85	360	1R6A or 2R1F	1R6A
	SGLGW-60A253C	170	720	3R8A	5R5A
	SGLGW-60A365C	255	1080	7R6A	
SGLF (Models with F-type Iron Cores)	SGLFW-20A090A	25	86	1R6A or 2R1F	1R6A
	SGLFW-20A120A	40	125		
	SGLFW-35A120A	80	220		
	SGLFW-35A230A	160	440	3R8A	5R5A
	SGLFW-50A200B	280	600	5R5A	
	SGLFW-50A380B	560	1200	120A	—
	SGLFW-1ZA200B			200A	
	SGLFW-1ZA380B	1120	2400		
	SGLFW2-30A070A	45	135	1R6A or 2R1F	1R6A
	SGLFW2-30A120A	90	270		
	SGLFW2-30A230A	180	540	3R8A	—
		170	500	2R8A or 2R8F	2R8A
	SGLFW2-45A200A	280	840	5R5A	
	SGLFW2-45A380A	560	1680	180A	—
			1500	120A	
	SGLFW2-90A200A□1	560	1680		
	SGLFW2-90A200A□L	896			
	SGLFW2-90A380A	1120	3360	200A	
	SGLFW2-90A560A	1680	5040	330A	
	SGLFW2-1DA380A	1680	5040	200A	
	SGLFW2-1DA560A	2520	7560	330A	

Continued on next page.

Continued from previous page.

Linear Servomotor Model		Rated Force N	Instantaneous Maximum Force N	SERVOPACK Model		
				SGD7S-□□□□	SGD7W-□□□□ SGD7C-□□□□	
SGLT (Models with T-type Iron Cores)	SGLTW-20A170A	130	380	3R8A	5R5A	
	SGLTW-20A320A	250	760	7R6A		
	SGLTW-20A460A	380	1140	120A	—	
	SGLTW-35A170A	220	660	5R5A		
	SGLTW-35A170H	300	600			
	SGLTW-35A320A	440	1320	120A	—	
	SGLTW-35A320H	600	1200			
	SGLTW-35A460A	670	2000	180A		
	SGLTW-40A400B	670	2600			
	SGLTW-40A600B	1000	4000	330A	—	
	SGLTW-50A170H	450	900	5R5A		
	SGLTW-50A320H	900	1800	120A	—	
	SGLTW-80A400B	1300	5000	330A		
	SGLTW-80A600B	2000	7500	550A		

Capacity Selection

2

This chapter describes calculation methods to use when selecting Servomotor capacities.


2.1 Selecting the Servomotor Capacity 2-2

2.1 Selecting the Servomotor Capacity

Contact your Yaskawa representative for information on the Servomotor capacity selection software.

Refer to the following selection examples to select Servomotor capacities with manual calculations.


1. Mechanical Specifications



Item	Code	Value
Load Mass	m_W	1 kg
Table Mass	m_T	2 kg
Motor Speed	v	2 m/s
Feeding Distance	l	0.76 m
Friction Coefficient	μ	0.2

Item	Code	Value
Acceleration Time	t_a	0.02 s
Constant-speed Time	t_c	0.36 s
Deceleration Time	t_d	0.02 s
Cycle Time	t	0.5 s
External Force on Linear Motion Section	F	0 N

2. Operation Pattern



3. Steady-State Force (Excluding Servomotor Moving Coil)

$$F_L = \{9.8 \times \mu \times (m_W + m_T)\} + F = 9.8 \times 0.2 \times (1 + 2) + 0 = 5.88 \text{ (N)}$$

4. Acceleration Force (Excluding Servomotor Moving Coil)

$$F_P = (m_W + m_T) \times \frac{v}{t_a} + F_L = (1 + 2) \times \frac{2}{0.02} + 5.88 = 305.88 \text{ (N)}$$

5. Provisional Selection of Linear Servomotor

① Selection Conditions

- $F_P \leq \text{Maximum force} \times 0.9$
- $F_S \leq \text{Maximum force} \times 0.9$
- $F_{rms} \leq \text{Rated force} \times 0.9$

The following Servomotor Moving Coil and Magnetic Way meet the selection conditions.

- SGLGW-60A253CP Linear Servomotor Moving Coil
- SGLGM-60□□□C Linear Servomotor Magnetic Way

② Specifications of the Provisionally Selected Servomotor

Item	Value
Maximum Force	440 (N)
Rated Force	140 (N)
Moving Coil Mass (m_M)	0.82 (kg)
Servomotor Magnetic Attraction (F_{att})	0 (N)

6. Verification of the Provisionally Selected Servomotor

- Steady-State Force

$$F_L = \mu \{9.8 \times (m_W + m_T + m_M) + F_{att}\} = 0.2 \{9.8 \times (1 + 2 + 0.82) + 0\} = 7.5 \text{ (N)}$$

- Verification of Acceleration Force

$$F_P = (m_W + m_T + m_M) \times \frac{v}{t_a} + F_L = (1 + 2 + 0.82) \times \frac{2}{0.02} + 7.5$$

$$= 389.5 \text{ (N)} \leq \text{Maximum force} \times 0.9 (= 396 \text{ N}) \dots \text{Satisfactory}$$

- Verification of Deceleration Force

$$F_S = (m_W + m_T + m_M) \times \frac{v}{t_d} - F_L = (1 + 2 + 0.82) \times \frac{2}{0.02} - 7.5$$

$$= 374.5 \text{ (N)} \leq \text{Maximum force} \times 0.9 (= 396 \text{ N}) \dots \text{Satisfactory}$$

- Verification of Effective Force

$$F_{rms} = \sqrt{\frac{F_P^2 \cdot t_a + F_L^2 \cdot t_c + F_S^2 \cdot t_d}{t}} = \sqrt{\frac{389.5^2 \times 0.02 + 7.5^2 \times 0.36 + 374.5^2 \times 0.02}{0.5}}$$

$$= 108.3 \text{ (N)} \leq \text{Rated force} \times 0.9 (= 132.3 \text{ N}) \dots \text{Satisfactory}$$

7. Result

It has been verified that the provisionally selected Servomotor is applicable.

Specifications, Ratings, and External Dimensions of SGLG Servomotors

3

This chapter describes how to interpret the model numbers of SGLG Servomotors and gives their specifications, ratings, and external dimensions.

3.1 Model Designations 3-2

- 3.1.1 Moving Coil 3-2
- 3.1.2 Magnetic Way 3-3
- 3.1.3 Precautions on Moving Coils with
Polarity Sensors (Hall Sensors) 3-4

3.2 Ratings and Specifications 3-5

- 3.2.1 Specifications: With Standard-Force Magnetic
Way 3-5
- 3.2.2 Ratings: With Standard-Force Magnetic Way ... 3-6
- 3.2.3 Force-Motor Speed Characteristics 3-7
- 3.2.4 Servomotor Overload Protection
Characteristics 3-8
- 3.2.5 Specifications: With High-Force Magnetic Way . . 3-9
- 3.2.6 Ratings: With High-Force Magnetic Way 3-9
- 3.2.7 Force-Motor Speed Characteristics 3-10
- 3.2.8 Servomotor Overload Protection
Characteristics 3-11

3.3 External Dimensions 3-12

- 3.3.1 SGLGW-30 3-12
- 3.3.2 SGLGW-40 3-15
- 3.3.3 SGLGW-60 3-19
- 3.3.4 SGLGW-90 3-23

3.4 Selecting Cables 3-25

- 3.4.1 Cable Configurations 3-25

3.1 Model Designations

3.1.1 Moving Coil

S	G	L	G	W	-	30	A	050	C	P	□	-	E
Linear Σ Series Linear Servomotors				1st digit	2nd digit	3rd+4th digits	5th digit	6th+7th+8th digits	9th digit	10th digit	11th digit		12th digit

1st digit Servomotor Type

Code	Specification
G	Coreless model

2nd digit Moving Coil/Magnetic Way

Code	Specification
W	Moving Coil

3rd+4th digits Magnet Height

Code	Specification
30	30 mm
40	40 mm
60	60 mm
90	86 mm

5th digit Power Supply Voltage

Code	Specification
A	200 VAC

6th+7th+8th digits Length of Moving Coil

Code	Specification
050	50 mm
080	80 mm
140	140 mm
200	199 mm
253	252.5 mm
365	365 mm
370	367 mm
535	535 mm

9th digit Design Revision Order

A, B...

10th digit Sensor Specification and Cooling Method

Code	Specifications		Applicable Models
	Polarity Sensor (Hall Sensor)	Cooling Method	
None	None	Self-cooled	All models
C	None	Air-cooled	SGLGW -40A, -60A, -90A
H	Yes	Air-cooled	
P	Yes	Self-cooled	All models

11th digit Connector for Servomotor Main Circuit Cable

Code	Specification	Applicable Models
None	Connector from Tyco Electronics Japan G.K.	All models
D	Connector from Interconnectron GmbH	SGLGW -30A, -40A, -60A

12th digit EU Directive Certification

Code	Specification
E	Certified
None	Not certified

Note: This information is provided to explain model numbers. It is not meant to imply that models are available for all combinations of codes.

3.1.2 Magnetic Way

S G L G M - 30 108 A □

Linear Σ Series
Linear Servomotors

1st digit

2nd digit

3rd+4th digits

5th+6th+7th digits

8th digit

9th digit

1st digit Servomotor Type
(Same as for the Moving Coil.)

2nd digit Moving Coil/Magnetic Way

3rd+4th digits Magnet Height
(Same as for the Moving Coil.)

5th+6th+7th digits Length of Magnetic Way

8th digit Design Revision Order
A, B, C*...

9th digit Options

Code	Specification
090	90 mm
108	108 mm
216	216 mm
225	225 mm
252	252 mm
360	360 mm
405	405 mm
432	432 mm
450	450 mm
504	504 mm

Code	Specification	Applicable Models
None	Standard-force	All models
-M	High-force	SGLGM-40, -60

Code	Specification
M	Magnetic Way

- * The SGLGM-40 and SGLGM-60 also have a CT code.
- C = Without mounting holes on the bottom
 - CT = With mounting holes on the bottom

Note: This information is provided to explain model numbers. It is not meant to imply that models are available for all combinations of codes.

3.1.3 Precautions on Moving Coils with Polarity Sensors (Hall Sensors)




Note


When you use a Moving Coil with a Polarity Sensor (Hall Sensor), the Magnetic Way must cover the bottom of the polarity sensor (hall sensor). Refer to the example that shows the correct installation.

When determining the length of the Moving Coil's stroke or the length of the Magnetic Way, consider the total length (L) of the Moving Coil and the polarity sensor (hall sensor). Refer to the following table.


Correct Installation



Incorrect Installation



◆ Total Length of Moving Coil with Polarity Sensor (Hall Sensor)



Moving Coil Model SGLGW-	Length of Moving Coil, L1 [mm]	Length of Polarity Sensor (Hall Sensor), A [mm]	Total Length, L [mm]
30A050□P□	50	0 (Included in the length of Moving Coil.)	50
30A080□P□	80		80
40A140□H□ 40A140□P□	140	16	156
40A253□H□ 40A253□P□	252.5		268.5
40A365□H□ 40A365□P□	365		381
60A140□H□ 60A140□P□	140	16	156
60A253□H□ 60A253□P□	252.5		268.5
60A365□H□ 60A365□P□	365		381
90A200□H□ 90A200□P□	199	0 (Included in the length of Moving Coil.)	199
90A370□H□ 90A370□P□	367		367
90A535□H□ 90A535□P□	535		535

3.2 Ratings and Specifications

3.2.1 Specifications: With Standard-Force Magnetic Way

Linear Servomotor Moving Coil Model SGLGW-		30A		40A			60A			90A		
		050C	080C	140C	253C	365C	140C	253C	365C	200C	370C	535C
Time Rating		Continuous										
Thermal Class		B										
Insulation Resistance		500 VDC, 10 M Ω min.										
Withstand Voltage		1,500 VAC for 1 minute										
Excitation		Permanent magnet										
Cooling Method		Self-cooled or air-cooled (Only self-cooled models are available for the SGLGW-30A.)										
Protective Structure		IP00										
Environmental Condi- tions	Surrounding Air Tempera- ture	0°C to 40°C (with no freezing)										
	Surrounding Air Humidity	20% to 80% relative humidity (with no condensation)										
	Installation Site	• Must be indoors and free of corrosive and explosive gases. • Must be well-ventilated and free of dust and moisture. • Must facilitate inspection and cleaning. • Must have an altitude of 1,000 m or less. • Must be free of strong magnetic fields.										
Shock Resis- tance	Impact Accelera- tion Rate	196 m/s ²										
	Number of Impacts	2 times										
Vibra- tion Resis- tance	Vibration Accelera- tion Rate	49 m/s ² (the vibration resistance in three directions, vertical, side-to-side, and front-to-back)										

3.2 Ratings and Specifications

3.2.2 Ratings: With Standard-Force Magnetic Way

3.2.2 Ratings: With Standard-Force Magnetic Way

Linear Servomotor		30A		40A			60A			90A		
Moving Coil Model SGLGW-		050C	080C	140C	253C	365C	140C	253C	365C	200C	370C	535C
Rated Motor Speed (Reference Speed during Speed Control)* ¹	m/s	1.5	1.5	2.0	2.0	2.0	2.3	2.3	2.3	1.8	1.5	1.5
Maximum Speed* ¹	m/s	5.0	5.0	5.0	5.0	5.0	4.8	4.8	4.8	4.0	4.0	4.0
Rated Force* ^{1, *2}	N	12.5	25	47	93	140	70	140	210	325	550	750
Maximum Force* ¹	N	40	80	140	280	420	220	440	660	1300	2200	3000
Rated Current* ¹	Arms	0.51	0.79	0.80	1.6	2.4	1.2	2.2	3.3	4.4	7.5	10.2
Maximum Current* ¹	Arms	1.6	2.5	2.4	4.9	7.3	3.5	7.0	10.5	17.6	30.0	40.8
Moving Coil Mass	kg	0.10	0.15	0.34	0.60	0.87	0.42	0.76	1.1	2.2	3.6	4.9
Force Constant	N/Arms	26.4	33.9	61.5	61.5	61.5	66.6	66.6	66.6	78.0	78.0	78.0
BEMF Constant	Vrms/(m/s)/phase	8.80	11.3	20.5	20.5	20.5	22.2	22.2	22.2	26.0	26.0	26.0
Motor Constant	N/√W	3.66	5.63	7.79	11.0	13.5	11.1	15.7	19.2	26.0	36.8	45.0
Electrical Time Constant	ms	0.19	0.41	0.43	0.43	0.43	0.45	0.45	0.45	1.4	1.4	1.4
Mechanical Time Constant	ms	7.5	4.7	5.6	5.0	4.8	3.4	3.1	3.0	3.3	2.7	2.4
Thermal Resistance (with Heat Sink)	K/W	5.19	3.11	1.67	0.87	0.58	1.56	0.77	0.51	0.39	0.26	0.22
Thermal Resistance (without Heat Sink)	K/W	8.13	6.32	3.02	1.80	1.23	2.59	1.48	1.15	1.09	0.63	0.47
Magnetic Attraction	N	0	0	0	0	0	0	0	0	0	0	0
Maximum Allowable Payload	kg	1.7	3.4	5.9	12	18	9.9	19	48	110	190	260
Maximum Allowable Payload (With External Regenerative Resistor and External Dynamic Brake Resistor* ³)	kg	1.7	3.4	5.9	12	18	9.9	19	48	110	190	260
Combined Magnetic Way, SGLGM-		30□□□A		40□□□C□			60□□□C□			90□□□A		
Combined Serial Converter Unit, JZDP-□□□□-		250	251	252	253	254	258	259	260	264	265	266
Applicable SERVOPACKs	SGD7S-	R70A, R70F	R90A, R90F		1R6A, 2R1F	2R8A, 2R8F	1R6A, 2R1F	2R8A, 2R8F	5R5A	120A	180A	200A
	SGD7W-SGD7C-	1R6A				2R8A	1R6A	2R8A	5R5A	-		

*1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. The values for other items are at 20°C. These are typical values.

*2. The rated forces are the continuous allowable force values at a surrounding air temperature of 40°C with an aluminum heat sink of the dimensions given in the following table.

• Heat Sink Dimensions












- 200 mm × 300 mm × 12 mm: SGLGW-30A050C, -30A080C, -40A140C, and -60A140C
- 300 mm × 400 mm × 12 mm: SGLGW-40A253C and -60A253C
- 400 mm × 500 mm × 12 mm: SGLGW-40A365C and -60A365C
- 800 mm × 900 mm × 12 mm: SGLGW-90A200C, -90A370C, and -90A535C

*3. To externally connect dynamic brake resistor, select hardware option specification 020 for the SERVOPACK. However, you cannot externally connect dynamic brake resistor if you use the following SERVOPACKs (maximum applicable motor capacity: 400 W).

- SGD7S-R70□□□A020 to -2R8□□□A020
- SGD7W-1R6A20A020 to -2R8A20A020
- SGD7C-1R6AMAA020 to -2R8AMAA020

3.2.3

A : Continuous duty zone ————— (solid lines): With three-phase 200-V input
B : Intermittent duty zone - - - - - (dotted lines): With single-phase 200-V input
 — — — (dashed-dotted lines): With single-phase 100-V input



* The characteristics are the same for three-phase 200 V and single-phase 200 V.

Note: 1. These values (typical values) are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C.





2. The characteristics in the intermittent duty zone depend on the power supply voltage.

3. If the effective force is within the allowable range for the rated force, the Servomotor can be used within the intermittent duty zone.

4. If you use a Servomotor Main Circuit Cable that exceeds 20 m, the intermittent duty zone in the torque-speed characteristics will become smaller because the voltage drop increases.

3.2.4 Servomotor Overload Protection Characteristics

The overload detection level is set for hot start conditions with a Servomotor surrounding air temperature of 40°C.



Note: The above overload protection characteristics do not mean that you can perform continuous duty operation with an output of 100% or higher. Use the Servomotor so that the effective force remains within the continuous duty zone given in 3.2.3 *Force-Motor Speed Characteristics* on page 3-7.

3.2.5 Specifications: With High-Force Magnetic Way

Linear Servomotor Moving Coil Model SGLGW-		40A			60A		
		140C	253C	365C	140C	253C	365C
Time Rating		Continuous					
Thermal Class		B					
Insulation Resistance		500 VDC, 10 M Ω min.					
Withstand Voltage		1,500 VAC for 1 minute					
Excitation		Permanent magnet					
Cooling Method		Self-cooled or air-cooled					
Protective Structure		IP00					
Environmental Conditions	Surrounding Air Temperature	0°C to 40°C (with no freezing)					
	Surrounding Air Humidity	20% to 80% relative humidity (with no condensation)					
	Installation Site	• Must be indoors and free of corrosive and explosive gases. • Must be well-ventilated and free of dust and moisture. • Must facilitate inspection and cleaning. • Must have an altitude of 1,000 m or less. • Must be free of strong magnetic fields.					
Shock Resistance	Impact Acceleration Rate	196 m/s ²					
	Number of Impacts	2 times					
Vibration Resistance	Vibration Acceleration Rate	49 m/s ² (the vibration resistance in three directions, vertical, side-to-side, and front-to-back)					

3.2.6 Ratings: With High-Force Magnetic Way

Linear Servomotor Moving Coil Model SGLGW-		40A			60A		
		140C	253C	365C	140C	253C	365C
Rated Motor Speed (Reference Speed during Speed Control)* ¹	m/s	1.0	1.0	1.0	1.0	1.0	1.0
Maximum Speed* ¹	m/s	4.2	4.2	4.2	4.2	4.2	4.2
Rated Force* ¹ , * ²	N	57	114	171	85	170	255
Maximum Force* ¹	N	230	460	690	360	720	1080
Rated Current* ¹	Arms	0.80	1.6	2.4	1.2	2.2	3.3
Maximum Current* ¹	Arms	3.2	6.5	9.7	5.0	10.0	14.9
Moving Coil Mass	kg	0.34	0.60	0.87	0.42	0.76	1.1
Force Constant	N/Arms	76.0	76.0	76.0	77.4	77.4	77.4
BEMF Constant	V _{rms} /(m/s)/phase	25.3	25.3	25.3	25.8	25.8	25.8
Motor Constant	N/ $\sqrt{W}$	9.62	13.6	16.7	12.9	18.2	22.3
Electrical Time Constant	ms	0.43	0.43	0.43	0.45	0.45	0.45
Mechanical Time Constant	ms	3.7	3.2	3.1	2.5	2.3	2.2
Thermal Resistance (with Heat Sink)	K/W	1.67	0.87	0.58	1.56	0.77	0.51
Thermal Resistance (without Heat Sink)	K/W	3.02	1.80	1.23	2.59	1.48	1.15
Magnetic Attraction	N	0	0	0	0	0	0
Maximum Allowable Payload	kg	12	24	58	18	61	91
Maximum Allowable Payload (With External Regenerative Resistor and External Dynamic Brake Resistor* ³)	kg	12	24	58	18	61	91

Continued on next page.

3.2 Ratings and Specifications

3.2.7 Force-Motor Speed Characteristics







Continued from previous page.

Linear Servomotor Moving Coil Model SGLGW-		40A			60A		
		140C	253C	365C	140C	253C	365C
Combined Magnetic Way, SGLGM-		40□□□□C□-M			60□□□□C□-M		
Combined Serial Converter Unit, JZDP- □□□□-		255	256	257	261	262	263
Applicable SERVOPACKs	SGD7S-	1R6A, 2R1F	2R8A, 2R8F	3R8A	1R6A, 2R1F	3R8A	7R6A
	SGD7W- SGD7C-	1R6A	2R8A	5R5A	1R6A	5R5A	7R6A

- *1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. The values for other items are at 20°C. These are typical values.
- *2. The rated forces are the continuous allowable force values at a surrounding air temperature of 40°C with an aluminum heat sink of the dimensions given in the following table.
- Heat Sink Dimensions
 - 200 mm × 300 mm × 12 mm: SGLGW-40A140C and -60A140C
 - 300 mm × 400 mm × 12 mm: SGLGW-40A253C and -60A253C
 - 400 mm × 500 mm × 12 mm: SGLGW-40A365C and -60A365C
- *3. To externally connect dynamic brake resistor, select hardware option specification 020 for the SERVOPACK. However, you cannot externally connect dynamic brake resistor if you use the following SERVOPACKs (maximum applicable motor capacity: 400 W).
- SGD7S-R70□□□A020 to -2R8□□□A020
 - SGD7W-1R6A20A020 to -2R8A20A020
 - SGD7C-1R6AMAA020 to -2R8AMAA020

3.2.7 Force-Motor Speed Characteristics



- [A] : Continuous duty zone ——— (solid lines): With three-phase 200-V input
- [B] : Intermittent duty zone - - - - - (dotted lines): With single-phase 200-V input
- · — (dashed-dotted lines): With single-phase 100-V input



- Note: 1. These values (typical values) are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C.
2. The characteristics in the intermittent duty zone depend on the power supply voltage.
3. If the effective force is within the allowable range for the rated force, the Servomotor can be used within the intermittent duty zone.
4. If you use a Servomotor Main Circuit Cable that exceeds 20 m, the intermittent duty zone in the torque-motor speed characteristics will become smaller because the voltage drop increases.

3.2.8 Servomotor Overload Protection Characteristics

The overload detection level is set for hot start conditions with a Servomotor surrounding air temperature of 40°C.




Note: The above overload protection characteristics do not mean that you can perform continuous duty operation with an output of 100% or higher. Use the Servomotor so that the effective force remains within the continuous duty zone given in 3.2.7 *Force-Motor Speed Characteristics* on page 3-10.

3.3 External Dimensions

3.3.1 SGLGW-30

◆ Moving Coils: SGLGW-30A□□□□



Unit: mm

Moving Coil Model SGLGW-	L1	L2	L3	L4	L5	W	G (Gap)	Approx. Mass* [kg]
30A050C□	50	48	30	20	20	5.9	0.85	0.14
30A080C□	80	72	50	30	25	5.7	0.95	0.19

* The mass is for a Moving Coil with a Polarity Sensor (Hall Sensor).

◆ Connector Specifications


• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	FG	Green

Plug: 350779-1
 Pins: 350924-1 or 770672-1
 From Tyco Electronics Japan G.K.
 Mating Connector
 Cap: 350780-1
 Socket: 350925-1 or 770673-1

• Polarity Sensor (Hall Sensor) Connector




1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	—	—


Pin connector: 17JE-23090-02 (D8C)-CG
 From DDK Ltd.
 Mating Connector
 Socket connector: 17JE-13090-02 (D8C)A-CG
 Studs: 17L-002C or 17L-002C1

◆ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Moving Coils: SGLGW-30A□□□C□D




Moving Coil Model SGLGW-	L1	L2	L3	L4	L5	W	G (Gap)	Approx. Mass* [kg]
30A050C□D	50	48	30	20	20	5.9	0.85	0.14
30A080C□D	80	72	50	30	25	5.7	0.95	0.19

* The mass is for a Moving Coil with a Polarity Sensor (Hall Sensor).

◆ Connector Specifications


• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	Not used	—
5	Not used	—
6	FG	Green

Extension: SROC06JMSCN169
Pins: 021.423.1020
From Interconnectron GmbH
Mating Connector
Plug: SPUC06KFSDN236
Socket: 020.030.1020

• Polarity Sensor (Hall Sensor) Connector




1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	—	—


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.
Mating Connector
Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

◆ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




◆ Standard-Force Magnetic Ways: SGLGM-30□□□A



Magnetic Way Model SGLGM-	L1	L2	N	Approx. Mass [kg]
30108A	108 ^{-0.1 -0.3}	54	2	0.6
30216A	216 ^{-0.1 -0.3}	162	4	1.1
30432A	432 ^{-0.1 -0.3}	378	8	2.3

3.3.2 SGLGW-40

◆ Moving Coils: SGLGW-40A□□□□




Moving Coil Model SGLGW-	L1	L2	L3	L4	L5	L6	N1	N2	Approx. Mass* [kg]
40A140C□	140	125	90	30	52.5	45	3	4	0.40
40A253C□	252.5	237.5	180	37.5	60	135	5	8	0.66
40A365C□	365	350	315	30	52.5	270	8	14	0.93

* The mass is for a Moving Coil with a Polarity Sensor (Hall Sensor).

◆ Connector Specifications


• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	FG	Green

Plug: 350779-1
Pins: 350561-3 or 350690-3 (No.1 to 3)
350654-1 or 350669-1 (No. 4)
From Tyco Electronics Japan G.K.
Mating Connector
Cap: 350780-1
Socket: 350570-3 or 350689-3

• Polarity Sensor (Hall Sensor) Connector




1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	—	—


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.
Mating Connector
Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

◆ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Moving Coils: SGLGW-40□□□C□D




Moving Coil Model SGLGW-	L1	L2	L3	L4	L5	L6	N1	N2	Approx. Mass* [kg]
40A140C□D	140	125	90	30	52.5	45	3	4	0.40
40A253C□D	252.5	237.5	180	37.5	60	135	5	8	0.66
40A365C□D	365	350	315	30	52.5	270	8	14	0.93

* The mass is for a Moving Coil with a Polarity Sensor (Hall Sensor).

◆ Connector Specifications

• Servomotor Connector




1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	Not used	–
5	Not used	–
6	FG	Green


Extension: SROC06JMSCN169
Pins: 021.423.1020
From Interconnectron GmbH
Mating Connector
Plug: SPUC06KFSDN236
Socket: 020.030.1020

◆ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




• Polarity Sensor (Hall Sensor) Connector



1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	–	–


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.
Mating Connector
Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

◆ Standard-Force Magnetic Ways:
 SGLGM-40□□□C (without Mounting Holes on the Bottom)
 SGLGM-40□□□CT (with Mounting Holes on the Bottom)



Type	Magnetic Way Model SGLGM-	L1	L2	N	Approx. Mass [kg]
Standard-Force	40090C or 40090CT	90 ^{-0.1} _{-0.3}	45	2	0.8
	40225C or 40225CT	225 ^{-0.1} _{-0.3}	180	5	2.0
	40360C or 40360CT	360 ^{-0.1} _{-0.3}	315	8	3.1
	40405C or 40405CT	405 ^{-0.1} _{-0.3}	360	9	3.5
	40450C or 40450CT	450 ^{-0.1} _{-0.3}	405	10	3.9


◆ High-Force Magnetic Ways:
 SGLGM-40□□□C-M (without Mounting Holes on the Bottom)
 SGLGM-40□□□CT-M (with Mounting Holes on the Bottom)



Type	Magnetic Way Model SGLGM-	L1	L2	N	Approx. Mass [kg]
High-Force	40090C-M or 40090CT-M	90 ^{-0.1} _{-0.3}	45	2	1.0
	40225C-M or 40225CT-M	225 ^{-0.1} _{-0.3}	180	5	2.6
	40360C-M or 40360CT-M	360 ^{-0.1} _{-0.3}	315	8	4.1
	40405C-M or 40405CT-M	405 ^{-0.1} _{-0.3}	360	9	4.6
	40450C-M or 40450CT-M	450 ^{-0.1} _{-0.3}	405	10	5.1

3.3.3 SGLGW-60

◆ Moving Coils: SGLGW-60A□□□C□




Moving Coil Model SGLGW-	L1	L2	L3	L4	L5	L6	N1	N2	Approx. Mass* [kg]
60A140C□	140	125	90	30	52.5	45	3	4	0.48
60A253C□	252.5	237.5	180	37.5	60	135	5	8	0.82
60A365C□	365	350	315	30	52.5	270	8	14	1.16

* The mass is for a Moving Coil with a Polarity Sensor (Hall Sensor).

◆ Connector Specifications


• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	FG	Green

Plug: 350779-1
 Pins: 350561-3 or 350690-3 (No.1 to 3)
 350654-1 or 350669-1 (No. 4)
 From Tyco Electronics Japan G.K.
 Mating Connector
 Cap: 350780-1
 Socket: 350570-3 or 350689-3

• Polarity Sensor (Hall Sensor) Connector




1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	—	—


Pin connector: 17JE-23090-02 (D8C)-CG
 From DDK Ltd.
 Mating Connector
 Socket connector: 17JE-13090-02 (D8C)A-CG
 Studs: 17L-002C or 17L-002C1

◆ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Moving Coils: SGLGW-60A□□□C□D



Moving Coil Model SGLGW-	L1	L2	L3	L4	L5	L6	N1	N2	Approx. Mass* [kg]
60A140C□D	140	125	90	30	52.5	45	3	4	0.48
60A253C□D	252.5	237.5	180	37.5	60	135	5	8	0.82
60A365C□D	365	350	315	30	52.5	270	8	14	1.16

* The mass is for a Moving Coil with a Polarity Sensor (Hall Sensor).

◆ Connector Specifications

• Servomotor Connector




1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	Not used	–
5	Not used	–
6	FG	Green


Extension: SROC06JMSCN169
Pins: 021.423.1020
From Interconnection GmbH
Mating Connector
Plug: SPUC06KFSDN236
Socket: 020.030.1020

◆ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




• Polarity Sensor (Hall Sensor) Connector



1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	–	–


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.
Mating Connector
Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

◆ Standard-Force Magnetic Ways:
 SGLGM-60□□□C (without Mounting Holes on the Bottom)
 SGLGM-60□□□CT (with Mounting Holes on the Bottom)



Type	Magnetic Way Model SGLGM-	L1	L2	N	Approx. Mass [kg]
Standard-Force	60090C or 60090CT	90 ^{-0.1 -0.3}	45	2	1.1
	60225C or 60225CT	225 ^{-0.1 -0.3}	180	5	2.6
	60360C or 60360CT	360 ^{-0.1 -0.3}	315	8	4.1
	60405C or 60405CT	405 ^{-0.1 -0.3}	360	9	4.6
	60450C or 60450CT	450 ^{-0.1 -0.3}	405	10	5.1


◆ High-Force Magnetic Ways:
 SGLGM-60□□□C-M (without Mounting Holes on the Bottom)
 SGLGM-60□□□CT-M (with Mounting Holes on the Bottom)



Type	Magnetic Way Model SGLGM-	L1	L2	N	Approx. Mass [kg]
High-Force	60090C-M or 60090CT-M	90 ^{-0.1} _{-0.3}	45	2	1.3
	60225C-M or 60225CT-M	225 ^{-0.1} _{-0.3}	180	5	3.3
	60360C-M or 60360CT-M	360 ^{-0.1} _{-0.3}	315	8	5.2
	60405C-M or 60405CT-M	405 ^{-0.1} _{-0.3}	360	9	5.9
	60450C-M or 60450CT-M	450 ^{-0.1} _{-0.3}	405	10	6.6

3.3.4 SGLGW-90

◆ Moving Coils: SGLGW-90A□□□□




Moving Coil Model SGLGW-	L1	L2	L3	L4	L5	L6	N1	N2	Approx. Mass* [kg]
90A200C□	199	189	130	40	60	95	3	4	2.2
90A370C□	367	357	260	40	55	285	5	8	3.65
90A535C□	535	525	455	40	60	380	8	10	4.95

* The mass is for a Moving Coil with a Polarity Sensor (Hall Sensor).

◆ Connector Specifications


• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	FG	Green

Plug: 350779-1
 Pins: 350218-3 or 350547-3 (No.1 to 3)
 350654-1 or 350669-1 (No. 4)
 From Tyco Electronics Japan G.K.
 Mating Connector
 Cap: 350780-1
 Socket: 350537-3 or 350550-3

• Polarity Sensor (Hall Sensor) Connector




1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	—	—


Pin connector: 17JE-23090-02 (D8C)-CG
 From DDK Ltd.
 Mating Connector
 Socket connector: 17JE-13090-02 (D8C)A-CG
 Studs: 17L-002C or 17L-002C1

◆ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the S_u , S_v , and S_w polarity sensor (hall sensor) output signals and the inverse power of each motor phase V_u , V_v , and V_w when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Standard-Force Magnetic Ways: SGLGM-90□□□A



Magnetic Way Model SGLGM-	L1	L2	N	Approx. Mass [kg]
90252A	252 ^{-0.1 -0.3}	189	4	7.3
90504A	504 ^{-0.1 -0.3}	441	8	14.7


3.4 Selecting Cables

3.4.1 Cable Configurations

Prepare the cable required for the encoder.

Refer to the following manual to select a Linear Encoder.

📖 *Σ-7-Series AC Servo Drive Peripheral Device Selection Manual* (Manual No.: SIEP S800001 32)






* You can connect directly to an absolute linear encoder.

Note: Refer to the following manual for the following information.

- Cable dimensional drawings and cable connection specifications
- Order numbers and specifications of individual connectors for cables
- Order numbers and specifications for wiring materials

📖 *Σ-7-Series AC Servo Drive Peripheral Device Selection Manual* (Manual No.: SIEP S800001 32)

◆ Linear Servomotor Main Circuit Cables

Linear Servomotor Model	Length (L)	Order Number	Appearance
SGLGW-30A, -40A, -60A	1 m	JZSP-CLN11-01-E	
	3 m	JZSP-CLN11-03-E	
	5 m	JZSP-CLN11-05-E	
	10 m	JZSP-CLN11-10-E	
	15 m	JZSP-CLN11-15-E	
	20 m	JZSP-CLN11-20-E	
SGLGW-90A	1 m	JZSP-CLN21-01-E	
	3 m	JZSP-CLN21-03-E	
	5 m	JZSP-CLN21-05-E	
	10 m	JZSP-CLN21-10-E	
	15 m	JZSP-CLN21-15-E	
	20 m	JZSP-CLN21-20-E	
SGLGW-30A□□□□□D -40A□□□□□D -60A□□□□□D	1 m	JZSP-CLN14-01-E	
	3 m	JZSP-CLN14-03-E	
	5 m	JZSP-CLN14-05-E	
	10 m	JZSP-CLN14-10-E	
	15 m	JZSP-CLN14-15-E	
	20 m	JZSP-CLN14-20-E	

*1. Connector from Tyco Electronics Japan G.K.

*2. Connector from Interconnectron GmbH

Specifications, Ratings, and External Dimensions of SGLF Servomotors

4

This chapter describes how to interpret the model numbers of SGLF Servomotors and gives their specifications, ratings, and external dimensions.

4.1 Model Designations 4-3

- 4.1.1 SGLFW2 Models 4-3
- 4.1.2 SGLFW Models 4-4
- 4.1.3 Precautions on Moving Coils with
Polarity Sensors (Hall Sensors) 4-5

4.2 Ratings and Specifications: SGLFW2 Models . . 4-6

- 4.2.1 Specifications 4-6
- 4.2.2 Ratings: Self-Cooled Models 4-7
- 4.2.3 Force-Motor Speed Characteristics:
Self-Cooled Models 4-9
- 4.2.4 Ratings: Water-Cooled Models 4-10
- 4.2.5 Force-Motor Speed Characteristics:
Water-Cooled Models 4-11
- 4.2.6 Servomotor Overload Protection
Characteristics 4-12

4.3 Ratings and Specifications: SGLFW Models . . 4-13

- 4.3.1 Specifications 4-13
- 4.3.2 Ratings 4-14
- 4.3.3 Force-Motor Speed Characteristics 4-15
- 4.3.4 Servomotor Overload Protection
Characteristics 4-16

4.4 External Dimensions4-17

4.4.1	SGLFW2-30	4-17
4.4.2	SGLFW2-45	4-22
4.4.3	SGLFW2-90: Self-Cooled Models	4-25
4.4.4	SGLFW2-90: Water-Cooled Models	4-28
4.4.5	SGLFW2-90: Self-Cooled and Water-Cooled Models	4-30
4.4.6	SGLFW2-1D	4-31
4.4.7	SGLFW-20	4-34
4.4.8	SGLFW-35	4-36
4.4.9	SGLFW-50	4-39
4.4.10	SGLFW-1Z	4-42

4.5 Selecting Cables 4-45

4.5.1	Cable Configurations	4-45
4.5.2	Linear Servomotor Main Circuit Cables	4-46

4.1 Model Designations

4.1.1 SGLFW2 Models

◆ Moving Coil

S G L F W 2 - 30 A 070 A T 1 H

Linear Σ Series
Linear Servomotors

1st
digit

2nd
digits

3rd+4th
digits

5th
digit

6th+7th+8th
digits

9th
digit

10th
digit

11th
digit

12th
digit

1st digit Servomotor Type

Code	Specification
F	With F-type iron core

5th digit Power Supply Voltage

Code	Specification
A	200 VAC

10th digit Sensor Specification

Code	Specification
S	With polarity sensor(hall sensor) and Thermal Protector
T	Without polarity sensor(hall sensor), with Thermal Protector

2nd digit Moving Coil/Magnetic Way

Code	Specification
W2	Moving Coil

6th+7th+8th digits Length of Moving Coil

Code	Specification
070	70 mm
120	125 mm
200	205 mm
230	230 mm
380	384 mm
560	563 mm

3rd+4th digits Magnet Height

Code	Specification
30	30 mm
45	45 mm
90	90 mm
1D	135 mm

11th digit Cooling Method

Code	Specification
1	Self-cooled
L	Water-cooled

9th digit Design Revision Order

A

12th digit Connector for Servomotor Main Circuit Cable and Cable Length

Code	Specification
None	Connector from Tyco Electronics Japan G.K., 300 mm
F	Loose lead wires with no connector, 300 m
G	Loose lead wires with no connector, 500 m
H	Connector from Tyco Electronics Japan G.K., 500 mm

Note: This information is provided to explain model numbers. It is not meant to imply that models are available for all combinations of codes.

◆ Magnetic Way

S G L F M 2 - 30 270 A

Linear S Series
Linear Servomotors

1st
digit

2nd
digits

3rd+4th
digits

5th+6th+7th
digits

8th
digit

1st digit Servomotor Type

(Same as for the Moving Coil.)

2nd digit Moving Coil/Magnetic Way

Code	Specification
M	Magnetic Way

3rd+4th digits Magnet Height

(Same as for the Moving Coil.)

5th+6th+7th digits Length of Magnetic Way

Code	Specification
270	270 mm
306	306 mm
450	450 mm
510	510 mm
630	630 mm
714	714 mm

8th digit Design Revision Order

A

4.1.2 SGLFW Models

◆ Moving Coil

S G L F W - 20 A 090 A P □ - E

Linear Σ Series Linear Servomotors

1st digit 2nd digit 3rd+4th digits 5th digit 6th+7th+8th digits 9th digit 10th digit 11th digit 12th digit

1st digit Servomotor Type

Code	Specification
F	With F-type iron core

5th digit Voltage

Code	Specification
A	200 VAC

10th digit Sensor Specification

Code	Specification
P	With polarity sensor (hall sensor)
None	Without polarity sensor (hall sensor)

2nd digit Moving Coil/Magnetic Way

Code	Specification
W	Moving Coil

6th+7th+8th digits Length of Moving Coil

Code	Specification
090	91 mm
120	127 mm
200	215 mm
230	235 mm
380	395 mm

3rd+4th digits Magnet Height

Code	Specification
20	20 mm
35	36 mm
50	47.5 mm
1Z	95 mm

11th digit Connector for Servomotor Main Circuit Cable

Code	Specification	Applicable Models
None	Connector from Tyco Electronics Japan G.K.	All models
D	Connector from Interconnectron GmbH	SGLFW-35, -50, -1Z□200B

9th digit Design Revision Order

A, B ...

12th digit EU Directive Certification

Code	Specification
E	Certified
None	Not certified

Note: This information is provided to explain model numbers. It is not meant to imply that models are available for all combinations of codes.

◆ Magnetic Way

S G L F M - 20 324 A □

Linear Σ Series Linear Servomotors

1st digit 2nd digit 3rd+4th digits 5th+6th+7th digits 8th digit 9th digit

1st digit Servomotor Type

(Same as for the Moving Coil.)

5th+6th+7th digits Length of Magnetic Way

Code	Specification
324	324 mm
405	405 mm
540	540 mm
675	675 mm
756	756 mm
945	945 mm

9th digit Options

Code	Specification
None	Without options
C	With magnet cover

2nd digit Moving Coil/Magnetic Way

Code	Specification
M	Magnetic Way

3rd+4th digits Magnet Height

(Same as for the Moving Coil.)

8th digit Design Revision Order

A, B ...

4.1.3 Precautions on Moving Coils with Polarity Sensors (Hall Sensors)




Note


When you use a Moving Coil with a Polarity Sensor (Hall Sensor), the Magnetic Way must cover the bottom of the polarity sensor (hall sensor). Refer to the example that shows the correct installation.

When determining the length of the Moving Coil's stroke or the length of the Magnetic Way, consider the total length (L) of the Moving Coil and the polarity sensor (hall sensor). Refer to the following table.


Correct Installation



Incorrect Installation



◆ Total Length of Moving Coil with Polarity Sensor (Hall Sensor)



Moving Coil Model SGLFW2-	Length of Moving Coil, L1 [mm]	Length of Polarity Sensor (Hall Sensor), A [mm]	Total Length, L [mm]
30A070AS	70	27	97
30A120AS	125		152
30A230AS	230		257
45A200AS	205	32	237
45A380AS	384		416
90A200AS	205		237
90A380AS	384	32	416
90A560AS	563		595
1DA380AS	384		416
1DA560AS	563	32	595

Moving Coil Model SGLFW-	Length of Moving Coil, L1 [mm]	Length of Polarity Sensor (Hall Sensor), A [mm]	Total Length, L [mm]
20A090AP	91	22	113
20A120AP	127		149
35A120AP□	127	22	149
35A230AP□	235		257
50A200BP□	215	22	237
50A380BP□	395		417
1ZA200BP□	215		237
1ZA380BP	395	22	417

4.2 Ratings and Specifications: SGLFW2 Models

4.2.1 Specifications

Linear Servomotor Moving Coil Model SGLFW2-		30A			45A		90A			1DA	
		070A□	120A□	230A□	200A□	380A□	200A□	380A□	560A□	380A□	560A□
Time Rating		Continuous									
Thermal Class		B									
Insulation Resistance		500 VDC, 10 M Ω min.									
Withstand Voltage		1,500 VAC for 1 minute									
Excitation		Permanent magnet									
Cooling Method		Self-cooled and water-cooled									
Protective Structure		IP00									
Environ- mental Condi- tions	Surrounding Air Temperature	0°C to 40°C (with no freezing)									
	Surrounding Air Humidity	20% to 80% relative humidity (with no condensation)									
	Installation Site	• Must be indoors and free of corrosive and explosive gases. • Must be well-ventilated and free of dust and moisture. • Must facilitate inspection and cleaning. • Must have an altitude of 1,000 m or less. • Must be free of strong magnetic fields.									
Shock Resis- tance	Impact Accelera- tion Rate	196 m/s ²									
	Number of Impacts	2 times									
Vibra- tion Resis- tance	Vibration Accel- eration Rate	49 m/s ² (the vibration resistance in three directions, vertical, side-to-side, and front-to-back)									

4.2.2 Ratings: Self-Cooled Models

Linear Servomotor Moving Coil Model SGLFW2-		30A				45A		
		070A□1	120A□1	230A□1		200A□1	380A□1	
Rated Motor Speed (Reference Speed during Speed Control)* ¹	m/s	4.0	4.0	4.0		4.0	4.0	
Maximum Speed* ¹	m/s	5.0	5.0	5.0		4.5	4.5	
Rated Force* ^{1, *2}	N	45	90	180	170	280	560	
Maximum Force* ¹	N	135	270	540	500	840	1680	1500
Rated Current* ¹	Arms	1.4	1.5	2.9	2.8	4.4	8.7	
Maximum Current* ¹	Arms	5.3	5.2	10.5	9.3	16.4	32.7	27.5
Moving Coil Mass	kg	0.50	0.90	1.7		2.9	5.5	
Force Constant	N/Arms	33.3	64.5	64.5		67.5	67.5	
BEMF Constant	V _{rms} / (m/s)/ phase	11.1	21.5	21.5		22.5	22.5	
Motor Constant	N/ $\sqrt{W}$	11.3	17.3	24.4		36.9	52.2	
Electrical Time Constant	ms	7.6	7.3	7.3		19	19	
Mechanical Time Constant	ms	3.9	3.0	2.9		2.1	2.0	
Thermal Resistance (with Heat Sink)	K/W	2.62	1.17	0.79		0.60	0.44	
Thermal Resistance (without Heat Sink)	K/W	11.3	4.43	2.55		2.64	1.49	
Magnetic Attraction	N	200	630	1260		2120	4240	
Maximum Allowable Payload	kg	5.6	9.4	34	10	58	110	95
Maximum Allowable Payload (With External Regenera- tive Resistor and External Dynamic Brake Resis- tor* ³)	kg	5.6	11	34	20	64	110	110
Combined Magnetic Way, SGLFM2-		30□□□A				45□□□A		
Combined Serial Converter Unit, JZDP-□□□□-		628	629	630		631	632	
Applicable SERVOPACKs	SGD7S-	1R6A, 2R1F		3R8A	2R8A, 2R8F	5R5A	180A	120A
	SGD7W- SGD7C-	1R6A		—	2R8A	5R5A	—	

*1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. The values for other items are at 20°C. These are typical values.

*2. The rated forces are the continuous allowable force values at a surrounding air temperature of 40°C with an aluminum heat sink of the dimensions given in the following table.

- Heat Sink Dimensions
 - 150 mm × 100 mm × 10 mm: SGLFW2-30A070A
 - 254 mm × 254 mm × 25 mm: SGLFW2-30A120A and -30A230A
 - 400 mm × 500 mm × 25 mm: SGLFW2-45A200A and -45A380A

*3. To externally connect dynamic brake resistor, select hardware option specification 020 for the SERVOPACK. However, you cannot externally connect dynamic brake resistor if you use the following SERVOPACKs (maximum applicable motor capacity: 400 W).

- SGD7S-R70□□□A020 to -2R8□□□A020
- SGD7W-1R6A20A020 to -2R8A20A020
- SGD7C-1R6AMAA020 to -2R8AMAA020

4.2 Ratings and Specifications: SGLFW2 Models

4.2.2 Ratings: Self-Cooled Models

Linear Servomotor Moving Coil Model SGLFW2-		90A			1DA	
		200A□1	380A□1	560A□1	380A□1	560A□1
Rated Motor Speed (Reference Speed during Speed Control)* ¹	m/s	4.0	4.0	4.0	2.0	2.0
Maximum Speed* ¹	m/s	4.0	4.0	4.0	2.5	2.5
Rated Force* ^{1, *2}	N	560	1120	1680	1680	2520
Maximum Force* ¹	N	1680	3360	5040	5040	7560
Rated Current* ¹	Arms	7.2	14.4	21.6	14.4	21.6
Maximum Current* ¹	Arms	26.9	53.9	80.8	53.9	80.8
Moving Coil Mass	kg	5.3	10.1	14.9	14.6	21.5
Force Constant	N/Arms	82.0	82.0	82.0	123	123
BEMF Constant	Vrms/ (m/s)/ phase	27.3	27.3	27.3	41.0	41.0
Motor Constant	N/√W	58.1	82.2	101	105	129
Electrical Time Constant	ms	24	23	24	25	25
Mechanical Time Constant	ms	1.6	1.5	1.5	1.3	1.3
Thermal Resistance (with Heat Sink)	K/W	0.45	0.21	0.18	0.18	0.12
Thermal Resistance (without Heat Sink)	K/W	1.81	1.03	0.72	0.79	0.55
Magnetic Attraction	N	4240	8480	12700	12700	19100
Maximum Allowable Payload	kg	130	160	360	690	1000
Maximum Allowable Payload (With External Regenera- tive Resistor and External Dynamic Brake Resistor)	kg	140	290	440	710	1000
Combined Magnetic Way, SGLFM2-		90□□□A			1D□□□A	
Combined Serial Converter Unit, JZDP-□□□□-		633	634	648	649	650
Applicable SERVOPACKs	SGD7S-	120A	200A	330A	200A	330A
	SGD7W- SGD7C-	—				

*1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. The values for other items are at 20°C. These are typical values.

*2. The rated forces are the continuous allowable force values at a surrounding air temperature of 40°C with an aluminum heat sink of the dimensions given in the following table.

- Heat Sink Dimensions
 - 400 mm × 500 mm × 25 mm: SGLFW2-90A200A
 - 609 mm × 762 mm × 40 mm: SGLFW2-90A380A
 - 900 mm × 762 mm × 40 mm: SGLFW2-90A560A and -1DA380A
 - 1,400 mm × 900 mm × 40 mm: SGLFW2-1DA560A

*3. To externally connect dynamic brake resistor, select hardware option specification 020 for the SERVOPACK. However, you cannot externally connect dynamic brake resistor if you use the following SERVOPACKs (maximum applicable motor capacity: 400 W).

- SGD7S-R70□□□A020 to -2R8□□□A020
- SGD7W-1R6A20A020 to -2R8A20A020
- SGD7C-1R6AMAA020 to -2R8AMAA020

4.2.4 Ratings: Water-Cooled Models


Linear Servomotor Moving Coil Model SGLFW2-		90A
		200A□L
Rated Motor Speed (Reference Speed during Speed Control)* ¹	m/s	4.0
Maximum Speed* ¹	m/s	4.0
Rated Force* ¹ , * ²	N	896
Maximum Force* ¹	N	1680
Rated Current* ¹	Arms	11.5
Maximum Current* ¹	Arms	26.9
Moving Coil Mass	kg	6.1
Force Constant	N/Arms	82.0
BEMF Constant	Vrms/(m/s)/ phase	27.3
Motor Constant	N/√W	58.1
Electrical Time Constant	ms	24
Mechanical Time Constant	ms	1.8
Thermal Resistance with Water Cooling	K/W	0.22
Thermal Resistance without Water Cooling	K/W	1.81
Magnetic Attraction	N	4240
Maximum Allowable Load Mass	kg	120
Maximum Allowable Payload (With External Regenerative Resistor and External Dynamic Brake Resistor)	kg	130
Cooling Water Flow Rate	L/min	4.0
Combined Magnetic Way, SGLFM2-		90□□□A
Combined Serial Converter Unit, JZDP-□□□□-		699
Applicable SERVOPACKs	SGD7S-	120A
	SGD7W-	—

*1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. The values for other items are at 20°C. These are typical values.

*2. Do not allow the effective load ratio to exceed 80% when the servo is locked or during very small round-trip operation.

4.2.5 Force-Motor Speed Characteristics: Water-Cooled Models

[A] : Continuous duty zone — (solid lines): With three-phase 200-V input
 [B] : Intermittent duty zone - - - (dotted lines): With single-phase 200-V input




- Note: 1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. These are typical values.
2. The characteristics in the intermittent duty zone depend on the power supply voltage.
3. If the effective force is within the allowable range for the rated force, the Servomotor can be used within the intermittent duty zone.
4. If you use a Servomotor Main Circuit Cable that exceeds 20 m, the intermittent duty zone in the torque-motor speed characteristics will become smaller because the voltage drop increases.


4.2.6 Servomotor Overload Protection Characteristics

The overload detection level is set for hot start conditions with a Servomotor surrounding air temperature of 40°C.


SGLFW2-30A070A




SGLFW2-30A120A and -230A



SGLFW2-45A, -90A□1, and -1DA□1



SGLFW2-90A□L



Note: The above overload protection characteristics do not mean that you can perform continuous duty operation with an output of 100% or higher. Use the Servomotor so that the effective force remains within the continuous duty zone given in 4.2.3 *Force-Motor Speed Characteristics: Self-Cooled Models* on page 4-9 and on page 4-11.

4.3

Ratings and Specifications: SGLFW Models

4.3.1

Specifications

Linear Servomotor Moving Coil Model SGLFW-		20A		35A		50A		1ZA	
		090A	120A	120A	230A	200B	380B	200B	380B
Time Rating		Continuous							
Thermal Class		B							
Insulation Resistance		500 VDC, 10 M Ω min.							
Withstand Voltage		1,500 VAC for 1 minute							
Excitation		Permanent magnet							
Cooling Method		Self-cooled							
Protective Structure		IP00							
Environmental Conditions	Surrounding Air Temperature	0°C to 40°C (with no freezing)							
	Surrounding Air Humidity	20% to 80% relative humidity (with no condensation)							
	Installation Site	• Must be indoors and free of corrosive and explosive gases. • Must be well-ventilated and free of dust and moisture. • Must facilitate inspection and cleaning. • Must have an altitude of 1,000 m or less. • Must be free of strong magnetic fields.							
Shock Resistance	Impact Acceleration Rate	196 m/s ²							
	Number of Impacts	2 times							
Vibration Resistance	Vibration Acceleration Rate	49 m/s ² (the vibration resistance in three directions, vertical, side-to-side, and front-to-back)							

4.3.2 Ratings

Linear Servomotor Moving Coil Model SGLFW-		20A		35A		50A		1ZA	
		090A	120A	120A	230A	200B	380B	200B	380B
Rated Motor Speed (Reference Speed during Speed Control)* ¹	m/s	5.0	3.5	2.5	3.0	1.5	1.5	1.5	1.5
Maximum Speed* ¹	m/s	5.0	5.0	5.0	5.0	5.0	5.0	4.9	4.9
Rated Force* ^{1, *2}	N	25	40	80	160	280	560	560	1120
Maximum Force* ¹	N	86	125	220	440	600	1200	1200	2400
Rated Current* ¹	Arms	0.70	0.80	1.4	2.8	5.0	10.0	8.7	17.5
Maximum Current* ¹	Arms	3.0	2.9	4.4	8.8	12.4	25.0	21.6	43.6
Moving Coil Mass	kg	0.70	0.90	1.3	2.3	3.5	6.9	6.4	12
Force Constant	N/Arms	36.0	54.0	62.4	62.4	60.2	60.2	69.0	69.0
BEMF Constant	Vrms/(m/s)/ phase	12.0	18.0	20.8	20.8	20.1	20.1	23.0	23.0
Motor Constant	N/√W	7.95	9.81	14.4	20.4	34.3	48.5	52.4	74.0
Electrical Time Constant	ms	3.2	3.3	3.6	3.6	16	16	18	18
Mechanical Time Constant	ms	11	9.4	6.3	5.5	3.0	2.9	2.3	2.1
Thermal Resistance (with Heat Sink)	K/W	4.35	3.19	1.57	0.96	0.56	0.38	0.47	0.20
Thermal Resistance (without Heat Sink)	K/W	7.69	5.02	4.10	1.94	1.65	0.95	1.30	0.73
Magnetic Attraction	N	310	460	810	1590	1650	3260	3300	6520
Maximum Allowable Payload	kg	3.2	4.8	8.7	29	33	67	66	78
Maximum Allowable Payload (With External Regenerative Resistor and External Dynamic Brake Resistor* ³)	kg	3.2	4.8	8.7	29	40	80	82	160
Combined Magnetic Way, SGLFM-		20□□□□□		35□□□□□		50□□□□□		1Z□□□□□	
Combined Serial Converter Unit, JZDP-□□□□-		017	018	019	020	181	182	183	184
Applicable SERVOPACKs	SGD7S-	1R6A, 2R1F			3R8A	5R5A	120A		200A
	SGD7W- SGD7C-	1R6A			5R5A		—		

*1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. The values for other items are at 20°C. These are typical values.

*2. The rated forces are the continuous allowable force values at a surrounding air temperature of 40°C with an aluminum heat sink of the dimensions given in the following table.









- Heat Sink Dimensions
 - 125 mm × 125 mm × 13 mm: SGLFW-20A090A and -20A120A
 - 254 mm × 254 mm × 25 mm: SGLFW-35A120A and -35A230A
 - 400 mm × 500 mm × 40 mm: SGLFW-50A200B, 50A380B, and -1ZA200B
 - 600 mm × 762 mm × 50 mm: SGLFW-1ZA380B

*3. To externally connect dynamic brake resistor, select hardware option specification 020 for the SERVOPACK. However, you cannot externally connect dynamic brake resistor if you use the following SERVOPACKs (maximum applicable motor capacity: 400 W).

- SGD7S-R70□□□□A020 to -2R8□□□□A020
- SGD7W-1R6A20A020 to -2R8A20A020
- SGD7C-1R6AMAA020 to -2R8AMAA020

4.3.3 Force-Motor Speed Characteristics




- A** : Continuous duty zone ——— (solid lines); With three-phase 200-V input
B : Intermittent duty zone - - - - - (dotted lines); With single-phase 200-V input
 - · - · - (dashed-dotted lines); With single-phase 100-V input



- Note: 1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. These are typical values.
2. The characteristics in the intermittent duty zone depend on the power supply voltage.
3. If the effective force is within the allowable range for the rated force, the Servomotor can be used within the intermittent duty zone.
4. If you use a Servomotor Main Circuit Cable that exceeds 20 m, the intermittent duty zone in the torque-motor speed characteristics will become smaller because the voltage drop increases.

4.3.4 Servomotor Overload Protection Characteristics

The overload detection level is set for hot start conditions with a Servomotor surrounding air temperature of 40°C.




Note: The above overload protection characteristics do not mean that you can perform continuous duty operation with an output of 100% or higher. Use the Servomotor so that the effective force remains within the continuous duty zone given in 4.3.3 *Force-Motor Speed Characteristics* on page 4-15.

4.4 External Dimensions

4.4.1 SGLFW2-30

◆ Moving Coil with Polarity Sensor (Hall Sensor): SGLFW2-30A070AS



Moving Coil Model SGLFW2-	L	Approx. Mass [kg]
30A070AS1	300 ±30	0.5
30A070AS1H	500 ±50	0.5

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No. 1 to 3)
350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350536-3 or 350550-3

• Polarity Sensor (Hall Sensor) and Thermal Protector Connector



1	+5 V (thermal protector), +5 V (power supply)	6	
2	Su	7	Not used
3	Sv	8	
4	Sw	9	Thermal protector
5	0 V (power supply)		

Pin connector: 17JE-23090-02 (D8C) -CG
From DDK Ltd.

Mating Connector

Socket connector: 17JE-13090-02 (D8C) A-CG
Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.






Figure 1: Dimensions of the Servomotor Main Circuit Cable. The diagram shows a cross-section of the cable assembly with various components and their dimensions. Key dimensions include: 40±0.1 (width of the main cable), 27.5 (width of the inner cable), 1.5 (gap), 7 (width of the outer cable), 50 (length of the main cable), 12 (width of the inner cable), 15 (width of the outer cable), 12.5±0.1 (width of the inner cable), 0.2 (width of the outer cable), 29±0.1 (width of the inner cable), 10.2 (width of the outer cable), 6 (width of the inner cable), 50 min. (length of the main cable), 7 dia. (diameter of the inner cable), 50 min. (length of the main cable), 12.6 (width of the inner cable), 26.7 (width of the outer cable), 33.2 (width of the main cable), 15 (width of the inner cable), 7.5 (width of the outer cable), 7 dia. (diameter of the inner cable), 50 min. (length of the main cable), 12.6 (width of the inner cable), 26.7 (width of the outer cable), 33.2 (width of the main cable), 15 (width of the inner cable), 7.5 (width of the outer cable), 7 dia. (diameter of the inner cable), 50 min. (length of the main cable).



Unit: mm

Moving Coil Model SGLFW2-	L1	L2	L3	L4	Approx. Mass [kg]
30A120AS1	125	52.5	105.9	300 ±30	0.9
30A120AS1H				500 ±50	
30A230AS1	230	157.5	210.9	300 ±30	1.7
30A230AS1H				500 ±50	

- Servomotor Connector




1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Socket: 350536-3 or 350550-3


1	+5 V (thermal protector), +5 V (power supply)		
2	Su	6	Not used
3	Sv	7	
4	Sw	8	
5	0 V (power supply)	9	Thermal protector

Studs: 17L-002C or 17L-002C1


The figure on the right shows the relationship between the S_u , S_v , and S_w polarity sensor (hall sensor) output signals and the inverse power of each motor phase V_u , V_v , and V_w when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Moving Coil without Polarity Sensor (Hall Sensor): SGLFW2-30A070AT



①SGLFW2-30A070AT




Unit: mm

Moving Coil Model SGLFW2-	L	Approx. Mass [kg]
30A070AT1	300 ±30	0.5
30A070AT1H	500 ±50	0.5

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No.1 to 3)

350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350536-3 or 350550-3

• Thermal Protector Connector



1	Thermal protector
2	Thermal protector

Receptacle housing: 5557-02R

Terminals: 5556T or 5556TL


From Molex Japan LLC

Mating Connector


Plug housing: 5559-02P

Terminals: 5558T or 5558TL


◆ Moving Coils without Polarity Sensors (Hall Sensors): SGLFW2-30A□□□AT



①SGLFW2-30A120AT



②SGLFW2-30A230AT




Unit: mm

Moving Coil Model SGLFW2-	L1	L2	L3	L4	Approx. Mass [kg]
30A120AT1	125	52.5	105.9	300 ±30	0.9
30A120AT1H				500 ±50	
30A230AT1	230	157.5	210.9	300 ±30	1.7
30A230AT1H				500 ±50	

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No.1 to 3)

350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350536-3 or 350550-3

• Thermal Protector Connector



1	Thermal protector
2	Thermal protector

Receptacle housing: 5557-02R

Terminals: 5556T or 5556TL

From Molex Japan LLC

Mating Connector

Plug housing: 5559-02P

Terminals: 5558T or 5558TL

Technical drawing of the mounting section details of the sensor.

Side View Dimensions:

- Total length: 10.2 ± 0.1
- Mounting tab width: 6
- Screw head height: 4.2 max.

Top View Dimensions:

- Overall width: 55
- Overall length: 45
- Distance between mounting holes: 27.5 (27.5)
- Distance from mounting holes to reference mark: 22.5 ± 0.1
- Distance between reference marks: 45
- Total length: $L1 \pm 0.1$
- Distance between reference marks: $L2$
- Reference mark: (Reference mark)

Mounting Details:

- 2 x N, 4.8-dia. mounting holes
- 8.5 dia. $\nabla 0.4$

Height of screw head: 4.2 max.


Mounting Section Details

Note: More than one Magnetic Way can be connected. Connect the Magnetic Ways so that the reference marks on them are aligned in the same direction as shown in the figure.

Magnetic Way Model SGLFM2-	L1 ± 0.1	L2	N	Approx. Mass [kg]
30270A	270	225 (45 × 5)	6	0.9
30450A	450	405 (45 × 9)	10	1.5
30630A	630	585 (45 × 13)	14	2.0

4.4.2 SGLFW2-45

◆ Moving Coils with Polarity Sensors (Hall Sensors): SGLFW2-45A□□□AS



Moving Coil Model SGLFW2-	L1	L2	L3	L4	Flatness	Approx. Mass [kg]
45A200AS1	205	89.5	187	300 ±30	0.2	2.9
45A200AS1H				500 ±50		
45A380AS1	384	268.5	365.5	300 ±30	0.3	5.5
45A380AS1H				500 ±50		

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No.1 to 3)

350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350536-3 or 350550-3

• Polarity Sensor (Hall Sensor) and Thermal Protector Connector



1	+5 V (thermal protector), +5 V (power supply)		
2	Su	6	Not used
3	Sv	7	
4	Sw	8	
5	0 V (power supply)	9	Thermal protector

Pin connector: 17JE-23090-02 (D8C) -CG
From DDK Ltd.


Mating Connector

Socket connector: 17JE-13090-02 (D8C) A-CG


Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




◆ Moving Coils without Polarity Sensors (Hall Sensors): SGLFW2-45A□□□AT



Moving Coil Model SGLFW2-	L1	L2	L3	L4	Flatness	Approx. Mass [kg]
45A200AT1	205	89.5	187	300 ±30	0.2	2.9
45A200AT1H				500 ±50		
45A380AT1	384	268.5	365.5	300 ±30	0.3	5.5
45A380AT1H				500 ±50		

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No.1 to 3)

350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350536-3 or 350550-3

• Thermal Protector Connector



1	Thermal protector
2	Thermal protector

Receptacle housing: 5557-02R

Terminals: 5556T or 5556TL


From Molex Japan LLC

Mating Connector

Plug housing: 5559-02P

Terminals: 5558T or 5558TL

◆ Magnetic Ways: SGLFM2-45□□□A




Unit: mm

Note: More than one Magnetic Way can be connected. Connect the Magnetic Ways so that the reference marks on them are aligned in the same direction as shown in the figure.

Magnetic Way Model SGLFM2-	L1 $\pm$ 0.1	L2	N	Approx. Mass [kg]
45306A	306	204 (102 $\times$ 2)	3	1.5
45510A	510	408 (102 $\times$ 4)	5	2.5
45714A	714	612 (102 $\times$ 6)	7	3.4

4.4.3 SGLFW2-90: Self-Cooled Models


◆ Moving Coils with Polarity Sensors (Hall Sensors): SGLFW2-90A□□□AS1



Moving Coil Model SGLFW2-	L1	L2	L3	L4	Flatness	Approx. Mass [kg]
90A200AS1	205	89.5	187	300 ±30	0.2	5.3
90A200AS1H				500 ±50		
90A380AS1	384	268.5	365.5	300 ±30	0.3	10.1
90A380AS1H				500 ±50		
90A560AS1	563	447.5	544	300 ±30	0.3	14.9
90A560AS1H				500 ±50		

■ Connector Specifications

• Servomotor Connector



A1	Phase U	Red
A2	Phase V	White
B1	Phase W	Black
B2	FG	Green

Tab housing: 1-917808-2

Contacts: 917803-2 (A1, A2, and B1)
84695-1 (B2)


From Tyco Electronics Japan G.K.

Mating Connector

Receptacle housing: 1-917807-2

Contacts: 179956-2

• Polarity Sensor (Hall Sensor) and Thermal Protector Connector



1	+5 V (thermal protector), +5 V (power supply)	
2	Su	6
3	Sv	7
4	Sw	8
5	0 V (power supply)	9
		Thermal protector

Pin connector: 17JE-23090-02 (D8C) -CG

From DDK Ltd.


Mating Connector

Socket connector: 17JE-13090-02 (D8C) A-CG


Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal


The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




◆ Moving Coils without Polarity Sensors (Hall Sensors): SGLFW2-90A□□□AT1




①SGLFW2-90A200AT



②SGLFW2-90A380AT



③SGLFW2-90A560AT




Unit: mm

Moving Coil Model SGLFW2-	L1	L2	L3	L4	Flatness	Approx. Mass [kg]
90A200AT1	205	89.5	187	300 ±30	0.2	5.3
90A200AT1H				500 ±50		
90A380AT1	384	268.5	365.5	300 ±30	0.3	10.1
90A380AT1H				500 ±50		
90A560AT1	563	447.5	544	300 ±30	0.3	14.9
90A560AT1H				500 ±50		

■ Connector Specifications

• Servomotor Connector



A1	Phase U	Red
A2	Phase V	White
B1	Phase W	Black
B2	FG	Green

Tab housing: 1-917808-2


Contacts: 917803-2 (A1, A2, and B1)
84695-1 (B2)

From Tyco Electronics Japan G.K.

Mating Connector

Receptacle housing: 1-917807-2
Contacts: 179956-2

• Thermal Protector Connector



1	Thermal protector
2	Thermal protector

Receptacle housing: 5557-02R

Terminals: 5556T or 5556TL

From Molex Japan LLC

Mating Connector


Plug housing: 5559-02P

Terminals: 5558T or 5558TL

4.4.4 SGLFW2-90: Water-Cooled Models

Contact your Yaskawa representative for information on the SGLFW2-90A380A□L□ and -90A560A□L□.

◆ Moving Coils with Polarity Sensors (Hall Sensors): SGLFW2-90A200ASL□




* Use R1/8 stainless steel joints for the cooling medium.
There is no directionality to the cooling medium ports. Use either side as the inlet port.

Moving Coil Model SGLFW2-	L	Approx. Mass [kg]
90A200ASL	300 ±30	6.1
90A200ASLH	500 ±50	6.1

■ Connector Specifications

• Servomotor Connector



A1	Phase U	Red
A2	Phase V	White
B1	Phase W	Black
B2	FG	Green


Tab housing: 1-917808-2
Contacts: 917803-2 (A1, A2, and B1)
84695-1 (B2)

From Tyco Electronics Japan G.K.

Mating Connector

Receptacle housing: 1-917807-2
Contacts: 179956-2

• Polarity Sensor (Hall Sensor) and Thermal Protector Connector



1	+5 V (thermal protector), +5 V (power supply)		
2	Su	6	Not used
3	Sv	7	
4	Sw	8	
5	0 V (power supply)	9	Thermal protector


Pin connector: 17JE-23090-02 (D8C) -CG
From DDK Ltd.

Mating Connector


Socket connector: 17JE-13090-02 (D8C) A-CG
Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Moving Coils without Polarity Sensors (Hall Sensors): SGLFW2-90A200ATL□



* Use R1/8 stainless steel joints for the cooling medium.
There is no directionality to the cooling medium ports. Use either side as the inlet port.

Moving Coil Model SGLFW2-	L	Approx. Mass [kg]
90A200ATL	300 ±30	6.1
90A200ATLH	500 ±50	6.1

■ Connector Specifications

• Servomotor Connector

B1	A1	Phase U	Red
B2	A2	Phase V	White
A1	B1	Phase W	Black
A2	B2	FG	Green

Tab housing: 1-917808-2
Contacts: 917803-2 (A1, A2, and B1)
84695-1 (B2)
From Tyco Electronics Japan G.K.

Mating Connector

Receptacle housing: 1-917807-2
Contacts: 179956-2

• Thermal Protector Connector

1	Thermal protector
2	Thermal protector

Receptacle housing: 5557-02R
Terminals: 5556T or 5556TL
From Molex Japan LLC

Mating Connector

Plug housing: 5559-02P
Terminals: 5558T or 5558TL


◆ Magnetic Ways: SGLFM2-90□□□A



Magnetic Way Model SGLFM2-	L1±0.1	L2	N	Approx. Mass [kg]
90306A	306	204 (102 × 2)	3	2.6
90510A	510	408 (102 × 4)	5	4.2
90714A	714	612 (102 × 6)	7	5.9

4.4.6 SGLFW2-1D


◆ Moving Coil with Polarity Sensor (Hall Sensor): SGLFW2-1DA□□□AS1



Moving Coil Model SGLFW2-	L1	L2	L3	L4	Flatness	Approx. Mass [kg]
1DA380AS1	384	268.5	365.5	300 ±30	0.3	14.6
1DA380AS1H				500 ±50		
1DA560AS1	563	447.5	544	300 ±30	0.3	21.5
1DA560AS1H				500 ±50		

■ Connector Specifications

• Servomotor Connector



A1	Phase U	Red
A2	Phase V	White
B1	Phase W	Black
B2	FG	Green


Tab housing: 1-917808-2
 Contacts: 917803-2 (A1, A2, and B1)
 84695-1 (B2)

From Tyco Electronics Japan G.K.

Mating Connector

Receptacle housing: 1-917807-2
 Contacts: 179956-2

• Polarity Sensor (Hall Sensor) and Thermal Protector Connector



1	+5 V (thermal protector), +5 V (power supply)	6	Not used
2	Su	7	
3	Sv	8	
4	Sw	9	
5	0 V (power supply)		Thermal protector


Pin connector: 17JE-23090-02 (D8C) -CG
 From DDK Ltd.

Mating Connector


Socket connector: 17JE-13090-02 (D8C) A-CG
 Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




◆ Moving Coil without Polarity Sensor (Hall Sensor): SGLFW2-1DA□□□AT1



Moving Coil Model SGLFW2-	L1	L2	L3	L4	Flatness	Approx. Mass [kg]
1DA380AT1	384	268.5	365.5	300 ±30	0.3	14.6
1DA380AT1H				500 ±50		
1DA560AT1	563	447.5	544	300 ±30	0.3	21.5
1DA560AT1H				500 ±50		

■ Connector Specifications

• Servomotor Connector

	A1	Phase U	Red
	A2	Phase V	White
	B1	Phase W	Black
	B2	FG	Green


Tab housing: 1-917808-2
Contacts: 917803-2 (A1, A2, and B1)
84695-1 (B2)

From Tyco Electronics Japan G.K.

Mating Connector

Receptacle housing: 1-917807-2
Contacts: 179956-2

• Polarity Sensor (Hall Sensor) and Thermal Protector Connector


	1	+5 V (thermal protector), +5 V (power supply)	
	2	Su	6
	3	Sv	7
	4	Sw	8
	5	0 V (power supply)	9
		Thermal protector	

Pin connector: 17JE-23090-02 (D8C) -CG
From DDK Ltd.

Mating Connector

Socket connector: 17JE-13090-02 (D8C) A-CG
Studs: 17L-002C or 17L-002C1

◆ Magnetic Ways: SGLFM2-1D□□□A




Note: More than one Magnetic Way can be connected. Connect the Magnetic Ways so that the reference marks on them are aligned in the same direction as shown in the figure.


Magnetic Way Model SGLFM2-	$L1 \pm 0.1$	$L2$	N	Approx. Mass [kg]
1D306A	306	204 (102 × 2)	3	3.7
1D510A	510	408 (102 × 4)	5	6.2
1D714A	714	612 (102 × 6)	7	8.6

4.4.7 SGLFW-20


◆ Moving Coils: SGLFW-20A□□□A□



① SGLFW-20A090A□



② SGLFW-20A120A□



Unit: mm

Moving Coil Model SGLFW-	L1	L2	L3	Approx. Mass [kg]
20A090A□	91	36	72	0.7
20A120A□	127	72	108	0.9

Note: The above dimensional drawing gives the dimensions for both models with polarity sensors (hall sensors) and models without polarity sensors (hall sensors).

■ Connector Specifications


• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Plug: 350779-1
Pins: 350218-3 or 350547-3 (No.1 to 3)
350654-1 or 350669-1 (No. 4)
From Tyco Electronics Japan G.K.
Mating Connector
Cap: 350780-1
Socket: 350536-3 or 350550-3

• Polarity Sensor (Hall Sensor) Connector




1	+5 V (thermal protector), +5 V (power supply)	6	Not used
2	Su	7	
3	Sv	8	
4	Sw	9	
5	0 V (power supply)		Thermal protector


Pin connector: 17JE-23090-02 (D8C) -CG
From DDK Ltd.
Mating Connector
Socket connector: 17JE-13090-02 (D8C) A-CG
Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




◆ Magnetic Ways: SGLFM-20□□□A



Note: More than one Magnetic Way can be connected. Connect the Magnetic Ways so that the reference marks on them are aligned in the same direction as shown in the figure.

Magnetic Way Model SGLFM-	L1	L2	(L3)	LA	N	Approx. Mass [kg]
20324A	324 ^{-0.1} _{-0.3}	270 (54 × 5)	(331.6)	30.8 ⁰ _{-0.2}	6	0.9
20540A	540 ^{-0.1} _{-0.3}	486 (54 × 9)	(547.6)	30.8 ⁰ _{-0.2}	10	1.4
20756A	756 ^{-0.1} _{-0.3}	702 (54 × 13)	(763.6)	30.8 ⁰ _{-0.2}	14	2


◆ Moving Coils: SGLFW-35A□□□A□




Note: The above dimensional drawing gives the dimensions for both models with polarity sensors (hall sensors) and models without polarity sensors (hall sensors).

Pin connector: 17JE-23090-02 (D8C) -CG
From DDK Ltd.
Mating Connector
Socket connector: 17JE-13090-02 (D8C) A-CG
Studs: 17L-002C or 17L-002C1


The figure on the right shows the relationship between the S_u , S_v , and S_w polarity sensor (hall sensor) output signals and the inverse power of each motor phase V_u , V_v , and V_w when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




◆ Moving Coils: SGLFW-35A□□□A□D



① SGLFW-35A120A□D



② SGLFW-35A230A□D



Unit: mm

Moving Coil Model SGLFW-	L1	L2	L3	Flatness	Approx. Mass [kg]
35A120A□D	127	72	108	0.1	1.3
35A230A□D	235	180	216	0.2	2.3

Note: The above dimensional drawing gives the dimensions for both models with polarity sensors (hall sensors) and models without polarity sensors (hall sensors).

■ Connector Specifications

• Servomotor Connector



1	Phase U	5	Not used
2	Phase V	6	Not used
4	Phase W	⊕	Ground

Extension: ARRA06AMRPN182

Pins: 021.279.1020


From Interconnection GmbH

Mating Connector

Plug: APRA06BFRDN170

Socket: 020.105.1020

• Polarity Sensor (Hall Sensor) Connector



1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	—	—

Pin connector: 17JE-23090-02 (D8C)-CG

From DDK Ltd.


Mating Connector

Socket connector: 17JE-13090-02 (D8C)A-CG

Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




Unit: mm

Note: More than one Magnetic Way can be connected. Connect the Magnetic Ways so that the reference marks on them are aligned in the same direction as shown in the figure.

Magnetic Way Model SGLFM-	L1	L2	(L3)	LA	N	Approx. Mass [kg]
35324A	324 ^{-0.1} _{-0.3}	270 (54 × 5)	(334.4)	32.2 ⁰ _{-0.2}	6	1.2
35540A	540 ^{-0.1} _{-0.3}	486 (54 × 9)	(550.4)	32.2 ⁰ _{-0.2}	10	2
35756A	756 ^{-0.1} _{-0.3}	702 (54 × 13)	(766.4)	32.2 ⁰ _{-0.2}	14	2.9

4.4.9 SGLFW-50

◆ Moving Coils: SGLFW-50A□□□□□




Moving Coil Model SGLFW-	L1	L2	L3	Flatness	Approx. Mass [kg]
50A200B□	215	120	180	0.2	3.5
50A380B□	395	300	360	0.3	6.9

Note: The above dimensional drawing gives the dimensions for both models with polarity sensors (hall sensors) and models without polarity sensors (hall sensors).

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No.1 to 3)
350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350536-3 or 350550-3

• Polarity Sensor (Hall Sensor) Connector



1	+5 V (thermal protector), +5 V (power supply)		
2	Su	6	Not used
3	Sv	7	
4	Sw	8	
5	0 V (power supply)	9	Thermal protector

Pin connector: 17JE-23090-02 (D8C) -CG

From DDK Ltd.


Mating Connector

Socket connector: 17JE-13090-02 (D8C) A-CG




Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Moving Coils: SGLFW-50A□□□B□D



Unit: mm

Moving Coil Model SGLFW-	L1	L2	L3	Flatness	Approx. Mass [kg]
50A200B□D	215	120	180	0.2	3.5
50A380B□D	395	300	360	0.3	6.9

Note: The above dimensional drawing gives the dimensions for both models with polarity sensors (hall sensors) and models without polarity sensors (hall sensors).

■ Connector Specifications


• Servomotor Connector



1	Phase U	5	Not used
2	Phase V	6	Not used
4	Phase W	⊕	Ground

Extension: ARRA06AMRPN182
Pins: 021.279.1020
From Interconnectron GmbH
Mating Connector
Plug: APRA06BFRDN170
Socket: 020.105.1020

• Polarity Sensor (Hall Sensor) Connector




1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	—	—


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.
Mating Connector
Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Magnetic Ways: SGLFM-50□□□A




Note: More than one Magnetic Way can be connected. Connect the Magnetic Ways so that the reference marks on them are aligned in the same direction as shown in the figure.

Magnetic Way Model SGLFM-	L1	L2	(L3)	LA	N	Approx. Mass [kg]
50405A	405 ^{-0.1} _{-0.3}	337.5 (67.5 × 5)	(416.3)	39.4 ⁰ _{-0.2}	6	2.8
50675A	675 ^{-0.1} _{-0.3}	607.5 (67.5 × 9)	(686.3)	39.4 ⁰ _{-0.2}	10	4.6
50945A	945 ^{-0.1} _{-0.3}	877.5 (67.5 × 13)	(956.3)	39.4 ⁰ _{-0.2}	14	6.5

4.4.10 SGLFW-1Z

◆ Moving Coils: SGLFW-1ZA□□□B□




Moving Coil Model SGLFW-	L1	L2	L3	Approx. Mass [kg]
1ZA200B□	215	120	180	6.4
1ZA380B□	395	300	360	11.5

Note: The above dimensional drawing gives the dimensions for both models with polarity sensors (hall sensors) and models without polarity sensors (hall sensors).

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Black
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No.1 to 3)

350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350536-3 or 350550-3

• Polarity Sensor (Hall Sensor) Connector



1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	-	-

Pin connector: 17JE-23090-02 (D8C)-CG

From DDK Ltd.


Mating Connector

Socket connector: 17JE-13090-02 (D8C)A-CG



Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




Specifications, Ratings, and External Dimensions of SGLF Servomotors




■ Connector Specifications

- Servomotor Connector




■ Polarity Sensor (Hall Sensor) Output Signal

- Polarity Sensor (Hall Sensor) Connector



4

◆ Magnetic Ways: SGLFM-1Z□□□A



Note: More than one Magnetic Way can be connected. Connect the Magnetic Ways so that the reference marks on them are aligned in the same direction as shown in the figure.

Magnetic Way Model SGLFM-	L1	L2	(L3)	LA	N	Approx. Mass [kg]
1Z405A	405 ^{-0.1 -0.3}	337.5 (67.5 × 5)	(423.9)	43.2 ^{0 -0.2}	6	5
1Z675A	675 ^{-0.1 -0.3}	607.5 (67.5 × 9)	(693.9)	43.2 ^{0 -0.2}	10	8.3
1Z945A	945 ^{-0.1 -0.3}	877.5 (67.5 × 13)	(963.9)	43.2 ^{0 -0.2}	14	12


4.5 Selecting Cables

4.5.1 Cable Configurations

Prepare the cable required for the encoder.

Refer to the following catalog to select a Linear Encoder.

📖 *AC Servo Drives Σ -7 Series* (Manual No.: KAEP S800001 23)










* You can connect directly to an absolute linear encoder.

Note: Refer to the following manual for the following information.

- Cable dimensional drawings and cable connection specifications
- Order numbers and specifications of individual connectors for cables
- Order numbers and specifications for wiring materials


📖 *Σ -7-Series AC Servo Drive Peripheral Device Selection Manual* (Manual No.: SIEP S800001 32)

4.5.2 Linear Servomotor Main Circuit Cables

Linear Servomotor Model	Length (L)	Order Number	Appearance
SGLFW-20A, -35A	1 m	JZSP-CLN11-01-E	
	3 m	JZSP-CLN11-03-E	
	5 m	JZSP-CLN11-05-E	
	10 m	JZSP-CLN11-10-E	
	15 m	JZSP-CLN11-15-E	
	20 m	JZSP-CLN11-20-E	
SGLFW-50A, -1ZA	1 m	JZSP-CLN21-01-E	
	3 m	JZSP-CLN21-03-E	
	5 m	JZSP-CLN21-05-E	
	10 m	JZSP-CLN21-10-E	
	15 m	JZSP-CLN21-15-E	
	20 m	JZSP-CLN21-20-E	
SGLFW-□□A□□□□□□□	1 m	JZSP-CLN14-01-E	
	3 m	JZSP-CLN14-03-E	
	5 m	JZSP-CLN14-05-E	
	10 m	JZSP-CLN14-10-E	
	15 m	JZSP-CLN14-15-E	
	20 m	JZSP-CLN14-20-E	
SGLFW2-30A070A□ SGLFW2-30A120A□ SGLFW2-30A230A□	1 m	JZSP-CL2N703-01-E	
	3 m	JZSP-CL2N703-03-E	
	5 m	JZSP-CL2N703-05-E	
	10 m	JZSP-CL2N703-10-E	
	15 m	JZSP-CL2N703-15-E	
	20 m	JZSP-CL2N703-20-E	
SGLFW2-45A200A□ SGLFW2-45A380A□	1 m	JZSP-CL2N603-01-E	
	3 m	JZSP-CL2N603-03-E	
	5 m	JZSP-CL2N603-05-E	
	10 m	JZSP-CL2N603-10-E	
	15 m	JZSP-CL2N603-15-E	
	20 m	JZSP-CL2N603-20-E	
SGLFW2-90A200A□ SGLFW2-90A380A□	1 m	JZSP-CL2N803-01-E	
	3 m	JZSP-CL2N803-03-E	
	5 m	JZSP-CL2N803-05-E	
	10 m	JZSP-CL2N803-10-E	
	15 m	JZSP-CL2N803-15-E	
	20 m	JZSP-CL2N803-20-E	
SGLFW2-90A560A□ SGLFW2-1DA380A□ SGLFW2-1DA560A□	1 m	JZSP-CL2N503-01-E	
	3 m	JZSP-CL2N503-03-E	
	5 m	JZSP-CL2N503-05-E	
	10 m	JZSP-CL2N503-10-E	
	15 m	JZSP-CL2N503-15-E	
	20 m	JZSP-CL2N503-20-E	

Continued on next page.

Continued from previous page.

Linear Servomotor Model	Length (L)	Order Number	Appearance
SGLFW2-90A200A□L□	1 m	JZSP-CLN423-01-E	
	3 m	JZSP-CLN423-03-E	
	5 m	JZSP-CLN423-05-E	
	10 m	JZSP-CLN423-10-E	
	15 m	JZSP-CLN423-15-E	
	20 m	JZSP-CLN423-20-E	

Note: Estimates are available for models other than those listed above (SGLFW2-90A□□□A□L and SGLFW2-1D□□□A□L).

*1. Connector from Tyco Electronics Japan G.K.

*2. Connector from Interconnectron GmbH

Specifications, Ratings, and External Dimensions of SGLT Servomotors

5

This chapter describes how to interpret the model numbers of SGLT Servomotors and gives their specifications, ratings, and external dimensions.

5.1 Model Designations 5-2

- 5.1.1 Moving Coil 5-2
- 5.1.2 Magnetic Way 5-3
- 5.1.3 Precautions on Moving Coils with Polarity
Sensors (Hall Sensor) 5-4

5.2 Ratings and Specifications 5-5

- 5.2.1 Specifications 5-5
- 5.2.2 Ratings 5-6
- 5.2.3 Force-Motor Speed Characteristics 5-7
- 5.2.4 Servomotor Overload Protection
Characteristics 5-9

5.3 External Dimensions 5-10

- 5.3.1 SGLTW-20: Standard Models 5-10
- 5.3.2 SGLTW-35: Standard Models 5-13
- 5.3.3 SGLTW-35□□□□H□: High-efficiency
Models 5-16
- 5.3.4 SGLTW-40: Standard Models 5-18
- 5.3.5 SGLTW-50: High-efficiency Models 5-21
- 5.3.6 SGLTW-80: Standard Models 5-23

5.4 Selecting Cables 5-26

- 5.4.1 Cable Configurations 5-26
- 5.4.2 Linear Servomotor Main Circuit Cables 5-27

5.1 Model Designations

5.1.1 Moving Coil

S	G	L	T	W	-	20	A	170	A	P	□	-	E
Linear Σ Series Linear Servomotors			1st digit	2nd digit		3rd+4th digits	5th digit	6th+7th+8th digits	9th digit	10th digit	11th digit		12th digit

1st digit Servomotor Type

Code	Specification
T	With T-type iron core

2nd digit Moving Coil/Magnetic Way

Code	Specification
W	Moving Coil

3rd+4th digits Magnet Height

Code	Specification
20	20 mm
35	36 mm
40	40 mm
50	51 mm
80	76.5 mm

5th digit Power Supply Voltage

Code	Specification
A	200 VAC

6th+7th+8th digits Length of Moving Coil

Code	Specification
170	170 mm
320	315 mm
400	394.2 mm
460	460 mm
600	574.2 mm

9th digit Design Revision Order

A, B ...
H: High-efficiency model

10th digit Sensor Specification and Cooling Method

Code	Specifications		Applicable Models
	Polarity Sensor (Hall Sensor)	Cooling Method	
None	None	Self-cooled	All models
C*	None	Water-cooled	SGLTW-40, -80
H*	Yes	Water-cooled	
P	Yes	Self-cooled	All models

11th digit Connector for Servomotor Main Circuit Cable

Code	Specification	Applicable Models
None	Connector from Tyco Electronics Japan G.K.	SGLTW-20A□□□□□□ -35A□□□□□□
	MS connector	SGLTW-40A□□□□B□ -80A□□□□B□
	Loose lead wires with no connector	SGLTW-35A□□□□H□ -50A□□□□H□

12th digit EU Directive Certification

Code	Specification
E	Certified
None	Not certified

* Contact your Yaskawa representative for the characteristics, dimensions, and other details on Servomotors with these specifications.

Note: This information is provided to explain model numbers. It is not meant to imply that models are available for all combinations of codes.

5.1.2

Magnetic Way



1st digit Servomotor Type
(Same as for the Moving Coil.)

2nd digit Moving Coil/Magnetic Way

Code	Specification
M	Magnetic Way

3rd+4th digits Magnet Height
(Same as for the Moving Coil.)

5th+6th+7th digits Length of
Magnetic Way

Code	Specification
324	324 mm
405	405 mm
540	540 mm
675	675 mm
756	756 mm
945	945 mm

8th digit Design Revision Order
A, B ...
H: High-efficiency model

9th digit Options

Code	Specification	Applicable Models
None	Without options	–
C	With magnet cover	All models
Y	With base and magnet cover	SGLTM-20, -35*, -40, -80

* The SGLTM-35□□□H (high-efficiency models) do not support this specification.

Note: This information is provided to explain model numbers. It is not meant to imply that models are available for all combinations of codes.

5.1.3 Precautions on Moving Coils with Polarity Sensors (Hall Sensor)




Note


When you use a Moving Coil with a Polarity Sensor (Hall Sensor), the Magnetic Way must cover the bottom of the polarity sensor (hall sensor). Refer to the example that shows the correct installation.

When determining the length of the Moving Coil's stroke or the length of the Magnetic Way, consider the total length of the Moving Coil and the polarity sensor (hall sensor). Refer to the following table.


Correct Installation



Incorrect Installation



◆ Total Length of Moving Coil with Polarity Sensor (Hall Sensor)



Moving Coil Model SGLTW-	Length of Moving Coil, L1 [mm]	Length of Polarity Sensor (Hall Sensor), A [mm]	Total Length, L [mm]
20A170AP□	170	34	204
20A320AP□	315		349
20A460AP□	460		494
35A170AP□	170	34	204
35A320AP□	315		349
35A460AP□	460		494
35A170HP□	170	34	204
35A320HP□	315		349
50A170HP□	170		204
50A320HP□	315	34	349
40A400BH□	394.2	26	420.2
40A400BP□			
40A600BH□	574.2	26	600.2
40A600BP□			
80A400BH□	394.2	26	420.2
80A400BP□			
80A600BH□	574.2	26	600.2
80A600BP□			

5.2 Ratings and Specifications

5.2.1 Specifications

Linear Servomotor Moving Coil Model SGLTW-		Standard Models								High-efficiency Models					
		20A			35A			40A		80A		35A		50A	
		170A	320A	460A	170A	320A	460A	400B	600B	400B	600B	170H	320H	170H	320H
Time Rating		Continuous													
Thermal Class		B													
Insulation Resistance		500 VDC, 10 MΩ min.													
Withstand Voltage		1,500 VAC for 1 minute													
Excitation		Permanent magnet													
Cooling Method		Self-cooled													
Protective Structure		IP00													
Environmental Condi- tions	Surround- ing Air Tempera- ture	0°C to 40°C (with no freezing)													
	Surround- ing Air Humidity	20% to 80% relative humidity (with no condensation)													
	Installation Site	• Must be indoors and free of corrosive and explosive gases. • Must be well-ventilated and free of dust and moisture. • Must facilitate inspection and cleaning. • Must have an altitude of 1,000 m or less. • Must be free of strong magnetic fields.													
Shock Resis- tance	Impact Accelera- tion Rate	196 m/s ²													
	Number of Impacts	2 times													
Vibra- tion Resis- tance	Vibration Accelera- tion Rate	49 m/s ² (the vibration resistance in three directions, vertical, side-to-side, and front-to-back)													

5.2.2 Ratings

Linear Servomotor Moving Coil Model SGLTW-		Standard Models										High-efficiency Models			
		20A			35A			40A		80A		35A		50A	
		170A	320A	460A	170A	320A	460A	400B	600B	400B	600B	170H	320H	170H	320H
Rated Motor Speed (Reference Speed during Speed Control)* ¹		3.0	3.0	3.0	2.5	2.5	2.5	1.5	2.0	2.0	2.0	2.5	2.0	2.0	2.0
Maximum Speed* ¹	m/s	5.0	5.0	5.0	5.0	5.0	5.0	3.1	3.1	2.5	2.5	4.8	4.8	3.2	3.1
Rated Force* ^{1, *2}	N	130	250	380	220	440	670	670	1000	1300	2000	300	600	450	900
Maximum Force* ¹	N	380	760	1140	660	1320	2000	2600	4000	5000	7500	600	1200	900	1800
Rated Current* ¹	Arms	2.3	4.4	6.7	3.5	7.0	10.7	7.3	10.9	11.1	17.1	5.1	10.1	5.1	10.2
Maximum Current* ¹	Arms	7.7	15.4	23.2	12.1	24.2	36.7	39.4	60.6	57.9	86.9	11.9	23.9	11.8	23.6
Moving Coil Mass	kg	2.5	4.6	6.7	3.7	6.8	10	15	23	24	35	4.9	8.8	6.0	11
Force Constant	N/Arms	61.0	61.0	61.0	67.5	67.5	67.5	99.1	99.1	126	126	64.0	64.0	95.2	95.2
BEMF Constant	Vrms/ (m/s)/ phase	20.3	20.3	20.3	22.5	22.5	22.5	33.0	33.0	42.0	42.0	21.3	21.3	31.7	31.7
Motor Constant	N/ $\sqrt{W}$	18.7	26.5	32.3	26.7	37.5	46.4	61.4	75.2	94.7	116	37.4	52.9	48.6	68.7
Electrical Time Constant	ms	5.9	5.9	5.9	6.9	6.8	6.9	15	15	17	17	15	16	16	17
Mechanical Time Constant	ms	7.1	6.6	6.4	5.2	4.8	4.6	4.0	4.1	2.7	2.6	3.5	3.1	2.5	2.4
Thermal Resistance (with Heat Sink)	K/W	1.01	0.49	0.38	0.76	0.44	0.32	0.24	0.20	0.22	0.18	0.76	0.40	0.61	0.30
Thermal Resistance (without Heat Sink)	K/W	1.82	1.11	0.74	1.26	0.95	0.61	0.57	0.40	0.47	0.33	1.26	0.83	0.97	0.80
Magnetic Attraction* ³	N	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Magnetic Attraction on One Side* ⁴	N	800	1590	2380	1400	2780	4170	3950	5890	7650	11400	1400	2780	2000	3980
Maximum Allowable Payload	kg	25	50	76	44	88	130	280	440	690	1000	33	67	92	190
Maximum Allowable Payload (With External Regenerative Resistor and External Dynamic Brake Resistor)	kg	25	50	76	44	88	130	280	440	690	1000	40	82	95	190
Combined Magnetic Way, SGLTM-		20□□□A□			35□□□A□			40□□□A□		80□□□A□		35□□□H□		50□□□H□	
Combined Serial Converter Unit, JZDP-□□□□-		011	012	013	014	015	016	185	186	187	188	105	106	108	109
Applicable SERVOPACKs	SGD7S-	3R8A	7R6A	120A	5R5A	120A	180A		330A		550A	5R5A	120A	5R5A	120A
	SGD7W-SGD7C-	5R5A	7R6A	—	5R5A	—						5R5A	—	5R5A	—

*1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. The values for other items are at 20°C. These are typical values.

*2. The rated forces are the continuous allowable force values at a surrounding air temperature of 40°C with an aluminum heat sink of the dimensions given in the following table.

• Heat Sink Dimensions

• 254 mm × 254 mm × 25 mm: SGLTW-20A170A and -35A170A

• 400 mm × 500 mm × 40 mm: SGLTW-20A320A, -20A460A, -35A170H, -35A320A, -35A320H, -35A460A, and -50A170H

• 609 mm × 762 mm × 50 mm: SGLTW-40A400B, -40A600B, -50A320H, -80A400B, and -80A600B


*3. The unbalanced magnetic gap that results from the Moving Coil installation condition causes a magnetic attraction on the Moving Coil.

*4. The value that is given is the magnetic attraction that is generated on one side of the Magnetic Way.

5.2.3 Force-Motor Speed Characteristics


A : Continuous duty zone ——— (solid lines): With three-phase 200-V input
B : Intermittent duty zone - - - - - (dotted lines): With single-phase 200-V input

Standard Models



- Note: 1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. These are typical values.
2. The characteristics in the intermittent duty zone depend on the power supply voltage.
3. If the effective force is within the allowable range for the rated force, the Servomotor can be used within the intermittent duty zone.
4. If you use a Servomotor Main Circuit Cable that exceeds 20 m, the intermittent duty zone in the torque-motor speed characteristics will become smaller because the voltage drop increases.




◆ High-efficiency Models



- Note: 1. These values are for operation in combination with a SERVOPACK when the temperature of the armature winding is 100°C. These are typical values.
2. The characteristics in the intermittent duty zone depend on the power supply voltage.
3. If the effective force is within the allowable range for the rated force, the Servomotor can be used within the intermittent duty zone.
4. If you use a Servomotor Main Circuit Cable that exceeds 20 m, the intermittent duty zone in the torque-motor speed characteristics will become smaller because the voltage drop increases.

5.2.4 Servomotor Overload Protection Characteristics

The overload detection level is set for hot start conditions with a Servomotor surrounding air temperature of 40°C.




Note: The above overload protection characteristics do not mean that you can perform continuous duty operation with an output of 100% or higher. Use the Servomotor so that the effective force remains within the continuous duty zone given in 5.2.3 Force-Motor Speed Characteristics on page 5-7.

5.3 External Dimensions

5.3.1 SGLTW-20: Standard Models

◆ Moving Coils: SGLTW-20A□□□A□



Moving Coil Model SGLTW-	L1	L2	(L3)	N	Approx. Mass [kg]
20A170A□	170	144 (48 × 3)	(16)	8	2.5
20A320A□	315	288 (48 × 6)	(17)	14	4.6
20A460A□	460	432 (48 × 9)	(18)	20	6.7

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No.1 to 3)
350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350537-3 or 350550-3

• Polarity Sensor (Hall Sensor) Connector



1	+5 V (DC)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V	—	—

Pin connector: 17JE-23090-02 (D8C)-CG

From DDK Ltd.


Mating Connector

Socket connector: 17JE-13090-02 (D8C)A-CG


Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the S_u , S_v , and S_w polarity sensor (hall sensor) output signals and the inverse power of each motor phase V_u , V_v , and V_w when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Magnetic Ways: SGLTM-20□□□A



Note: 1. Two Magnetic Way tracks are used together as a set. For safety, when they are shipped, the two tracks are secured to a mounting spacer made from aluminum.

2. More than one Magnetic Way can be connected.

3. Dimensions with asterisks are the distances between the Magnetic Way tracks. Install the tracks according to the specified dimensions. Observe the dimensions given in *Mounting Section Details* after installation. Dimensions when the Magnetic Way is shipped from the factory are indicated by ♣.


4. Use socket head screws of strength class 10.9 or higher for the Magnetic Way mounting screws. (Do not use stainless steel screws.)

Magnetic Way Model SGLTM-	L1	L2	LA	LB	LC	LD	N	Approx. Mass [kg]
20324A□	324 ^{-0.1} _{-0.3}	270 (54 × 5)	31.7 ⁰ _{-0.2}	13.7 ⁰ _{-0.2}	40.3 ⁰ _{-0.2}	62 ^{+0.6} ₀	6	3.4
20540A□	540 ^{-0.1} _{-0.3}	486 (54 × 9)	31.7 ⁰ _{-0.2}	13.7 ⁰ _{-0.2}	40.3 ⁰ _{-0.2}	62 ^{+0.6} ₀	10	5.7
20756A□	756 ^{-0.1} _{-0.3}	702 (54 × 13)	31.7 ⁰ _{-0.2}	13.7 ⁰ _{-0.2}	40.3 ⁰ _{-0.2}	62 ^{+0.6} ₀	14	7.9

5.3 External Dimensions

5.3.1 SGLTW-20: Standard Models

◆ Magnetic Ways with Bases: SGLTM-20□□□AY




Note: Two Magnetic Way tracks are used together as a set. More than one Magnetic Way can be connected.

Magnetic Way Model SGLTM-	L1	L2	L3	L4	L5	N1	N2	Approx. Mass [kg]
20324AY	324 ^{-0.1} _{-0.3}	270	310	162	162	6	2	5.1
20540AY	540 ^{-0.1} _{-0.3}	486	526	378	189	10	3	8.5
20756AY	756 ^{-0.1} _{-0.3}	702	742	594	198	14	4	12

5.3.2 SGLTW-35: Standard Models


◆ Moving Coils: SGLTW-35A□□□A□



Moving Coil Model SGLTW-	L1	L2	(L3)	N	Approx. Mass [kg]
35A170A□	170	144 (48 × 3)	(16)	8	3.7
35A320A□	315	288 (48 × 6)	(17)	14	6.8
35A460A□	460	432 (48 × 9)	(18)	20	10

■ Connector Specifications

• Servomotor Connector



1	Phase U	Red
2	Phase V	White
3	Phase W	Blue
4	FG	Green

Plug: 350779-1

Pins: 350218-3 or 350547-3 (No.1 to 3)

350654-1 or 350669-1 (No. 4)


From Tyco Electronics Japan G.K.

Mating Connector

Cap: 350780-1

Socket: 350537-3 or 350550-3

• Polarity Sensor (Hall Sensor) Connector



1	+5 V (DC)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V	—	—

Pin connector: 17JE-23090-02 (D8C)-CG

From DDK Ltd.


Mating Connector

Socket connector: 17JE-13090-02 (D8C)A-CG


Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the S_u , S_v , and S_w polarity sensor (hall sensor) output signals and the inverse power of each motor phase V_u , V_v , and V_w when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Magnetic Ways: SGLTM-35□□□A□



Note: 1. Two Magnetic Way tracks are used together as a set. For safety, when they are shipped, the two tracks are secured to a mounting spacer made from aluminum.


2. More than one Magnetic Way can be connected.

3. Dimensions with asterisks are the distances between the Magnetic Way tracks. Install the tracks according to the specified dimensions. Observe the dimensions given in *Mounting Section Details* after installation. Dimensions when the Magnetic Way is shipped from the factory are indicated by ♣.

4. Use socket head screws of strength class 10.9 or higher for the Magnetic Way mounting screws. (Do not use stainless steel screws.)

Magnetic Way Model SGLTM-	L1	L2	LA	LB	LC	LD	N	Approx. Mass [kg]
35324A□	324 ^{-0.1} _{-0.3}	270 (54 × 5)	33 ⁰ _{-0.2}	15 ⁰ _{-0.2}	39 ⁰ _{-0.2}	62 ^{+0.6} ₀	6	4.8
35540A□	540 ^{-0.1} _{-0.3}	486 (54 × 9)	33 ⁰ _{-0.2}	15 ⁰ _{-0.2}	39 ⁰ _{-0.2}	62 ^{+0.6} ₀	10	8
35756A□	756 ^{-0.1} _{-0.3}	702 (54 × 13)	33 ⁰ _{-0.2}	15 ⁰ _{-0.2}	39 ⁰ _{-0.2}	62 ^{+0.6} ₀	14	11

◆ Magnetic Ways with Bases: SGLTM-35□□□AY



Note: Two Magnetic Way tracks are used together as a set. More than one Magnetic Way can be connected.

Magnetic Way Model SGLTM-	L1	L2	L3	L4	L5	N1	N2	Approx. Mass [kg]
35324AY	324 ^{-0.1} _{-0.3}	270	310	162	162	6	2	6.4
35540AY	540 ^{-0.1} _{-0.3}	486	526	378	189	10	3	11
35756AY	756 ^{-0.1} _{-0.3}	702	742	594	198	14	4	15

◆ SGLTW-35□□□□H□: High-efficiency Models



■ Connector Specifications

(Viewed from the top surface
of the Moving Coil.)


Secure the lead from the Moving Coil of the Linear Servomotor so that it moves together with the Moving Coil.

1	+5 V (DC)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V	—	—


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.

Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

The figure on the right shows the relationship between the S_u , S_v , and S_w polarity sensor (hall sensor) output signals and the inverse power of each motor phase V_u , V_v , and V_w when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Magnetic Ways: SGLTM-35□□□□H□



Note: 1. Two Magnetic Way tracks are used together as a set. For safety, when they are shipped, the two tracks are secured to a mounting spacer made from aluminum.

2. More than one Magnetic Way can be connected.

3. Dimensions with asterisks are the distances between the Magnetic Way tracks. Install the tracks according to the specified dimensions. Observe the dimensions given in *Mounting Section Details* after installation.


Dimensions when the Magnetic Way is shipped from the factory are indicated by ♣.

4. Use socket head screws of strength class 10.9 or higher for the Magnetic Way mounting screws. (Do not use stainless steel screws.)

Magnetic Way Model SGLTM-	L1	L2	LA	LB	LC	LD	N	Approx. Mass [kg]
35324H□	324 ^{-0.1} _{-0.3}	270 (54 × 5)	33 ⁰ _{-0.2}	15 ⁰ _{-0.2}	39 ⁰ _{-0.2}	82 ^{+0.6} ₀	6	4.8
35540H□	540 ^{-0.1} _{-0.3}	486 (54 × 9)	33 ⁰ _{-0.2}	15 ⁰ _{-0.2}	39 ⁰ _{-0.2}	82 ^{+0.6} ₀	10	8
35756H□	756 ^{-0.1} _{-0.3}	702 (54 × 13)	33 ⁰ _{-0.2}	15 ⁰ _{-0.2}	39 ⁰ _{-0.2}	82 ^{+0.6} ₀	14	11

5.3.4 SGLTW-40: Standard Models

◆ Moving Coils: SGLTW-40A□□□B□



Moving Coil Model SGLTW-	L1	L2	(L3)	N	Approx. Mass [kg]
40A400B□	394.2	360 (60 × 6)	(15)	14	15
40A600B□	574.2	540 (60 × 9)	(15)	20	22

■ Connector Specifications

• Servomotor Connector




A	Phase U
B	Phase V
C	Phase W
D	Ground

Receptacle: MS3102A-22-22P
From DDK Ltd.

Mating Connector

Right-angle plug: MS3108B22-22S
Straight plug: MS3106B22-22S
Cable clamp: MS3057-12A

• Polarity Sensor (Hall Sensor) Connector



1	+5 V (power supply)	6	
2	Phase U	7	Not used
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	-	-


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.

Mating Connector


Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Magnetic Ways: SGLTM-40□□□□□



Note: 1. Two Magnetic Way tracks are used together as a set. For safety, when they are shipped, the two tracks are secured to a mounting spacer made from aluminum.


2. More than one Magnetic Way can be connected.

3. Dimensions with asterisks are the distances between the Magnetic Way tracks. Install the tracks according to the specified dimensions. Observe the dimensions given in *Mounting Section Details* after installation. Dimensions when the Magnetic Way is shipped from the factory are indicated by ♣.

4. Use socket head screws of strength class 10.9 or higher for the Magnetic Way mounting screws. (Do not use stainless steel screws.)

Magnetic Way Model SGLTM-	L1	L2	LA	LB	LC	LD	N	Approx. Mass [kg]
40405A□	405 ^{-0.1} _{-0.3}	337.5 (67.5 × 5)	37.5 ⁰ _{-0.2}	15 ⁰ _{-0.2}	52.5 ⁰ _{-0.2}	100 ^{+0.6} ₀	6	9
40675A□	675 ^{-0.1} _{-0.3}	607.5 (67.5 × 9)	37.5 ⁰ _{-0.2}	15 ⁰ _{-0.2}	52.5 ⁰ _{-0.2}	100 ^{+0.6} ₀	10	15
40945A□	945 ^{-0.1} _{-0.3}	877.5 (67.5 × 13)	37.5 ⁰ _{-0.2}	15 ⁰ _{-0.2}	52.5 ⁰ _{-0.2}	100 ^{+0.6} ₀	14	21

◆ Magnetic Ways with Bases: SGLTM-40□□□AY




Note: Two Magnetic Way tracks are used together as a set. More than one Magnetic Way can be connected.

Magnetic Way Model SGLTM-	L1	L2	L3	L4	L5	N1	N2	Approx. Mass [kg]
40405AY	405 ^{-0.1 -0.3}	337.5	387.5	202.5	202.5	6	2	13
40675AY	675 ^{-0.1 -0.3}	607.5	657.5	472.5	236.25	10	3	21
40945AY	945 ^{-0.1 -0.3}	877.5	927.5	742.5	247.5	14	4	30

5.3.5 SGLTW-50: High-efficiency Models

◆ Moving Coils: SGLTW-50A□□□H□



Moving Coil Model SGLTW-	L1	L2	(L3)	N	Approx. Mass [kg]
50A170H□	170	144 (48 × 3)	(16)	8	6
50A320H□	315	288 (48 × 6)	(17)	14	11

■ Connector Specifications

• Moving Coil Lead

Phase U	Red	U	2 mm ²
Phase V	White	V	
Phase W	Black	W	
Ground	Green	—	

(Viewed from the top surface of the Moving Coil.)

Secure the lead from the Moving Coil of the Linear Servomotor so that it moves together with the Moving Coil.

• Polarity Sensor (Hall Sensor) Connector

1	+5 V (DC)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V	—	


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.

Mating Connector


Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the S_u , S_v , and S_w polarity sensor (hall sensor) output signals and the inverse power of each motor phase V_u , V_v , and V_w when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.



◆ Magnetic Ways: SGLTM-50□□□H□




- Note: 1. Two Magnetic Way tracks are used together as a set. For safety, when they are shipped, the two tracks are secured to a mounting spacer made from aluminum.
2. More than one Magnetic Way can be connected.
3. Dimensions with asterisks are the distances between the Magnetic Way tracks. Install the tracks according to the specified dimensions. Observe the dimensions given in *Mounting Section Details* after installation. Dimensions when the Magnetic Way is shipped from the factory are indicated by ♣.
4. Use socket head screws of strength class 10.9 or higher for the Magnetic Way mounting screws. (Do not use stainless steel screws.)

Magnetic Way Model SGLTM-	L1	L2	LA	LB	LC	LD	N	Approx. Mass [kg]
50324H□	324 ^{-0.1} _{-0.3}	270 (54 × 5)	27 ⁰ _{-0.2}	9 ⁰ _{-0.2}	45 ⁰ _{-0.2}	82 ^{+0.6} ₀	6	8
50540H□	540 ^{-0.1} _{-0.3}	486 (54 × 9)	27 ⁰ _{-0.2}	9 ⁰ _{-0.2}	45 ⁰ _{-0.2}	82 ^{+0.6} ₀	10	13
50756H□	756 ^{-0.1} _{-0.3}	702 (54 × 13)	27 ⁰ _{-0.2}	9 ⁰ _{-0.2}	45 ⁰ _{-0.2}	82 ^{+0.6} ₀	14	18

5.3.6 SGLTW-80: Standard Models

◆ Moving Coils: SGLTW-80□□□□B□



Moving Coil Model SGLTW-	L1	L2	(L3)	N	Approx. Mass [kg]
80A400B□	394.2	360 (60 × 6)	(15)	14	24
80A600B□	574.2	540 (60 × 9)	(15)	20	35

■ Connector Specifications

• Servomotor Connector




A	Phase U
B	Phase V
C	Phase W
D	Ground

Receptacle: MS3102A-22-22P
From DDK Ltd.

Mating Connector

Right-angle plug: MS3108B22-22S
Straight plug: MS3106B22-22S
Cable clamp: MS3057-12A

• Polarity Sensor (Hall Sensor) Connector



1	+5 V (power supply)	6	Not used
2	Phase U	7	
3	Phase V	8	
4	Phase W	9	
5	0 V (power supply)	-	-


Pin connector: 17JE-23090-02 (D8C)-CG
From DDK Ltd.

Mating Connector


Socket connector: 17JE-13090-02 (D8C)A-CG
Studs: 17L-002C or 17L-002C1

■ Polarity Sensor (Hall Sensor) Output Signal

The figure on the right shows the relationship between the Su, Sv, and Sw polarity sensor (hall sensor) output signals and the inverse power of each motor phase Vu, Vv, and Vw when the Moving Coil moves in the direction indicated by the arrow in the dimensional drawings of the Moving Coil.




Magnetic Ways: SGLTM-80□□□A□



- Note: 1. Two Magnetic Way tracks are used together as a set. For safety, when they are shipped, the two tracks are secured to a mounting spacer made from aluminum.
- 2. More than one Magnetic Way can be connected.
- 3. Dimensions with asterisks are the distances between the Magnetic Way tracks. Install the tracks according to the specified dimensions. Observe the dimensions given in Mounting Section Details after installation. Dimensions when the Magnetic Way is shipped from the factory are indicated by ♣.
- 4. Use socket head screws of strength class 10.9 or higher for the Magnetic Way mounting screws. (Do not use stainless steel screws.)

Magnetic Way Model SGLTM-	L1	L2	L3	LA	LB	LC	LD	N1	N2	Approx. Mass [kg]
80405A□	405 ^{-0.1} _{-0.3}	337.5 [♣] (67.5 × 5)	337.5 [♣] (33.75 × 10)	39.4 ⁰ _{-0.2}	16.9 ⁰ _{-0.2}	50.6 ⁰ _{-0.2}	100 ^{+0.6} ₀	6	11	14
80675A□	675 ^{-0.1} _{-0.3}	607.5 [♣] (67.5 × 9)	607.5 [♣] (33.75 × 18)	39.4 ⁰ _{-0.2}	16.9 ⁰ _{-0.2}	50.6 ⁰ _{-0.2}	100 ^{+0.6} ₀	10	19	24
80945A□	945 ^{-0.1} _{-0.3}	877.5 [♣] (67.5 × 13)	887.5 [♣] (33.75 × 26)	39.4 ⁰ _{-0.2}	16.9 ⁰ _{-0.2}	50.6 ⁰ _{-0.2}	100 ^{+0.6} ₀	14	27	34

◆ Magnetic Ways with Bases: SGLTM-80□□□AY



Note: Two Magnetic Way tracks are used together as a set. More than one Magnetic Way can be connected.

Magnetic Way Model SGLTM-	L1	L2	L3	L4	L5	N1	N2	N3	Approx. Mass [kg]
80405AY	405 ^{-0.1/-0.3}	337.5	387.5	202.5	202.5	6	2	11	18
80675AY	675 ^{-0.1/-0.3}	607.5	657.5	472.5	236.25	10	3	19	31
80945AY	945 ^{-0.1/-0.3}	877.5	927.5	742.5	247.5	14	4	27	43


5.4 Selecting Cables

5.4.1 Cable Configurations

Prepare the cable required for the encoder.

Refer to the following catalog to select a Linear Encoder.

📖 *AC Servo Drives Σ -7 Series* (Manual No.: KAEP S800001 23)






* You can connect directly to an absolute linear encoder.

Note: Refer to the following manual for the following information.

- Cable dimensional drawings and cable connection specifications
- Order numbers and specifications of individual connectors for cables
- Order numbers and specifications for wiring materials

📖 *Σ -7-Series AC Servo Drive Peripheral Device Selection Manual* (Manual No.: SIEP S800001 32)

5.4.2 Linear Servomotor Main Circuit Cables


Linear Servomotor Model	Length (L)	Order Number	Appearance
SGLTW-20A, -35A	1 m	JZSP-CLN21-01-E	
	3 m	JZSP-CLN21-03-E	
	5 m	JZSP-CLN21-05-E	
	10 m	JZSP-CLN21-10-E	
	15 m	JZSP-CLN21-15-E	
	20 m	JZSP-CLN21-20-E	
SGLTW-□□A□□□□□□□□	1 m	JZSP-CLN14-01-E	
	3 m	JZSP-CLN14-03-E	
	5 m	JZSP-CLN14-05-E	
	10 m	JZSP-CLN14-10-E	
	15 m	JZSP-CLN14-15-E	
	20 m	JZSP-CLN14-20-E	
SGLTW-40□□□□□□□□ -80□□□□□□□□	1 m	JZSP-CLN39-01-E	
	3 m	JZSP-CLN39-03-E	
	5 m	JZSP-CLN39-05-E	
	10 m	JZSP-CLN39-10-E	
	15 m	JZSP-CLN39-15-E	
	20 m	JZSP-CLN39-20-E	

*1. Connector from Tyco Electronics Japan G.K.

*2. Connector from Interconnectron GmbH

*3. A connector is not provided on the Linear Servomotor end. Obtain a connector according to your specifications. Refer to the next page for information on connectors.

JZSP-CLN39-□□-E Cables



◆ Wiring Specifications


SERVOPACK Leads		Servomotor Connector	
Wire Color	Signal	Signal	Pin
Red	Phase U	Phase U	A
White	Phase V	Phase V	B
Blue	Phase W	Phase W	C
Green/yellow	FG	FG	D

◆ JZSP-CLN39 Cable Connectors

Applicable Servomotor	Connector Provided with Servomotor	Plug		Cable Clamp
		Straight	Right-angle	
SGLTW-40 and -80	MS3102A22-22P	MS3106B22-22S or MS3106A22-22S	MS3108B22-22S	MS3057-12A

◆ MS3106B22-2S: Straight Plug with Two-piece Shell


Unit: mm



Shell Size	Joint Thread A	Length of Joint J ± 0.12	Joint Nut Outer Diameter Q $^{+0}_{-0.38}$	Effective Thread Length W min.
22	1-3/8-18UNEF	18.26	40.48	9.53

◆ MS3106A22-2S: Straight Plug with Solid Shell


Unit: mm



Shell Size	Joint Thread A	Length of Joint J ± 0.12	Joint Nut Outer Diameter Q $^{+0}_{-0.38}$	Effective Thread Length W min.
22	1-3/8-18UNEF	18.26	40.48	9.53

◆ MS3108B22-2S: Right-angle Plug with Two-piece Shell


Unit: mm



Shell Size	Joint Thread A	Length of Joint J ± 0.12	Joint Nut Outer Diameter Q $^{+0}_{-0.38}$	Effective Thread Length W min.
22	1-3/8-18UNEF	18.26	40.48	9.53

◆ Dimensional Drawings: MS3057-12A Cable Clamp with Rubber Bushing

Unit: mm



Applicable Connector Shell Size	Effective Thread Length C	Mounting Thread V	Attached Bushing
20.22	10.3	1-3/16-18UNEF	AN3420-12

Equipment Design Precautions

6

This chapter provides precautions for equipment design.


6.1	Influence of Magnetic Attraction	6-2
6.1.1	SGLF Servomotors	6-2
6.1.2	SGLT Servomotors	6-3
6.2	Influence of Magnetic Way Leakage Flux . .	6-4
6.2.1	SGLG Servomotors	6-4
6.2.2	SGLF Servomotors	6-4
6.2.3	SGLT Servomotors	6-5
6.3	Special Precautions for SGLT Servomotors . .	6-6
6.4	Precautions for Water-Cooled Models	6-7

6.1 Influence of Magnetic Attraction

6.1.1 SGLF Servomotors

The Moving Coil and Magnetic Way face each other, so magnetic attraction will occur. Consider the following magnetic attractions when you design the equipment.

Moving Coil Model		Gap, G* ¹ (mm)	Magnetic Attraction, F* ² (N)
SGLFW-	20A090	0.7 (0.5)* ³	410
	20A120		600
	35A120		1100
	35A230		2100
	50A200		2100
	50A380		4100
	1ZA200		4200
	1ZA380		6520
SGLFW2-	30A070	0.5	240
	30A120		750
	30A230		1490
	45A200		2390
	45A380		4770
	90A200		4770
	90A380		9550
	90A560		14300
	1DA380		14300
	1DA560		21500



*1. Gap values are given for the design value minus 0.3 mm.

*2. The maximum force is given for the magnetic attraction.

*3. Dimensions in parentheses are for when the magnet cover is attached.

6.1.2 SGLT Servomotors


The Magnetic Way tracks are located on both sides of the Moving Coil. If the gaps on both sides of the Moving Coil are the same, the magnetic attraction is canceled. However, it is difficult to obtain the same gaps due to Servomotor precision, the precision of the user's equipment, error when assembling the Servomotor, and other factors. Consider the following magnetic attractions when you design the equipment.

Moving Coil Model SGLTW-	Magnetic Gap, $G1^{*1}$ (mm)	Magnetic Gap, $G2^{*1}$ (mm)	Magnetic Attraction, $F1^{*2}$ (N)	Magnetic Attraction, $F2^{*2}$ (N)	Difference in Magnetic Attraction, ΔF (N)
20A170	1.3 (1.1) ^{*3}	0.7 (0.5) ^{*3}	760	1030	270
20A320			1510	2040	530
20A460			2260	3050	790
35A170	1.3 (1.1) ^{*3}	0.7 (0.5) ^{*3}	1330	1800	470
35A320			2650	3570	920
35A460			4000	5400	1400
40A400	1.7 (1.5) ^{*3}	1.1 (0.9) ^{*3}	4700	5900	1200
40A600	1.7 (1.5) ^{*3}	1.1 (0.9) ^{*3}	7000	8700	1700
50A170	1.3 (1.1) ^{*3}	0.7 (0.5) ^{*3}	1900	2600	700
50A320			3750	5100	1350
80A400	1.7 (1.5) ^{*3}	1.1 (0.9) ^{*3}	9200	11400	2200
80A600			13600	16900	3300

*1. Gap values are given for the design value plus 0.3 mm on one side and minus 0.3 mm on the other side.

*2. The maximum force is given for the magnetic attraction.

*3. Dimensions in parentheses are for when the magnet cover is attached.




6.2 Influence of Magnetic Way Leakage Flux

The Magnetic Way has leakage flux. Particularly in locations where the leakage flux is 10 gauss or higher, the influence of the leakage flux will be strongly felt. Consider this in the equipment design. The following tables give the locations where the leakage flux will be 10 gauss for each Servomotor model.


6.2.1 SGLG Servomotors

Magnetic Way Model SGLGM-	Location of 10-Gauss Leakage Flux			
	X (mm)	+Y (mm)	-Y (mm)	Z (mm)
30	25	25	5	35
40□□□C□	30	30	5	40
40□□□C□-M	50	50	5	60
60□□□C□	45	40	5	55
60□□□C□-M	65	60	5	75
90	100	85	5	115




6.2.2 SGLF Servomotors

Magnetic Way Model	Location of 10-Gauss Leakage Flux			
	X (mm)	Y (mm)	+Z (mm)	-Z (mm)
SGLFM-20	60	35	65	5
SGLFM-35	70	45	85	5
SGLFM-50	90	50	105	5
SGLFM-1Z	120	60	135	5
SGLFM2-30	60	30	70	5
SGLFM2-45	90	50	105	5
SGLFM2-90	120	60	135	5
SGLFM2-1D	130	70	150	5




6.2.3 SGLT Servomotors

Magnetic Way Model SGLTM-	Location of 10-Gauss Leakage Flux		
	X (mm)	Y (mm)	Z (mm)
20	55	40	10
35□□□A	60	40	10
35□□□H	65	45	15
40	80	60	15
50	70	50	15
80	90	60	20



6.3 Special Precautions for SGLT Servomotors

To mount the Magnetic Way, space is required between the Magnetic Way yoke and the positioning ridges on the equipment. Design the equipment with the following recommended values (W2) for the positioning ridges on the equipment.



Magnetic Way Model SGLTM-	Dimensions (mm)	
	W1 (Factory Distance between Magnetic Way Yokes)	W2 (Recommended Positioning Ridge Dimensions for Equipment)
20	71.5 ± 1	70 ± 0.15
35□□□□		
40	113 ± 1	111.8 ± 0.15
80		
35□□□□H	91.5 ± 1	90 ± 0.15
50		

6.4

Precautions for Water-Cooled Models

SGLFW2 Servomotors (SGLFW2-□□□□□□□□□□) use forced cooling with a cooling medium. Observe the following precautions if you use one of these Servomotors.

Cooling System Design and Installation

- You must design, purchase, and install the portion of the cooling system that is external to the Servomotor, such as the cooling medium, piping, and chiller or other cooling device.
- The joints on the Servomotor are made of stainless steel. Use parts that will not corrode for the connecting joints, piping, and other connecting parts. (We recommend that you use stainless steel parts.)
- The joints on the Servomotor are Rc1/8 (taper pipe thread). Wrap joints with sealing tape or take other measures to prevent the cooling water from leaking.
- Use flexible piping tubes to prevent leaking.

Cooling Medium

- Use cooling water for the cooling medium.
- Use cooling water that meets the water quality standards given in the following table (conforming to JRA GL-02 1994 of the Japan Refrigeration and Air Conditioning Industry Association).
If the water quality standards are not met, cooling performance will suffer and corrosion may cause problems.

Item	Water Quality Standard (Makeup Water Requirements for Cooling Water)
pH (25°C)	6.8 to 8.0
Conductivity (mS/m) (25°C)	30 max.
Chloride ions (mgCl-/l)	50 max.
Sulfate ions (mgSO ₄ ²⁻ /l)	50 max.
Alkalinity (pH4.8) (mgCaCO ₃ /l)	50 max.
Total hardness (mgCaCO ₃ /l)	70 max.
Calcium hardness (mgCaCO ₃ /l)	50 max.
Ionic silica (mgSiO ₂ /l)	30 max.
Iron (mgFe/l)	0.3 max.
Copper (mgCu/l)	0.1 max.
Sulfide ions (mgS ²⁻ /l)	Must not be detected.
Ammonium ions (mgNH ₄ ⁺ /l)	0.1 max.
Residual chlorine (mgCl/l)	0.3 max.
Free carbon dioxide (mgCO ₂ /l)	4.0 max.

- The temperature range for the cooling medium supplied to the Servomotor is 5°C to 25°C. Using a colder cooling medium will increase cooling performance, but make sure that freezing or condensation does not occur.
- The rated cooling medium flow rate is 4 L/min. This is the minimum flow rate required to prevent burning in the Servomotor for the current flow that corresponds to the rated force. If the flow rate is less than 4 L/min, install a protective circuit to cut off the current to the Servomotor.
- The maximum cooling medium flow rate is 6 L/min.
- Do not allow cooling water to be contaminated with oils, chemicals, or other impurities.

Preventing Contamination by Foreign Matter

Any foreign matter that is 0.5 mm or larger must not be allowed to enter the cooling piping to the Servomotor. Install a strainer, filter, or similar device to remove such foreign matter from the cooling water in the piping upstream from the cooling medium inlet port on the Servomotor.

Pressure

- Install a safety valve or other mechanism to keep the pressure in the Servomotor cooling piping below 1.0 MPa.
- The normal withstand pressure of the Servomotor is 0.5 MPa.
Do not allow the pressure to increase even momentarily to greater than 1.0 MPa, e.g., for cooling medium surges.
Do not allow the pressure to exceed 0.5 MPa more than 99 times.

Checking the Flow Rate

Use a flow rate meter or other device to confirm that the required flow rate is achieved.

If the flow rate is too low, burning may occur in the Servomotor and cooling performance may suffer.

Storage and Periods of Nonuse

- If you store the Servomotor or do not use it for a period of time, remove all of the cooling medium from the cooling piping.
- Observe the following conditions when you store the Servomotor or do not use it for a period of time.
Temperature: -20°C to $+60^{\circ}\text{C}$ (with no freezing)
Humidity: 20% to 80% relative humidity (with no condensation)

Other Precautions

- If cooling medium leaks from the Servomotor, stop using the Servomotor immediately. Then, inspect the Servomotor and take suitable countermeasures.
- After you install the Servomotor, make sure that there is no cooling medium or other liquid on the Servomotor.
If you find any liquid, wipe it off immediately and dry the Servomotor sufficiently.
A Servomotor may be damaged if it is used with liquid on it.
- If you disconnect the piping during maintenance or at any other time, do not allow the cooling water to get on the Servomotor.

Servomotor Installation

7

This chapter describes the installation conditions, procedures, and precautions for Servomotors.

7.1	Installation Conditions	7-2
7.1.1	Installation Environment	7-2
7.1.2	Installation Orientation	7-2
7.2	Installation Procedure	7-3
7.2.1	SGLG Servomotors (Coreless Models)	7-3
7.2.2	SGLF Servomotors (Models with F-type Iron Cores)	7-5
7.2.3	SGLT Servomotors (Models with T-type Iron Cores)	7-10
7.3	Servomotor Temperature Increase	7-16

7.1 Installation Conditions



The service life of a Servomotor will be shortened or unexpected problems will occur if the Servomotor is installed incorrectly or in an inappropriate location. Always observe the following installation instructions.

7.1.1 Installation Environment

Refer to the specifications for each type of Servomotor for the mechanical specifications, protective structure, and environmental conditions related to Servomotor installation.

7.1.2 Installation Orientation

You can install the Servomotor in any orientation.

Installation Orientation	Figure	Precautions
Horizontal Direction		—
Hung		Install a mechanism on the equipment to provide protection in case the Servomotor falls off.
Vertical Direction (Stroke in Vertical Direction)		• Implement safety measures, such as attaching a counterbalance, so that the workpiece will not fall, e.g., when an alarm occurs, when overtravel occurs, or when the power supply is interrupted. • Set the parameters so that the Servomotor will stop in the zero clamping state when overtravel occurs.

7.2 Installation Procedure


7.2.1 SGLG Servomotors (Coreless Models)

Mounting the Magnetic Way



Note


The SGLG Magnetic Ways consist of C-shaped steel plates with magnets facing each other attached between them. Be careful not to let foreign matter (magnetic material) enter between the magnets.



Use the following procedure.

1. Confirm the mounting reference surfaces of the Magnetic Way and place the Magnetic Way on one of the reference surfaces. There are two mounting reference surfaces, as shown in the following figure. Select the appropriate reference surface for your system.

Note: Be careful not to pinch your hands between the equipment and the Magnetic Way.




2. Press the Magnetic Way tightly against the equipment and secure it with screws.

Magnetic Way Model SGLGM-	Screw Nominal Size	Tightening Torque (N·cm)
30	M4	360 to 500
40	M5	720 to 1,010
60		
90	M6	1,220 to 1,710

Note: Use socket head screws with a strength class of 10.9.

3. Place the second Magnetic Way in line with and at least 30 mm away from the first Magnetic Way.
4. Align the corners of the connecting surfaces of the Magnetic Ways and then rotate the second Magnetic Way so that it connects to the first Magnetic Way.

Note: The magnetic attraction will pull the Magnetic Ways together. Be careful not to pinch your fingers.



5. Secure the second Magnetic Way with screws.

6. Mount the third and any other Magnetic Ways in the same way.



This concludes the procedure.

Mounting the Moving Coil




An SGLGW Moving Coil consists of an aluminum base and a winding section that is protected by plastic. Do not subject them to shock. Doing so may result in injury or equipment damage.

Use the following procedure.

1. Insert the winding section between the magnets of the Magnetic Ways that you previously installed.**2. Attach the Moving Coil to the moving table that is supported by the linear motion guides.**

3. Confirm that the gap, G, between the winding section of the Moving Coil and the magnets of the Magnetic Way are as given in the following table.



Moving Coil Model SGLGW-	Dimensions (mm)		
	H	P	G
30A050	1 ± 0.3	1 ± 0.1	0.85 ± 0.3
30A080	1 ± 0.3	1 ± 0.1	0.95 ± 0.3
40	1 ± 0.3	0 ± 0.1	0.8 ± 0.3
60	1 ± 0.3	0 ± 0.1	0.8 ± 0.3
90	2 ± 0.3	0.9 ± 0.1	1 ± 0.3

4. Move the Moving Coil back and forth to the ends of the Magnetic Ways several times and confirm the following items.
- That the Moving Coil does not come into contact with the Magnetic Ways
 - That there is no foreign matter (magnetic material) between the magnets

This concludes the procedure.


7.2.2 SGLF Servomotors (Models with F-type Iron Cores)

Outline


1. Mount one Magnetic Way.




To install the Moving Coil, you need a Magnetic Way that is longer than the Moving Coil. If one Magnetic Way is shorter than the Moving Coil, install two Magnetic Ways first and then install the Moving Coil.



2. Separate the moving table that is supported by the linear motion guides from the Magnetic Way and attach the Moving Coil to it.






3. Place the Moving Coil on top of the Magnetic Way.




4. Attach the second and any other Magnetic Ways.




This concludes the procedure.

Mounting the First Magnetic Way




Use the following procedure.





1. Remove the dummy plates to reduce magnetic force and the cardboard from the surface of the Magnetic Way.
2. Face the reference marks on the Magnetic Way (depressions of approx. 4 mm in diameter) toward the equipment and set down the Magnetic Way.

Note: Be careful not to pinch your hands between the equipment and the Magnetic Way.



3. Press the Magnetic Way tightly against the equipment and secure it with screws.

Magnetic Way Model	Screw Nominal Size	Tightening Torque (N·cm)	Screw Head Height, K (mm)	Reference
SGLFM-20	M4	360 to 500	4.2 max.	Figure 1
SGLFM-35				
SGLFM-50	M5	720 to 1,010	5.2 max.	Figure 2
SGLFM-1Z	M6	1,220 to 1,710	6.7 max.	
SGLFM2-30	M4	360 to 500	4.2 max.	
SGLFM2-45	M5	720 to 1,010	5.2 max.	
SGLFM2-90	M6	1,220 to 1,710	6.7 max.	
SGLFM2-1D	M8	2,970 to 4,150	8.2 max.	



Note: Use socket head screws with a strength class of 10.9.

This concludes the procedure.

Mounting the Moving Coil



Note


An SGLF Moving Coil consists of an iron core and a winding section that is protected by plastic. Do not subject them to shock. Doing so may result in injury or equipment damage.

Use the following procedure.

1. On a line extending from the Magnetic Way that you previously mounted, attach the Moving Coil to the moving table supported by the linear motion guides.
2. Confirm that the gap, G, between the Moving Coil and the Magnetic Way are as given in the following table.

7.2 Installation Procedure

7.2.2 SGLF Servomotors (Models with F-type Iron Cores)



Moving Coil Model		Dimensions (mm)		
		H	P	G (Gap)
SGLFW-	20	45 ± 0.1	22 ± 0.2	1 (0.8)*
	35		21 ± 0.2	
	50	58 ± 0.1	25.8 ± 0.2	
	1Z		27 ± 0.2	
SGLFW2-	30A070	40 ± 0.1	27.5 ± 0.2	0.8
	30A120		20 ± 0.2	
	30A230		26 ± 0.2	
	45	50 ± 0.1	30 ± 0.2	
	90		42.5 ± 0.2	
	1D			


*Dimensions in parentheses are for when the magnet cover is attached.

- Place a thin nonmagnetic sheet in the gap between the Moving Coil and Magnetic Way. The sheet must be approximately 0.5 mm thick, and we recommend using a plastic sheet.
- Slowly move the Moving Coil toward the Magnetic Way and confirm that there are no noises, such as noise from contact between the Moving Coil and Magnetic Way.



Important

As the Moving Coil approaches the Magnetic Way, magnetic attraction will pull on the Moving Coil. Be careful not to pinch your fingers or tools.



- Move the Moving Coil back and forth to the ends of the Magnetic Ways several times and confirm the following items.
 - That the Moving Coil does not come into contact with the Magnetic Ways
 - That there is no foreign matter (magnetic material) between the magnets

6. Remove the thin nonmagnetic sheet.
7. Use a nonmagnetic gap gauge to confirm that the gap between the Moving Coil and Magnetic Way is $1 \pm 0.3 \text{ mm}^*$ at all locations. (We recommend a brass or stainless steel gauge.)

*If the magnet cover is in place, the gaps should be $0.8 \pm 0.3 \text{ mm}$


This concludes the procedure.

Mounting the Second and Any Other Magnetic Ways

Use the following procedure.


1. Place the second Magnetic Way in line with and at least 30 mm away from the first Magnetic Way.

Note: Face the Magnetic Ways in same orientation using the locations of the reference marks as a guide (depressions of approx. 4 mm in diameter).



2. Hold down the Magnetic Way tightly, press the second Magnetic Way against the first Magnetic Way, and then secure the second Magnetic Way with screws.

Note: The magnetic attraction will pull the Magnetic Ways together. Be careful not to pinch your fingers.



3. Mount the third and any other Magnetic Ways using steps 1 and 2, above.

This concludes the procedure.

7.2.3 SGLT Servomotors (Models with T-type Iron Cores)


Outline

1. Mount one Magnetic Way.



Important

To install the Moving Coil, you need a Magnetic Way that is longer than the Moving Coil. If one Magnetic Way is shorter than the Moving Coil, install two Magnetic Ways first and then install the Moving Coil.




2. Separate the moving table that is supported by the linear motion guides from the Magnetic Way and attach the Moving Coil to it.



Important


If you will use only one Magnetic Way, the linear motion guide may not be sufficiently long enough to install the Moving Coil at a location separated from the Magnetic Way. Install a dummy linear motion guide and use it to mount the Moving Coil.



3. Place the Moving Coil on top of the Magnetic Way.



4. Attach the second and any other Magnetic Ways.



Mounting the First Magnetic Way

There are two types of Magnetic Ways: Magnetic Ways with mounting spacers, and Magnetic Ways with Magnetic Way yokes secured to bases.

- Magnetic Ways with mounting spacers: SGLTM-□□□□□A and SGLTM-□□□□□AC
- Magnetic Ways with Magnetic Way yokes secured to bases: SGLTM-□□□□□AY


The installation procedure depends on the type of Magnetic Way.

◆ SGLTM-□□□□□A and SGLTM-□□□□□AC



Important


When the Magnetic Way is shipped, the two Magnetic Way yokes are secured to mounting spacers made from aluminum. Never remove these mounting spacers until the Magnetic Way is provisionally installed on the equipment.



Use the following procedure.


1. Without removing the mounting spacers, place the Magnetic Way on the positioning ridges on the equipment. There should be a gap between the positioning ridges on the equipment and the Magnetic Way yokes.

Note: Be careful not to damage the equipment and the Magnetic Way.



2. Place a mounting screw in one of the Magnetic Way yokes and secure it provisionally

3. Hold the provisionally mounted Magnetic Way yoke tightly against the positioning ridges and secure it completely with screws.



Magnetic Way Model SGLTM-	Screw Nominal Size	Tightening Torque (N·cm)
20	M6	1,220 to 1,710
35		
50		
40	M8	2,970 to 4,150
80		

Note: These values are for the following conditions.

- Equipment materials: Iron
- Use of socket head screws with a strength class of 10.9

4. Remove the bolts from mounting spacers on the side of the Magnetic Way yoke that you mounted.
5. Hold the other Magnetic Way yoke tightly against the positioning ridges and secure it completely with screws.
Note: Be careful not to let the Magnetic Way yoke slip in the direction of Moving Coil forward movement.
6. Remove the mounting spacers. If there are Magnetic Way mounting holes in the positions where the mounting spacers were attached, secure the yokes with screws in those mounting holes as well.

This concludes the procedure.

◆ SGLTM-□□□□□AY

Use the following procedure.

1. Place the base to which the Magnetic Way yokes are attached in the specific location in the equipment.
2. Firmly secure the base to the equipment with bolts using the base mounting bolt holes.

This concludes the procedure.

Mounting the Moving Coil




Note


An SGLT Moving Coil consists of an aluminum or steel base, iron core, and a winding section that is protected by plastic. Do not subject them to shock. Doing so may result in injury or equipment damage.

Use the following procedure.

1. On a line extending from the Magnetic Way that you previously mounted, attach the Moving Coil to the moving table supported by the linear motion guides.



2. Confirm that the gaps, G1 and G2, between the Moving Coil and the Magnetic Way are as given in the following table.



Moving Coil Model SGLTW-	Dimensions (mm)		
	H	A	G1 , G2
20	55 ± 0.3	15 ± 0.1	1 ± 0.3 (0.8 ± 0.3)*
35	70 ± 0.3		
50	85 ± 0.3	19.1 ± 0.1	1.4 ± 0.3 (1.2)*
40	83 ± 0.3	19.1 ± 0.1	
80	120 ± 0.3		

*Dimensions in parentheses are for when the magnet cover is attached.


3. Place a thin nonmagnetic sheet in the gap between the Moving Coil and Magnetic Way. The sheet must be approximately 0.5 mm thick, and we recommend using a plastic sheet.

4. Slowly move the Moving Coil attached to the moving table toward the Magnetic Way and confirm that there are no noises, such as noise from contact between the Moving Coil and Magnetic Way.



Important

As the Moving Coil approaches the Magnetic Way, magnetic attraction will pull on the Moving Coil. Be careful not to pinch your fingers or tools.



5. Move the Moving Coil back and forth to the ends of the Magnetic Ways several times and confirm the following items.
 - That the Moving Coil does not come into contact with the Magnetic Ways
 - That there is no foreign matter (magnetic material) between the magnets
6. Remove the thin nonmagnetic sheet.
7. Use a nonmagnetic gap gauge to confirm that the gap between the Moving Coil and Magnetic Way is $1 \pm 0.3 \text{ mm}^*$ at all locations. (We recommend a brass or stainless steel gauge.)

*If the magnet cover is in place, the gaps should be $0.8 \pm 0.3 \text{ mm}$


This concludes the procedure.

Mounting the Second and Any Other Magnetic Ways

Use the following procedure.

1. Place the second Magnetic Way in line with and at least 30 mm away from the first Magnetic Way.
2. Press the second Magnetic Way against the first Magnetic Way and secure it with screws.

Note: The magnetic attraction will pull the Magnetic Ways together. Be careful not to pinch your fingers.



3. Mount the third and any other of the Magnetic Ways using steps 1 and 2, above.

This concludes the procedure.

7.3 Servomotor Temperature Increase

This section describes measures to suppress temperature increases in the Servomotor.

- When you install the Servomotor, observe the cooling conditions (heat sink sizes) that are given in the specifications for each type of Servomotor.

The Servomotor generates heat when it operates. The heat generated by the Servomotor radiates to the heat sink through the motor mounting surface. Therefore, if the surface area of the heat sink is too small, the temperature of the Servomotor may increase abnormally.

- If the operating environment makes it difficult to use a large heat sink, or if the ambient operating temperature or altitude given in the specifications is exceeded, implement the following measures.
 - Derate the Servomotor.
Contact your Yaskawa representative for information on derating.
 - Use external forced-air cooling for the Servomotor with a cooling fan or other means.



Important

Do not place packing or any other insulating material between the Servomotor and heat sink. Doing so will cause the motor temperature to increase, affect resistance to noise, and may cause motor failure.

Connecting Linear Encoders

8

This chapter describes the conditions and procedures for mounting linear encoders.

8.1 Installation Conditions for Linear Encoders . . 8-2

- 8.1.1 SGLG Servomotors 8-2
- 8.1.2 SGLF Servomotors 8-3
- 8.1.3 SGLT Servomotors 8-3

8.2 Mounting Linear Encoders 8-4

- 8.2.1 Linear Encoders from Heidenhain Corporation . . 8-4
- 8.2.2 Linear Encoders from RSF Elektronik GmbH . . . 8-4
- 8.2.3 Linear Encoders from Renishaw PLC 8-4
- 8.2.4 Linear Encoders from RLS d.o.o. 8-4
- 8.2.5 Absolute Linear Encoders from Mitutoyo Corporation 8-5
- 8.2.6 Linear Encoders from Magnescale Co., Ltd. . . . 8-5

8.3 Adjusting Linear Encoders 8-6

8.1 Installation Conditions for Linear Encoders

Observe the following installation conditions so that leakage flux from the Servomotor does not cause the linear encoder to malfunction.

Refer to the specifications for each type of linear encoder for the installation conditions outside a magnetic field.

Manufacturer	Model	External Magnetic Field Strength
Magnescale Co., Ltd.	SR75/77	5 mT max.
	SR85/87	
	SL710/PL101	0.5 mT max.
	SQ10	0.5 mT max.
	SQ47/SQ57	5 mT max.
Mitutoyo Corporation	ST78□A	3 mT max.

Mounting location guidelines for the linear encoders are given below.



Note


If the linear encoder mounting materials or the Magnetic Way mounting materials are magnetic materials, the magnetic field strength may exceed the specified values even for the following installation conditions. Implement the following measures.

- Use a nonmagnetic material for the structure (SUS, aluminum, etc.).
- Install a magnetic material between the Magnetic Way and the linear encoder.

If implementing the above measures is not possible, install the linear encoder in a location where the magnetic field strength is less than the specified value.


8.1.1 SGLG Servomotors

Magnetic Way Model SGLGM-	Distance from Magnetic Way			
	X (mm)	+Y (mm)	-Y (mm)	Z (mm)
30	35	35	10	50
40□□□□	45	40	10	55
40□□□□-M	65	60	10	75
60□□□□	65	55	10	75
60□□□□-M	85	75	10	100
90	130	110	10	155




8.1.2 SGLF Servomotors

Magnetic Way Model		Distance from Magnetic Way			
		X (mm)	Y (mm)	+Z (mm)	-Z (mm)
SGLFM-	20	85	55	85	10
	35	100	65	110	10
	50	125	80	135	10
	1Z	165	95	170	10
SGLFM2-	30	85	50	95	10
	45	120	75	140	10
	90	160	90	175	10
	1D	175	90	200	10



8.1.3 SGLT Servomotors

Magnetic Way Model SGLTM-	Distance from Magnetic Way		
	X (mm)	Y (mm)	Z (mm)
20	70	50	20
35□□□A	80	55	25
35□□□H	85	60	25
50	85	65	30
40	110	80	35
80	120	80	40



8.2 Mounting Linear Encoders


Attach the linear encoder so that the forward direction of the Servomotor is the count-up direction of the linear encoder.

If wiring or other restrictions prevent using the same directions for the forward direction and count-up direction, set parameter Pn080 to n.□□1□ (phase-B lead and phase sequence of U, V, W).




If the forward direction of the Servomotor and the count-up direction of the linear motor do not agree, the Servomotor may not operate or it may run out of control.

The forward direction for the motor is toward the side where the cable is connected. (The forward direction is the direction in which the Moving Coil moves when current flows in a phase sequence of U, V, W.)




8.2.1 Linear Encoders from Heidenhain Corporation




If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the right.

8.2.2 Linear Encoders from RSF Elektronik GmbH




If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the right.

8.2.3 Linear Encoders from Renishaw PLC



If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the left.


8.2.4 Linear Encoders from RLS d.o.o.



If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the right.


8.2.5 Absolute Linear Encoders from Mitutoyo Corporation

ST781A□, ST783A□, ST788A□, and ST789A□



If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the right.


ST782A□ and ST784A□



If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the right.


8.2.6 Linear Encoders from Magescale Co., Ltd.

SR75-□□□R, SR85-□□□R, SR77-□□□R, and SR87-□□□R




If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the right.

SR75-□□□L, SR85-□□□L, SR77-□□□L, and SR87-□□□L



If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the right.

SL700, SL710, SL720, and SL730



If the linear encoder is installed as shown in the diagram on the left, the count is incremented when the scanning head moves to the left.

8.3 Adjusting Linear Encoders

- Exposed Linear Encoders
Always adjust the mounting of the scanning head. Consult the manufacturer of the linear encoder for the adjustment method.
- Sealed Linear Encoders
No adjustment is necessary. However, you must observe the dimensional tolerances for mounting. Consult the manufacturer of the linear encoder for details.

Connections between Servomotors and SERVOPACKs

9

This chapter describes the cables that are used to connect the Servomotors and SERVOPACKs. It also provides information on peripheral devices and provides related precautions.

9.1 **Selecting Cables 9-2**


- 9.1.1 Linear Encoder Cables 9-2
- 9.1.2 Serial Converter Unit Cables 9-2
- 9.1.3 Sensor Cables 9-3
- 9.1.4 Serial Converter Units 9-4

9.2 **Wiring Servomotors and SERVOPACKs . . . 9-7**

- 9.2.1 Wiring Precautions 9-7
- 9.2.2 Wiring Procedure 9-10


9.1 Selecting Cables

9.1.1 Linear Encoder Cables




Name	Servomotor Model	Length (L)*	Order Number	Appearance
For linear encoder from Renishaw PLC	All Models	1 m	JZSP-CLL00-01-E	
		3 m	JZSP-CLL00-03-E	
		5 m	JZSP-CLL00-05-E	
		10 m	JZSP-CLL00-10-E	
		15 m	JZSP-CLL00-15-E	
For linear encoder from Heidenhain Corporation		1 m	JZSP-CLL30-01-E	
		3 m	JZSP-CLL30-03-E	
		5 m	JZSP-CLL30-05-E	
		10 m	JZSP-CLL30-10-E	
		15 m	JZSP-CLL30-15-E	

* When using a JZDP-J00□-□□□-E Serial Converter Unit, do not exceed a cable length of 3 m.

9.1.2 Serial Converter Unit Cables

Servomotor Model	Length (L)	Order Number	Appearance
All Models	1 m	JZSP-CLP70-01-E	
	3 m	JZSP-CLP70-03-E	
	5 m	JZSP-CLP70-05-E	
	10 m	JZSP-CLP70-10-E	
	15 m	JZSP-CLP70-15-E	
	20 m	JZSP-CLP70-20-E	

9.1.3 Sensor Cables




Servomotor Model	Length (L)	Order Number	Appearance
SGLGW-□□A SGLFW-□□A SGLTW-□□A	1 m	JZSP-CLL10-01-E	
	3 m	JZSP-CLL10-03-E	
	5 m	JZSP-CLL10-05-E	
	10 m	JZSP-CLL10-10-E	
	15 m	JZSP-CLL10-15-E	
SGLFW2-□□A□□□AS□ (With Polarity Sensor (Hall Sensor))	1 m	JZSP-CL2L100-01-E	
	3 m	JZSP-CL2L100-03-E	
	5 m	JZSP-CL2L100-05-E	
	10 m	JZSP-CL2L100-10-E	
	15 m	JZSP-CL2L100-15-E	
SGLFW2-□□A□□□AT□ (Without Polarity Sensor (Hall Sensor))	1 m	JZSP-CL2TH00-01-E	
	3 m	JZSP-CL2TH00-03-E	
	5 m	JZSP-CL2TH00-05-E	
	10 m	JZSP-CL2TH00-10-E	
	15 m	JZSP-CL2TH00-15-E	

9.1.4 Serial Converter Units

Order Number

Use the following tables to select the Serial Converter Unit.

JZDP - 00 -

Serial Converter Unit Model					Applicable Linear Servomotor						
Code	Appearance	Applicable Linear Encoder	Polarity Sensor (Hall Sensor)	Thermal Protector	Servomotor Model		Code	Servomotor Model		Code	
H003 J003		From Heidenhain Corp.	None	None	SGLGW - (coreless models) For Standard-force Magnetic Way	30A050C	250	SGLFW- (models with F-type iron cores)	20A090A	017	
H005 J005		From Renishaw PLC	None	None		30A080C	251		20A120A	018	
H006 J006		From Heidenhain Corp.	Yes	Yes		40A140C	252		35A120A	019	
						40A253C	253		35A230A	020	
H008 J008		From Renishaw PLC	Yes	Yes		40A365C	254		50A200B	181	
						60A140C	258		50A380B	182	
						60A253C	259		1ZA200B	183	
						60A365C	260		1ZA380B	184	
						90A200C	264		SGLTW- (models with T-type iron cores)	20A170A	011
						90A370C	265			20A320A	012
					90A535C	266	20A460A	013			
SGLGW - + SGLGM -  -M (coreless models) For High-force Magnetic Way	40A140C	255	SGLTW- (models with T-type iron cores)	35A170A	014						
	40A253C	256		35A320A	015						
	40A365C	257		35A460A	016						
	60A140C	261		35A170H	105						
	60A253C	262		35A320H	106						
	60A365C	263		50A170H	108						
SGLFW2- (models with F-type iron cores)	30A070A	628	SGLFW2- (models with F-type iron cores)	50A320H	109						
	30A120A	629		40A400B	185						
	30A230A	630		40A600B	186						
	45A200A	631		80A400B	187						
	45A380A	632		80A600B	188						
	90A200A□1	633									
	90A380A□1	634									
	90A560A□1	648									
	1DA380A□1	649									
	1DA560A□1	650									
	90A200A□L	699									
	90A380A□L	700									
	90A560A□L	701									
	1DA380A□L	702									
1DA560A□L	703										

Note: Refer to the following manual for detailed specifications of the Serial Converter Units.

 *Σ-7-Series AC Servo Drive Peripheral Device Selection Manual (Manual No.: SIEP S800001 32)*

Characteristics and Specifications

Item		JZDP-H00□-□□□	JZDP-J00□-□□□
Electrical Characteristics	Power Supply Voltage	+5.0 V ±5%, ripple content: 5% max.	
	Current Consumption*1	120 mA Typ, 160 mA max.	
	Signal Resolution	1/256 pitch of input two-phase sine wave	1/4,096 pitch of input two-phase sine wave
	Maximum Response Frequency	250 kHz	100 kHz
	Analog Input Signals*2 (cos, sin, and Ref)	Differential input amplitude: 0.4 V to 1.2 V Input signal level: 1.5 V to 3.5 V	
	Polarity Sensor (Hall Sensor) Input Signal	CMOS level	
	Thermal Protector Input Signal	Connect the thermal protector built into the Linear Servomotor *3	
	Output Signals	Position data, polarity sensor (hall sensor) information, and alarms	
	Output Method	Serial data transmission	
	Output Circuit	Balanced transceiver (SN75LBC176 or the equivalent), internal terminating resistance: 120 Ω	
Mechanical Characteristics	Approximate Mass	150 g	
	Vibration Resistance	98 m/s ² max. (10 Hz to 2,500 Hz) in three directions	
	Shock Resistance	980 m/s ² , (11 ms) two times in three directions	
Environment	Operating Temperature Range	0°C to 55°C	
	Storage Temperature Range	-20°C to 80°C	
	Humidity Range	20% to 90% relative humidity (with no condensation)	

*1. The current consumptions of the Linear Encoder and the polarity sensor (hall sensor) are not included in this value.
The current consumption of the polarity sensor (hall sensor) is approximately 40 mA. Confirm the current consumption of the Linear Encoder that you will use and make sure that the current capacity of the SERVOPACK is not exceeded.

*2. If you input an out-of-range value, the correct position information will not be output. Also, the device may be damaged.

*3. Only SGLFW2 Servomotors come equipped with thermal protectors.


Analog Signal Input Timing

Input the analog signals with the timing shown in the following figure.

The /cos and /sin signals are the differential signals when the cos and sin signals are shifted 180°. The specifications of the cos, /cos, sin, and /sin signals are identical except for the phases.

The Ref and /Ref signals are input to the comparator. Input a signal that will exceed the hysteresis of the comparator (i.e., the broken lines in the following figure).

When they are crossed, the output data will be counted up.



*1. If the analog signal amplitude declines to approximately 0.35 V because of the differential amplitude, the Serial Converter Unit will output an alarm.

*2. This is the hysteresis width.



Application Precautions

1. Never perform insulation resistance or withstand voltage tests.
2. When analog signals are input to the Serial Converter Unit, they are very weak signals, and therefore noise influence on the analog signals affects the Unit's ability to output correct position information. Keep the analog signal cable as short as possible and implement proper shielding.
3. Use the Serial Converter Unit in a location without gases such as H₂S.
4. Do not replace the Unit while power is being supplied. There is a risk of device damage.
5. If you use more than one axis, use a shielded cable for each axis.
Do not use one shielded cable for multiple axes.
6. If you use any Linear Encoder other than a recommended Linear Encoder, evaluate the system in advance before you use it.

9.2

Wiring Servomotors and SERVOPACKs

9.2.1

Wiring Precautions

**CAUTION**


- Do not connect the Servomotor directly to an industrial power supply. Doing so will destroy the Servomotor. You cannot operate a Servomotor without a SERVOPACK that is designed for it.

General Precautions

- Never perform any wiring work while the power supply is ON.
- Always connect the Servomotor Main Circuit Cable before you connect the Encoder Cable. If you connect the Encoder Cable first, the encoder may be damaged due to the difference in electrical potential from the FG.
- Never touch the connector pins on the Servomotor directly with your hands. Particularly the encoder may be damaged by static electricity.
- Separate the Servomotor Main Circuit Cable from the I/O Signal Cables and Encoder Cable by at least 30 cm.
- Do not connect magnetic contactors, reactors, or other devices on the cables that connect the SERVOPACK and Servomotor. Failure to observe this caution may result in malfunction or damage.
- Do not subject the cables to excessive bending stress or tension. The conductors in the Encoder Cable and Servomotor Main Circuit Cable are as thin as 0.2 mm² or 0.3 mm². Wire them so that they are not subjected to excessive stress.
- If you secure the cables with cable ties, protect the cables with cushioning material.
- If the cable will be bent repeatedly, e.g., if the Servomotor will move in the equipment, use Flexible Cables. If you do not use Flexible Cables, the cables may break.
- Before you connect the wires, make sure that there are no mistakes in the wiring.
- Always use the connectors specified by Yaskawa and insert them correctly.
- When you connect a connector, check it to make sure there is no foreign matter, such as metal clippings, inside.
- The connectors are made of resin. To prevent damage, do not apply any strong impact.
- Perform all wiring so that stress is not applied to the connectors. The connectors may break if they are subjected to stress.
- If you move the Servomotor while the cables are connected, always hold onto the main body of the Servomotor. If you lift the Servomotor by the cables when you move it, the connectors may be damaged or the cables may be broken.

Grounding Precautions

The ground terminal on the SERVOPACK is used to ground the Servomotor.



Precautions for Standard Cables

Do not use standard cables in applications that required a high degree of flexibility, such as twisting and turning, or in which the cables themselves must move. When you use Standard Cables, observe the recommended bending radius given in the following table and perform all wiring so that stress is not applied to the cables. Use the cables so that they are not repeatedly bent.


Cable Diameter	Recommended Bending Radius [R]
Less than 8 mm	15 mm min.
8 mm	20 mm min.
Over 8 mm	Cable diameter × 3 mm min.

Precautions for Flexible Cables

- The Flexible Cables have a service life of 10,000,000 operations minimum when used at the recommended bending radius of 90 mm or larger under the following test conditions. The service life of a Flexible Cable is reference data under special test conditions. The service life of a Flexible Cable greatly depends on the amount of mechanical shock, how the cable is attached, and how the cable is secured.

Test Conditions

- One end of the cable is repeatedly moved forward and backward for 320 mm using the test equipment shown in the following figure.
- The lead wires are connected in series, and the number of cable return operations until a lead wire breaks are counted. One round trip is counted as one bend.




Note: The service life of a Flexible Cable indicates the number of bends while the lead wires are electrically charged for which no cracks or damage that affects the performance of the cable sheathing occur. Breaking of the shield wire is not considered.

- Straighten out the Flexible Cable when you connect it. If the cable is connected while it is twisted, it will break faster. Check the indication on the cable surface to make sure that the cable is not twisted.
- Do not secure the portions of the Flexible Cable that move. Stress will accumulate at the point that is secured, and the cable will break faster. Secure the cable in as few locations as possible.
- If a Flexible Cable is too long, looseness will cause it to break faster. If the Flexible Cable is too short, stress at the points where it is secured will cause it to break faster. Adjust the cable length to the optimum value.
- Do not allow Flexible Cables to interfere with each other. Interference will restrict the motion of the cables, causing them to break faster. Separate the cables sufficiently, or provide partitions between them when wiring.

9.2.2 Wiring Procedure

SGLG Servomotors


Refer to the following figures for wiring.



* You can connect directly to an absolute linear encoder.

SGLF Servomotors


Refer to the following figures for wiring.



* You can connect directly to an absolute linear encoder.

SGLT Servomotors

Refer to the following figures for wiring.



* You can connect directly to an absolute linear encoder.

Maintenance and Inspection

10

This chapter describes the maintenance, inspection, and disposal of a Servomotor.

10.1 Periodic Inspections 10-2

10.1.1 Linear Servomotor Inspections 10-2

10.1.2 Linear Encoder Inspections 10-3

10.2 Disposing of Servomotors 10-4

10.1 Periodic Inspections

10.1.1 Linear Servomotor Inspections

The following table gives the periodic inspection items for a Servomotor. The inspection periods given in the table are guidelines. Determine the optimum inspection periods based on the application conditions and environment.



CAUTION

- Before you perform any maintenance or inspection work, turn OFF the power supply, confirm that the CHARGE indicator on the front of the SERVOPACK has gone out, and then use a tester to check the voltage between the positive and negative terminals on the SERVOPACK. Start inspection work only after you have confirmed that the main circuit voltage has dropped.
If there is any main circuit voltage left, the risk of electric shock still exists. Do not touch the Servomotor or any wiring.
- All inspection and maintenance work must be performed by a trained technician.
Failure to observe this caution may result in electric shock or injury.
- Contact your Yaskawa representative for help with failures, repairs, or part replacement.

Item		Inspection Period	Basic Inspection and Maintenance Procedure	Remarks
Daily Inspections	Check for vibration and noise.	Daily	Inspect by touching and by listening in a safe location.	There should be no more vibration or noise than normal.
	Exterior	Daily	Confirm that there are no cracks, splitting, or chipping, and that there is no rubbing with the Magnetic Way.	If any abnormality is found, repair it or replace the part. Contact your Yaskawa representative.
			Make sure that there are no scratches or splitting.	
			Make sure that there is no splitting or chipping.	
			Make sure that there is no deformation or rubbing with the Moving Coil.	
			Make sure that there are no loose screws.	Tighten any loose screws.
	Dirt and foreign matter	As required by conditions	Clean off any dirt or foreign matter with a cloth or pressurized air.	Use alcohol as a solvent.

Continued on next page.

Continued from previous page.

Item		Inspection Period	Basic Inspection and Maintenance Procedure	Remarks
Periodic Inspections	Gaps between Moving Coil and Magnetic Way	At least once a year	Disconnect the Servomotor from the SERVOPACK and confirm that there is no foreign matter caught inside the Servomotor and that none of the gaps has increased in size since the Servomotor was first used.	—
	Measure the insulation resistance.	At least once a year	Disconnect the Servomotor from the SERVOPACK and measure the insulation resistance at 500 V with an insulation resistance meter. (Measurement method: Measure the resistance between phase U, V, or W on the Servomotor's power line and FG.) The insulation is normal if the resistance is 10 MΩ or higher.	• If the resistance is less than 10 MΩ, contact your Yaskawa representative. • Do not perform insulation resistance measurements or withstand voltage tests on the sensor.
	Overhaul	At least once every 5 years	Contact your Yaskawa representative.	Never attempt to disassemble or clean a Servomotor yourself.

10.1.2 Linear Encoder Inspections

Consult the manufacturer of the linear encoder for maintenance and inspection information.

10.2 Disposing of Servomotors

When disposing of a Servomotor, treat it as ordinary industrial waste.

However, local ordinances and national laws must be observed. Implement all labeling and warnings as a final product as required.



CAUTION

- When you dispose of a Linear Servomotor, heat the Magnetic Way to 300°C or higher for one hour to demagnetize it.
There is a risk of injury from the strong magnetic attraction.

Revision History

The revision dates and numbers of the revised manuals are given at the bottom of the back cover.

MANUAL NO. SIEP S800001 37B <1>-0

Published in Japan September 2014

WEB revision number
Revision number
Date of publication

Date of Publication	Rev. No.	Web Rev. No.	Section	Revised Content
December 2019	<4>	0	All chapters	Partly revised.
			Back cover	Revision: Address
July 2017	<3>	0	Preface	Revision: Information on certification for standards
			Back cover	Revision: Address
April 2017	<2>	0	All chapters	Deleted the SGLC, corrected mistakes, and made changes to some parts.
			Chapter 4	Addition: SGLFW2-90A200A□L
			6.4	Addition: Precautions for water-cooled models
			8.1	Addition: SG10 and SQ47/SQ57
September 2014	<1>	0	All chapters	Corrected mistakes and made changes to some parts.
			Preface	Addition: Troubleshooting precautions Revision: Compliance with UL Standards, EU Directives, and Other Safety Standards
			Chapters 1, 4, and 10	Addition: Information on SGLFW2-90A560AS and -1DA560AS
			Chapters 1, 5, and 7	Addition: Information on SGLTW-40A600B, -80A400B, and -80A600B
May 2014	—	—	—	First edition

Σ-7-Series AC Servo Drive Linear Servomotor Product Manual

IRUMA BUSINESS CENTER (SOLUTION CENTER)

480, Kamifujisawa, Iruma, Saitama, 358-8555, Japan
Phone: +81-4-2962-5151 Fax: +81-4-2962-6138
www.yaskawa.co.jp

YASKAWA AMERICA, INC.

2121, Norman Drive South, Waukegan, IL 60085, U.S.A.
Phone: +1-800-YASKAWA (927-5292) or +1-847-887-7000 Fax: +1-847-887-7310
www.yaskawa.com

YASKAWA ELÉTRICO DO BRASIL LTDA.

777, Avenida Piraporinha, Diadema, São Paulo, 09950-000, Brasil
Phone: +55-11-3585-1100 Fax: +55-11-3585-1187
www.yaskawa.com.br

YASKAWA EUROPE GmbH

Hauptstraße 185, 65760 Eschborn, Germany
Phone: +49-6196-569-300 Fax: +49-6196-569-398
www.yaskawa.eu.com E-mail: info@yaskawa.eu.com

YASKAWA ELECTRIC KOREA CORPORATION

35F, Three IFC, 10 Gukjegeumyung-ro, Yeongdeungpo-gu, Seoul, 07326, Korea
Phone: +82-2-784-7844 Fax: +82-2-784-8495
www.yaskawa.co.kr

YASKAWA ASIA PACIFIC PTE. LTD.

30A, Kallang Place, #06-01, 339213, Singapore
Phone: +65-6282-3003 Fax: +65-6289-3003
www.yaskawa.com.sg

YASKAWA ELECTRIC (THAILAND) CO., LTD.

59, 1F-5F, Flourish Building, Soi Ratchadapisek 18, Ratchadapisek Road, Huaykwang, Bangkok, 10310, Thailand
Phone: +66-2-017-0099 Fax: +66-2-017-0799
www.yaskawa.co.th

YASKAWA ELECTRIC (CHINA) CO., LTD.

22F, Link Square 1, No.222, Hubin Road, Shanghai, 200021, China
Phone: +86-21-5385-2200 Fax: +86-21-5385-3299
www.yaskawa.com.cn

YASKAWA ELECTRIC (CHINA) CO., LTD. BEIJING OFFICE

Room 1011, Tower W3 Oriental Plaza, No.1, East Chang An Avenue,
Dong Cheng District, Beijing, 100738, China
Phone: +86-10-8518-4086 Fax: +86-10-8518-4082

YASKAWA ELECTRIC TAIWAN CORPORATION

12F, No. 207, Section 3, Beishin Road, Shindian District, New Taipei City 23143, Taiwan
Phone: +886-2-8913-1333 Fax: +886-2-8913-1513 or +886-2-8913-1519
www.yaskawa.com.tw

YASKAWA

YASKAWA ELECTRIC CORPORATION

In the event that the end user of this product is to be the military and said product is to be employed in any weapons systems or the manufacture thereof, the export will fall under the relevant regulations as stipulated in the Foreign Exchange and Foreign Trade Regulations. Therefore, be sure to follow all procedures and submit all relevant documentation according to any and all rules, regulations and laws that may apply.

Specifications are subject to change without notice for ongoing product modifications and improvements.

© 2014 YASKAWA ELECTRIC CORPORATION

MANUAL NO. SIEP S800001 37D <4>-0

Published in Japan December 2019
19-10-16

Original instructions