Industriestrasse 66, Postfach 59, 6301 Zug Telefon +41 58 767 67 67, Fax +41 58 767 67 67 info@vzug.com, www.vzug.com

Error message list GK11TI(X)FKZ, CTI6T-31132, CTI6T-31134

1010833-01-AJ

Serial production



Error code	F-/U-/A-messages	Error diagnostics (through microcontroller)	Possible causes (ranked by probability; changes or additions to be reported to the compiler)	
E1	F5	EEPROM Read error	Moisture on control unit Replace control unit if error persists	
E2	F5	EEPROM Write error	Moisture on control unit Replace control unit if error persists	
E5	F5	Incorrect firmware Checksum	Reload software Replace control unit	
E6		Watchdog reset	Reload software Replace control unit	
E7	F16	Temperature Sensor Display 1 – short circuit	Short circuit in temperature sensor Display 1 (lower right side of display). Replace temperature sensor Replace control unit	
E8	F16	Temperature Sensor Display 1 – open circuit	Break in temperature sensor Display 1 (lower right side of display). Replace temperature sensor 2) Replace control unit	
E9	F16	Temperature Sensor Display 2– short circuit	1) Short circuit in temperature sensor Display 2 (upper right side of display)	
E10	F16	Temperature Sensor Display 2 – open circuit	Break in temperature sensor Display 2 (upper right side of display). Replace temperature sensor 2) Replace control unit	
E11	F16	Temperature Sensor Display 3 – short circuit	Short circuit in temperature sensor Display 3 (upper left side of display). Replace temperature sensor 2) Replace control unit	
E12	F16	Temperature Sensor Display 3 – open circuit	Break in temperature sensor Display 3 (upper left side of display). Replace temperature sensor 2) Replace control unit	
E13	F16	Temperature Sensor Display 4 – short circuit	Short circuit in temperature sensor Display 4 (lower left side of display). Replace temperature sensor 2) Replace control unit	
E14		Temperature Sensor Display 4 – open circuit	Break in temperature sensor Display 4 (lower left side of display). Replace temperature sensor 2) Replace control unit	
E15	F14	Temperature Sensor Control unit – short circuit	Short circuit in ambient temperature sensor on control unit. Replace control unit	
E16	F14	Temperature Control unit – open circuit	1) Break in ambient temperature sensor on control unit. Replace control unit	
E17	F30	Communication control unit – power unit Error	 Check connection between power unit and control unit Replace control unit Replace power unit 	
E18	F31	Communication control unit – power unit – incompatible SW	Reload software of control unit Reload software of power unit Replace power unit Replace control unit	
E19	F3	Communication Touchpanel- control unit error	Check connection of Touchpanel on control unit Replace Touchdisplay/Control unit.	
E20		Communication V-Zug Home -control unit error	1) Check connection of V-Zug Home interface with the control unit	
E21	F5	Control unit MAIN DATA invalid	Reload software Replace control unit	
E22	F5	Control unit MAIN DATA incompatible	Reload software Replace control unit	

Industriestrasse 66, Postfach 59, 6301 Zug Telefon +41 58 767 67 67, Fax +41 58 767 67 67 info@vzug.com, www.vzug.com

Error message list GK11TI(X)FKZ, CTI6T-31132, CTI6T-31134

1010833-01-AJ

Serial production

created 11.12.2019 chha modified 11.02.2020 User Agent checked 18.12.2019 scur 2 /



			checked 18.12.2019 scur 2 / 8	
E24	F5		Reload software Replace control unit	
E25	F5	Control unit Text Lib Error	Reload software Replace control unit	
E26	F5	Control unit Extfw Lib Error	Reload software Replace control unit	
E27	F5	Control unit Font Lib Error	Reload software Replace control unit	
E28		Power unit no or invalid coding plug detected	Check coding plug on Power unit Replace power unit	
E29	F5	Control unit Sound Lib Error	Reload software Replace control unit	
E30	F5	Control unit Picture Lib Error	Reload software Replace control unit	
E31	F5	Control unit Factory Settings Lib Error	Reload software Replace control unit	
E32	F5	Control unit invalid coding plug detected		
E33	A0	Pan on display detected	1) Remove Pan from display	
E34	A 1	Hot Pan on display	1) Remove Pan from display	
E35	U0	Mains voltage – supply connected incorrectly	Voltage at L1 is/was greater than 380V AC 1) Faulty connection or neutral conductor break with unbalanced load – check connection 2) Problems with mains power supply 3) Moisture on power unit 4) Power unit defective	
E36	U0	Mains voltage – overvoltage L1	Voltage at L1 is/was greater than 280V AC for longer than 3 seconds 1) Faulty connection or neutral conductor break with unbalanced load 2) Problems with mains power supply 3) Moisture on power unit 4) Power unit defective	
E37		Mains voltage – high voltage	Voltage at L1 is/was between 260V and 280V for longer than 3 seconds 1) Check mains power supply 2) Moisture on power unit 3) Replace power unit	
E38		Mains voltage- low voltage L1	Voltage at L1 is/was between 176V and 198V for longer than 3 seconds 1) Check mains power supply 2) Moisture on power unit 3) Replace power unit	
E39	U1	Mains voltage – undervoltage L1	Voltage at L1 is/was between 155V and 176V AC 1) Check mains power supply 2) Replace power unit	
E40		Mains voltage – undervoltage L1	Voltage at L1 is/was lower than 155V 1) Check mains power supply 2) Replace power unit	
E43	U0	Mains voltage – supply connected incorrectly	Voltage at L2 is/was greater than 380V AC 1) Faulty connection or neutral conductor break with unbalanced load – check connection 2) Problems with mains power supply 3) Moisture on power unit 4) Power unit defective	
E44	U0	Mains voltage – overvoltage L2	Voltage at L2 is/was greater than 280V AC for longer than 3 seconds 1) Faulty connection or neutral conductor break with unbalanced load 2) Problems with mains power supply 3) Moisture on power unit 4) Power unit defective	
E45		Mains voltage – high voltage L2	Voltage at L2 is/was between 260V and 280V for longer than 3 seconds 1) Check mains power supply	

Industriestrasse 66, Postfach 59, 6301 Zug Telefon +41 58 767 67 67, Fax +41 58 767 67 67 info@vzug.com, www.vzug.com

Error message list GK11TI(X)FKZ, CTI6T-31132, CTI6T-31134

1010833-01-AJ

Serial production

created 11.12.2019 chha
modified 11.02.2020 User Agent
checked 18.12.2019 scur 3 / 3/8

			2) Moisture on power unit 3) Replace power unit	
E46		Mains voltage- low voltage L2	Voltage at L2 is/was between 176V and 198V for longer than 3 seconds 1) Check mains power supply 2) Moisture on power unit 3) Replace power unit	
E47	U1	Mains voltage – undervoltage L2	Voltage at L2 is/was between 155V and 176V AC 1) Check mains power supply 2) Replace power unit	
E48		Mains voltage – undervoltage L2	Voltage at L2 is/was lower than 155V	
E51	U0	Mains voltage – supply connected incorrectly	Voltage at L3 is/was greater than 380V AC 1) Faulty connection or neutral conductor break with unbalanced load – check connection 2) Problems with mains power supply 3) Moisture on power unit 4) Power unit defective	
E52	U0	Mains voltage – overvoltage L3	Voltage at L3 is/was greater than 280V AC for longer than 3 seconds	
E53		Mains voltage – high voltage L3	Voltage at L3 is/was between 260V and 280V for longer than 3 seconds 1) Check mains power supply 2) Moisture on power unit 3) Replace power unit	
E54		Mains voltage- low voltage L3	Voltage at L3 is/was between 176V and 198V for longer than 3 seconds 1) Check mains power supply 2) Moisture on power unit 3) Replace power unit	
E55	U1	Mains voltage – undervoltage L3	Voltage at L3 is/was between 155V and 176V AC 1) Check mains power supply 2) Replace power unit	
E56		Mains voltage – undervoltage L3	Voltage at L3 is/was lower than 155V 1) Check mains power supply 2) Replace power unit	
E59		Mains voltage – calibration error	1) Replace power unit	
E60		Mains connection Invalid phase connection	Phase shift between two phases is invalid. 1) When connected to Belgian power grid: Check if Software Baseline R05 or higher is installed. 2) Check mains power supply for faulty connection 3) Replace power unit	
E61	F5	Power unit - Incorrect process data device Id	Reload software Replace power unit	
E62	F5	Power unit – incorrect process data checksum	Reload software Replace power unit	
E63	F5	Power unit – incorrect firmware checksum	Reload software Replace power unit	
E64		Power unit watchdog reset	Reload software Replace power unit	
E65	F12	Ambient temperature sensor on power unit - short circuit	Short circuit in ambient temperature sensor on power unit. Replace power unit	
E66	F12	Ambient temperature sensor on power unit - open circuit	Break in ambient temperature sensor on power unit. Replace power unit	
E67		12V Power Supply on power unit – too high voltage	Moisture on powerl unit Replace power unit	
E68		12V Power Supply on power unit – too low voltage	Moisture on powerl unit Replace power unit	

Industriestrasse 66, Postfach 59, 6301 Zug Telefon +41 58 767 67 67, Fax +41 58 767 67 67 info@vzuq.com, www.vzuq.com

Error message list GK11TI(X)FKZ, CTI6T-31132, CTI6T-31134

1010833-01-AJ

Serial production

created 11.12.2019 chha
modified 11.02.2020 User Agent
checked 18.12.2019 scur 4 /



12V/2 Power Supply on 1) Moisture on powerl unit E69 power unit – too high voltage 2) Replace power unit 12V/2 Power Supply on 1) Moisture on powerl unit E70 power unit - too low voltage 2) Replace power unit E71 Relais not calibrated 1) Replace power unit 1) Check if Software Baseline R03 or higher is installed 2) Check connection with Induction modules 3) Check which induction module is not answering Communication error power E72 F12 4) check all connection on induction modules (coding plug, power supply, unit – induction modules communication) 5) Replace defective induction module 6) Replace power unit 1) Check if fans of modules 1+2 are connected No fans for modules 1+2 E73 F4 2) Replace the fans detected 3) Replace the power unit 1) Check if fans of modules 1+2 are connected Short circuit of fan Modules E75 F4 2) Replace the fans 1+2 3) Replace the power unit 1) Check if fans of modules 3+4 are connected **E76** No fans for modules 3+4 2) Replace the fans 3) Replace the power unit 1) Check if fans of modules 3+4 are connected Short circuit of fan Modules F4 2) Replace the fans E78 3+4 3) Replace the power unit 1) Check if fans of modules 5+6 are connected No fans for modules 5+6 F4 E79 2) Replace the fans detected 3) Replace the power unit 1) Check if fans of modules 5+6 are connected Short circuit of fan Modules F4 E81 2) Replace the fans 5+6 3) Replace the power unit 1) Check if something is on the touch area and remove it. Touch button permanent E85 A0 2) Replace control unit press 3) Replace power unit 1) Check if something is on the touch area and remove it. **E86** F2 Touch button error 2) Replace control unit 3) Replace power unit Power unt RTC calibration E87 1) Replace power unit error 1) Check mains connection Induction module Voltage too 2) If failure persists after turning mains supply Off/On: Change Induction E88 high module Coil temperature sensor short F1 1) Replace affected Temperature sensor and coil E89 circuit Coil temperature sensor open E90 F1 1) Replace affected Temperature sensor and coil circuit Coil temperature sensor – 1) Check if problem persist after restart, if related coils is used again E91 F1 2) Replace affected Temperature sensor and coil fixed value Short circuit in coil winding. 1) Check coil connection E92 F0 Induction coil – Short circuit 2) Replace coil 3) Replace induction module Bad pan used or defect in coil or coil control Induction coil - Current out of 1) Check if error appears also with other pans E93 F0 2) Replace coil normal range 3) Replace induction module Temperature on coil is/was too high. Induction coil – too high Possible reasons: E94 Empty Pan used with high power setting temperature Pan is not even on glass surface (air between pan and glass)

Industriestrasse 66, Postfach 59, 6301 Zug Telefon +41 58 767 67 67, Fax +41 58 767 67 67 info@vzug.com, www.vzug.com

Error message list GK11TI(X)FKZ, CTI6T-31132, CTI6T-31134

1010833-01-**∆**.I

10108	33-01-AJ	1 V /
Serial pro	ZUG	
created	11.12.2019 chha	
modified	11.02.2020 User Agent	
checked	18.12.2019 scur 5 /	8

		1	10.12.2010 3001 576	
			Check for empty or bad pan Check power setting and use case	
			No coil connected or faulty connection. 1) Check if Software Baseline R06 or higher is installed	
	F0	Induction coil – open circuit	2) Check coil connection	
	10	Open circuit	3) Replace coil	
			4) replace induction module	
E95			No coil connected or faulty connection.	
			Check if Software Baseline R06 or higher is installed	
	A2	Induction coil – open circuit	2) Check coil connection	
			3) Replace coil	
			4) replace induction module	
			Short circuit in cooler temperature sensor on induction module. Replace	
E96	F11		induction module.	
			Break in cooler temperature sensor on induction module. Replace	
E97	F11		induction module.	
		•	Check air input of device if it is blocked by tissues or other parts	
-00	-44	Temperature sensor Cooler 1	2) Check if there is enough space for the air circulation in the kitchen	
E98	F11		furniture	
			3) Check if fans are blocked by dust, tissues or other parts	
E99	F11	Temperature sensor Cooler 2	1) Short circuit in cooler temperature sensor on induction module. Replace	
E33	ГП	– short circuit	induction module.	
E100	F11		Break in cooler temperature sensor on induction module. Replace	
_100		– open circuit	induction module.	
			Check air input of device if it is blocked by tissues or other parts	
E101	F11		2) Check if there is enough space for the air circulation in the kitchen	
			furniture	
			3) Check if fans are blocked by dust, tissues or other parts	
E102	F11		1) Short circuit in ambient temperature sensor on induction module. Replace	
			induction module.	
E103	F11		Break in ambient temperature sensor on induction module. Replace induction module.	
		— open circuit	Check air input of device if it is blocked by tissues or other parts	
		Temperature sensor Ambient	Check if there is enough space for the air circulation in the kitchen	
E104	F11		furniture	
			3) Check if fans are blocked by dust, tissues or other parts	
	Induction module1) Peload Software		1) Reload Software	
E108			2) Replace Induction module	
			Error in Measurement circuit on induction module.	
E109	F7	Induction module – error in	Check for moisture or dust on induction module	
		current measurement	2) Replace Induction module	
			Temperature on glass is/was too high.	
			Possible reasons:	
E110		Induction coil – too high	- Empty Pan used with high power setting	
		temperature on glass	- Pan is not even on glass surface (air between pan and glass)	
			1) Check for empty or bad pan	
			2) Check power setting and use case	
E111		Induction module –	Error in Measurement circuit on induction module.	
[=111]		Multiplexer error	Check for moisture or dust on induction module Replace Induction module	
			The maximum power which can be set in the user menu is/was exceeded.	
			Possible reasons:	
		Power Unit - Too high power	- Pan(s) have too high power-setting, so that not all pans can be	
E120		setting	supplied with the desired power without exceeding the set maximal	
			power.	
			-> reduce power setting of Pan(s)	
			The hob cooling is not sufficient which can be caused by:	
E121		Cooling not sufficient	Blocked air intake at the back of the hob: check for tissues or other	
- ' - '			material which can block the air intake.	
			Blocked air outlet: check if air outlet (front-side of hob) is blocked	

Industriestrasse 66, Postfach 59, 6301 Zug Telefon +41 58 767 67 67, Fax +41 58 767 67 67 info@vzug.com, www.vzug.com

Error message list GK11TI(X)FKZ, CTI6T-31132, CTI6T-31134

1010833-01-AJ

Serial production created 11.12.2019 chha modified 11.02.2020 User Agent checked 18.12.2019 scur 6 / 8



E122	Pan not induction compatible	 The Pan material or size is not compatible with the induction hob 1) Check if the Pan material is induction compatible -> check pan instruction manual or check if induction symbol is on pan or check if pan is magnetic. 2) Check if the Pan size is not too small (diameter >10cm)
E123	Inconsinstency of power on control unit	Consistence between GUI (shown pans) and power-request to the power unit is not consistent. 1) Reload Software
E124	Measured coil power does not match with set value	Inconsistency between coil power request and corresponding feedback. (Coil locked after too many tries). 1) Reload Software 2) Replace induction module
E125	Measured coil power does not match with set value	Inconsistency between coil power request and corresponding feedback. (Single error, but recovered after retry. Only for logging purpose for service) 3) Reload Software 4) Replace induction module

FAQs

How the hob reacts	Cause	Solution to problem			
	Display errors				
The hob detects pans that are standing closely together as just one pan, and in the display it indicates fewer pans than are standing on the hob.	The user turns the hob on when the pans are already standing on the hob and are positioned very closely together.	Lift up the pans one after the other and wait until the hob responds to this (pan display moves or appears in dotted form) before putting them back down again. Or move the pans apart.			
The hob cannot detect which pan is where and clears all the settings apart from one. It's not possible to tell which this will be. Depending where the pans are repositioned, the hob detects a single pan where there are more than one.	The user is moving more than one pan at a time.	Lift up the pans one after the other and wait until the hob responds to this (pan display moves or appears in dotted form) before putting them back down again. Only move one pan at a time.			
Not all the pans that are standing on the hob are shown in the display.	Either not all the pans are suitable for use with induction hobs or two pans were moved at the same time.	Use pans that are suitable for use with induction hobs. Only move one pan at a time.			
The display suddenly shows two pans, one above the over.	The user is tilting the pan, e.g. when stirring a sauce, then standing it back on the hob. The hob thinks that when a pan is tilted it's being moved. When it's put back down flat, the hob thinks that a second pan has been placed next to the first pan and so shows a second pan in the display.	Lift up the pan and wait until only one pan is shown in the display. Then set the pan down on the hob.			

Industriestrasse 66, Postfach 59, 6301 Zug Telefon +41 58 767 67 67, Fax +41 58 767 67 67 info@vzug.com, www.vzug.com

Error message list GK11TI(X)FKZ, CTI6T-31132, CTI6T-31134

1010833-01-AJ

Serial production

created 11.12.2019 chha
modified 11.02.2020 User Agent
checked 18.12.2019 scur 7 / 7/8

		checked 18.12.2019 scur 7
Two pans with the same size are shown with different sizes on the display.	Depending on the magnetic bottom side of the pan and the position of the pan it can cover 4-7 coils. The appliance cannot exactly detect the size of the pan.	Lift up the pan and set it up again Check if the whole bottom side of the pan is magnetic
Loss of nor		ionality
The appliance does not have enough power, and often indicates that maximum power has been exceeded.	The appliance originally had a 2-phase connection and then a 3-phase connection. As a consequence, power consumption was limited to 7,400 W.	In the user settings, under Assistance functions, increase the power consumption to 11,100 W.
The GourmetGuide functions are not working properly (temperature is too high).	The user moves a pan that is using the GourmetGuide function (melting, keeping warm, reheating, simmering). It takes a certain amount of time for the temperature sensors below the glass to measure the correct temperature. During this time, the temperature in the pan can go up.	Pans being used with a GourmetGuide function should not be moved.
Within minutes of cooking, the fan is already running at full power. The fan is loud.	The kitchen cabinet provides insufficient ventilation.	When cooking, open the drawer below the hob slightly. Have your cabinet fitter rectify the problem.
It is not possible to operate the appliance and the user cannot switch off the demo mode.	The appliance was delivered with the demo mode activated.	In the user settings, under Service functions (code 6301), uncheck the demo mode option.
No good heat distribution	Coils that have bad coverage have to be shut down because of EMV regulations. Depending on the position the coverage can be better or worse. Pans without aluminum core (for example Iron cast pans) have worse heat distribution.	Replace the pan to another spot (not just a slight movement) Use pans with bigger and permanent aluminium cores (induction compatible) Software update to R10 or higher
Reference water boiling speed		Pan: WMF without cover, Diameter = 150mm Volume: 1 litter of water, 10°C to boiling point Coils: 3 coils running (green) Time: approx. 4min
Maximal power per phase		GK11TIFKZ(S) (31062) & CTI6T-31134: 3.7 kW per one-third at 11.1 kW. At 7.4 kW connection, 3.7 kW each half

Industriestrasse 66, Postfach 59, 6301 Zug Telefon +41 58 767 67 67, Fax +41 58 767 67 67 info@vzug.com, www.vzug.com

Error message list GK11TI(X)FKZ, CTI6T-31132, CTI6T-31134

1010833-01-AJ

Serial production

created 11.12.2019 chha modified 11.02.2020 User Agent checked 18.12.2019 scur 8 / 8/8



		GK11TIXFKZ (31093) &
		CTI6T-31132: 7.4 kW on the
		whole cooking hob
Pan switches off for a short	To get a correct pan	Nothing wrong
duration	detection the cooking hob	
44.4.6.1	has sometimes to switch off	
	power for a new detection	
The Teppan Yaki is showed as a	Not the original V-ZUG	Place the Teppan Yaki
round pan.	Teppan Yaki or the Teppan	vertically centric on the right
Tourid pari.	Yaki is on the wrong place.	or the left side of the display.
Can the Teppan Yaki be used on	Taki is on the wrong place.	The Teppan Yaki especially
other cooking hobs?		for the V-ZUG FullFlex. Not
other cooking hobs?		
		tested for other cooking
Cooking bob switches of while	Dan is placed too close to	hobs.
Cooking hob switches of while	Pan is placed too close to	Move pan away from the
running	the on/off button	on/off button
Pan switches to 0 while running	Pan isn't induction	Use pans with more than
	compatible or the bottom	10cm diameter
	side is less than 10cm	Just use induction
	diameter	compatible pans
What is the maximal size of a pan?		As long as the pan can be
		placed within the marked
		zone and it is induction
		compatible it can be used.
	Error messages	
The hob switches itself on and then	There is some liquid on the	Clean the hob and then wipe
off again, detects liquid on the	ON/OFF button or on the	dry. Next, touch the ON/OFF
display or on the ON/OFF button	display, which could have	button for 3 seconds. The
and displays a message. It is not	come from cleaning or from	display is recalibrated and
possible to quit the message	a pan boiling over.	then it is possible to quit the
because the display is not	a part soming ever:	message.
responding properly.		moodage.
<u> </u>	lpotollotion orroro	I.
	Installation errors	
Scratches on the bottom side of the	1	Don't remove the sealing
	the knife	bead or do it with the fingers
glass after removing the sealing	ano ramo	
glass after removing the sealing bead		and without other tools
glass after removing the sealing	Cable is not installed	and without other tools Put the connection cable
glass after removing the sealing bead		and without other tools
glass after removing the sealing bead Connection cable and drawer	Cable is not installed	and without other tools Put the connection cable and LAN cable into the