SK[®] 604 Non-VLP 604/41TE & 606/42LE 1989-2006 Also fits 42RLE 2003-2006

Corrects / Prevents / Reduces

Delay or No Forward or Reverse, Rough Coast Down 4-3, Stabilizes Clutch Pressure & CVI's.

Working on **604 or 42RLE VLP** model that has a Pressure Control Solenoid? Order P/N **SK 42RLE-VLP** Fits: 2006up 604 and 42RLE **VLP** Models

Hello Mechanic -- We LOVE this trans.

From 1989 we got hundreds of calls--The trans would go to **Limp** or **burn** OD clutches. At first we thought there must be **BIG errors** in the system that we could **find/fix.** We bought a van, installed 6 gauges, a scan tool. While installing dozens of parts we received from shops we managed to **burn** it up **20 times** in 60,000 miles of road testing.

For the first time in 35 years we had a trans control system that was *Intelligent & adaptive*. It took us two years to catch up with it. It had **no BIG** system **errors**, but it does have about ten things that **need** your careful **attention**. This trans loves the little things you do for it, so that it will shift good, stay out of **Limp** and please your **customer**.


If trans is in vehicle skip Step 1.

Step 1

Discard OE Housing Gasket. Install new *Non Shrinking Gasket* under Piston Housing. Gasket works with all piston housings.







Models with Pressure Control Solenoid (VLP Models) Use **SK 42RLE-VLP** Fits 42RLE & 604 VLP Models.


Gasket


Housing




This Page 604/41TE, 606/42LE & 42RLE

Do NOT use Plastic Accumulator Pistons! All 1989-2006 must have aluminum pistons!









VLP Check-ball layout & PR lineup are different than shown.


Use **SK42RLE** for 42RLE & 604 **VLP Models**.

Roller ·

2/4

Reuse,

Step 1 Install Orange PR Spring, tapered end in first.



Step 2 Grind 1/8" (.125) chamfer on outboard end of reducer bushing.

Retainer

Worn bushing bore causes high line PSI. Rough or chatter on 1-2, 4-3 coast clunk and lock up plate failure. Order TransGo 604-BSH.

*Bracket

606, 42LE & 42RLE Install #5 Ball. (All others= No ball here)

92up with a two piece lockup control valve, has a retainer here. Missing retainer causes low line and

All Models Install check

balls 2,3 & 4.

Retainer

Retainer

trans burn up.

Do NOT use Plastic Accumulator Pistons! Aluminum Only! **Step 3** 2/4 Accum Piston. Install Wire Expander & the new Seal on closed end of the **Aluminum** Piston.

Step 4 Discard inner Spring. Install **Large Spacer** inside the original outer Spring.

Park lever installation:

While rotating detent plate in direction of arrow hook roller assemble into bracket.

TransGo 2020

Retainer

LISTEN UP:

If VB has bathtub, Install #1 ball.

604/42RLE 4th Type** Stack-up

UD clutch: Has four .073 thick frictions. High Energy/Brown Paper

OD clutch: Has four .073 thick frictions should be High Energy.

Reverse clutch: Has two .073 frictions High Energy/Brown Paper

Note: Some small engine models can come equipped with only 3 OD clutches & 1 Reverse clutch. This stack-up is not covered here. Use your specific vehicle data when ordering replacement parts.

UD stack- Start with .068 steel plate, alternate .073 clutch plates, the stack will end with a friction. Install .061" flat snap-ring, 4th design UD/OD Pressure plate then tapered .090 snap-ring.

OD stack- Start with .073 friction plate, alternate with .068 steel plate. The stack will end with a friction plate. Install waved snap-ring, OD/Rev Pressure Plate then install flat snap-ring.

*Rev stack- Start with .073friction, .068 steel, .073 friction, Pressure Plate and flat selective snap-ring.

Selective Rev Snap Rings: 1.53-1.58mm- # 04377195, 1.77-1.83mm- # 04412871, 2.02-2.07mm- # 04412872, 2.27-2.32mm- # 04412873.

^{**}Earlier stack-up- Types 1 through 3 can be found in the SK 604 kit Additional Information Lesson 3A

