

MARINFLOC SB 09 Content Hub Instructions



Contents

[1 Service Bulletin](#)

[1.1 no. 09, 2005-09-01](#)

[1.2 Installation precaution, recommended maintenance](#)

[2 Documents / Resources](#)

[2.1 References](#)

Service Bulletin

no. 09, 2005-09-01

Installation precaution, recommended maintenance

System applicability: Marinfloc WhiteBox® installations - overboard lines

Important!

The installation and proper operation of a Marinfloc WhiteBox® at your overboard line assures the operator that treated bilge water in excess of 15 ppm will not be discharged overboard.

Background

Many operators have chosen to install the Marinfloc WhiteBox® using their crew or appointed subcontractor. The ease of installation encourages this practice, however, recent reports of graphitization in the horizontal discharge line warrants the issuance of this Service Bulletin.

When installing the WhiteBox®, take special consideration to the difference in piping material leading into and out of the WhiteBox®. As the flanges and pipes of the WhiteBox® are 316L stainless steel, attention and preparation to the inlet and outlet piping must be taken to minimize any corrosion due to the difference in material composition. It is recommended that the flanges be suitably grounded either side of the WhiteBox®.

Furthermore, Marinfloc AB utilizes 316L stainless steel piping in the WhiteBox® to enhance durability and longevity of the system as well as reducing pipe degradation which may be caused by seawater contamination of the bilge tank.

It should be noted that during port state inspections, vessels are often asked to open their overboard line for examination. It has been reported that graphitized deposits from metal pipes may be misconstrued as oil residue. In addition, oil residue on the overboard pipe in the range of 2-3 ppm is not uncommon as water treated to levels below 15 ppm may have residual levels of oil which will adhere to the overboard line. Checking and maintaining the quality of the overboard line should be included in the vessel's preventive maintenance schedule and history of

same available for Port state/Class review.


All previous service bulletins and other important information, e.g. updated lists of approved chemicals and flocculants, can be found on our website www.marinfloc.com

Marinfloc AB
Industrivägen 10
472 95 Varekil, Sweden

Marinfloc Service Bulletin no. 09, ver. 1.1

Phone: +46 304 60 63 00
marinfloc@marinfloc.com
www.marinfloc.com

Documents / Resources

	<p>MARINFLOC SB 09 Content Hub [pdf] Instructions SB 09, SB 12, SB 11, SB 10, SB 09 Content Hub, SB 09, Content Hub, Hub</p>
--	--

References

- [User Manual](#)

[Manuals+](#), [Privacy Policy](#)

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.