

metrix MTX 3297Ex Multimeters With 60000-pt Digital Display User Guide

Home » metrix » metrix MTX 3297Ex Multimeters With 60000-pt Digital Display User Guide 🖺



Contents

- 1 MTX 3297Ex Multimeters With 60000-pt Digital Display
- 2 Precautions for use:
- 3 Inserting the batteries:
- 4 Voltage: VAC, VDC, VAC+DC or VlowZ
- **5 OPERATING INSTRUCTIONS**
- 6 Current by voltage output clamp
- 7 Operation of the switch keys and measurement
- 8 Documents / Resources
 - 8.1 References

MTX 3297Ex Multimeters With 60000-pt Digital Display

Before using the multimeter for the first time, read the ATEX/IECEx Instructions Manual.

It is used to make electrical measurements in potentially explosive zones in categories 0, 1, 2, 20, 21, 22, and MI, per Directive 2014/34/EU (ATEX).

For measurements on protected electric circuits:

- In conformity for all zones: instrument group II, explosion group IIC (explosive gases, vapours, and mists), temperature category T4.
- In conformity for the following zones: instrument group II, explosion group IIIC, dust, fibres, and conductive or nonconductive projections.
- In conformity for use in mines. Instrument group I, explosion group I, methane and coal dust.

For connections to intrinsically safe circuits, check these connections: refer to the user manual.

During measurements on an intrinsically safe circuit, the electrical parameters must comply with the following values: $U \le 65 \text{ V}$ (RMS value) or $I \le 5 \text{ A}$.

If you use this instrument other than as specified, the protection it provides may be impaired, endangering you. The safety of any system in which this instrument might be incorporated is the responsibility of the integrator of the system.

Precautions for use:

For your safety, use only the leads (15 A, 1,000 V) supplied with the instrument.

They are in conformity with standard EN 61010-031. Before each use, make sure that they are in perfect condition.

When the instrument is connected to the measurement circuits, never touch an unused terminal.

Use only suitable accessories, those supplied with the multimeter or approved by the manufacturer.

If the measurement category of the accessory is different from that of the instrument, the lowest category applies to the whole assembly.

Fuse: 10 A, 10×38, 1,000 V, F, breaking capacity > 30 kA

Inserting the batteries:



Remove the safety tabs from the batteries to make the instrument operational:

- Unscrew the 3 screws,
- Remove the membrane covering the battery,
- Remove the battery safety tabs,
- Replace the membrane covering the battery,
- Tighten the 3 screws and press on ON key.



In an Ex-classified hazardous area:

- -do not open the instrument
- -use only qualified batteries.


Terminal block: with 3 4 mm banana jacks and an optical socket for USB communication in a safe area:



Function keypad:



Voltage: VAC, VDC, VAC+DC or VlowZ






Activation of the MAX, MIN, AVG measurements:

- MAX and MIN report the highest and lowest values of the RMS measurement.
- AVG displays the mean value of the signal since the key press.

Time-stamped value for the MIN and the MAX [temporary display (4s) on the main display unit, followed by return to present value.


If the time (h:min:sec) exceeds (9:59:59), «—-» is displayed:

- - 1st press: recording of the MAX, MIN, AVG (on the 2nd display unit). The max. value is displayed by default.
- Subsequent presses: look-up of the stored values (volatile).



OPERATING INSTRUCTIONS

Visit our web site to download the operating instructions for your instrument: www.chauvin-arnoux.com
Search on the name of your instrument. When the instrument has been found, select the page. The operating instructions are on the right. Download them.




Current by voltage output clamp

 $(U \le 65 \text{ V in Ex use})$



- 1. Activate:
- 2. Select the type of signal AC, DC or AC+DC by pressing displays AC, DC or AC+DC.
- 3. Connect the black lead to the "COM" terminal and the red lead to "V".
- 4. Select the transformation ratio (the same as that of the clamp) 1 mV/A, 10 mV/A, 100 mV/A, 1000 mV/A by pressing on "clamp": to have a direct reading of the current.



Operation of the switch keys and measurement

Functions of the switch and keys

For access to the following functions: , , , , , , , , , , , , , , , , dBm, W, continuity, diode, duty cycle, and pulse duration functions, press the button of the switch corresponding to the chosen function.

Here are the combinations that are possible according to the type of measurement:

| Type of measurement | MAX/MIN/ AVG | PEAK ± | ΔREL | RANGE | | | _ |
|--|-----------------|----------|----------|----------|----------|----------|-----|
| | | | | Auto. | Manu. | HOLD | |
| VLowZ voltage VAC voltage VAC+DC voltage AAC, AAC+DC current | ~ | ~ | · | ~ | ~ | * | · |
| VDC voltage ADC current | ✓ | • | ✓ | ~ | · | ~ | |
| 60mVDC voltage | · | • | ✓ | | ~ | V | - 3 |
| 60mVAC voltage 60mVAC+DC voltage | ✓ | ✓ | ✓ | • | ~ | ✓ | ~ |
| Temperature | ~ | | √ | 1 | * | V | - |
| Ohmmeter | ✓ | | √ | ✓ | V | ✓ | 1. |
| Capacity | ~ | • | ✓ | · | ✓ | ✓ | |
| Frequency | ✓ | • | ✓ | ✓ | | ~ | ~ |
| Period (1/F) | V | - | 1 | ~ | - | V | 1 |
| Continuity | | (*· | - | ✓ | - | | |
| Diode | | | • | ✓ | • | ✓ | |
| dBm | | | 8 | ✓ | | ✓ | - |
| w | - | - | - | ✓ | - | ✓ | - |
| Duty cycle (Dc+, DC-) | | | | 1 | - | ✓ | - |
| Pulse duration (Pw+, Pw-) | • | | | V | | ✓ | |

Configuration parameters:

USER/BASIC mode: During power up, the device isin BASIC mode (default configuration VAC+DC). The main display unit indicates, for 3 s, the change to USER or BASIC mode.

- If, when you power up your multimeter, you want to activate the USER mode to recover the configuration when the multimeter was switched off, press Range and hold it down, then press **ON/OFF**.
- After an automatic power down, the device restarts in USER mode.
- The 0 center bargraph is managed automatically in IDC and VDC.
- Activation/Deactivation of auto power off by a long press on
- Activation of the Backlight ::
 - successive presses to increase the brightness
 - circular operation: brightness 1 → brightness 2 → brightness 3 → brightness 1

MLI 300 Hz filter

· in voltage measurement



- Select the type of signal AC+DC or AC by pressing AC/DC.
 Depending on what you select, the screen displays: AC or AC+DC.
- 4. Connect the black lead to the "COM" terminal and the red lead to "V". The presence of the indicates that the filter is active.

· in current measurement

- 1. Press: A or
- Select the type of signal AC+DC or AC by pressing AC/DC.
 Depending on what you select, the screen displays: AC or AC+DC.
- 4. Connect the black lead to the "COM" terminal and the red lead to "A". The presence of the indicates that the filter is active.



Documents / Resources



metrix MTX 3297Ex Multimeters With 60000-pt Digital Display [pdf] User Guide MTX 3297Ex, ASYC IV, MTX 3297Ex Multimeters With 60000-pt Digital Display, MTX 3297Ex, Multimeters With 60000-pt Digital Display, Display, Display, Display, Display, Display

References

• User Manual

Manuals+, Privacy Policy

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.