



OMRON ZS-HL-N Series Smart Sensors User Manual

[Home](#) » [Omron](#) » OMRON ZS-HL-N Series Smart Sensors User Manual 

Contents

- 1 OMRON ZS-HL-N Series Smart Sensors
- 2 Non-procedural Communication Command Reference
- 3 Product Introduction
- 4 Product Setting the Communication Specifications
- 5 Product Format
- 6 Introduction
- 7 Setting the Communication Specifications
- 8 Format
- 9 List of Non-procedural Commands
- 10 List of Parameters
- 11 FLOWDATA Reference
 - 11.1 [FLOWDATA setting example]
- 12 Example of Usage
- 13 Revision History
- 14 OMRON Corporation
- 15 Documents / Resources
- 16 Related Posts

OMRON

OMRON ZS-HL-N Series Smart Sensors



Non-procedural Communication Command Reference

- Cat. No. Z472-E1-01

Product Introduction

Thank you for purchasing the ZS-HL-N Series. This manual provides reference information on non-procedural communication commands for ZS-HL-N Series.

Product Setting the Communication Specifications

To change the settings of the controller communication specifications for non-procedural communication with the external device, follow these steps:

1. Set the mode switch to FUN.
2. Select [System] – [Communication] – [Mode] menu.
3. Select [non-procedural].
4. For RS-232C cable connection, select the [System] – [Communication] – [RS-232C] menu to set the appropriate communication specifications for the external device.
5. Save the settings.

Product Format

The format of non-procedural commands are as follows:

Example: A command to acquire a measured value MEASURE command

Each character is output as an ASCII code (except for the FLOWDATA response).

- M E A

Please refer to the manual for the full list of non-procedural commands and parameters, as well as examples of usage and revision history.

Introduction

Thank you for purchasing the ZS-HL-N Series. This manual provides reference information on non-procedural communication commands for ZS-HL-N Series. When using the ZS-HL-N Series, be sure to observe the following:

- The ZS-HL-N Series must be operated by personnel knowledgeable in electrical engineering.
- To ensure correct use, please read this manual thoroughly to deepen your understanding of the product.
- Please keep this manual in a safe place so that it can be referred to whenever necessary.

Setting the Communication Specifications

Change the settings of the controller communication specifications for non-procedural communication with the external device.



CHECK! Use USB cable or RS-232C cable to connect ZS-HL-N Series controllers to external devices. For USB cable connection, install Smart Monitor ZS and USB driver beforehand. After installing Smart Monitor ZS, USB ports are recognized as standard COM ports, and communication is achieved as with the RS-232C. (Setting the communication specifications including baud rate is not necessary.) For details on how to connect cable, refer to the User's Manual for each controller.


1. Set the mode switch to "FUN".
2. Select [System] – [Communication] – [Mode] menu.
3. Select [non-procedural].
4. For RS-232C cable connection, select [System] – [Communication] – [RS-232C] menu to set the appropriate communication specifications for the external device.
5. Save the settings.

Format

The format of non-procedural commands are as follows:

Example: A command to acquire a measured value MEASURE command

- Each character is output as an ASCII code (except for FLOWDATA response).



The format of returned values changes depending on the command. For the description of each command, refer to "List of Non-procedural Commands" section.

- MEASURE / M / DATAGET

- The returned value consists of right-aligned 11 characters and a delimiter. The unit is nm for a displacement value. The shortfalls of the characters are filled with spaces from the left.

Example: The returned value is -30.719923 mm.

		-	3	0	7	1	9	9	2	3	CR
--	--	---	---	---	---	---	---	---	---	---	----

- BANKGET command

- The returned value is output as 1 character bank No.

Example: The bank No. is 2.

1	CR
---	----

- VERGET command

- The returned value is output in the following format:

Z	S	-	L	D	C		2	.	0	0	0	CR
---	---	---	---	---	---	--	---	---	---	---	---	----

↑
Version

- Other commands

- Either OK or ER is returned according to the result of the command. The command was executed properly:

O	K	CR
---	---	----

The command was not executed properly or the setting was NG:

E	R	CR
---	---	----

- The delimiter can be selected from the following three types.
 - CR/LF/CR+LF

List of Non-procedural Commands

Command name	Format	Returned value	Description

MEASURE	MEASURE <Task No.> <delimiter>	<measured value> > <delimiter>	Acquires a measured value. If <Task No.> is omitted, it requires the displayed measured value.
M	M <Task No.> <delimiter>	<measured value> > <delimiter>	Same as MEASURE command.
DATASET	DATASET <Unit No.> <Data No.> <delimiter>	<Data> <delimiter>	Acquires measurement data or setting data of the processing unit. * For details of numbers, refer to “List of Parameters.”
DATASET	DATASET <Unit No.> <Data No.> <Setting value> <delimiter>	OK <delimiter> E R <delimiter>	Changes setting data of the processing unit. * For details of numbers, refer to “List of Parameters.”
BANKGET	BANKGET<delimiter> >	<Bank No.> <delimiter>	Acquires the current bank No.
BANKSET	BANKSET<Bank No.> > <delimiter>	OK <delimiter> E R <delimiter>	Switches to the designated bank No.

ZERORST	ZERORST <Task No.> <delimiter>	OK <delimiter> E R <delimiter>	Executes a zero-reset. If <Task No.> is omitted, it executes on the task currently displayed as a result. If <Task No.> is set to 4, it executes on all the tasks.
ZEROCLR	ZEROCLR <Task No.> <delimiter>	OK <delimiter> E R <delimiter>	Cancels a zero-reset. If <Task No.> is omitted, it executes on the task currently displayed as a result. If <Task No.> is set to 4, it executes on all the tasks.
DATASAVE	DATASAVE <delimiter>	OK <delimiter> E R <delimiter>	Saves all the bank data on the flash memory of the controller.
VERGET	VERGET<delimiter>	<Type/Version> <delimiter>	Acquires version information of the system. Example: ZS-LDC 1.100<delimiter>
FLOWDATA	FLOWDATA <delimiter>	OK <delimiter> E R <delimiter>	Used to acquire measurement data at the shortest intervals possible. For details, refer to “FLOWDATA Reference.”

- Specifying the node
 - Specify @xx at the beginning of the command.
 - If the node No. is 1, specify @01. (Be sure to note double digits.)
 - If the node No. is omitted, the command operates on the node that received it.
- Format of a returned value
 - A returned value for MEASURE,M,DATAGET, CFLOGGET,CFDATGET is the right aligned 11 characters.
- Upper case and lower case characters
 - For alphabetic, only upper case characters are accepted.
- Task No.
 - Omit <Task No.> when issuing a command for ZS-LDC.
 - Task Nos are assigned as follows: 0: TASK1 1: TASK2 2: TASK3 3: TASK4.

List of Parameters

The following parameters can be obtained or set by DATASET or DATASET command:

Unit No.	Data No.	Parameter	Setting range/Output range	Others
0	0	Measurement mode	0: STANDARD	When multi-task mode
			1: HI-RESO	is OFF.
			2: HI-SPEED	
			3: HI-SENS	
			4: CUSTOM	
		Measurement mode	1: STANDARD	When multi-task mode
			2: HI-RESO	is ON.
			3: HI-SENS	
			4: CUSTOM	
	12	Start position of area 1	0 to 639 (pix)	

	14	End position of area 1	0 to 639 (pix)	
	13	Start line of area 1	0 to (No. of additional lines – 1)	
	15	End line of area 1	0 to (No. of additional lines – 1)	
	24	Start position of area 2	0 to 639 (pix)	
	26	End position of area 2	0 to 639 (pix)	
	25	Start line of area 2	0 to (No. of additional lines – 1)	
	27	End line of area 2	0 to (No. of additional lines – 1)	
	18	Exposure time	2 to 200 (1 div: 0.1ms)	Parameters for
			When multi-task mode is OFF.	CUSTOM mode
			5 to 200 (1 div: 0.1ms)	
			When multi-task mode is ON.	

	19	Number of additional	1 to 200	
		lines	When multi-task mode is OFF.	
			8 to 200	
			When multi-task mode is ON.	
	20	Line skipping	0: OFF	
			1: ON	
	22	2-area mode	0: OFF	
			1: ON	
	23	Compensation mode	0: OFF	
			1: Start position compensation	
			2: End position compensation	
			3: Start/End position	

2	Surface to be controlled for light amount	0: Peak 1: First surface 2: Second surface 3: Third surface	
6	LD power when fixed	0 to 800 (1 div: 0.1%)	
13	Lower limit of LD power	0 to 800 (1 div: 0.1%)	
14	Upper limit of LD power	0 to 800 (1 div: 0.1%)	
32	Incident level	0 to 4095	
36	LD power	0 to 800 (1 div: 0.1%)	
37	Incident level (First surface)	0 to 4095	

	38	Incident level (Second surface)	0 to 4095	
	39	Incident level (Third surface)	0 to 4095	
	0	Measurement object	When multi-task mode is OFF. 0: STANDARD 1: PCB 2: Mirror 3: Glass surface 4: Glass thickness	
			When multi-task mode is ON. 0: STANDARD 1: PCB 2: Mirror 3: Glass surface	
	2	GLASS/GLASS THICKNESS mode	0: Mode 1 1: Mode 2	

3	3	Image smoothing level	0: No filter 1: Filter size 2 2: Filter size 4 3: Filter size 8 4: Filter size 16	When the measurement object is changed, the settings are initialized according to the selected object.
	4	Background removing level before addition	0 to 255 (tone)	
	6	Edge threshold	0: 0% 1: 12.5% 2: 25% 3: 37.5% 4: 50% 5: 62.5% 6: 75% 7: 87.5%	

Unit No.	Data No.	Parameter	Setting range/Output range	Others
4	0	Mutual interference prevention mode	0: OFF 1: ON	

	1	Mutual interference prevention timing	0: Timing A 1: Timing B	
5	0	Gain setting	1 to 5	
	0	Measurement mode	0: OFF 1: Average 2: Peak 3: Bottom 4: Thickness 5: Gap 6: K+mX; +nY	
	3	Parameter X	0: None 1: TASK 1 2: TASK 2 3: TASK 3 4: TASK 4	
	4	Parameter Y	0: None 1: TASK 1 2: TASK 2 3: TASK 3 4: TASK 4	

40

5	Parameter K	-999999999 to 999999999 (nm)
8	Parameter M	-100 to 100 (1div: 0.1)
9	Parameter N	-100 to 100 (1div: 0.1)
1	Surface for measurement (Area 1)	0: First surface 1: Second surface 2: Third surface 3: Peak
10	Surface for measurement (Area 2)	0: First surface 1: Second surface 2: Third surface 3: Peak
11	Measurement position 1 (for thickness measurement)	0: None 1: Average 2: Peak 3: Bottom

TASK1 settings.

The settings in Unit Number 40 are valid only for multi-task mode.

	12	Measurement position 2 (for thickness measurement)	0: None 1: Average 2: Peak 3: Bottom
	13	Measurement area	0: Area 1 1: Area 2
	14	Width of peak bottom	0 to 255
	32	Measurement value (First surface)	– (nm)
	33	Measurement value (Second surface)	– (nm)

Unit No.	Data No.	Parameter	Setting range/Output range	Others
40	34	Measurement value (Third surface)	– (nm)	

41	0	Scaling mode	0: OFF 1: ON
	1	Span value	-20000 to 20000 (1 div: 0.000 1)
	2	Offset value	-999999999 to 999999999 (nm)
42	2	Smooth	0: OFF 1: ON
43	2	Average	0: 1 time 1: 2 times 2: 4 times 3: 8 times 4: 16 times 5: 32 times 6: 64 times 7: 128 times 8: 256 times 9: 512 times 10: 1024 times 11: 2048 times 12: 4096 times

44	2	Differential type	0: OFF 1: ON	TASK1 settings. The settings in Unit Number 40 are valid only for multi-task mode .
	3	Differentiation cycles	1 to 5000 (ms)	
45	2	Hold type	0: Through 1: Peak 2: Bottom 3: Peak to peak 4: Average 5: Sampling	
	3	Trigger method	0: External input 1: Self up 2: Self down	
	4	Trigger level	-999999999 to 999999999 (nm)	
	5	Trigger hysteresis	0 to 999999999 (nm)	
	6	Trigger delay (ms)	0 to 5000 (ms)	

	7	Sampling period (ms)	1 to 5000 (ms)
	8	Trigger delay mode	0: OFF 1: ON
46	5	Offset at zero reset	-999999999 to 999999999 (nm)
	7	Zero reset mode	0: REAL 1: HOLD
	64	Status	0: OFF 1: ON

- If GLASS/MODE 2 or GLASS THICKNESS/MODE 2 is selected, a process using multiple tasks will be performed, as in the multi-task mode.

The following processes are assigned to the respective tasks:

TASK 1	Calculates Area 1 displacement value.
TASK 2	Calculates Area 2 displacement value.
TASK 3	GLASS: Calculates the result of the NEAR side of TASK 1 and TASK 2.
	GLASS THICKNESS: Calculates the difference value between TASK1 and TASK2.
TASK 4	Unused

The measurement conditions can be set for each task in this mode.

- Configuration of Task
 - The ZS-HLDC-N performs task processing.
 - The processing units for each task are grouped into 20 units.
 - To refer to the processing unit of TASK N, therefore, add $20 \times (N-1)$ to the above processing unit No.

Example: To change the averaging process of TASK2, refer to or set to a parameter with:

- Process unit No.= $43+20 \times (2-1)=63$ and
- Data No.=2

Unit No.	Data No.	Parameter	Setting range/Output range	Others
120	0	Hysteresis width	0 to 999999999 (nm)	Setting judgment proces
	1	Timer mode	0: OFF 1: OFF-Delay 2: ON-Delay 3: One shot	

	2	Delay time	1 to 5000 (ms)	s
	3	Judgment output TASK	0: TASK 1 1: TASK 2 2: TASK 3 3: TASK 4	
121	0	Non-measurement settings	0: Keep 1: Clamp	
	2	Monitor focus mode	0: OFF 1: ON	
	3	Monitor focus distance value 1	-999999999 to 999999999 (nm)	
	4	Monitor focus distance value 2	-999999999 to 999999999 (nm)	
122				

	5	Monitor focus current value 1	4 to 20 (mA)	
	6	Monitor focus current value 2	4 to 20 (mA)	
	7	Monitor focus voltage value 1	-10 to 10 (V)	
	8	Monitor focus voltage value 2	-10 to 10 (V)	

			When multi-task mode is OFF. 0: OFF 1: ON	

	21	Output mode TASK	<div>When multi-task mode is ON. 0: OFF 1: TASK 1 2: TASK 2 3: TASK3 4: TASK4</div>	

122	23	Output at CLAMP	Voltage output 0: MAX
			1: 10 V
			2: 9 V
			3: 8 V
			4: 7 V
			5: 6 V
			6: 5 V
			7: 4 V
			8: 3 V
			9: 2 V
			10: 1 V
			11: 0 V
			12: -1 V
			13: -2 V
			14: -3 V
			15: -4 V
			16: -5 V
			17: -6 V
			18: -7 V
			19: -8 V
			20: -9 V
			21: -10 V
			22: MIN

			<p>Current output 0: MAX</p> <p>1: 20 mA</p> <p>2: 19 mA</p> <p>3: 18 mA</p> <p>4: 17 mA</p> <p>5: 16 mA</p> <p>6: 15 mA</p> <p>7: 14 mA</p> <p>8: 13 mA</p> <p>9: 12 mA</p> <p>10: 11 mA</p> <p>11: 10 mA</p> <p>12: 9 mA</p> <p>13: 8 mA</p> <p>14: 7 mA</p> <p>15: 6 mA</p> <p>16: 5 mA</p> <p>17: 4 mA</p>	
--	--	--	--	--

	2	Monitor focus mode	<p>0: OFF</p> <p>1: ON</p>	

123 Digital output	3	Monitor focus distance value 1	-999999999 to 999999999 (nm)	
	4	Monitor focus distance value 2	-999999999 to 999999999 (nm)	
	5	Monitor focus current value 1	0 to 65535	
	6	Monitor focus current value 2	0 to 65535	
	7	Clear monitor focus	1: Clear	
123	8	Output at CLAMP	0 to 65535	
	10	Output TASK (When the measurement value is output)	0: TASK 1 1: TASK 2 2: TASK 3 3: TASK 4 4: Consecutively	

	11	Output mode	0: OFF 1: Measurement value 2: Judgment	
	12	Update cycle	0 to 100	
124 Logging	2	Mode	0: OFF 1: ON	
	3	Buffering period	1 to 65535	
	4	Buffer size per item of data	1 to 1000	
	14	TASK 1	0: OFF 1: ON	When multi-task mode is ON.
	15	TASK 2	0: OFF 1: ON	

	16	TASK 3	0: OFF 1: ON	
	17	TASK 4	0: OFF 1: ON	
240 Parallel input	4	Input 0	0: Low Active 1: High Active	
	5	Input 1		
	6	Input 2		
	7	Input 3		
	8	External input mode	0: Normal mode 1: Bank switching mode	
	9	Control TASK setting	0: TASK1 1: TASK2 2: TASK3 3: TASK4	

When multi-task mode is OFF

- When selecting a mode other than “GLASS/MODE 2” and “GLASS THICKNESS/ MODE 2”.

Unit No.	Data No.	Parameter	Setting range/Output range	Others
48	2	Lower limit of threshold	-999999999 to 999999999 (nm)	
	3	Upper limit of threshold	-999999999 to 999999999 (nm)	
	4	Hysteresis width	0 to 999999999 (nm)	
	5	Timer mode	0:OFF 1:OFF DELAY 2:ON DELAY 3:ONE SHOT	
	6	Delay time	1 to 5000 (ms)	

- When selecting “GLASS/MODE 2” or “GLASS THICKNESS/MODE 2” mode.

Unit No.	Data No.	Parameter	Setting range/Output range	Others
88	2	Lower limit of threshold	-999999999 to 999999999 (nm)	
	3	Upper limit of threshold	-999999999 to 999999999 (nm)	
	4	Hysteresis width	0 to 999999999 (nm)	
	5	Timer mode	0:OFF 1:OFF DELAY 2:ON DELAY 3:ONE SHOT	
	6	Delay time	1 to 5000 (ms)	

When multi-task mode is ON

- Can be set for each TASK.

Unit No	Data No.	Parameter	Setting range/Output range	Others	
48	2	Lower limit of	-999999999 to 99999999 (nm)	TASK1 settings.	
		threshold		For TASK2 to	
	3	Upper limit of	-999999999 to 99999999 (nm)	TASK4, the unit	
		threshold		numbers are as	
	4	Hysteresis width	0 to 999999999 (nm)	follows:	
	5	Timer mode	0:OFF 1:OFF DELAY	TASK2: 68	
			2:ON DELAY 3:ONE SHOT	TASK3: 88 TASK4: 108	
	6	Delay time	1 to 5000 (ms)		

FLOWDATA Reference

What is FLOWDATA?

- The ZS-HL-N series implements high speed sampling measurement up to 110us.
- Handling these measurement data with an external device requires reading in a large amount of data.
- The ZS-HL-N series are provided with a mechanism which enables to handle and acquire measurement data by a given bundle.
- This bundle of data is called a FLOWDATA.

How to acquire FLOWDATA

FLOWDATA is batch output if the controller has accepted the command for acquiring a FLOWDATA when data is accumulated for the specified buffer size (max. 1000 data). A device receiving data (such as PC) needs to issue the command before the ZS controller accumulates measurement data for the buffer size.

Unit No.	Data No.	Parameter	Description
124	2	FLOWDATA accumulation mode	0: OFF 1: ON
	3	Buffer intervals	1 to 65535 (pcs)
	4	Buffer size	1 to 1000 (pcs)

Logging data

Data to be accumulated in the ZS controller can be selected.

- When multi-task mode is OFF
- When GLASS/MODE 2 or GLASS THICKNESS/MODE 2 is selected for the measurement object

Unit No.	Data No.	Value	Description
124	5	0	No accumulation
		1	Accumulation of result of area 1
		2	Accumulation of result of area 2
		3	Accumulation of result of glass surface or glass thickness

- When a mode other than the above is selected for the measurement object.

Unit No.	Data No.	Value	Description
124	5	0	No accumulation
		1	Accumulation

- When multi-task mode is ON

Unit No.	Data No.	Value	Description
124	14	0	Does not accumulate the result of TASK 1
		1	Accumulate the result of TASK 1
	15	0	Does not accumulate the result of TASK 2
		1	Accumulate the result of TASK 2
	16	0	Does not accumulate the result of TASK 3
		1	Accumulate the result of TASK 3
	17	0	Does not accumulate the result of TASK 4
		1	Accumulate the result of TASK 4

Configuration of FLOWDATA Response

1 packet of FLAWDATA													
Header division												Data division	
1st byte	2nd byte				3rd byte			4th byte				—	
A	B	C	D	E	F	G	H	I	J	K	L	Data	Meaning of data
8	1	1	2	4	5	1	2	1	1	1	5	32	Number of bits

- =Total
 - 64 bits

Details of header division

Data	Name	Description
------	------	-------------

A	Unused	Reserved bit
B	FLOWDATA overflow bit	Normally set to 0.Set to 1 when there is an overflow in FLOWDATA accumulation.
C	Decimal information	Normally set to 0.0: nm order, 1: mm order
D	TASK No.	TASK1 to TASK4 (*1)
E	Unused	Always 0
F	Unit states (Input)	Indicates ON/OFF states of various input lines. (*2)
G	FLOWDATA stop bit	<ul style="list-style-type: none"> • All data are set to 1 if FLOWDATA does not flow over subsequently. (Always set to 1 for one-shot requests) • All data are set to 0 if FLOWDATA continues to flow over. (Until FLOWDATA is stopped after requested (in succession))
H	TASK judgment result bit	Indicates the TASK judgment result of data source. (*3)
I		

J	Disabled	Reserved bit
K		
L	Unit states (Output)	Indicates output states (states of measurement results). (*4)
Data	Measurement data	<p>Signed 32 bit data</p> <p>When the decimal info division is 0, the unit of the data is nm. When the decimal info division is 1, the unit of the data is mm</p>

- TASK No.=bit data+1

Example: bit data=10B=2 (dec) indicates TASK3 data.

The input lines are, from the lower bit, assigned to:

In case of ZS

- Input terminal 4 (Unused. Always set to 0.)
- Input terminal 3
- Input terminal 2
- Input terminal 1
- Input terminal 0 (5 inputs in total.)

Data to be received and their states are as follows:

- 00b=Not executed
- 01b=LOW
- 10b=PASS
- 11b=HIGH

The output states are, from the lower bit, assigned to:

In case of ZS


- Output terminal 4 (Busy output)
- Output terminal 3 (Enable output)
- Output terminal 2 (Low output)
- Output terminal 1 (Pass output)
- Output terminal 0 (High output)

(5 outputs in total). States in parenthesis indicate the standard states.

[FLOWDATA setting example]

- **DATASET 124 2 1:** FLOWDATA accumulation mode ON
- **DATASET 124 3 1:** 1 buffer interval
- **DATASET 124 4 1:** 1 buffer size
- **DATASAVE:** Data save

FLOWDATA




Example of Usage

To give an example, provided below is a procedure to communicate by non-procedural commands using Windows standard tool HyperTerminal.

Start up HyperTerminal


HyperTerminal is located under [Program]-[Accessory]-[Communication].




1. Enter an appropriate project name.



2. Select the COM port connected to the ZS in the Connection Method section.




3. Set the communication conditions.




4. HyperTerminal is started up.


To make the interaction with commands easier, set echo and other functions



1. Open [Property].




2. Select the setting tag, and then ASCII settings.




3. Check the following items, and press OK to complete the setting.

- Change ZS into "RUN" mode.
- Perform non-procedural communication.



1. Input a command, and then press the return key.



2. A returned value responding to the command is returned from the controller.

Revision History

A manual revision code appears as a suffix to the catalog number at the bottom of the front and back covers of this manual.

Cat. No. Z472-E1-01
↑
Revision code

Revision code	Date	Revised contents
01	2022, Nov.	Original production

OMRON Corporation

Industrial Automation Company

- Kyoto, JAPAN
- Contact: www.ia.omron.com

Regional Headquarters

OMRON EUROPE B.V.

- Wegalaan 67-69, 2132 JD Hoofddorp The Netherlands
- Tel: (31) 2356-81-300
- Fax: (31) 2356-81-388

OMRON ASIA PACIFIC PTE. LTD.

- 438B Alexandra Road, #08-01/02 Alexandra Technopark, Singapore 119968

- **Tel:** (65) 6835-3011
- **Fax:** (65) 6835-2711

OMRON ELECTRONICS LLC

- 2895 Greenspoint Parkway, Suite 200 Hoffman Estates, IL 60169 U.S.A.
- **Tel:** (1) 847-843-7900
- **Fax:** (1) 847-843-7787

OMRON (CHINA) CO., LTD.


- Room 2211, Bank of China Tower, 200 Yin Cheng Zhong Road, PuDong New Area, Shanghai, 200120, China
- **Tel:** (86) 21-5037-2222
- **Fax:** (86) 21-5037-2200

©OMRON Corporation 2022 All Rights Reserved.

In the interest of product improvement, specifications are subject to change without notice.

Cat. No. Z472-E1-01

Documents / Resources

	<p>OMRON ZS-HL-N Series Smart Sensors [pdf] User Manual ZS-HL-N Series Smart Sensors, ZS-HL-N Series, Smart Sensors, Sensors</p>
---	--