



PCE Instruments PCE-ERT 10 Earth Tester Earth Resistance Meter User Manual

[Home](#) » [PCE Instruments](#) » PCE Instruments PCE-ERT 10 Earth Tester Earth Resistance Meter User Manual 

PCE Instruments PCE-ERT 10 Earth Tester Earth Resistance Meter User Manual



Contents

- 1 Safety notes
- 2 Delivery contents
- 3 Technical specifications
- 4 Device description
- 5 Operating instructions
- 6 DC/AC voltage measurement
- 7 Maintenance and cleaning
- 8 Contact
- 9 Disposal
- 10 PCE Instruments contact information
- 11 Documents / Resources
 - 11.1 References
- 12 Related Posts

Safety notes

Please read this manual carefully and completely before you use the device for the first time. The device may only be used by qualified personnel and repaired by PCE Instruments personnel. Damage or injuries caused by non-observance of the manual are excluded from our liability and not covered by our warranty.

- The device must only be used as described in this instruction manual. If used otherwise, this can cause dangerous situations for the user and damage to the meter.
- The instrument may only be used if the environmental conditions (temperature, relative humidity, ...) are within the ranges stated in the technical specifications. Do not expose the device to extreme temperatures, direct sunlight, extreme humidity or moisture.
- Do not expose the device to shocks or strong vibrations.
- The case should only be opened by qualified PCE Instruments personnel.
- Never use the instrument when your hands are wet.
- You must not make any technical changes to the device.
- The appliance should only be cleaned with a damp cloth. Use only pH-neutral cleaner, no abrasives or solvents.
- The device must only be used with accessories from PCE Instruments or equivalent.
- Before each use, inspect the case and test leads for visible damage. If any damage is visible, do not use the device.
- Do not use the instrument in explosive atmospheres.
- The measurement range as stated in the specifications must not be exceeded under any circumstances.
- If the battery is flat (e.g. indicated by the battery indicator), the meter must no longer be used as incorrect measured values can cause life-threatening situations. When full batteries are used again, the measuring operation may be continued.
- Before each use, check the meter by measuring a known quantity.
- This meter is suitable for measurements in circuits with an overvoltage category CAT III up to a voltage of 1000 V.
- To ensure safe operation before starting the measurement, always check whether the correct measurement range is selected and whether the test leads are plugged into the sockets intended for the respective







measurement.

- Measurements of resistance, capacitance and temperature as well as diode tests may only be carried out in voltage-free state.
- The bare measuring tips must never be touched because there is a risk of electric shock.
- Be extra careful when measuring high voltages.
- Before opening the housing to replace the battery or fuse, remove all test leads, otherwise there is a risk of electric shock.
- If you do not want the meter to be used for a long time, remove the batteries to avoid damage caused by battery leakage.
- Non-observance of the safety notes can cause damage to the device and injuries to the user.

We do not assume liability for printing errors or any other mistakes in this manual.

We expressly point to our general guarantee terms which can be found in our general terms of business.

Safety symbols

	General warning. Consult the documentation
	Warning of dangerous electrical voltage
	Continuous double insulation or reinforced insulation
	Earth (ground)
	DC (direct current)
	Operating voltage below target Replace batteries, otherwise incorrect measurements can occur


Delivery contents

- 1 x earth resistance tester PCE-ERT 10
- 1 x set of test leads (approx. 15m)
- 4 x ground spikes
- 6 x batteries
- 1 x carrying case
- 1 x instruction manual

Technical specifications

Measurement rangesEarth resistanceEarth voltageDC voltageAC voltageResistance	20 0 / 200 0 / 2000 0200 V1000 V750 V (40 Hz – 400 Hz)200 k Ω
ResolutionEarth resistanceEarth voltageDC voltageAC voltageResistance	0.01 0 / 0.1 0 / 1 00.1 V1 V1 V0.1 k Ω
AccuracyEarth resistanceEarth voltageDC voltageAC voltageResistance	$\pm(2 \% + 10 \text{ dgt}) / \pm(2 \% + 3 \text{ dgt}) / \pm(2 \% + 3 \text{ dgt}) \pm(3 \% + 3 \text{ dgt})$ $\pm(0.8 \% + 3 \text{ dgt})$ $\pm(1.2 \% + 10 \text{ dgt})$ $\pm(1 \% + 2 \text{ dgt})$
Sampling rate	2.5 / second
Display	LCD with backlight
Power supply	6 x 1.5 V AA batteries
Environmental conditions	0 +40 °C / <80 % RH
Dimensions	200 x 92 x 50 mm
Weight	700 g
Standards	IEC10101, CAT111000V

Device description



1. Display
2. „HOLD“ key
3. Zero adjustment wheel

4. Backlight key
5. „TEST“ key
6. Measuring function selector
7. V/ Ω /C socket
8. P socket
9. COM socket
10. Holder for carrying strap
11. Battery compartment cover


Operating instructions

Measurement of the effective resistance of earth electrodes

Warning: Before you start the measurement, read the safety instructions above.

Note: Low batteries can falsify the measurement results. Therefore, pay attention to the battery level and replace the batteries before starting the measurement if necessary.

1. Short-circuit the test leads and press the “TEST” key. Use the zero adjustment wheel to set the value to 0 Ω .
2. Move the measuring function selector to the “EARTH VOLTAGE” position and press the “TEST” key. The ground voltage is shown on the display. If the voltage is more than 10 V, this can lead to an incorrect measurement of the earth resistance.
3. To make a precise measurement of the earth resistance:
 1. Connect the green, yellow and red test leads to the device connections E, P and C.
 2. Connect the crocodile clips of the test leads to the earth electrodes (according to the figure below). The auxiliary electrodes attached to P and C must form a straight line with the electrode to be tested (attached to E).
 3. Set the measuring function selector to a suitable measurement range, press the “TEST” key and read the measured value.




To use a simplified measurement procedure, proceed as follows:

1. This method is recommended where the earth resistance is higher than 10 Ω and where it is not possible to drive auxiliary electrodes into the ground. An approximate value can be determined by the two-wire system which can be seen in the figure below.
2. Move the measuring function selector to the “EARTH VOLTAGE” position and press the “TEST” key. Make sure

that the ground voltage is below 10 V.

3. First, move the measuring function selector to the measurement range 200 Ω , press the "TEST" key and read the measured value. If the display shows "1" (measurement range exceeded), switch to the range 2000 Ω and read the value.



4. The read value (R_e) is an approximate earth resistance value. In this measurement, the test leads P and C do not have to be short-circuited before the start of the measurement as the special included test lead is used. This test lead already has a connection between the two sockets (red test line, see figure).
5. Actual grounding resistance = read value – earth resistance of earth electrode
 $R_X = R_e - r_e$

DC/AC voltage measurement

1. Set the measuring function selector to DC/AC (1000 V DC or 750 V AC).
2. Plug the black test lead into the negative COM port.
3. Plug the red test lead into the positive port V.
4. Contact the tip of the black test lead with the negative side of the circuit.
5. Contact the tip of the red test lead with the positive side of the circuit.
6. Read the voltage value in the display.

Note: If the polarity is reversed, there is a minus sign in front of the measured value.

Resistance measurement



Warning: To avoid electric shock, check that the circuit or electrical component is voltage-free before starting the measurement.

1. Set the measuring function selector to 200 k Ω .
2. Plug the black test lead into the negative COM port.
3. Plug the red test lead into the positive port Ω .
4. Contact the tips of the test leads with the component/circuit to be tested.
5. Read the resistance value in the display.

„HOLD“ function

The "HOLD" function "freezes" the measured value on the display. Press the "HOLD" key at the desired moment to capture a displayed reading. Pressing again terminates the function.


Backlight




Press  to enable the display backlight. The backlight will switch off automatically after 15 seconds.

Maintenance and cleaning

Battery replacement



A low battery level is indicated by the  icon in the display.

Warning: Before opening the earth resistance tester, disconnect it from the measuring circuit, remove the test leads from the meter and carefully remove the fold-down device stand.

To insert the batteries when restarting or to replace the batteries with insufficient voltage, loosen the four screws of the battery compartment cover on the back of the device, remove the lid, insert the batteries or remove the old batteries, replace them with new ones, insert the lid and screw it back in.

Cleaning

Clean the device with a dry cloth. Do not use any abrasives or solvents.

Contact

If you have any questions, suggestions or technical problems, please do not hesitate to contact us. You will find the relevant contact information at the end of this user manual.

Disposal

For the disposal of batteries in the EU, the 2006/66/EC directive of the European Parliament applies. Due to the contained pollutants, batteries must not be disposed of as household waste.

They must be given to collection points designed for that purpose.

In order to comply with the EU directive 2012/19/EU we take our devices back. We either re-use them or give them to a recycling company which disposes of the devices in line with law.

For countries outside the EU, batteries and devices should be disposed of in accordance with your local waste regulations.

If you have any questions, please contact PCE Instruments.



product search on: www.pce-instruments.com

PCE Instruments contact information

Germany

PCE Deutschland GmbH Im Langel 26 D-59872 Meschede Deutschland

Tel.: +49 (0) 2903 976 99 0

Fax: +49 (0) 2903 976 99 29

info@pce-instruments.com

www.pce-instruments.com/deutsch

France

PCE Instruments France EURL

23, rue de Strasbourg

67250 Soultz-Sous-Forêts France

Téléphone: +33 (0) 972 3537 17 Numéro de

fax: +33 (0) 972 3537 18 info@pce-france.fr

www.pce-instruments.com/french

Spain

PCE Ibérica S.L.

Calle Mayor, 53 02500 Tobarra (Albacete)

España

Tel.: +34 967 543 548

Fax: +34 967 543 542

info@pce-iberica.es

www.pce-instruments.com/espanol

United Kingdom

PCE Instruments UK Ltd

Unit 11 Southpoint Business Park

Ensign Way, Southampton Hampshire

United Kingdom, SO31 4RF

Tel: +44 (0) 2380 98703 0

Fax: +44 (0) 2380 98703 9

info@pce-instruments.co.uk

www.pce-instruments.com/english

Italy

PCE Italia s.r.l

Via Pesciatina 878 / B-Interno 6

55010 Loc. Gragnano

Capannori (Lucca)

Italia

Telefono: +39 0583 975 114

Fax: +39 0583 974 824

info@pce-italia.it

www.pce-instruments.com/italiano

Turkey

PCE Teknik Cihazları Ltd.Şti.

Halkalı Merkez Mah.

Pehlivan Sok. No.6/C

34303 Küçükçekmece – İstanbul

Türkiye

Tel: 0212 471 11 47

Faks: 0212 705 53 93

info@pce-cihazlari.com.tr

www.pce-instruments.com/turkish

The Netherlands

PCE Brookhuis B.V.

Institutenweg 15

7521 PH Enschede

Nederland
Telefoon: +31 (0)53 737 01 92 info@pcebenelux.nl
www.pce-instruments.com/dutch


United States of America
PCE Americas Inc.
1201 Jupiter Park Drive, Suite 8
Jupiter / Palm Beach
33458 FL
USA

Tel: +1 (561) 320-9162
Fax: +1 (561) 320-9176
info@pce-americas.com
www.pce-instruments.com/us

Denmark
PCE Instruments Denmark ApS
Birk Centerpark 40
7400 Herning
Denmark
© PCE Instruments





Documents / Resources

	<p>PCE Instruments PCE-ERT 10 Earth Tester Earth Resistance Meter [pdf] User Manual PCE-ERT 10 Earth Tester Earth Resistance Meter, PCE-ERT 10, Earth Tester Earth Resistance Meter, Tester Earth Resistance Meter, Earth Resistance Meter, Resistance Meter, Meter</p>
---	---

References

- [France.fr : Actualités, destinations et infos du tourisme en France](#)
- [iberica.es](#)
- [Make an offer on the domain instruments.co.uk - Domains.co.uk](#)
- [Computer Instruments | Home](#)
- [Discover Italy: Official Tourism Website - Italia.it](#)
- [Industrial Measurement Products and Solutions | PCE Instruments](#)
- [PCE Deutschland GmbH Prüfgeräte vom Hersteller | PCE Instruments](#)
- [PCE Brookhuis B.V. | PCE Instruments](#)
- [PCE Americas Inc. : Test Instruments | PCE Instruments](#)
- [PCE Iberica S.L. Instrumentación | PCE Instruments](#)
- [PCE Instruments France | PCE Instruments](#)

-  [PCE Italia s.r.l. / Strumenti di Misura | PCE Instruments](#)
-  [PCE Teknik Cihazlar Paz. Tic. Ltd.Şti. | PCE Instruments](#)
-  [PCE Americas Inc. : Test Instruments | PCE Instruments](#)
- [User Manual](#)

Manuals+.