



# Home » Precision Electric » Precision Electric 574-256-1000 Variable Frequency Drives Owner's Manual ₹

#### Contents [ hide ]

- 1 Precision Electric 574-256-1000 Variable Frequency Drives
- 2 INTRODUCTION
- 3 Causes of VFD Ground Fault Trips
- 4 Causes of VFD Short-Circuit Trips
- 5 How Modern VFDs Detect Ground Faults and Short Circuits
- 6 Insulation Resistance Standards (IEEE 43 & NETA ATS) and Testing Practices
- 7 Real-World Examples and Diagnostic Insights
- 8 Best Practices for Prevention and Troubleshooting
- 9 References
- 10 Documents / Resources
  - 10.1 References



Precision Electric <u>574-256-1000</u> Variable Frequency Drives



#### INTRODUCTION

# VFD Ground Fault Trip and Short-Circuit Faults: Causes, Detection, and Best Practices

Variable Frequency Drives (VFDs) are equipped with protective features to handle ground fault trips and short-circuit trips. A VFD ground fault trip occurs when current leaks from the motor or cable to ground (earth) beyond a safe threshold, while a short-circuit trip indicates a direct phase-to-phase or phase-to-ground short causing a surge in current. Understanding why these faults happen and how modern drives detect them is crucial for troubleshooting and prevention. This article provides a detailed look at the causes of ground fault and short-circuit trips in VFD systems, how manufacturers' documentation (ABB, Eaton, Yaskawa, Hitachi, Lenze, etc.) explains their detection methods, insulation resistance standards (IEEE 43, NETA ATS), real-world diagnostic examples, and best practices for testing and maintenance. The goal is a practical, "VFD fault troubleshooting" guide to keep your drives and motors running reliably.

## **Causes of VFD Ground Fault Trips**

Ground faults in VFD-driven systems are typically caused by insulation breakdown or unintended current paths from the motor windings or cables to ground. Common causes include:

Damaged Insulation in Motors or Cables: Aging, overheating, physical damage, or manufacturing defects can compromise insulation. Once insulation is weak, normal AC drive output can leak current to the motor frame or cable shielding, triggering a ground fault. For example, ABB notes that deteriorated motor winding insulation or cable damage often leads to leakage current and an imbalance in phase currents, causing the drive's ground fault protection to trip. A motor that has been in service for many years or exposed to harsh conditions may develop cracks in the varnish or cable nicks that result in a ground fault.

Moisture and Contamination: Water ingress, condensation, or conductive dust and debris can create a path from live conductors to ground. Moisture is a frequent culprit in VFD earth fault causes – when a motor sits idle in a humid environment, condensation can form on the windings or in junction boxes. This lowers the insulation resistance and can cause intermittent ground fault trips, especially at startup or when the motor heats up (driving out moisture). Technicians often report that simply drying out a motor (e.g. with space heaters or oven baking) and cleaning out contamination can raise insulation resistance from a few megohms (or less) to hundreds of megohms, resolving ground fault trips.

Improper Wiring or Installation: Using the wrong type of cable, poor terminations, or routing motor leads near grounded metal can increase leakage currents. Long cable runs between VFD and motor have high capacitance to ground, which means even a perfectly healthy insulation system will source some high-frequency leakage current. If the leakage is high enough, the VFD may interpret it as a ground fault. Lenze's documentation explicitly notes that excessive capacitive charging current in long motor cables can cause ground fault trips, and recommends using shorter cables, low-capacitance cable types, or installing output reactors/filters to mitigate this. Poor grounding practices or cables run in wet conduits can also contribute to nuisance trips.

**External Surges or Events:** Lightning strikes or transient overvoltages on the motor feeder can punch through insulation. Likewise, if a motor experiences a surge (for instance, from switching a power factor correction capacitor on the line) it might momentarily overcome insulation, causing a ground fault. These events are less common but can be severe. If multiple VFDs in a facility start tripping ground fault

around the same time, an external event like a lightning surge or a voltage transient on the supply should be considered. In one case, a facility with several ABB drives found that an upstream capacitor switching transient led to input current spikes that fooled the drives' ground fault detection.

Internal Drive Hardware Faults: Sometimes the VFD might indicate a ground fault when the actual issue is internal. A failed output transistor (IGBT) or a malfunctioning current sensor in the drive can simulate a ground fault condition. For instance, if an IGBT shorts internally, it can create an imbalance in currents or directly connect an output phase to ground. Some drives will flag this as a different fault (like a short-circuit or transistor fault), but others might show it as a ground fault depending on which protection triggers first. As an example, users of Allen-Bradley PowerFlex drives have noted that a persistent ground fault trip, even after eliminating motor/cable issues, pointed to a failed IGBT in the drive. The drive's diagnostics logged a ground fault simplin practice, the symptoms of a VFD ground fault trip can vary. Some drives trip immediately upon energizing or starting the motor (especially if the fault is solid, like a bolted ground in the motor), while others may run for some time and only trip under certain conditions (e.g. when moisture condenses or when drive output exceeds a threshold). An intermittent ground fault that occurs after some runtime might indicate a heating-related insulation issue – for example, a motor that runs for 30-60 minutes before tripping could have a winding defect that shows up only when hot, or a cable that vibrates into contact with a grounded surface at certain load conditions. Careful observation of when the trip occurs (immediately at start vs. during operation vs. at stop) provides clues to the cause.

# **Causes of VFD Short-Circuit Trips**

A short-circuit trip on a VFD usually indicates a high magnitude, instantaneous current spike on the output – essentially a phase-to-phase short or a direct phase-to-ground short that is not limited by impedance. Causes include:y because that was the first condition it detected when the transistor failed. Always consider the drive itself if ground fault trips continue with known-good motors and wiring.

Motor or Cable Short-Circuits: A catastrophic failure in the motor such as winding-towinding short, or a cable insulation failure that shorts two phases together, will cause a huge current surge as soon as the drive tries to energize the motor. Drives monitor output current and will trigger a "short-circuit" fault almost immediately in such cases to protect the IGBTs. For example, ABB drive fault codes like "2340 – Short Circuit" explicitly point to a short in the motor or motor cables as the cause, and advise checking the motor and cabling for phase-to-phase faults. Similarly, Eaton's drive manuals list "Output Phase Fault" or short-circuit faults when two output phases are inadvertently connected or the motor windings are internally shorted.

Incorrect Wiring or Phasing Errors: If during installation or maintenance a mistake is made such that two output terminals of the VFD are connected together (e.g., wiring the motor leads incorrectly so that phases short), the drive will likely trip the instant it tries to output voltage. This is effectively a direct short on the inverter output. Always verify motor lead connections and check for any phase-to-phase contact. Even a strand of wire bridging between terminals in the VFD or motor junction box can create a partial short.

Failed IGBTs or Power Devices: An output transistor that has failed in a shorted state will present a phase-to-phase or phase-to-DC-bus short inside the drive. When the next run command is given, the fault is detected and the drive will usually register a short-circuit or sometimes a generic over-current fault. Many modern drives include hardware desaturation detection on the IGBTs –effectively a circuit that monitors the transistor's V\_ce (voltage) to detect if it's in a saturated (overcurrent) condition – to shut down in microseconds if a short is present. This protects the drive from blowing out completely. As a result, a power component failure tends to trip the drive instantly. If you have ruled out the motor and cables, a persistent short-circuit fault can indicate that the drive's output stage is damaged (shorted transistor or other component).

Locked Rotor or Mechanical Jams: Although not a literal electrical short, a motor that is seized (or a process that is jammed) can cause the drive to hit its current limit very abruptly, sometimes registering as a short-circuit or overcurrent fault. Some drives differentiate "overcurrent" (moderate overcurrent for several milliseconds) from "short-circuit" (extremely high current in a few microseconds). For instance, Yaskawa drives separate OC (Overcurrent) from SC (Short Circuit) faults – overcurrent might occur at ~200% load, whereas a dead short produces a much faster, higher surge. A locked rotor draws a large current that might trip overcurrent protection rather than immediate short-

circuit, but if the drive is set very sensitive or the motor instantly stalls, it could flag a short. In any case, if a drive trips on short-circuit right when starting a motor, ensure the motor can spin freely and isn't mechanically bound.

Capacitive or Resonant Surges During Stopping: One lesser-known cause of output short-circuit or ground fault trips can be certain braking or filtering scenarios. For example, using DC injection braking or special braking techniques improperly can momentarily fool the drive's protection. In a documented case with a Lenze drive, enabling a flux braking function at the same time as a dynamic braking resistor caused some of the braking current to bypass the current sensors (flowing into the resistor) and resulted in the drive tripping on output ground fault during stop. In effect, the drive "saw" missing return current and interpreted it as a ground fault or short. While this is technically a configuration issue rather than a true short, it highlights that certain parameter settings (like braking modes, multi-motor operation, or output filter networks) can cause false short-circuit or ground fault detections. Always follow the manufacturer's instructions for enabling brake units or special functions — e.g. do not simultaneously use DC injection and external dynamic braking unless the manual allows it, as it may trigger protective trips.

In summary, a VFD short-circuit trip usually points to a severe condition: either the motor/cable system has a true short, or the drive's output stage is compromised. The immediate action on seeing a short-circuit fault is to disconnect the motor leads from the drive and test the motor and cables with a megohmmeter (and an ohmmeter) for shorts. If no issues are found and the fault persists when reconnecting or trying another motor, suspect internal drive damage.

#### **How Modern VFDs Detect Ground Faults and Short Circuits**

Modern VFDs incorporate electronic protection circuits to sense ground faults and short-circuits very rapidly. While specifics vary by manufacturer, the fundamental principles are similar:

**Residual Current Monitoring (Sum-of-Phases):** Most drives detect ground faults by measuring the imbalance among the three phase output currents. Essentially, the drive's output current sensors (CTs or Hall effect sensors on each phase) feed into a logic that

sums the three phase currents. In a normal healthy system, the vector sum of currents in three phases should be zero (what goes out on phase A + B + C returns through the neutral/ground path in a balanced way). If there is a leakage to ground, the sum will not be zero – some current is "missing" and must be going to ground. The drive's firmware triggers a ground fault trip if that residual (imbalanced) current exceeds a threshold. This method is analogous to how a Residual Current Device (RCD or GFCI) works, though drives are typically set to trip at a much higher level than household GFCIs. Yaskawa's drives, for example, specify that the internal ground fault circuit activates when ground current exceeds approximately 50% of the drive's rated output current. That is a high threshold aimed at protecting equipment, not personnel – it will catch a major insulation failure (e.g. a winding short to ground) but not trip on a few milliamps of leakage. Yaskawa also allows this protection to be disabled via a parameter if needed (for instance, when using multiple motors or an ungrounded system), although disabling is generally not recommended except in controlled scenarios.

Direct DC Bus Ground Monitoring: Some VFD designs use an alternate method to detect ground faults, particularly in certain ABB drives. Instead of summing AC phase currents, they monitor currents in the DC bus or measure any current flowing from the DC bus to ground. ABB's ACS880 drives, for instance, compare the current leaving the DC link to the inverter section versus the current returning, effectively detecting if some current is leaking to ground before returning to the DC bus. ABB representatives have noted that on those models, an imbalance caused by, say, a severe input voltage unbalance or certain ground conditions could trigger a ground fault trip even if the traditional residual method might not have tripped. The key point is that the drive uses internal sensors to watch for any unexpected current path to ground and will shut down in microseconds once detected. In ungrounded or high-resistance grounded systems, drives may offer special settings or modules to adjust ground fault sensitivity (since the fault currents in those systems are limited). For example, ABB provides an optional ground fault monitoring kit for operation on ungrounded (IT) systems, with adjustable sensitivity to avoid nuisance alarms.

**Threshold and Filtering:** Manufacturers set specific thresholds and time delays to differentiate a real fault from noise. As mentioned, Yaskawa uses ~50% of rated current. Rockwell Allen-Bradley PowerFlex drives have ground fault trip levels around 25–50% of

drive rating depending on model, and they often trip within a few milliseconds of detecting that level. Schneider Electric Altivar drives similarly monitor the summed currents and will declare a fault (often labeled "GF" or "earth fault") when the residual current exceeds a set percentage of drive rating for a very short duration. The drives' control program usually includes a filter so that very brief spikes (from noise or switching transients) don't cause trips – the condition typically needs to persist for a few milliseconds (e.g. 1–2 ms) continuously before tripping. This prevents nuisance trips from, say, capacitive inrush when first energizing long motor cables. ABB's ACS880 hardware manual notes a "fault detection time" of about 200 ms for certain faults, but ground fault tends to be sensed much faster – practically in the order of the PWM cycle or two, since it's an important protection.

Short-Circuit (Overcurrent) Detection: Drives protect against output short-circuits using two main strategies. First, the drive's control software monitors output current magnitude on each phase. If the current exceeds a programmed threshold (often 200%) or more of rated current) almost instantaneously, the drive assumes a short and trips. This is essentially a fast overcurrent fault. Second, at the hardware level, IGBT-based drives use desaturation detection on each transistor. When an IGBT is conducting normally, the voltage across it (V<sub>CE</sub>) stays low; if a short occurs, the current skyrockets and the IGBT starts to come out of saturation, causing V<sub>CE</sub> to rise. The driver circuitry senses this rise (desaturation) and quickly turns off the IGBT to prevent damage. This can happen in microseconds – far faster than the software loop. So in a dead short scenario, the hardware may actually shut the output down before the CPU even registers the fault. The drive will still display a "Short Circuit" or "Fuse Blown" fault afterward. For instance, Schneider's ATV series drives have a fault code for "IGBT desaturation" which is triggered by either a true output short or a failing transistor, and they explicitly advise to "Check the motor insulation and wiring with a 1000V Megger" when that fault occurs.

**Ground Fault on Start (Pre-Start Check):** Some drives perform a health check for ground faults before or during ramp-up. Hitachi inverters (SJ series) illustrate this: the Hitachi SJ-P1 drive will display fault code E014 (Ground Fault Error) if a ground fault is detected when the drive is first powered on, before the motor even starts 1. Essentially, the inverter pulses a small voltage and checks for excessive leakage. This function is

meant to protect the inverter – if you attempt to power up into a grounded motor, the drive catches it immediately. (Hitachi notes this protection might not catch a fault if the motor is spinning and acting as a generator – so it's mainly a startup check.) Many other drives similarly will fault out if a severe ground fault is present at start; for example, powering up a WEG or Fuji drive with a grounded motor will usually result in an instantaneous GF alarm.

Nuisance Tripping Considerations: Because VFDs use high-frequency PWM, they inherently produce common-mode currents (leakage to ground through cable capacitance and motor parasitic capacitance). Manufacturers are aware that false ground fault trips can occur if the drive is too sensitive or the system has unusually high leakage (very long cables, multiple motors, etc.). To address this, some drives allow adjusting the ground fault sensitivity or blanking time. For example, ABB drives often have a parameter to set ground fault protection to "Normal" or "Reduced Sensitivity" if you are experiencing nuisance trips in a high-leakage system. Eaton's application notes also mention that noise on the grounding system can trigger false ground fault alarms, and they recommend checking grounding integrity and cable shielding if intermittent faults occur. In extreme cases, an RCD device upstream of the drive (like a GFI-protected circuit breaker) may trip due to the VFD's normal leakage – standard AC drives are not designed to meet personnel-protection leakage levels (mA range) and often require special "RCD filters" or RCDs rated for high-frequency currents to avoid nuisance tripping.

In summary, VFDs detect ground faults by monitoring current imbalance and detect short-circuits by sensing rapid overcurrent conditions. These protective features act in fractions of a second to prevent damage to the drive and motor. It's important to consult the drive's manual for specific fault code definitions – each manufacturer documents what triggers a given fault and often provides guidance for troubleshooting it. For instance, the ABB ACS880 Technical Manual explains that a ground fault (code 2330) triggers when the imbalance in the three-phase currents exceeds a preset value, and advises inspecting the motor and cable insulation immediately. The manual even notes a parameter (31.20) that can disable ground fault trips in special cases – though only after confirming the hardware is sound. Likewise, Eaton's drive fault guide suggests that upon a ground fault alarm, one should disconnect the motor and test if the fault persists; if the

drive still reports a ground fault with no motor, the cause could be a "current measurement error" (i.e. a bad CT or internal issue). This kind of information, available in manufacturer documentation, is invaluable for diagnosing the difference between a real ground fault and an internal drive fault.

# Insulation Resistance Standards (IEEE 43 & NETA ATS) and Testing Practices

When facing ground fault trips, measuring the insulation resistance (IR) of the motor and cables is a critical diagnostic step. Industry standards provide guidelines on what IR values are considered acceptable or suspect:

**IEEE Std 43** (IEEE Recommended Practice for Testing Insulation Resistance of Rotating Machinery) is the key standard for motor IR testing. IEEE 43 (2013 edition) specifies that for most modern random-wound motors (rated below 1 kV), the minimum IR (corrected to 40°C) should be 5 MΩ, and for form-wound coils (typically medium-voltage machines >1 kV), the minimum IR should be 100 MΩ 2 . These are baseline values for a safe megohm reading. Older guidance (from IEEE 43-1974) allowed a rule-of-thumb of "1 MΩ + 1 MΩ per kV" for older machines, but for any motor built after about 1970, the 5 MΩ and 100 MΩ criteria apply. In practice, a healthy new low-voltage motor often has IR in the hundreds of megohms or even gigaohm range, and a used but serviceable motor might read tens of megohms. If a motor's insulation resistance is below 1 MΩ, it is generally unsafe to run – most manufacturers would consider that ground-fault territory. Values in the 1–5 MΩ range (for LV motors) are marginal and warrant drying/cleaning or further analysis (perhaps a polarization index test) before re-energizing.

**NETA ATS (Acceptance Testing Specification)** provides recommended IR test voltages and minimum values for field testing of equipment. NETA's guidelines align with IEEE 43 for motors: roughly 5 M $\Omega$  for motors <1 kV and 100 M $\Omega$  for >1 kV as minimum acceptance values. NETA also suggests test DC voltages (typically 500 V DC for 480 V motors, 1000 V DC for 4160 V motors, etc.) and requires IR tests for new or rebuilt equipment. If a motor or cable does not meet the minimum megohm criteria at the time of installation, it should be corrected (dried, cleaned, reinsulated or repaired) before being placed in service. Additionally, NETA standards discuss Polarization Index (PI) — the ratio of 10-minute to 1-minute IR readings — where a PI >2.0 is often considered

indicative of good insulation condition for larger motors. A low PI (below 2) with an overall low IR suggests contamination or moisture that needs to be addressed.

Real-World Megger Testing: In troubleshooting a ground fault trip, performing an insulation resistance test (megger test) on the motor and cables is usually the first step. Best practice: Always disconnect the drive completely before meggering the motor or cable. High-voltage DC from an insulation tester can damage VFD electronic components or give misleading readings through the drive's input filters. As one forum expert succinctly put it, "Disconnect the drive and megger the motor circuit. If the motor checks out, then the problem may be in the drive itself". When testing, megger each phase lead to ground (motor frame) individually, and also phase-to-phase if a shortcircuit is suspected. For a 480 V motor, use at least a 500 V DC megohmmeter; many technicians prefer 1000 V DC for a more stressing test (as another expert noted, VFDs can put higher peak voltages into the motor windings than line frequency – e.g. a 480 V VFD can have PWM spikes over 600 V – so using a 1000 V DC test on a 480 V motor is reasonable). Good insulation will show a steady increasing resistance as the winding charges; suspect insulation will show a very low resistance immediately or rapidly drop towards zero. If the motor IR is below threshold, it needs drying or repair before running on the VFD.

**Cable Insulation:** Don't forget to megger test the motor cables themselves. A common scenario is that a motor passes an IR test, but the drive still trips on ground fault – the issue can be in the cable from drive to motor (especially if it runs through wet conduit or has jacket damage). To test cables, disconnect them from both the drive and motor, then megger each conductor to ground and to each other. New 600 V-rated cable typically should show 100+  $M\Omega$  easily in a short run. NETA ATS gives guidance for cable IR as well – for example, a new 600 V cable may have an expected IR of 100  $M\Omega$  or more (corrected to 20°C) per 1000 feet, while lower values could indicate moisture or damage. If cable IR is low, try isolating sections (if possible) or replace the cable.

**After-Fault Repairs:** If you find a motor with very low IR (say a few hundred kilohms or less), it's likely the cause of the ground fault trip. Drying the motor in a controlled oven or with space heaters can significantly improve insulation resistance if moisture is the only issue. It's not uncommon to see a wet motor go from <1 M $\Omega$  to >100 M $\Omega$  after a 24-hour

dry-out. If the IR remains low, the motor may have a serious insulation breakdown and might need re-winding or varnish treatment. Document the values before and after: for example, Motor #3 meggered at  $0.2~\text{M}\Omega$  to ground before repair; after 48 hours of bake and re-varnish, IR = 250 M $\Omega$  at 40°C – ground fault trips cleared. This not only confirms the fix but provides baseline data for future maintenance.

Standards for Trending: IEEE 43 encourages trending insulation resistance over time. A gradual downward trend in IR (after temperature correction) can warn of developing problems before a ground fault trip actually occurs. Many maintenance programs, such as per NETA Maintenance Testing Specification (MTS), recommend annual IR tests on critical motors and comparison against prior results. If a motor that used to read 200 M $\Omega$  now reads 20 M $\Omega$ , it's a red flag to inspect for contamination or moisture – even if 20 M $\Omega$  is above the "minimum", the drop indicates deterioration. It's much better to intervene early than to have an unplanned VFD trip and downtime.

In essence, adhering to standards like IEEE 43 and NETA ATS ensures you have quantitative benchmarks for insulation health. When ground fault trips occur, these benchmarks help assess if the motor/cable is the culprit. Always record the conditions of the test (temperature, duration, test voltage) and correct readings to 40°C for proper comparison to standards. If unsure of interpretation, consult a motor testing professional or reference material – for example, EASA (Electrical Apparatus Service Association) publishes guides on insulation testing that explain how to interpret results and perform polarization index tests.

### **Real-World Examples and Diagnostic Insights**

Let's examine a few real-world scenarios that illustrate the process of diagnosing and resolving VFD ground fault and short-circuit trips:

Example 1: Moisture-Induced Ground Fault in an HVAC Fan Motor – A 30 HP fan VFD (480 V) was tripping on ground fault every Monday morning when started, but ran fine later in the day. Maintenance suspected condensation build-up over the weekend. IR testing Monday morning showed only ~1 M $\Omega$  to ground on the motor. They ran space heaters on the motor for a few hours and meggered again in the afternoon – IR had risen to 50 M $\Omega$ . The drive then started the motor without tripping. The root cause was

condensation in the motor windings; the solution was to install a motor space heater to keep the motor warm during downtime and add routine IR tests. This eliminated the nuisance trips. It underlines that marginal insulation (a few megohms) can trip modern drives, and that environmental control is important for motors in damp conditions.

Example 2: Cable Fault vs. Drive Fault Isolation – A plant had a VFD that would trip on "GF fault" even with the motor disconnected, as soon as a run command was given. Using diagnostic tips from the manufacturer, they performed these steps: (1) Meggered the motor – it was >200 M $\Omega$  (very good). (2) Disconnected the motor leads at the drive and taped them off, then started the drive in test mode – it still gave a ground fault trip immediately. This indicated the problem was not in the motor or cable (since the cable wasn't energizing anything). (3) Upon inspection of the VFD's output terminals, they found evidence of flash and a partially shorted output transistor in phase T2. The drive's internal protection was picking up this internal ground leakage. Replacing the drive solved the issue. The key insight: if a drive trips with no motor connected, the fault is internal. Eaton's troubleshooting flowchart emphasizes this by suggesting to try a known-good motor or run with no motor to see if the ground fault indication clears. In this case, it did not clear, hence the drive was at fault.

Example 3: Long Cable, Multiple Motors – Nuisance Trips – An irrigation pump system had a single VFD driving two motors in parallel (via a splitter cable). The cable runs were long (~150 meters to each motor). The VFD would occasionally trip on ground fault, especially at certain speeds. Investigation revealed the long, paralleled cable run had high capacitance and was causing circulating common-mode currents. The drive's sum-of-current algorithm saw imbalance and occasionally tripped. The fix was two-fold: they installed an output reactor (choke) at the VFD output, and also slightly increased the ground fault trip delay via a parameter recommended by the drive manufacturer. The output reactor limits high-frequency current and effectively isolated the leakage beyond the reactor (as noted by an engineer, "What happens below the reactor becomes irrelevant as far as the VFD is concerned"). After these changes, no further nuisance trips occurred. Lesson learned: with long cable runs or multiple motor leads, adding reactors or filters and consulting drive settings can cure false trips.

Example 4: DC Braking Causing Ground Fault Trip – A woodworking machine using

a Lenze SMVector VFD was configured with an external braking resistor for quick stops. The technician also enabled DC injection braking at stop, not realizing this was doubleconfiguring the braking. The drive would consistently trip "Ground Fault" the moment the stop button was pressed (during braking). The Lenze manual's fault code description indicated either a true ground fault or "excessive capacitive current" as possible causes. Through help from a drive expert, they discovered that the flux (DC) braking plus the dynamic brake was the culprit – some braking current was bypassing the phase sensors via the resistor, so the drive thought current was missing (i.e. leaking to ground). The solution was to disable the DC injection feature and rely solely on the dynamic brake resistor (i.e. set the drive to ramp-to-stop with the brake chopper, instead of DC braking). This immediately resolved the ground fault trips. The drive was not actually seeing a ground fault; it was a byproduct of how the current flowed during that improper setup. This case underscores the importance of following the manual for brake configuration and understanding that drive ground fault circuits can Each of these examples reinforces a diagnostic approach: measure insulation, isolate sections, swap components if needed, and consult the drive's documentation/forums for known issues or parameter tweaks. Technicians often share their experiences on forums, and manufacturers publish application notes – for instance, KEB America published a whitepaper on ground fault nuisance tripping in VFD applications which discusses how high-frequency leakage and RCD (residual current device) compatibility issues can be mitigated. In complex or repeated nuisance cases, those kinds of resources can provide new angles to solve the problem (such as upgrading to RCDs designed for drives, using shielded cables grounded at both ends, ensuring the drive's EMC filters are properly configured, etc.).

# **Best Practices for Prevention and Troubleshooting**

Finally, let's compile best practices to avoid ground fault and short-circuit trips in the first place, and efficiently troubleshoot them when they do occur:

1. Insulation Resistance Testing Routine: Regularly megger test motors and critical cables, especially before connecting to a new VFD. This is often done as part of commissioning and preventative maintenance. Follow IEEE 43 guidelines – test for 1 minute, correct to 40°C – and keep records. If a motor has borderline IR (just a few megohms), schedule a cleaning or drying. Do not connect a VFD to a motor with known low insulation resistance hoping it will "burn off moisture" – modern drives will

- likely just trip repeatedly (and it's risky for the inverter). Instead, dry or repair the motor offline first. Also, always disconnect the drive from the circuit during IR tests to avoid damage to its input/output circuits.
- 2. Proper Grounding and Cable Selection: Use VFD-rated motor cables with proper shielding and low capacitance if available. Ground the motor frame, VFD ground terminal, and cable shields per the drive manual (typically grounded at both ends for high-frequency containment). Good grounding helps carry away leakage currents safely and can reduce noise-induced trips. Avoid running VFD output cables in parallel with sensitive signal cables (to prevent noise coupling) and keep them spaced from metal enclosures when possible to reduce capacitance. If you have especially long cable runs, consider installing output reactors or dv/dt filters these not only protect the motor from voltage spikes but also slow the rise time of pulses, reducing capacitive leakage current. Manufacturers like ABB and Siemens recommend reactors/filters for cable lengths beyond certain thresholds (e.g. >50m) to prevent both motor insulation stress and possible ground fault sensor trips.
- 3. **Keep It Dry and Clean:** For motors in wet or dirty environments, take steps to prevent contamination. Use space heaters in large motors to prevent condensation when the motor is off (most medium voltage motors and many low voltage motors >50HP come with heater terminals for this reason). If a motor is out of service, have a plan to either energize heaters or run it periodically to keep moisture out. Ensure conduit boxes are properly sealed against water ingress. If a motor has been subjected to water (flooding, wash-down overspray, etc.), dry it and test insulation before re-energizing with a VFD. Contamination like carbon dust, oil, or salt can create leakage paths too regular cleaning might be needed in those environments (using non-conductive solvent or CO2 cleaning as appropriate).
- 4. Follow Manufacturer Fault Guidance: When a drive throws a fault code, always consult the manual for that code's meaning and recommended actions. For instance, an "Output Ground Fault" fault on a Lenze SMV drive will point you to check for grounded motor phases and also mentions long cable charging current as a possible cause. ABB's fault codes will explicitly say "Short-circuit in motor or motor cable check for wiring errors or for power factor capacitors on output" (since connecting PF correction capacitors on a VFD output can look like a short). The manuals often contain nuggets of advice that can save time, such as instructing how to distinguish between a motor fault and a drive fault (e.g., "disconnect motor and restart drive if

- fault still occurs, internal issue likely"). Many manufacturers also have technical support lines and knowledge bases; don't hesitate to use those resources if a fault is perplexing or persistent.
- 5. System Design to Minimize Ground Fault Risks: When designing or modifying a system, consider features that can reduce fault occurrence. In high-resistance grounded networks, use the drive's grounding recommendations (some drives may need an isolated ground fault detector because the drive's own might not function properly with HRG ABB offers an optional module for ungrounded systems). If using multiple motors on one drive, recognize that the drive's built-in protection might not reliably detect an imbalance if the motors are far apart external protection or disabling the drive GF trip in favor of an external ground relay might be necessary in those cases (with the guidance of the drive manufacturer). Always ensure any output contactors or motor switching devices are interlocked such that the drive is disabled before opening/closing motor circuits breaking a current path under load can cause transients that may look like ground faults or damage the drive.
- 6. Careful Parameter Tweaks: Many drives allow certain parameters to be changed that affect protection. For instance, some Yaskawa drives have a parameter L8-09 to enable/disable ground fault trip, intended for special cases like systems with output contactors or very high leakage situations. ABB drives have a sensitivity setting (normal/reduced). Schneider drives have a setting for "Ground fault detection" that can be turned off if you have an upstream GF protection device handling it. These should remain ON under normal circumstances for safety of the drive. Only adjust them if you understand the implications and have other means to detect faults. One scenario where you might reduce sensitivity: a system that must run on an ungrounded supply might otherwise nuisance trip on the first ground fault – some drives let you turn off ground fault trip to allow continued operation with one ground present (since on ungrounded systems a single ground fault doesn't cause immediate hazards). If you do this, implement external ground fault relays and alarms so that maintenance knows a fault is present and can fix it before a second fault occurs (which would be catastrophic). Always document any protection settings you change and inform operators/maintenance.
- 7. **Thoroughly Investigate Before Resetting Repeatedly:** A drive trip is a message if a VFD ground fault trip happens, investigate it rather than simply resetting the drive over and over. Repeated high leakage or slight ground faults can stress the drive's

power devices. Worse, if it's a true insulation breakdown, every restart could be causing arcing in the motor, further degrading it (and potentially damaging the drive). Never bypass or disable trips blindly. Only override a protection (like disabling ground fault alarm via parameter) after you have verified the hardware is sound, and even then, consider it temporary. In one ABB ACS880 case, the user disabled the ground fault alarm (Parameter 31.20 = 0) to keep a process running, but they did so only after megger testing the motor and cables to be absolutely sure nothing was actually wrong. This was a stopgap measure while waiting for a replacement drive, because the drive's circuit had a known false-trigger issue. They closely monitored the system during this period. This kind of action should be the last resort and under engineering supervision, as it carries risk.

8. Use Diagnostic Tools: If a ground fault or overcurrent trip is mysterious, tools like clamp-on ammeters, insulation analyzers, or power quality analyzers can provide insights. A clamp meter that can measure leakage current to ground (measuring current on the ground conductor or using a loop around all phase conductors plus neutral) can reveal if there is significant ground leakage during operation. Some advanced drives or external modules can monitor cumulative leakage current. Power analyzers can catch transient events – in the earlier example where multiple drives tripped, a power analyzer captured a voltage sag/transient that coincided with the trips. That pointed the investigation toward an upstream source (in that case, capacitor switching on the supply). Thermal cameras might spot a cable heating at a chafed spot where insulation is failing. Modern motor testers can perform surge tests to detect turn-to-turn shorts that a simple megger won't find – a turn-to-turn short might not trip a ground fault but could blow the drive with overcurrent. So if repeated faults occur and basic tests don't find it, escalate to advanced testing methods.

By following these best practices, you can significantly reduce the incidence of VFD ground fault and short-circuit trips in your facility. A combination of adhering to standards (like IEEE/NETA for insulation values), using proper installation techniques, and leveraging the drive's built-in diagnostics and manufacturer resources will lead to quicker troubleshooting and more reliable operation.

#### References

- ABB ACS880 Technical Manual ABB Oy, detailed fault descriptions and parameters for ground fault protection. PDF Link
- Eaton "10 Most Common Fault Codes and How to Solve" Eaton Corporation, application note including ground fault troubleshooting logic. PDF Link
   Yaskawa E7 Drive User Manual – Yaskawa Electric, includes ground fault protection explanation (50%current threshold) and parameter L8-09 for enabling/disabling GF detection. PDF Link
- Hitachi SJ-P1 Inverter Basic Guide Hitachi Industrial, lists fault code E014 for ground fault at power-on and troubleshooting steps. PDF Link Lenze/AC Tech SMVector Drive Manual – Lenze Americas, fault code descriptions for Output Ground Fault and recommendations regarding motor cable length and reactors. PDF Link
- IEEE Std 43-2013 IEEE Recommended Practice for Testing Insulation Resistance of Electric Machinery (sets 5 M $\Omega$ /100 M $\Omega$  minimum IR guidelines). IEEE Standards Abstract
  - NETA ATS-2017 Table 100.1 NETA Acceptance Testing specifications for insulation resistance minimum values for motors and cables, aligning with IEEE 43 criteria (5 M $\Omega$  for <1 kV motors, 100 M $\Omega$  for >1 kV). (Available via NETA publications)
- KEB America Ground Fault Nuisance Tripping Article discusses high-frequency leakage currents, RCD compatibility with VFDs, and mitigation techniques. Online Article
- Technical Forums (Mike Holt, PLCS.net, etc.) numerous discussion threads where
  professionals share ground fault trip cases and solutions (e.g. verifying motor vs drive
  fault, effects of ungrounded systems on VFD GF protection, etc.). These can be
  searched by key phrases like "VFD ground fault trip forum" for further reading.

By combining the knowledge from manufacturer manuals, industry standards, and real-world experience, one can confidently approach VFD ground fault and short-circuit trips with a methodical strategy – ensuring safety and minimizing downtime in industrial and commercial applications.

2 Insulation resistance testing: How low can megohms go? – Resource Library – EASA | The Electro•Mechanical Authority

https://easa.com/resources/resource-library/insulation-resistance-testing-how-low-can-

### www.precision-elec.com

# **Documents / Resources**



<u>Precision Electric 574-256-1000</u> Variable Frequency Drives [pdf] Owner's Manual

<u>574-256-1000</u> Variable Frequency Drives, <u>574-256-1000</u>, Variable Frequency Drives, Frequency Drives, Drives

#### References

- User Manual
- Precision

Electric

Email

▶ 574-256-1000, 574-256-1000 Variable Frequency Drives, Precision Electric, Variable Frequency Drives

Drives

# Leave a comment

Your email address will not be published. Required fields are marked*
Comment *
Name

Website	
☐ Save my name, email, and website in this browser for the next time I comment.	
Post Comment	

#### Search:

e.g. whirlpool wrf535swhz Search

Manuals+ | Upload | Deep Search | Privacy Policy | @manuals.plus | YouTube

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.