



rotronic CP11 Handheld Instrument for CO2 Humidity and Temperature Instruction Manual

[Home](#) » [ROTRONIC](#) » rotronic CP11 Handheld Instrument for CO2 Humidity and Temperature Instruction Manual 

rotronic CP11 Handheld Instrument for CO2 Humidity and Temperature Instruction Manual



Contents

- 1 GENERAL DESCRIPTION
- 2 PROGRAMMING
- 3 POWER SUPPLY
- 4 CONNECTION TO PC OR LAPTOP
- 5 FUNCTION KEYS
- 6 DISPLAY
- 7 USE
 - 7.1 DATE/TIME SETTINGS
 - 7.2 SETTING OF THE UNITS
 - 7.3 TAKING MEASUREMENTS
 - 7.4 HUMIDITY
 - 7.5 TEMPERATURE, DEW POINT, WET BULB TEMPERATURE
 - 7.6 CO₂ (CARBON DIOXIDE)
- 8 DATA HOLD
 - 8.1 BACKLIGHT
 - 8.2 MIN, MAX, AVG, CURRENT VALUES
 - 8.3 ALARM
 - 8.4 AUTO POWER OFF
 - 8.5 MANUAL RECORDING
 - 8.6 99 SETPOINT MEMORY
 - 8.7 DATA LOGGING
- 9 INSTRUMENT SETTINGS
- 10 BATTERY INDICATOR
- 11 HUMIDITY CALIBRATION
- 12 CO₂ CALIBRATION
- 13 TROUBLESHOOTING
- 14 TECHNICAL DATA
- 15 OPTIONAL ACCESSORIES
- 16 DELIVERY PACKAGE
- 17 Documents / Resources
 - 17.1 References
- 18 Related Posts

GENERAL DESCRIPTION

The CP11 is a precise, portable instrument that can display and save relative humidity, temperature and CO₂ content and calculate parameters such as dew point or wet bulb temperature.

PROGRAMMING

Most settings, such as clearing the memory, CO₂ alarm, the units (OC /OF), sampling rate and real time clock can be changed with the function keys.




POWER SUPPLY

The CP11 is battery powered and requires 4 AA alkaline batteries or a 5 VDC adapter (optional accessory). To insert or change the batteries, use the enclosed screwdriver. Unscrew the two screws and insert the batteries correctly. Ensure contact with the battery poles.


CONNECTION TO PC OR LAPTOP

Connect the CP11 to a PC or laptop using a mini USB cable. The stored data can then be downloaded easily with the HW4 software. The software can be downloaded free of charge from www.rotronic.com.

FUNCTION KEYS

















DISPLAY

- **Top LCD line:** Humidity/Temperature/CO₂ measurement
- **Bottom LCD line:** Real time clock
- **CO₂:** Carbon dioxide measurement
- **HOLD:** The measurements are halted unchanged
- **MIN/MAX:** Minimum and maximum measurements
- **AVG:** Average measurements
-  : Low battery
- **DP:** Dew point temperature
- **TEMP:** Ball temperature
- **WBT:** Wet bulb temperature
- **%RH:** Unit of relative humidity
- **°C/°F:** Celsius/Fahrenheit (temperature)
- **CAL:** In calibration mode
- **REC:** In manual/automatic logging state
- **RECALL:** Recall mode in manual recording









USE

DATE/TIME SETTINGS

When the instrument is on, press  for more than 2 seconds to enter setting mode. Press  or  to select the program P80 (rtc) and press  to start the program.

First select the time format by pressing  or . You can select between 12h and 24h mode and confirm this by pressing the key . Then select the date format by pressing  or . You can display the date either as month-day-year or as day-month-year. Press  to confirm your selection. Then set the year, month, day, hours, minutes and seconds. Press  or  to set the values and press  to confirm them. Press  to return to normal mode.


SETTING OF THE UNITS

When the instrument is in operation, press  for more than 2 seconds to enter setting mode. Press  or  to select the program P50 (Unit) and press  to start the program. Press  or  to select °C or °F and press  to confirm your selection. Press  to return to normal mode.


TAKING MEASUREMENTS

The instrument starts measuring when it is on and refreshes the measurements every second. If the environment changes, it takes 30 seconds before the CO₂ sensor reacts. **NOTE:** Keep the instrument away from faces as exhalation can change the CO₂ value.


HUMIDITY

Press  to view the humidity. The bottom line of the display shows the real time clock.



TEMPERATURE, DEW POINT, WEB BULB TEMPERATURE

Press  to view the temperature. The bottom line of the display shows the real time clock.

CO₂ (CARBON DIOXIDE)

Press  to view the CO₂ content. Users see the CO₂ measurement in ppm on the main display. The bottom line of the display shows the real time clock.

DATA HOLD

When you are in the normal display, press  to stop the measurements. The “HOLD” symbol flashes at the top left of the LCD screen. All measurements taken so far remain unchanged. Press  again to cancel the “HOLD” function. NOTE: The hold function is not available in Min/Max/ AVG mode.

BACKLIGHT


The backlight is activated by pressing any key for 10 seconds.


MIN, MAX, AVG, CURRENT VALUES

This instrument enables you to check the minimum, maximum, average and current values as soon as you press



. By pressing in normal mode, the MIN, MAX, AVG and current values are shown one after the other.

Press  to return to normal mode. In this mode, the corresponding measurements and time that this mode has been active are shown. This mode can be active for up to 18 hours.

You can change the parameter shown by pressing .

ALARM


The instrument sounds an audible alarm when the CO₂ limit is exceeded. (You can set the respective limit values in the instrument’s settings.) It beeps (approx. 80 dB) when the CO₂ content exceeds the set limit, and only stops again when the measurements drop below the set value. It beeps again when the value exceeds the limit again.


AUTO POWER OFF

The instrument switches itself off automatically when it has not been used for 20 minutes. To override this




function, first switch the instrument off. Then press  and  hold and for 2 seconds and switch on the instrument until an “n” appears.

MANUAL RECORDING

The instrument has a 99 data point memory. In normal mode or hold mode, press  to start recording. The **REC** symbol and main display light up three times. Up to 99 measured values can be stored for later viewing directly on the instrument’s display. The log data contains all information on the parameters, not only of the one being shown at the moment. When the 99 data point memory is full, the message “FULL” appears on the screen. If





you feel that the readings are changing too quickly, you can press  to stop the current recordings and then record the data manually. The function is not available in min/max mode.






99 SETPOINT MEMORY

Press and hold  in normal mode or in hold mode for more than 2 seconds until the **Recall** symbol appears. Press  or  to scroll through the contents. The log sequence number is shown on the main LCD display first, then the readings. The time in memory mode shows how long readings were recorded.



DATA LOGGING

The instrument can record the humidity, temperature and CO₂ content automatically and monitor the environment over the long term. The memory has a capacity of 6000 points for every parameter. Users can set the sampling rate from 1 second to 4 hours, 59 minutes and 59 seconds. The factory defaults are 30 seconds.


To set the sampling rate while the instrument is on, press and hold  for more than 2 second to enter setting mode. Press  or  to select the program P60 (rAtE) and press  to start the program.









Press  or  to select the hours, minutes and seconds of the sampling rate and press  to confirm your selection. Press  to return to normal mode. When you have set the sampling rate, press  and hold for 2 seconds in normal mode to start the logging program. The **REC** symbol appears to show the logging status. The main LCD display shows the real time value. The bottom line of the display shows the real time clock.








Repeat the above to create another log. When the log memory is full, the message “FULL” appears on the screen.




Press and hold  for 2 seconds to close the data log. The **REC** symbol goes out. Press  to enter the mode of your choice. Except for the mode selection function, auto power off, min/max, manual recording, and the hold and memory function are not available during logging.

INSTRUMENT SETTINGS

When the instrument is on, press and hold  for more than 2 seconds to enter setting mode.

Press  to return to normal mode. Press  or  to select the program and press  to start it. The programmable settings light up on the display. Press  or  to select the settings and press  to confirm your selection. If you wish to return to the main menu without saving your selection, press .

P 10, clear 99 data point memory		
P 11, select yes or no		Note: “ done ” appears when the memory has been cleared.
P20, delete auto log data		
P21, select yes or no		Note: “ done ” appears when the memory has been cleared.
P30, CO2 alarm settings		Note: <ul style="list-style-type: none"> • The factory defaults are 1400 ppm • The scale can always be adjusted by 100 ppm
P31, select between 1000 and 9900		
P40, CO2 ABC settings		Note: <ul style="list-style-type: none"> • The ABC function is factory-set







P41, ON or OFF		
P70, pressure equalization		Note: <ul style="list-style-type: none"> • The factory defaults are 1013 hpa • The scale can always be adjusted by 1 hpa
P71, select between 700 and 1990 hpa		

BATTERY INDICATOR

The battery indicator lights up when the battery level is low. Please replace the batteries to ensure accurate measurement. For long-term measurements and data records, use of an adapter is recommended (optional accessory: AC1214).

HUMIDITY CALIBRATION






The instrument can be calibrated either with a 35 % or 80 % salt solution or a humidity generator. It is recommended that the ambient conditions are at 25 °C. Place the measurement probe in a 35 % salt solution


while the instrument is off. Press and hold , ,  simultaneously for 3 seconds to enter calibration mode. Press  or  to select the 35.0 % calibration and press  to stop it. "CAL" and the calibration value light up on the LCD screen.

WARNING: Do not calibrate the humidity without the standard calibration salt because otherwise serious damage could result. For the calibration salt or other services, contact your dealer.

CO₂ CALIBRATION

The sensor has an automatic calibration function to ensure long-term accuracy. If you nevertheless wish to

calibrate the sensor, press and hold , ,  simultaneously for 3 seconds in off-state to enter calibration mode. Press  or  to select 400 ppm calibration (outdoor air calibration).

Press  to enter the mode. "CAL" and the CO₂ value light up on the LCD screen. Wait for about 10 minutes until the display stops flashing and calibration is finished.

TROUBLESHOOTING

Error	Message	Solution
E01	The CO2 sensor is not working	Switch the instrument off and back on again
E33	The CO2 sensor is not working	Repeat the CO2 calibration
E02	The measured value is too low	Place the device in a normal environment
E03	The measured value is too high	Place the device in a normal environment
E04	The dew point and wet bulb temperature cannot be determined because the necessary values for calculation were not measured correctly. (DP, WB)	Correct the error
E11	RH calibration error	Repeat the humidity calibration
E31	Temperature sensor or AD damaged	Send the instrument in for repair
E32	Memory IC damaged	Send the instrument in for repair
E33	RH sensor or circuit damaged	Send the instrument in for repair

TECHNICAL DATA

Humidity / Accuracy	@23 °C (±0.5 K) ±2 %rh (10...90 %rh), others ±5 %rh
Temperature / Accuracy	@23 °C (±0.5 K) ±0.3 K
CO₂ accuracy	0...9999 ppm/±-(30 ppm+5 % of the measurements) @0~5000 ppm
Storage and transmission	-20...60 °C/10...90 %RH, non-condensing
Operating limit of the electronics	0...50 °C for CO ₂ , -20...60 °C for the other parameters, non-condensing
Memory	99 manual readings, 18000 readings in auto logging
Size, mm	234 (L) x 77 (W) x 42 (H)
Weight	200 g
Battery	4 AA alkaline batteries
Power supply	5 VDC, 250 mA (available as optional extra AC1214)
PC connection	Mini USB port

OPTIONAL ACCESSORIES


Order code	
AC1214	5 VDC universal adapter

DELIVERY PACKAGE

- CP11
- Mini USB cable
- Screwdriver

Website: www.rotronic.com

Documents / Resources



[Rotronic CP11 Handheld Instrument for CO2 Humidity and Temperature](#) [pdf] Instruction Manual
CP11, Handheld Instrument for CO2 Humidity and Temperature, Instrument for CO2 Humidity and Temperature, CO2 Humidity and Temperature Instrument

References

- [ro Measurement Solutions - Humidity, Temperature, CO2 and Differential Pressure Measurement \(EN_US\)](#)

[Manuals+](#).