




## YITAHOME MAYIHdRKQB Variable Speed Mini Lathe Instruction Manual

[Home](#) » [YITAHOME](#) » YITAHOME MAYIHdRKQB Variable Speed Mini Lathe Instruction Manual 



Instruction Manual  
VARIABLE SPEED MINI LATHE



Before Using Be Sure To Read This Manual  
This Mow Sift Only From 12€35C/38F+9F

## Contents

- 1 Safety Rules For Lathe
- 2 Product Features
- 3 Grounding And Insulation
- 4 Adjustment And Preparation
- 5 Operation & Replacement
- 6 Documents / Resources
  - 6.1 References

## Safety Rules For Lathe

1. Before you turn on the motor, be Sure that you have put in suitable lubrication ac cording to manual s instruction. Also check carefully to see all the tool work pieces etc are in proper positions
2. Always use your hand to (is mount the Chuck or the lathe s face plate. Do not use power tools.
3. After installation to the chuck, remove the wrenches and tools in order not to Cause any accents when the machined is turn On
4. When the bathe is on, do not use a wrench to fox or adjust the workpiece or any other rotating parts of the machines
5. When the machine is in motion, do not us an instruments to measure the machine, nor test the sharpness of the cutter with your hand
6. Do not use too large a tool cutter to do your feeding with too large a workpiece. Thus will easily cause an accident because of a broken workpiece
7. Always use the night tools and stand at the proper position when performing your wot
8. Do not change the gear when the machine is in operation
9. Always keep a proper distance from the machine in order to avoid being struck by a broken workpiece

## Product Features

1. Thus precision mirin lathe is designç to perform various types ot processing jobs Counteracted turning, riling, threading. and cutting jobs on materials made up of round bar and bar materials can b PGR formed wth this machine Thi machine can be used in areas such as rniri permission parts processing. sample processing and modeling works
2. The lathe bed is made of high grade iron The rigidity of lathe, the handiness and accuracy of the v -slier ways are obtained by raw materials, heat hardening and grinding
3. mess machine i DC motor driven
4. The spindle speed is variable from zero to 2500RP4
5. The teed speed can be adjusted according to the requirrnrnts of different work pieces

The major parts of the lathe are shown in Fig. 2 and in Fig. 3.




Fig. 2 Front View Of The Lathe




Fig. 3 Back View Of The Lathe

- |                                |                              |                                |
|--------------------------------|------------------------------|--------------------------------|
| 1. Control box (see page 4)    | handwheel                    | 21. Rear splash guard          |
| 6. Chuck                       | 13. Tailstock set screw      | 22. Feeding direction selector |
| 7. Compound rest               | 14. Compound rest crank      | 23. Power cord                 |
| 8. Tool post                   | 15. Feeding control wheel    | 24. Chip tray                  |
| 9. Fixed center                | 16. Cross feeding crank      | 25. Motor cover                |
| 10. Tailstock quill fix holder | 17. Automatic feeding handle | 26. End cover                  |
| 11. Tailstock                  | 19. Bed way                  |                                |
| 12. Tailstock quill adjust     | 20. Lead screw               |                                |

## Grounding And Insulation

1. in the event of a malfunction or break down, grounding provides a path of least resistance for electric current to reduce the risk of electric shock. This tool is equipped with an electric cord having an equipment-grounding conductor and a grounding plug. The plug must be plugged into a matching outlet that is properly installed and grounded in accordance with all local codes and ordinances.
2. Do not modify the plug provided even if it will not fit the outlet, have the proper outlet installed by a qualified electrician.
3. Improper connection of the equipment grounding conductor can result in a risk of electric shock. The conductor with insulation having an outer surface which is green with or without yellow stripe is the equipment-grounding conductor, if repair or replacement of the electric cord or plug is necessary, do not connect the equipment-grounding conductor to a live terminal.
4. Check with a qualified electrician or serviceman if the grounding instructions are not completely understood, or if in doubt as to whether the tool is properly grounded.

5. Use only 3-wire extension cords that have 3-prong grounding plugs and 3-pole receptacles that accept the tool's plug
6. Repair or replace damaged or worn cord immediately.


**Note:**

The type of electrical plug and receptacle differs from country to country

## Adjustment And Preparation

1. Clean off grease on the machine
2. Check that the 3 set screws of the chuck are tight
3. Turn the chuck by hand and check if it rotates freely
4. Move the Feeding direction selector from the back of the body to the middle.
5. First shut off the switch 1 Adjust the switch 3 by turning to G position and turn the switch 2 to STOP position. If the lathe needs to be started, turn the switch according to direction marked on switch to the normal position and turn the switch 2 to FORWARD + REVERSE position. The spindle will turn immediately by turning the switch, The speed can be adjusted by turning the switch, if the lathe needs to be stopped, turn the switch 3 to "0" position.


If the direction of the lathe spindle needs to be changed, the switch (3 must be turned to p position at first. If the lathe must be stopped under emergency situation, press the Emergency Switch immediately. If the lathe needs to be started again, do so again according to the above mentioned process (SEE Fig.4)



**Fig. 4 Control Panel:**

1. Emergency stop switch
2. Forward – reverse switch
3. Speed control knob
4. Fuse
6. Check the compound rest Crank and the cross feeding crank and see if they work properly. When they are too

ought are Tao nose = tum the adjusting screws located at both sides 'Fig 5)




**Fig. 5 Adjustment Of Saddle , Cross Slide And Compound Rest**

## **Operation & Replacement**

### **Replacement of chuck**

When replacing the chuck, place a clot. of da DCCC CI woad on the bed way at the bottom af trecmuck. This is to avoid damages to ine bed way Caused vu, cure- lecaly arcecing tn2 chuck. Loasen :1é 3 SAT Screws as S100 ING 6 LA) te -e piece the chuck,





A

Fig. 6 Replacement Of Chuck



Fig. 7 Replacement Of Jaws



A

Fig. 8 Compound Rest Adjustment


### Replacement of jaws

There are two types of jaws: Internal and external. Please note that the number of jaws (it with the number inside the chuck's groove) Do not mix them together. When you are going to mount them, please mount them in ascending order 1-2-3, when you are going to take them out, be sure to take them out in descending order (3-2-1) one by one. After you finish this procedure, rotate the jaws to the smallest diameter and check that the three jaws are well fitted. If not you need to reassemble them again as they are not properly assembled (Fig 7) When you are going to mount the work piece you need only to loosen one jaw. However we recommend you loosen the three jaws at the same time, in this way you can protect them and will not damage the thread inside. Compound rest adjustment

Loosen the two screws as shown in (A) of Fig. 8. After you have obtained the angle you desire, please do not forget to tighten them.

### Tailstock rest adjustment

When you are going to change position or replace the tailstock you need to follow the steps as shown in (A) of Fig 9



A

Fig. 9 Tailstock Rest Adjustment





Fig. 11 Tool Post Adjustment

### Replacement of carbon brushes

Replace the carbon brushes by removing the brush covers both on Motor cover as shown in Act Fig 10-A and the right bottom side of speed controller as shown in 6 of Fig. 10-B



**Fig. 10 Replacement Of Carbon Brushes**

#### **Tool post adjustment**

When you are going to adjust the tool post position you only need to loosen the lever shown in (B) of Fig. 11. After you have done this be sure to tighten it. If you are going to replace the work cutter then you need to loosen the screws of (A) with the allen wrench provided.


#### **Tailstock rest adjustment**

When you are going to change position or replace the tailstock you need to loosen the nut as shown in (A) of Fig 9



A

**Fig 9 Tailstock Rest Adjustment**



**Fig. 11 Tool Post Adjustment**



### Replacement of carbon brushes

Replace the carbon brushes by remount the brush covers both on Motor cover as shown in Act Fig 10-A and the ninth bottom side of speed controter as shown in 6 of Fig. '0-B





Fig. 10 Replacement Of Carbon Brushes

### Tool post adjustment

When you are going to adjust the tool post position you only need to loosen the lever shown in (B) of Fig. 11. After you have finished be sure to tighten. If you are going to replace the work cutter then you need to loosen the screws of (A) with the allen wrench provided.



### Documents / Resources

	<p><a href="#">YITAHOME MAYIHdRKQB Variable Speed Mini Lathe</a> [pdf] Instruction Manual MAYIHdRKQB Variable Speed Mini Lathe, MAYIHdRKQB, Variable Speed Mini Lathe, Speed Mini Lathe, Mini Lathe, Lathe</p>
---	--

### References

- [User Manual](#)

