

S5860-48SC Switch FSOS Instructions

Home » FS » S5860-48SC Switch FSOS Instructions



Contents

- **1 Version Information**
- 2 Problem Solved
- 3 Documents /

Resources

4 Related Posts

Version Information

Basic Information

Version Number	FSOS 11.0(5)B13S2
Applicable Products	S5860-48SC
Version Type	Official Version
Release Date	2021-8
Baseline Version	11.0(5)B13S1
Reason of Release	Renew and revised WEB functions

Using show version detail commands to check version number examples are as follows

FS#show version detail	
System description	: FS Campus Switch (S5860-48SC) By FS.COM Inc
System start time	: 2021-07-16 17:37:28
System uptime	: 4:16:04:14
System hardware version	: 1.00
System software version	: S5860_FSOS 11.0(5)B13S2
System patch number	: NA
System software number	: M16064307162021
System serial number	: 1234942570067
System boot version	: 1.3.8.ca18d14(180905)
System core version	: 2.6.32.c557c01d43b8ed
System CPU partition	: 3
Module information: Slot 0: S5860-48SC	
Hardware version	: 1.00
Boot version	: 1.3.8.ca18d14(180905)
Software version	: S5860_FSOS 11.0(5)B13S2
Software number	: M16064307162021
Serial number	: 1234942570067

Problem Solved

I D	Summary
1	The ARP table item list cannot display the specified number of items
2	The upgrade function on the WEB is unavailable, and it prompts failure
3	The footer link FS community cannot be opened after switching language
4	The STP configuration on the WEB does not display, and the device does not support showing spanning-tre e WEB info
5	The traceroute function on the WEB cannot be used, and the device-side commands are not supported
6	The one-click collection function on the WEB cannot be used, and the device-side commands are not supported
7	Sometimes the mirror configuration cannot be configured abnormally, and the interface does not display aft er the configuration is successful





http://www.fs.com

All statements, technical information, and recommendations related to the products here are based upon information believed to be reliable or accurate. However, the accuracy or completeness thereof is not guaranteed, and no responsibility is assumed for any inaccuracies. Please contact FS for more information.

S5860-48C SWITCH FSOS SOFTWARE RELEASE NOTES www.fs.com

Documents / Resources

