

# **DEWALT D25416 Critical Connection Undercut Anchoring System Instruction Manual**

Home » Dewalt » DEWALT D25416 Critical Connection Undercut Anchoring System Instruction Manual



#### **DEWALT D25416 Critical Connection Undercut Anchoring System Instruction Manual**



### **CCU Critical Connection Undercut Anchoring System**

The DeWALT Critical Connection Undercut (CCU+TM) Anchoring system is a specified anchor system incorporating an undercut anchor and various installation accessories and specific power tools. The contents of this manual will help guide the installer through proper preparation, installation, maintenance and troubleshooting of the CCU+TM anchoring system. This manual is not a substitute for construction drawings or specifications. CCU+TM anchors may be part of an engineered structure. Proper anchor placement and installation are critical to the performance of the structure.

The installer should make sure they have the correct anchors, bits, hammers, vacs and accessories to install CCU+TM anchors as per any construction drawings.

#### **Contents**

- 1 THE CRITICAL CONNECTION UNDERCUT SYSTEM (CCU+ $^{TM}$ )
- **2 COMPLIANCE**
- **3 SPECIFICATION OF THE ANCHOR**
- **4 INSTALLATION**
- **5 GENERAL / GETTING PREPARED**
- **6 PRIMARY HOLE DRILLING**
- **7 UNDERCUTTING**
- **8 ANCHOR SETTING**
- **9 REPLACING WEAR PARTS**
- 10 TROUBLE SHOOTING
- 11 Documents / Resources
  - 11.1 References

# THE CRITICAL CONNECTION UNDERCUT SYSTEM (CCU+™)

#### A. Anchor



#### B. Primary bit



**HSDB:** Hollow stop drill bit for specific drilling depth, primarily used for drilling until collar touches the concrete surface in case of preset installation

**HDB:** Hollow drill bit for variable drilling depth, primarily used for drilling through the fixture in case of thrubolt installation.



### C. Undercut bit



**HUCB:** Hollow undercut bit for dust-free undercutting



**UCB:** Undercut bit for economic undercutting.

#### D. Setting tool



Setting tool for power tool installation with SDS connector Setting tool for manual installation with hand held hammer



#### **COMPLIANCE**

#### A. ICC-ES

Steel grades A36 and A193, Gr. B7 and SS316 qualified according to ACI 355.2 for design according to ACI 318: ESR-4810 Download Anchor Design Software DDA™ at:



#### **DEWALT.COM/DDA**

#### B. OSHA

Part of an OSHA Table 1 compliant system.

Dust Extractor System with HEPA Filtration and /Auto Cleaning
Hollow Bit System: HDB, HSDB, HUCB (see above)

Use hood, shroud, etc. to control dust when using conventional bits.



#### C. Anchors Made In The USA\*


We can certify CCU+™ anchors for Trade Agreements Act (TAA), Buy American Act (BAA), American Iron and Steel (AIS), Build America, Buy America Act (BABA), and Buy America (FHWA, FAA, FRA, FTA). Please email <a href="mailto:anchors@dewalt.com">anchors@dewalt.com</a> for certification information.



\*As of the date of this Instruction Manual, DeWALT Critical Connection Undercut Anchors meet the requirements of the Trade Agreements Act (TAA), Buy American Act (BAA), American Iron and Steel (AIS), Build America, Buy America Act (BABA), and Buy America (FHWA, FAA, FRA, FTA).


# SPECIFICATION OF THE ANCHOR

# A. Material



- 1. Rod
- 2. Sleeve
- 3. Cone
- 4. Nut
- 5. Washer

Component N		Specifications							
Component N o.	Description	Carbon Steel Version (A36 or B7)	High Strength Stainless Steel (316 SS)						
1	Rod	ASTM A36 or ASTM A193 Grade B7, Zinc Plated ASTM B633, SC1 (Fe/Zn 5)	ASTM A193, Grade 8BM, Class 2 (3 16 SS)						
2	Sleeve	Carbon Steel, Zinc Plated ASTM B63 3, SC1 (Fe/Zn 5)	AISI 316 SS						
3	Cone	Carbon Steel, Zinc Plated ASTM B63 3, SC1 (Fe/Zn 5)	AISI 316 SS						
4	Nut	3/8" DIA A36: SAE J955 Grade 23/8" DIA B7: SAE J955 Grade 81/2", 5/8", 3/4" DIA: ASTM A563, Grade C	3/8" DIA SS2: ASTM F594SS 316 All oy Group 21/2", 5/8", 3/4" DIA: ASTM A194, Grade 8M (316 SS)						
5	Washer	ASTM F844; Meets ANSI/ASMEB18. 22.1, Type A plain (wide)	AISI 316 SS; meets ANSI/ASMEB18. 22.1, Type A plain (wide)						




Material Identification Code	A36	B7	SS2			
Length Identification Code	Refer to Installation Parameter Section					

Anchor Size	Symbo I	Unit	3/8"	1/2"	5/8"	3/4"	
Nominal ancho		da	in. (m m)	3/8 = 0.375(9.5	1/2 = 0.5(12.7	5/8 = 0.625(1 5.9)	3/4 = 0.75(19. 1)
Outside ancho	-	dnom = dbit	in. (m m)	11/16 = 0.688( 17.5)	13/16 = 0.813 (20.6)	1 = 1.000(25. 4)	1-1/4 = 1.250( 31.8)
1	al embedment dept als drill hole depth]		in. (m m)	4-1/4 (108)	5-3/8 (137)	8(203)	10-5/8 (270)
Effective embers h [the anchor is or]	hef	in. (m m)	4.0(102)	5.0(127)	7.5(191)	10.0(254)	
Minimum cond er thickness	rete memb	hmin	in. (m m)	6.0(152)	7.0(178)	9.75(248)	12.0(305)
Minimum edge	distance	cmin	in. (m m)	2.5(64)	3.0(76)	4.5(114)	6.0(152)
Minimum space	ing distanc	smin	in. (m m)	3.0(76)	3.75(95)	5.625(143)	7.5(191)
Installation to	A36		ftlbf.	11(15)	29(38)	70(95)	118(160)
rque	B7 and SS 2	Tinst	(Nm)	37(50)	70(95)	118(160)	221(300)
Torque wrench / socket si ze		_	in.	9/16	7/8	11/16	1-1/4


# B. Installation parameter

In case of the Preset (PS), installation, the anchor is installed first, and then the attachment (fixture or baseplate) is put in place.



Rod Dia.		3/8"	1/2"		5/8"		3/4"		
Max. Fixt ure Thick ness	in. ( mm)	0.875(22)	1.25(32)	2(51)	1.625(41)	2.375(60)	2.0(51)	4.0(102)	
	PS A 36	3/8 X 6	1/2 X 7-1/2 1/2 X 8-1/4		5/8 X 10-3/ 4	5/8 X 11-1/ 2	3/4 X 14	3/4 X 16	
		DFM13110 50	DFM13111 00	DFM13111 50	DFM13112 00	DFM13112 50	DFM13113 00	DFM13113 50	
Steel G	PS B 7	3/8 X 6	1/2 X 7-1/2	1/2 X 8-1/4	5/8 X 10-3/ 4	5/8 X 11-1/ 2	3/4 X 14	3/4 X 16	
rade		DFM13710 50	DFM13711 00	DFM13711 50	DFM13712 00	DFM13712 50	DFM13713 00	DFM13713 50	
	PS S S2	3/8 X 6	1/2 X 7-1/2 1/2 X 8-		5/8 X 10-3/ 4	5/8 X 11-1/ 2	3/4 X 14	3/4 X 16	
		DFM13610 50	DFM13611 00	DFM13611 50	DFM13612 00	DFM13612 50	DFM13613 00	DFM13613 50	

In case of the Thrubolt (TB) installation, the anchor is installed through the attachment (fixture or baseplate).



**Thrubolt Anchor Installation System Components** 

Rod Dia.		3/8"	1/2"		5/8"		3/4"	
Max. Fixt ure Thick ness	in. ( mm)	0.875(22)	1.25(32)	2(51)	1.625(41)	2.375(60)	2.0(51)	4.0(102)
	ТВ А	3/8 X 6	1/2 X 7-1/2 1/2 X 8-1/4		5/8 X 10-3/ 4	5/8 X 11-1/ 2	3/4 X 14	3/4 X 16
	36	DFM13115 50	DFM13116 00	DFM13116 50	DFM13117 00	DFM13117 50	DFM13118 00	DFM13118 50
Steel G	TB B 7	3/8 X 6	1/2 X 7-1/2	1/2 X 8-1/4	5/8 X 10-3/ 4	5/8 X 11-1/ 2	3/4 X 14	3/4 X 16
rade		DFM13715 50	DFM13716 00	DFM13716 50	DFM13717 00	DFM13717 50	DFM13718 00	DFM13718 50
	TB S S2	3/8 X 6	1/2 X 7-1/2	1/2 X 8-1/4	5/8 X 10-3/ 4	5/8 X 11-1/ 2	3/4 X 14	3/4 X 16
		DFM13615 50	DFM13616 00	DFM13616 50	DFM13617 00	DFM13617 50	DFM13618 00	DFM13618 50

# **INSTALLATION**

# A. Power Tools

# • Vacuums

DCV585



DWV010



DWV012 or DWV015



SDS+ Hammers
 DCH416 Cordless / Battery / DC Tool



D25416 Corded / AC tool



# • SDSMAX Hammers

DCH614 Cordless / Battery / DC Tool



D25614 Corded / AC tool



Primary Bit Underc ut Bit Tool
The Heat Heat Heat Heat Heat Heat Heat Hea

			S D S+		Pr es et	DF X1 13							
3 / 8 "	11 /1 6"	4 - 1/ 4 "	D C H4 16		Th	80	D W A5 41 16	D W5 80 8 <sup>1</sup>	DF X2 13 80	DF X2 13 81	DF X3 13 80 5	DF X3 13 82 5	
			or D2 54 16		bo It	_							
			S D S+		Pr es et	DF X1 11							
1 / 2 "	13 /1 6"	5 - 3/ 8 "	D C H4 16		Th ru	20	D W A5 43 16	D W5 81 4 <sup>1</sup>	DF X2 11 20	DF X2 11 21	DF X3 11 21 0	DF X3 11 23 0	
			or D2 54 16	D W V	bo It	_							
			S D S M A X	0 1 0 or D W	Pr es et	DF X1 15 80							
5 / 8 "	1"	8 "	D C H6 14	0 1 2 or D C	Th ru		D W A5 80 01	D W5 85 2 <sup>1</sup>	DF X2 15 80 2	DF X2 15 81 1,2	DF X3 15 81 5	DF X3 15 83 5	
			or D2 56 14	V 5 8 5	bo It								
			S D S M A X		Pr es	DF X1							
3 /	1-	1 0 -	D C		et	13 40	D W	D W5	DF X2	DF X2	DF X3	DF X3	

4 "	1/ 4"	5/ 8 "	H6 14			A5 81 15	85 5 <sup>1</sup>	13 40	13   41   1	13 42 0	13 44 0	
				Th ru	_	13					J	
			or D2 56 14	bo It								

#### **DWH050K 1**

The hood allows dust free drilling if conventional primary bits or UCB are used; use of hollow bits is suggested.



#### DW5891 2

SDSMAX to SDS+ adapter, allowing to use a SDSMAX hammer for a bit with a SDS+ shank; alternatively, use a SDS+ hammer tool.




### B. Installation instructions

#### **GENERAL / GETTING PREPARED**


#### **Power Tool: Hammer and Vacuum**

Connect the bit to the proper hammer and, in case of a hollow bit, to the proper vacuum using the DEWALT AirLock™ connector system.




#### **Hollow Bits**

Make sure that air flows freely, clean if required.



#### **Undercut Bits**


Make sure the cutter blades slides easily over the bow jaw and the gap can be fully closed.



#### PRIMARY HOLE DRILLING


#### **HOLLOW BITS**

### **Preset Installation**




**1a.** Before drilling, ensure hollow drill bit holes are not clogged. Using a HSDB of proper size, drill a hole into the base material to the required depth, i.e. until the collar of the bit touches the concrete surface. Continue with Step 3.

#### **Thrubolt Installation**




**1b.** Before drilling, ensure hollow drill bit holes are not clogged. Using a HDB of proper size drill a hole into the base material to the required depth. For this, mark the depth on the bit shank taking the fixture thickness into account. Continue with Step 3.

#### **Preset Installation**




**1c.** Using the proper drill bit size, drill a hole into the base material to the required depth. The tolerances of the drill bit used should meet the requirements of ANSI Standard B212.15. Mark the depth on the bit. Continue with Step 2.




2. Remove dust and debris from the hole following drilling (e.g. suction, forced air). Continue with Step 3.

#### **Thrubolt Installation**

**1c.** Using the proper drill bit size, drill a hole into the base material to the required depth. The tolerances of the drill bit used should meet the requirements of ANSI Standard B212.15. Mark the depth on the bit taking the fixture thickness into account. Continue with Step 2.




2. Remove dust and debris from the hole following drilling (e.g. suction, forced air). Continue with Step 3



#### **HOLLOW BITS**


**Preset Installation** 



**3a.** Insert a HUCB of proper size until it hits the bottom of the hole. Start the hammer at low speed and undercut. Undercutting is complete when the stopper sleeve is fully compressed, i.e. the gap is closed. Continue with Step 5.

# **UNDERCUTTING**


#### **Thrubolt Installation**




**3b.** Insert a HUCB of proper size until it hits the bottom of the hole. Start the hammer at low speed and undercut. Undercutting is complete when the stopper sleeve is fully compressed, i.e. the gap is closed. Continue with Step 5.

# **CONVENTIONAL BITS**

### **Preset Installation**




**3c.** Insert a UCB of proper size until it hits the bottom of the hole. Start the hammer at low speed and undercut. Undercutting is complete when the stopper sleeve is fully compressed, i.e. the gap is closed. Continue with Step 5.




4. Remove dust and debris from the hole following drilling (e.g. suction, forced air).

# **Thrubolt Installation**




**3c.** Insert a UCB of proper size until it hits the bottom of the hole. Start the hammer at low speed and undercut. Undercutting is complete when the stopper sleeve is fully compressed, i.e. the gap is closed. Continue with Step 5.




4. Remove dust and debris from the hole following drilling (e.g. suction, forced air).

# **ANCHOR SETTING**


**Preset Installation** 



**5.** Insert the anchor into hole. Place setting sleeve over anchor and drive the sleeve over the cone. For this, use either a setting tool for manual installation or a setting tool for power tool installation. Take care that the thread does not get damaged during installation.




**6.** Verify that the red setting mark is visible on the theaded rod at or above the sleeve.




7. Apply proper torque; Do not exceed maximum torque.


# **Thrubolt Installation**



**5.** Insert the anchor into hole. Place setting sleeve over anchor and drive the sleeve over the cone. For this, use either a setting tool for manual installation or a setting tool for power tool installation. Take care that the thread does not get damaged during installation.



**6.** Verify that the red setting mark is visible on the theaded rod at or above the sleeve.



7. Apply proper torque; Do not exceed maximum torque.

# **REPLACING WEAR PARTS**

A. Bow jaw



B. Cutter blade




C. Instructions


Anchors	Bow Jaw	Cutter Blade		
	нисв	UCB	HUCB & UCB	
3/8"	DFX213807	DFX213805	DFX213825	
1/2"	DFX211212	DFX211210	DFX211230	
5/8"	DFX215817	DFX215815	DFX215835	
3/4"	DFX213422	DFX213420	DFX213440	

The cutter blade wears and has to be replaced, depending on the condition of the concrete. Also the bow jaw experience wear at its head over time and needs to be replaced occasionally. The following procedure explains how the cutter blade and the bow jaw, if required, can be changed.


1. Press the pin on the undercutter using a screwdriver




2. Pull out the bow jaw



3. Change the cutter blade




4. Insert the bow jaw




**Note:** The bow jaw used for the HUCB has an air exhaust on one side. Therefore it is important to ensure that the bow jaw is oriented correctly to match the air inlet in the bit chassis!

5. Align the pin and pinhole and reinsert




#### TROUBLE SHOOTING

**A.** Cleaning of primary hollow bit Hollow bits work best in dry concrete. Take care when drilling in wet concrete. The internal hollow channel of smaller diameter HSDB can clog with concrete dust. It is recommended to occasionally blow through the small hole at the rear of the bit using dry compressed air in case of SDS+ bits. The SDSMAX bits can be cleaned from the inlets at the front using a thin gauge wire to dislodge material build up..



**B.** Un-jamming of undercut bit When the cutter blade of the UCB is stuck while undercutting and it cannot be pulled out from the hole, use wrenches as shown in below picture to relieve the cutter blade closed and remove the undercutter from the hole. After removal, retighten the loosened screw and continue undercutting. This feature is not available for HUCB as these do not tend to jam because of the dust constantly removed during undercutting.



#### FOR TECHNICAL ASSISTANCE PLEASE CONTACT:

anchors@DEWALT.com 1-800-524-3244

The information contained herein is accurate to the best of DEWALT's knowledge as of the date of publication and is provided for guidance and informational purposes only. Refer to website for most up to date version of this document. To obtain a project specific certification contact DEWALT engineering at <a href="mailto:anchors@DEWALT.com">anchors@DEWALT.com</a>



#### **Documents / Resources**



**DEWALT D25416 Critical Connection Undercut Anchoring System** [pdf] Instruction Manual D25416 Critical Connection Undercut Anchoring System, D25416, Critical Connection Undercut Anchoring System, Connection Undercut Anchoring System, Undercut Anchoring System, Anchoring System, System

# References

User Manual

Manuals+, Privacy Policy

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.