

OK : Operate properly  
NG : Do not operate  
- Mark abnormality

✓ : Can supply  
7.5W or more.  
N/A : Power  
supply capacity is  
less than 7.5W  
— : Not checked

**Notes :**

Examples when a power consumption of BT-45C goes over the power supply capacity of the smartphone:

\* Video recording definition or frame rate is high

\* Multiple functions ( display, camera, sensor, microphones, speakers and so on ) operate in the same time

Or BT-45C could not display a screen copy of AQUOS R6/R7. For further information, refer to the sheet "AQUOS R6/R7".

\*2. USB Type-C of this model does not support DisplayPort Alternate Mode.

- If you exit the app or remove or insert the BT-40 during video playback, video playback may result in an error.

- Depending on the content, it may not be playable.

If the phenomenon occurs, you can restore it by removing the BT-42 from the smartphone and inserting it again, or restarting

\*S The headset setting is not available due to Hoverlink does not start while displaying "App launching".

The BT-45C's built-in speakers, earphone jack, and Bluetooth earphones are all the same.

#### Shapiro-Wilk test result

step2: Play YouTube (Sound comes out of Bluetooth earphones, video can play normally)

step2: Connect BT-45C

<sup>a</sup> Values are means ± SD;  $n = 6$ . \* $P < 0.05$ , \*\* $P < 0.01$ , \*\*\* $P < 0.001$ .

Earphone jack test result

step1: Connect BT-45C to BO-3C400N, and change audio output destination to earphone jack with Moverio Link Pro  
step2: Open the Link Pro on iPhone

step2: Connect BIT-45C

→ Video appears on BT-45C, but sound stops, and YouTube video also stops

\*7 The permission dialog to allow access to M1-254 doesn't appear, and cannot record sound from microphone.