



## **Release Note**

**Software Version:** 2.12.50.4

**Models:** i504/i504W/i506W

**Date:** 2025.7.4

# Content

---

- Content ..... 2**
- 1 Revise History ..... 3**
- 2 Release 2.12.50.4 ..... 4**
  - 2.1 New Features ..... 4
  - 2.2 Optimization ..... 4
  - 2.3 Bug Fix ..... 4
- 3 Release 2.12.48.12.6 ..... 5**
  - 3.1 New Features ..... 5
  - 3.2 Bug Fix ..... 5
- 4 Release 2.12.45.10 ..... 6**
  - 4.1 New Features ..... 6
  - 4.2 Bug Fix ..... 6

## 1 Revise History

---

No.	Version	Release Time
1	2.12.45.10	2024.9.20
2	2.12.48.12.6	2024.11.8
3	2.12.50.4	2025.7.4

## 2 Release 2.12.50.4

---

Models	Software Version	Comment
i504/i504W/i506W	2.12.50.4	

### 2.1 New Features

1. Added screensaver image carousel feature
2. Added support for Chinese input method
3. Added customizable standby desktop and icons
4. Added customizable door unlock button during calls
5. Added door unlock and call functions during monitoring
6. Added missed call auto snapshot and manual screenshot during calls
7. Added monitoring timeout auto-exit function
8. Function key interface can now be set as the default standby screen
9. Added arming modes: Home, Away, and Night

### 2.2 Optimization

1. Improved contact search via the web interface
2. Added support for configuring monitoring and door unlock via the web interface
3. Added Polish and Arabic

### 2.3 Bug Fix

1. Fixed failure to upgrade certain certificate files
2. Fixed issue where the device continuously rang after input trigger and could not stop

### 3 Release 2.12.48.12.6

---

Models	Software Version	Comment
i504/i504W/i506W	2.12.48.12.6	

#### 3.1 New Features

1. Compatible with FCMS, allowing management settings through FCMS to reduce user operations. When used in conjunction with the Fanvil Link APP, it enables remote door opening, monitoring, and other features, providing users with a more convenient experience.
2. Supports diagnostics through FDMCS to obtain device information.
3. Supports automatic discovery, enabling the automatic detection and configuration of door phone devices on the local area network.

#### 3.2 Bug Fix

1. Supports one-click export of debugging information through the web interface.

## 4 Release 2.12.45.10

---

Models	Software Version	Comment
i504/i504W/i506W	2.12.45.10	

### 4.1 New Features

1. Add Korean.

### 4.2 Bug Fix

1. Fix the problem that the peer device hears a low voice after a call is set up.
2. Fix the problem that the ringtone has a pop sound when the wireless button is triggered.
3. Fix faults related to short-circuit input triggering.
4. Fix slow screenshots through the web page.