

Firmware Change History for TM-L100

Version	Category	Detail
1.03 ESC/POS	Function change	Modified the firmware so that the alternative part operates correctly on the printer to deal with EOL of the current USB HUB.
1.04 ESC/POS	Bug fix	Fixed a bug that commands cannot be sent because Printer Busy is output while the printer is waiting for removal of paper.
		Fixed a bug that unintended reading result is produced when some 2-byte characters are included in the QR code in the ePOS-Print and the ePOS-Display.
		Fixed a bug that unintended display result is produced when trying to display some 2-byte characters on the ePOS-Display.
		Fixed a bug that some 2-byte characters could not be printed even if the 2-byte character selector was used in the ePOS-Print.
1.05 ESC/POS	Bug fix	Fixed a bug where executing the real-time command repeatedly, the printer stop responding to the command.