

DP755 Firmware Release Notes

Table of Content

Table of Content.....	1
FIRMWARE VERSION 1.0.1.15	2
PRODUCT NAME.....	2
DATE	2
FIRMWARE FILE INFORMATION	2
SUPPORTED HARDWARE	2
SUMMARY OF UPDATE	2
ENHANCEMENT	3
BUG FIX	3
NEW P-VALUE	3
NEW HTTP API	3

FIRMWARE VERSION 1.0.1.15

PRODUCT NAME

DP755

DATE

10/16/2023

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 7452c1f403cff911b515012179da647c
(*Basestation: Boot 1.0.1.15; Core 1.0.1.15; Prog 1.0.1.15; CPE 1.0.4.75*
Handset: 1.0.19.16)
- **FW1.0.1.13 is the initial launching firmware for DP755**

SUPPORTED HARDWARE

Basestation:

- *DP755 HW1.0; 1.1*

Handsets:

- *DP730 HW1.0; 1.1; 1.2*
- *DP722 HW1.0; 1.1*
- *DP720 HW1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*

Relay:

- *DP760 HW1.0; 1.1; 1.2; 1.3*

NOTE:

- **DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.**
- **DP755 NOT include DP760 firmware, but can work with DP760 to extend range**
- **Handset firmware can NOT downgrade to 1.0.19.15 or below.**

SUMMARY OF UPDATE

The main purpose of this release is bug fixes for initial firmware release 1.0.1.13

ENHANCEMENT

- None

BUG FIX

- Fixed TR069 registration information SIP server on the account status page not updated immediately
- Fixed using vocodec G.722 the background noise is very loud
- Fixed some options not restored to default values after handset factory reset
- Fixed the account status of HS1 wrongly flashed in the webUI during intercom
- Fixed group ringer HS display error
- Fixed inaccurate prompt after closing the user permission page access
- Fixed set to IPv6 only but an IPv4 address will randomly appear after long standby
- Fixed Metaswitch IOT related bugs.
- Fixed RTP Payload Type displayed error messages in IETF of G726-32 packing mode

NEW P-VALUE

- None

NEW HTTP API

- None

For detailed information about DP755, please refer to User Manual and Resource Center:

<https://documentation.grandstream.com/article-categories/dect-base-stations/>