

Release Notes for the Cisco WAP150 Wireless-AC/N Dual Radio Access Point Firmware Version 1.0.0.13

January 2016

These release notes describe the known issues in the Cisco WAP150 Wireless-AC/N Dual Radio Access Point firmware version 1.0.0.13.

Known Issues

The following table lists the known issue in firmware version 1.0.0.13:

Ref Number	Description
CSCuy00590	The range of TFTP Source File Name on the OLH page in Clustering Firmware Upgrade is incorrect; should be 128 not 256. Workaround None.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP150	www.cisco.com/go/100_wap_resources
Regulatory Compliance and Safety Information	www.cisco.com/en/US/docs/switches/lan/csb_switching_general/rcsi/Switch_ClassA_RCSI.pdf
Warranty Information	www.cisco.com/go/warranty

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2016 Cisco Systems, Inc. All rights reserved.