

KYALAMI SOFTWARE VERSION HISTORY

VERSION	RELEASE DATE	DMX CHART	MODIFICATIONS
V101	2024.02.28	V1	Formal version
V102	2024.03.08	V1	Modified PAN Default Position Fixed tilt encoder error
V103	2024.03.28	V1	Increase a bit the sensibility on PAN / TILT put the signal selection inside the DMX addressing add the RDM QR code
V104	2024.04.11	V1	Modified button function in address page Optimized/corrected Defog Auto mode
V105	2024.05.07	V1	Data collect in Fixture manager open consent privacy Settings, the menu unable to reloaded Improve the gobo wheel reset chanel(fast reset) Fixed random P/T issue new setting of blanking zone Optimize network upgrade
V106	22-Jul-24	V106	new setting of blanking zone, dimmer can be set by Distance new setting of blanking zone, dimmer off when staying in zone for 10s Fixed of random P/T issue Add P/T Speed Turbo mode
V107	29-Jul-24	V106	Minor Bug Fixes
V109	2-Sep-24	V106	Turn off P/T when you enter the menu (10s) Improve positioning Add Blanking zone setting
V110	18-Nov-24	V106	Improve Blanking Zone (FM_V210F) Improve Prism Rotation Improve Auto IP
V113	3-Jul-25	V113	Improved Auto IP value accuracy Fixed issue where Fixture Manager could not report air leakage data Increased maximum temperature for Auto IP testing from 60°C to 75°C Resolved DMX and W-DMX data reception bug Added FDA status display: default is Off, can be enabled when blanking zones are active Introduced Threshold Detect option Added CMY Path setting: choose between "Shortcut" (default) or "Spinout" Added 360SC feature Fixed issue where Pan or Tilt synchronization failed across multiple units in infinite rotation mode Updated Laser hour counter logic Added "Reset Option" function in menu Added Unlink WDMX in shorcut menu Removed Turbo Speed setting (now Fast = Turbo)
V114	11-Jul-25	V113	Improve CMY driving, to correct bug (random flash between colours)

NOTE: Updating software does not restore factory default settings