

MULTIPLEX
645 PARK EAST BLVD SUITE 5, NEW ALBANY, IN 47150
844-724-CARE
WWW.MULTIPLEXBEVERAGE.COM
Refreshing the Experience

Service Bulletin

Subject: BIC MF Truck Stock February 2022

SCOPE: ALL MULTIPLEX BIC MANUAL FILLS MCDONALD'S

Each branch authorized to work on Multiplex BIC MANUAL FILL blended ice machines will be required to have truck stock minimum items on this list.

Qty	Part #	Description
2	020008742	BLENDER SHAFT
1	020008744	120V SAMMIC MIXER MOTOR WITHOUT SHAFT
1	020005547	SOLENOID
1	3239675	FLOJET PUMP
1	2195363	CONTROL BLENDER BIC HSM
1	2195346	SRB BOARD
1	VMP00123	SHAVER BELT
1	VMP00175	HALL EFFECT SENSOR
1	2198523	BLANK USB STICK, 8GB OR SMALLER
1	020008501	USB STICK WITH 4.0.10 FIRMWARE AND RECIPE FILES
		(PART NUMBER DOES NOT INCLUDE RECIPE FILES,
		CONTACT WELBILT FOR RECIPE FILES.)
1	020009050	USB STICK WITH 5.0.10 FIRMWARE AND RECIPE FILES
		(PART NUMBER DOES NOT INCLUDE RECIPE FILES,
		CONTACT WELBILT FOR RECIPE FILES.)
1	000-CZ0-0096-S	USB STICK WITH 4.0.2 FIRMWARE (PART NUMBER DOES
		NOT INCLUDE RECIPE FILES, CONTACT WELBILT FOR
		RECIPE FILES.)

NOTE: Do NOT put multiple firmware versions on same USB. Each firmware version needs to be on separate USB sticks.

NOTE: 5.0.10 firmware is NOT compatible with 4.0.10 or earlier versions. Any displays with REV letters A-S will need to have the 4.0.10 firmware loaded. Any REV letters T-Z will require the 5.0.10 firmware package. REV letter can be found on a sticker on the outside frame of the screen. Do NOT use the sticker on the board.

FURTHER ACTIONS

Contact Welbilt KitchenCare 1-844-724-2273 if you have any questions or concerns.



1 of 1 Document Number: MPX-185 March 28, 2022