

2012 Mercedes Benz Truck ML 63 AMG (166.074) V8-5.5L Turbo (157.980)

Vehicle > Technical Service Bulletins

ALL TECHNICAL SERVICE BULLETINS



Search Components

TSB NUMBER ▾	TSB DATE ▾	TSB TITLE ▾
LI32.34-P-056198	2017/08/31	Fault message "AIRMATIC" or "Active Curve System" in instrument cluster
LI54.30-P-066154	2017/08/31	Instrument cluster: HOLD indicator continues to be lit for a few seconds although the vehicle is moving
LI77.20-P-063070	2017/08/25	Water entry at sliding roof in heavy rain
LI42.10-P-066237	2017/08/15	Squeaking noises from area of front axle brake
LI00.20-P-066887	2017/08/14	Service: Service display implausible
LI00.00-P-066047	2017/08/11	Odor like crayon or vinegar entering the passenger compartment through the ventilation system
LI00.00-P-066036	2017/08/08	Odor like crayon or vinegar entering the passenger compartment through the ventilation system (USA)
LI54.10-P-066344	2017/08/08	Vehicle does not start, battery discharged.
T-SC-2017020020	2017/07/31	Models 166 and 292; Model Year 2016 Correct Torque of Front Left and Right Torsion (Stabilizer) Bar Linkage Nut
LI83.30-P-059119	2017/07/25	Odor from the air conditioning
LI82.70-P-066767	2017/07/19	COMAND Online: Some contacts on the telephone are not found via voice control.
LI82.85-P-066769	2017/07/19	COMAND Online: After map update is aborted, navigation no longer functions

LI42.10-P-066238	2017/07/12	Squeaking noises from area of front axle brake
LI42.10-P-061801	2017/06/28	Vibration or noise when braking.
LI54.10-P-058943	2017/06/27	Fault message in instrument cluster "Additional Battery - Service Required" - FC B11C11B
LI54.30-P-066410	2017/06/13	Message "Mercedes me connect services limited. See owner's manual" in instrument cluster multifunction display
LI32.34-P-058736	2017/06/06	ACTIVE CURVE SYSTEM malfunction in instrument cluster.
LI82.85-P-065949	2017/06/06	Message "SOS - Service Not Activated" in instrument cluster
LI54.70-P-066353	2017/06/05	Message in instrument cluster "Collision Prevention Assist Inoperative"
LI54.70-P-065987	2017/05/24	Message in instrument cluster "Collision Prevention Assist Inoperative"
LI54.65-P-066284	2017/05/24	The flap of the reversing camera opens and closes by itself during forward travel
LI72.00-P-066220	2017/05/19	Noises at doors in window frame area
LI54.30-P-063675	2017/05/17	Instrument cluster: Nothing shown on display in instrument cluster
LI91.18-P-053842	2017/05/02	Damages To Seat Covers
LI91.10-P-063393	2017/05/02	Splitting of Seat Covers
LI54.30-P-061127	2017/04/25	Instrument cluster - Fuel gauge does not indicate "Full"
LI91.60-P-064763	2017/04/25	PRE-SAFE Impulse Side
LI91.18-P-065627	2017/04/24	AMG Ornamental Molding Piece On Seats
LI18.40-P-066105	2017/04/19	Engine oil level above max.

LI82.10-P-062056	2017/04/17	Headlamps fogged
LI54.30-P-064548	2017/04/13	Instrument cluster: Always boots in main menu (trip/total mileage) / Last mode inoperative
LI83.30-P-066030	2017/04/05	HVAC refrigerant lines leaking
S-RC-2017030015	2017/04/01	Perform SCN Coding in Various Control Modules as per DAS/Xentry
LI49.10-P-064655	2017/03/14	Squeaking noise from exhaust flap
NHTSA17V177000	2017/03/14	Wrong Control Unit Software Installed
LI54.71-P-056477	2017/03/03	Blind Spot Assist inoperative
LI82.95-P-056646	2017/02/22	Troubleshooting mbrace issues prior to replacement
LI20.40-P-050513	2017/02/21	Radiator fan run-on after ignition OFF
LI68.20-P-065525	2017/02/03	Noises at center console
LI98.00-P-058914	2017/02/03	Clearcoat peeling / flaking / bubbling
LI33.20-P-054920	2017/01/31	Creaking/crackling noises from area of front axle wheel bearing
LI46.15-P-063353	2017/01/30	Height adjustment of electric steering column inoperative
LI91.25-P-058219	2017/01/26	Front active multicontour seat/ rear multicontour seats/ massage/ pump inoperative and no communication possible via diagnosis
LI82.85-P-063081	2017/01/11	Deactivation of selected MB Apps
LI54.10-P-064158	2017/01/10	Malfunction of additional battery in IC and fault code B11C11B in CBC (SAM) N10

LI49.00-P-054888	2017/01/03	Engine diagnosis warning lamp active - The fault code P262600 or P262900 relating to the oxygen sensor upstream of the catalytic converter may be stored in the engine control unit
LI82.85-P-064311	2016/12/19	Garmin MAP PILOT - General information in the event of complaints
LI82.85-P-065461	2016/12/19	Garmin MAP PILOT: Test SD cards W 000 589 03 22 00 and W 000 589 04 22 00 cannot be used
LI91.29-P-053247	2016/12/01	Electric seat adjustment, seat heater/seat ventilation of front seat, or rear monitor nonfunctional
LI82.60-P-053573	2016/12/01	CD/DVD is no longer ejected
LI07.02-P-054717	2016/11/14	Ticking or pulsing noise from high-pressure pump and fuel injectors
LI82.85-P-065110	2016/10/25	Garmin MAP PILOT: After a navigation software update, the user is instructed to connect the SD card with the vehicle
LI54.65-P-065038	2016/10/15	Parktronic system has a malfunction
LI27.50-P-049281	2016/10/10	Harsh engagement when changing gear range from P to D
LI82-85_P-063619	2016/10/06	Comand Online Live Traffic Free Browsing Inoperative
LI82-85_P-064765	2016/09/22	Garmin: Traffic Info. Service and or Voice Control Inoperative
LI80-45_P-064913	2016/09/20	Power Windows Sliding Roof or Vario Roof/Soft Top Inoperative
LI80-61_P-060558	2016/09/13	Opening Via Radio Remote Control or Keyless/Keyless Start Inop
LI91-22_P-048771	2016/09/09	Folding Mechanism of 3rd Row Seat Makes Noises or is Inoperative
LI91-12_P-055797	2016/09/06	Impairment of Electrical Folding Function of 2nd Row Seat
LI82-85_P-058185	2016/08/16	Central Display Intermittently Displays Antitheft Protection

LI82.61-P-055130	2016/08/09	Becker MAP PILOT Gen 1.0 to 2.5 (2.6 in China) - Message 'The internal battery is missing or faulty' appears in the display
LI83-10_P-063859	2016/08/08	HVAC Blower Motor Inoperative and DTC 912F87
LI46-35_P-062292	2016/08/02	Vehicle Wanders to Left or Right
LI91-12_P-063995	2016/07/25	Backrest Flap Mechanism on 2nd Seat Row Nonfunctional/Sluggish
LI91-10_P-064557	2016/07/22	Reset Function of Backrest Adjustment
LI05-10_P-056435	2016/07/21	Rattling Noise After Engine Start For Several Seconds
LI32-34_P-064466	2016/07/14	Jerky Movements of Body
LI82-10_P-064405	2016/07/01	Running Board Illumination Inoperative
T-RC-2016060014	2016/07/01	Models 166, 292; Model Years 2015 - 2016 Check Right Rear Seat Belt end Fitting, Rework if Necessary
LI91-22_P-064370	2016/06/27	3rd Seat Row Adjustment Motor Inoperative, Model Series X166
LI82.95-P-064353	2016/06/22	Automatic emergency call triggered for no obvious reason
LI82-85_P-064225	2016/06/13	Garmin Map Pilot: Notes On Voice Input
LI82.60-P-064168	2016/05/27	Audio 20 - Music does not continue automatically after a call
LI82-85_P-063849	2016/04/11	Starting - Mbrace(R) Mobile App is Inop or Partially Available
LI88-00_P-063728	2016/04/01	Body - License Plate Adapter Mounting Screws
LI27-00_P-063664	2016/03/22	A/T - Harsh 1-2 Shift in Transmission Mode S+

LI80-35_P-063677	2016/03/19	Keyless Entry - Battery in Transmitter Key Discharged
LI42.10-P-063502	2016/03/02	Brake noises on AMG vehicles
LI91-10_P-063385	2016/02/22	Restraints - Noise From Seats Passenger and Drivers
LI91-16_P-063435	2016/02/22	Restraints - Vibration From Headrest When Seat is Unoccupied
LI88-70_P-063310	2016/02/18	Body - Exterior Mirrors Cannot Be Fully Adjusted
LI82-85_P-062889	2016/02/02	Collision Avoidance - Rear Camera Text Displays in 2 Languages
LI72-00_P-063146	2016/01/20	Body - Door Entry Edge Protector Is Loose
2015120001	2016/01/01	Campaign - Update Fuel Control Module Software
LI68-20_P-062424	2015/11/11	Stowage Compart. in Center Console Makes Noises Rough Terrain
LI30-30_P-062554	2015/11/06	Collision Avoidance - False Warning Visual and Audible
LI49-10_P-062519	2015/11/05	Engine - MIL ON, DTC's P042000/P043000
LI82-95_P-062403	2015/10/15	MBRACE(R) - Please Press I Button or Call to Activate
LI54-21_P-062109	2015/08/26	Traction Control - Incorrect Coding
LI82-70_P-062003	2015/08/07	Cell Phone - iPhone (R) Address Book Doesn't Display
LI82-85_P-061613	2015/06/10	Infotainment - Facebook(R) App. Cannot be Opened
LI82-95_P-061544	2015/05/29	Infotainment - Unable to Log on Facebook(R)/App Doesn't Show
S-01_10-34	2015/05/06	Engine - Standard Procedures for Engine Complaints

LI82-61_P-061310	2015/04/20	Infotainment - 'Navigation is Being Activated' Displayed
S-98_00-32	2015/04/15	Body - Paint Drying Information
LI91-22_P-060891	2015/02/23	Interior - Third Row Seat Adjustment Inoperative
LI83-40_P-060850	2015/02/20	Blower Runs Up, No Air From the Outlets
S-15_10-74	2015/02/09	Ignition System - Spark Plug Connector Grease Information
LI27-60_P-060724	2015/01/28	A/T - Can not shift in D or R after Long Idle Periods DTC B2266
LI91-40_P-060559	2015/01/12	Restraints - Seat Belt Tensioner Retracts Too Fast
S-80_61-63	2015/01/12	Keyless Entry, Keyless Start - Smart Key Functions
LI83-30_P-060551	2015/01/07	A/C - System Failure, Heats up Suddenly, Stays Hot
S-42_10-123A	2014/12/11	Brakes/Wheels - Brake Disc Installation Information
LI54-21_P-060308	2014/11/26	Engine Controls - Engine No Start or Dies After Software Update
LI47-30_P-060249	2014/11/20	Emissions - DTC P04F000 Charcoal Canister Malfunction
LI54-30_P-060206	2014/11/12	Instruments - Message, Attention Assist Inoperative
LI28-00_P-060078	2014/10/24	Drivetrain - Humming Howling Droning Noise From Drivetrain
LI82-95_P-060072	2014/10/22	Cell Phone - i-call May Not Connect
LI91-12_P-060009	2014/10/20	Restraints - 2nd Row Seat Head Restraint Replacement
LI82-70_P-060004	2014/10/15	Cell Phone - Various Complaints After Software Update to IOS8

LI91-22_P-059988	2014/10/14	2nd Row Power Easy Entry Function Impairment of Backrest Folding
LI54-15_P-057754	2014/09/26	Collision Avoidance - Cover of Reverse Camera Not Actuated
LI25-00_P-059830	2014/09/15	Engine Controls - Jolting On Startoff After Start/Stop
S-67_10-30	2014/04/11	Windows/Glass - Windshield Bonding System Change
LI82-85_P-058859	2014/04/09	Infotainment - Drive Kit Plus: Car-to-X Function Issues
LI46-15_P-058505	2014/02/25	Interior - Creaking Noise When Adjusting Steering Column
T-68_30-83	2014/02/20	Interior - Notes on Attaching Magnets to Headliner
S-00_01-104	2014/02/19	Infotainment - Content and Application of Data Mediums
LI27-50_P-0497103	2014/02/19	A/T - Limp-home Mode, Gearshifts No Longer Possible, DTC's
LI46-10_P-0546993	2014/02/18	Steering - Crack, Clunk, Or Jolt When Braking Or 'Moving Off'
LI54-21_P-0579304	2014/02/13	Interior - Rear Seat Heating Cannot be Activated
LI54-15_P-0579294	2014/02/11	Body - Liftgate Cannot be Opened
T-32_34-84	2014/02/11	ABS/TCS - Check Active Curve System Hydraulic Pump
LI54-25_P-0564722	2014/02/10	Starting System - Key in Ignition Switch is NOT Recognized
LI91-25_P-058219	2014/01/23	Interior - Multiple Front Active Multicontour Seat Failure's

LI54-18_P-0562204	2014/01/14	Electrical - Corrosion at Connecting Point X174-1
LI82-61_P-058186	2013/12/23	Navigation - GPS Inoperative/Navigation Display Freezes
LI91-10_P-0536012	2013/12/20	Interior - Play/Noises In Front Seat Cushion Shell Area
LI82-10_P-0517694	2013/12/20	Lighting - Headlamp Unit Fogged/Droplets Forming
LI72-20_P-0553014	2013/12/20	Body - Automatic Liftgate Intermittently Doesn't Open
LI68-20_P-057931	2013/12/20	Interior - Noises at Center Console
LI91-10_P-057914	2013/12/20	Interior - Noises in Area of Front Seat Backrests
LI91-60_P-056473	2013/11/21	Air Bag - SRS Indicator Lamp Lights Up After Engine Start
LI54-70_P-057813	2013/11/19	Collision Avoidance- Random Triggering of Proximity Warning Dev
S-54_65-261	2013/11/08	Collision Avoidance - Painted PARKTRONIC(R) Sensors Available
LI07-08_P-0562452	2013/11/06	Engine Controls - DTC U040208 Stored in ECM
LI83-10_P-057727	2013/11/05	A/C/Interior - Center Console Rear Vent Grilles Broken/Loose
P-88_40-90	2013/11/01	Body - Permanently Illuminated Star Installation Instructions
2013070003	2013/11/01	Campaign - Replace Rear Axle Collar Nuts
2013110002	2013/11/01	Campaign- Update Fuel System Control Module Software

S-42_10-119	2013/10/29	Brakes - Fabrication of Brake Lines
LI82-85_P-0571912	2013/10/28	Infotainment - Mute Function Not Active After a Restart
LI42-10_P-0555713	2013/10/22	Brakes - Brake Squeal Just Before Standstill
LI54-65_P-057398	2013/10/22	Instruments - Reversing Camera Noise
LI83-30_P-0562193	2013/10/03	A/C - Heater Blower Start Delayed/A/C Display OFF
LI82-10_P-0534393	2013/09/13	Lighting - 'High Beam Assist Inoperative' Message Appears
LI82-85_P-057192	2013/09/09	Infotainment - Intermittently NO Audio Output after Engine Star
LI82-85_P-057016	2013/09/06	Infotainment - Drive Kit Plus Stability Improvements
LI82-62_P-056934	2013/09/05	Audio System - Interference Noises from LR of Bass Box
2013050002	2013/09/01	Campaign - Update Engine Control Module Software
LI82-85_P-0556953	2013/08/28	Infotainment - Doesn't Start, Can't Be Operated, Dark Display
LI72-20_P-056907	2013/08/26	Body - Noises When Opening and Closing Automatic Liftgate
LI82-70_P-056963	2013/08/21	Infotainment - Cell Phone Connectivity via Bluetooth(R) Concern
LI82-61_P-0560442	2013/08/08	Navigation - Becker(R)MAP PILOT House Address Numbers Not Found

LI82-61_P-0563882	2013/08/08	Navigation System - Navigation Announcements Inoperative
S-67_00-29	2013/07/23	Windows/Glass - Omission of Glass Breakage Loops
LI82-95_P-0566552	2013/07/23	Instruments - Battery Drain Bus Keepawake Detected, Low Battery
S-40_10-79	2013/07/23	Wheels/Tires - Cosmetic Processing of Light Alloy Wheels
LI32-34_P-056667	2013/07/22	Steering/Suspension - Thump Noises at the Front Axle
LI83-00_P-0554252	2013/07/18	Interior/A/C - Flap/Rattle from Rear Area of Center Console
S-60_00-22	2013/07/02	Body - Handling Lead-Free Filling Solder
S-82_61-702	2013/06/26	Navigation - Becker(R) MAP PILOT Module Information
LI88-70_P-056532	2013/06/19	Body - Wind Noises From Door Mirror
S-32_25-82C	2013/06/04	Suspension - Strut/Shock Absorber Replacement Guidelines
S-54_10-243B	2013/05/30	Electrical - Battery Test & Inspection Information
S-91_40-200	2013/05/29	Restraint- Reversible Emergency Tensioning Retractor Adaptation
LI32-22_P-056230	2013/05/10	Steering/Suspension - Vehicle Drops at One or more Struts
LI72-00_P-055920	2013/05/01	Body - Outside Door Handle Inoperative After Operation
LI67-30_P-0528372	2013/04/23	Doors/Glass - Side Window Noise/Reverse When Closing

LI83-30_P-056231	2013/04/22	Heating/A/C - Front Heater Blower Runs With Ignition OFF
LI33-30_P-055908	2013/04/12	Drivetrain - Noises at Full Lock From Front Axle Area
LI72-30_P-055921	2013/04/12	Body - Front/Rear Door Closing Assist Inoperative
S-80_61-61A	2013/04/04	Antitheft System - 'Replace Key Battery' Message Displayed
LI82-70_P-0542272	2013/03/26	Cell Phone - Called Party Difficult To Understand/Interference
LI82-70_P-0542264	2013/03/01	Cell Phone/Voice Control - Interference/Background Noise
2013030001	2013/03/01	Campaign - Update Transmission Control Module Software
LI32-22_P-055731	2013/02/28	Steering/Suspension - Vehicle Drops At One Or More Struts
LI91-22_P-055640	2013/02/21	Interior - 2nd Row Seat Black/Red Release Handle Can Break
LI82-10_P-0545522	2013/02/12	Lighting - Headlamp Unit Fogged/Droplets Forming
LI82-60_P-055630	2013/02/12	Infotainment - No Navigation, Media Interface Inoperative
LI32-22_P-055559	2013/02/11	Steering/Suspension - Squeak/Honk Noise From Front Axle
LI65-10_P-0549802	2013/02/05	Body - Warps In The Roof Paneling
LI77-21_P-055302	2013/02/04	Body - Wind Deflector Net Loose
LI68-30_P-0549832	2013/02/04	Interior/Restraints - Noises In B-Pillar Area

S-14_00-31	2013/02/01	Emissions - I/m Dynamometer Emissions Testing
C1A140101	2013/02/01	Campaign - Verizon(R) Telematics i-button Call
S-80_35-60	2013/01/23	Anti-theft - Transmitter Key Replacement Operation Code
2012080006A	2013/01/18	Recall - Replace Accessory All Weather Floor Mats
T-72_20-115A	2013/01/09	Body - Liftgate Control Drive Unit
S-98_00-31	2013/01/09	Body - Cleaning Tin-Plated Surfaces
LI72-40_P-0550452	2013/01/07	Body/Electrical - Various Door Control Function Failures
S-42_15-122	2012/12/13	Brakes - Brake Rotors Treated With Zinc Dust Spray Paint
S-54_50-256	2012/12/10	Instruments - Reset Trip Computer After ECU Software Update
S-40_00-77	2012/12/06	Steering/Suspension - Wheel Alignment Data
2012110001	2012/12/01	Campaign - Check/Replace Front Air Suspension Struts
LI91-40_P-0535723	2012/11/27	Restraints - Noise From Seat Belt Height Adjustment
S-58_40-161	2012/10/24	Body/Frame - Dedicated Frame Straightener
LI88-50_P-0535862	2012/10/23	Body - Rear Spoiler On Liftgate Door Is Loose
S-80_61-59	2012/10/22	Keyless System/Instruments - 'Replace Key Battery' Displayed
LI15-12_P-054772	2012/10/15	Engine Controls - Can't Check Oil Level Or No Oil Temp. Display

S-27_00-124	2012/10/03	A/T - 722.9 Additional Adaptation Counter Indicator
LI68-50_P-054110	2012/10/03	Body - Noises When Retracting The Twin Roller Blinds
S-28_00-12	2012/09/26	A/T - 722.96 Transmission Group 28 Damage Code Changes
S-88_30-88	2012/09/26	Body - License Plate Bracket Installation Precautions
LI46-35_P-054644	2012/09/20	Steering - 'Power Steering Malfunction, Service Required' ON
LI80-50_P-0538133	2012/09/14	Antitheft - Various Symptoms Including Random Alarm Trigger
LI20-30_P-054503	2012/09/06	Engine - Coolant Too Low Fault Message In Instrument Cluster
LI68-20_P-0536072	2012/09/05	Interior - Noises in Center Console Area
S-30_30-67	2012/08/15	Collision Avoidance - Short Range Sensor Replacement Info.
S-83_30-136	2012/08/15	A/C - A/C Sealant
LI46-35_P-054316	2012/08/09	Steering - DTC U044700 Stored In Electric Steering Control Unit
2012080003	2012/08/01	Campaign - Check/Retrofit Air Intake Cover Panels
LI54-25_P-053515	2012/07/09	Steering - High-Frequency Squeak Noise In Steering Column
S-54_10-255	2012/07/03	Battery - Battery Charging Information
LI67-10_P-053633	2012/06/07	Windows/Glass - Spotting In Area Of Rain/Light Sensor
LI27-57_P-0534962	2012/05/22	A/T - ECO Start/Stop Inoperative, DTC P0944 Stored In TCM

LI32-22_P-053867	2012/05/22	Air Suspension - Thumping Noised From Front/Rear Axle
LI28-10_P-0519352	2012/05/22	Drivetrain - Oil Leak At Seam Between A/T And Transfer Case
S-80_57-57A	2012/05/17	Keyless Entry/Start - Replacement And Diagnosis Revision
LI54-65_P-053709	2012/05/09	Collision Avoidance - Reverse Camera Displays No Picture
S-91_40-198	2012/04/27	Restraints - Seat Belt Buckle Warranty Replacement Information
T-54_15-254	2012/04/26	Electrical - Model 166 Fuses Now Uses Silver-Plated Contacts
LI72-00_P-053606	2012/04/19	Body - Door Lock Does Not Lock
S-46_10-72	2012/04/09	Steering - Warranty Policy Regarding Steering Wheels
LI72-20_P-052641	2012/03/22	Body - Automatic Liftgate Issue
LI72-00_P-053016	2012/01/18	Body - Outside Door Handle Doesn't Return To End Position
LI27-60_P-051470	2011/03/23	A/T - Hard 2-3 Upshift Or Slips, No 3rd Gear/DTC's Stored

