

IMPORTANT QUALITY RECALL

Product: MotoMaster 900A Booster Pack with Air Compressor 011-2065



This recall involves the MotoMaster 900A Booster Pack with Air Compressor. This recall is batch related and only units with the following batch codes are affected: 13920, 15320, 33520, 33820, 33920, 35220, 35320, 43320, 45220, 45320, 50221, 53320, 53420, 53520, 53620, 53720.

The batch code can be found on both the packaging and unit. Please see images below for an example of where the batch code can be located.

Unit



Packaging



Issue: Due to a manufacturing defect, the affected units will self-discharge much quicker than normal. Consumers who have an affected unit may notice the charge level of their booster pack will fall to 75% or less within only a few days after fully charging.

What should you do: Consumers who are experiencing this type of failure, with a unit that matches one of the sixteen batch codes, should visit their local Canadian Tire for a refund or replacement.

For additional info, please contact Customer Relations English: 1-800-387-8803 and French: 1-800-565-3356