

17.15.1 SOFTWARE Interim/BETA RELEASE NOTES Build 17.15.1EFT4

Beta Build: 17.15.1EFT4

17.15.1EFT4 Interim/Beta Release 4th Refresh.

The following Beta software is posted on the cisco.com

Image Name	MD5 Checksum	Supported Platforms
C9800-L-universalk9_wlc.17.15.01prd21.SPA.bin	4ec41954b14ea1cc5b088d9d385aff41	Interim software for C9800-L, C9800-LC, C9800-LF platforms
C9800-universalk9_wlc.17.15.01prd21.SPA.bin	9e895164696fdcf86f533d2c0c369e0b	Interim software for C9800-80/40 platform
C9800-CL-universalk9.17.15.01prd21.SPA.bin	6a1b9a56a81d06b2c428574db293f979	Interim software for C9800-CL platform
CW9800-wlc-universalk9.17.15.01prd21.SPA.bin	646f70dbde4abfe8ef834fa4ae66f682	Interim software for CW9800-H/M platform
C9800-AP-universalk9.17.15.01prd21.zip	c5f6095eff099e37829bd1cf33e1a655	Interim software for C9800 EWC platform

Resolved Caveats

CSCwh56566	9800 manual flow record parameters causing flow monitor to fail and not been able to remove it
CSCwh80060	COS APs connected with 9800 WLC losing Flex WLAN VLAN mapping
CSCwh81071	91xx Country for Radio Slot 0/2 shows Blank or NA
CSCwi16509	Loadbalancer server holding wrong AP IP address and stale AP entries seen
CSCwi22895	WLC Crash due to ReloadReason=Critical process rrm fault on rp_0_0 (rc=134)
CSCwi27380	Media stream feature is not working
CSCwi28382	WLC crash due Keymgmt: Failed to eapol key m1 retransmit failure. Max retries for M1 over
CSCwi55714	Cat9800 WLC Reboot when Handling NMSP TLS Connection
CSCwi56780	The MAB is not initiated unless that the device is deauthenticated
CSCwi69251	C9800-40 // 17.12.02 crashes on Critical process rrm fault on rp_0_0
CSCwi75759	C9800-40 WLC reload due to Critical process wncd fault on rp_0_1 (rc=139)
CSCwi99276	NAC is not in the policy profile configuration when deployed from Prime Infrastructure
CSCwj08367	9800 segmentation fault - Process = IGMPN
CSCwj09698	C9800 Unexpected Reset in wncmgrd with a scaled setup and managed by the Meraki Dashboard
CSCwj25187	Redundancy details not populated in GUI for EWC.
CSCwj26196	WLC crash due Keymgmt: Failed to eapol key m1 retransmit failure. Max retries for M1 over
CSCwj31356	C9800 WLC reboot due to RRM process fault
CSCwj36962	C9800 WLC unexpected cpp_mcplo-ucode restart due to invalid QOS parameters
CSCwj42408	9800 Posturing flow not working while PMF is Optional
CSCwj68763	Enhanced URL missing after Flex AP CAPWAP flap

Americas Headquarters

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2008 Cisco Systems, Inc. All rights reserved. 95134-1706 USA

CSCWj79545	IOS-XE WLC unexpected reboot wncd process reboot due to assertion failed with invalid BSSID
CSCWj86938	9800 Memory leak in scale network with telemetry sending client events to DNAC
CSCWj93153	C9800 Might Reload Unexpectedly due to wncmgrd Process Fault
CSCWk05030	WLC crash due to Critical software exception
CSCWk35891	C9800 WLC crashed after issuing \"clear ap geolocation derivation\"
CSCWk44459	Loadbalancer server holding wrong AP IP address and stale AP entries seen
CSCWh88246	URL Filter not applied after invalid configuration
CSCWi01382	9800 support for -E domain access points in Gabon
CSCWi29216	Unsupported character in description prevents re-sync
CSCWi44211	show run results (trapflags ap noradiocards) are different from restore config
CSCWi47294	WLC changes - Per client rate limit with flex connect local switching APs is not working
CSCWi48980	WLC 9800 local password policy not taking effect as expected for GUI login
CSCWi50732	C9800 VLAN group for static IP client does not work on FlexConnect Central Switching
CSCWi64010	WLC accepts reserved IPv6 mcast addr to be configured as Mobility Multicast Ipv6 address
CSCWi66582	C9800 returns 400 bad request error when uploading backup file with FTP on GUI
CSCWi69093	WLC GUI showing incorrect number of clients attached on AP
CSCWi70760	9800 encrypts ApDnaGlobalCfg token when password encryption aes is config increasing size of toke
CSCWi83124	Dark Mode Display Issue on Catalyst 9800 - Pop ups and Rogue AP Rules Data not visible
CSCWj00465	C9800: Active controller become ActiveRecovery when RP link down on 17.9
CSCWj01446	PIV auth requires additional backslash on the redirection URL for it to work.
CSCWj04177	AP doing 802.1X will fail authentication if password is more than 31 characters
CSCWj15376	Multiple NMSP security protocol problems
CSCWj25110	OIDs bsnAPIfStationCountOnRSSI and bsnAPIfStationCountOnSNR are reporting incorrect values on 9800
CSCWj29406	sh ap summary sort descending client-count command showing wrong client count
CSCWj33376	Incorrect selection of all APs in load balancing, and invalid minimum client count criteria
CSCWj33979	\"show ap summary\" output taking more than 6+ minutes to complete
CSCWj34379	Cat9K Wireless Controller: WNCd Crash when Accessing Crimson Database
CSCWj40202	9800 not sending RADIUS acct msg when client send subsequent assoc req before client is moved to RUN
CSCWj42562	PC Analytics Statistics Not Displayed on GUI
CSCWj60910	RRM message mismatch between WLC9800 and PI report.
CSCWj67158	9800 not sending ADD mobile to AP if CoA is received when client is ip learn for dot1x SSID
CSCWj72370	C9800 Controller use incorrect username for 'show platform' command when login WEB GUI
CSCWj76892	2802 Low downlink speed noticed due to WLC not configuring aggregation schedule parameter correctly.
CSCWj77128	URL Filter Only Allow Letters as First Character
CSCWj83935	9800 show tech X is empty if previous sh tech X term length stop didn't finish before SSH close
CSCWj94201	C9800 crash due to CPUhog, watchdog timeout by IGMPsN process.
CSCWj96620	Syntax errors in CISCO-LWAPP-DOT11-CLIENT-MIB
CSCWj96666	Syntax errors in CISCO-LWAPP-DOT11-MIB
CSCWj97107	Standby does not take the active role after reloading the active controller with \"reload slot X\"
CSCWk02633	RSA keypair in the config when selecting a EC key on the GUI
CSCWk25182	C9800 Password Policy alert while login GUI using tacacs credential after upgrade to 17.14.x
CSCWk28680	C9800-L/CL Unexpected reload due to QFP ucode while updating drop stats

Americas Headquarters

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2008 Cisco Systems, Inc. All rights reserved. 95134-1706 USA

Beta/EFT image is a temporary release delivery of fixes until CCO release is available. Cisco EFT and Betas are covered by Cisco Non-disclosure agreement. **Customers are requested to migrate to next CCO release as soon as it is available.** We request you to drop a note to wnbu-mrbeta@external.cisco.com. Any feedback would be appreciated either via TAC or this alias.

ENGINEERING SPECIAL USE DISCLAIMER

The Engineering Special fix supplied herewith is a Temporary Software Module which has undergone limited testing. This temporary software module is provided “AS-IS” without warranty under the terms of the END USER LICENCE FOR THIS PRODUCT. Please use this software at your own risk. The intention for this code fix is for you to use in your production environment until a released version is available.

This code is supported by the TAC organization. Please report all comments, suggestions, and problems about this code directly to wnbu-escalation@cisco.com. If you are satisfied with the solution, please inform the alias.

Contact wnbu-escalation@cisco.com with any questions.



Americas Headquarters

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2008 Cisco Systems, Inc. All rights reserved. 95134-1706 USA