# **QUICK REFERENCE GUIDE**



# HI520 Universal Process Controller Multiparameter Platform

### Dear Customer,

Thank you for choosing Hanna Instruments.

For more information about Hanna Instruments and our products, visit www.hannainst.com or e-mail us at sales@hannainst.com. For technical support, contact your local Hanna Instruments office or e-mail us at tech@hannainst.com.

Please scan the **QR code** or use the link below to download the user manual.

https://manuals.hannainst.com/HI520



#### Available Models







HI520-0540
5 relays & 4 analog outputs

# **Package Contents**

- HI520
- Cable gland seals (1 set)
- Power cable, 3 m (9.84') long
- · Quick reference quide
- Instrument quality certificate

Note: Save all packing material. Any damaged or defective item must be returned in its original packing material with the supplied accessories.

#### Main Features


- Hanna Instruments smart digital probes
- Modbus RS-485 serial communication protocol
- Independent/sequential channel control
- Flexible function assignment for control, cleaning, Hold relays
- Waterproof IP65 enclosure

### **Safety Precautions**

- Electrical connection must be carried out by specialized personnel only. Read safety manual instructions before connecting to power.
- Do not make electrical connections with device connected to power.
- Do not run other cables through the designated power cable aland.
- Have a disconnect switch installed in the vicinity of the instrument to ensure electrical circuit is de-energized for installation.


# Connecting to Power

- Loosen the four screws, enough for the springs to push them out.
- Grasp the front bezel and swing open to access the two-terminal power supply board.
- Remove the safety cover to access Terminal 1 block (power path).
- Remove the blank plug and thread the cable through the power cable gland.
- Connect the power cable leads to the removable terminal connector marked POWER.
- Follow L (live), PE (ground), N (neutral) lead markings for correct wiring of output leads.
- Carefully put wired terminal connector into place on the board.
- Replace safety cover over Terminal 1.



# **Controller Wiring**

- High voltage connections: POWER, ALARM, REL 1 to REL 5 (relays) are made to the Terminal 1 block.
- Low voltage connections: COMM (RS-485), PROBE1, IN1 and IN2 (digital inputs), A01 to A04 (analog outputs), and PROBE2 are made to the raised Terminal 2 block.
- Follow the positive/negative lead markings to ensure that output leads are wired to the correct position on the main board.





Hanna Instruments is committed to developing and deploying digital solutions with a positive impact on the environment and climate.

All Hanna instruments conform to the CE European Directives, and our production facilities are ISO 9001 certified. HIS20 is warranted for a period of two years against defects in workmanship and materials when used for its intended purpose and maintained according to instructions.

Please retain for future use

QR520 07/25



# **Probe Wiring**

- 1. Ensure the controller is not powered.
- 2. Run the probe cable through the conduit opening.
- Connect probe leads to the removable terminal connector marked PROBE1 or PROBE2.
  - Follow the lead markings (positive/negative) for correct wiring.
- 4. Carefully put the wired terminal connector into place on the board.
- 5. Position excess cable through the cable gland before tightening the nut.
- Remove the ground screw and hardware located below the PROBE1 or PROBE2 connector. Attach the ground lead (
  ).

### Probe cabling color code

Tone raning roloi rode									
Probe	Marking	Attached Cable	Patch Cable	Function					
90	_	GREEN	BLACK	0 V					
٦,	В	WHITE	WHITE	RS485 D —					
pH, ORP, EC, DO	A	YELLOW	BLUE	RS485 D+					
	+	BROWN	RED	5 V					
	4	GREEN-YELLOW	GREEN-YELLOW	PROTECTIVE GROUND					
(	_	GREEN							
bidity (TU)	В	WHITE	Note:						
	A	YELLOW	Ensure wiring i	egulations are correctly					
9	+	BROWN		r controller unit is nart					


of a larger industrial installation.

#### **Accessories**

ዾ፟

Installation accessories can be ordered from your local sales office.

GREEN-YELLOW











HI510-02 Wall mount

HI510-03 Pipe mount

Scan the QR codes to download probes user manuals.



pН









# Probe Series and Configurations

HII	0	χ	χ	]_	Υ	8	Z	Z		pН	& Temperature	
ΧХ	v 06 PTFE junction											
۸۸	16	Ceramic junction										
	Glass sensor				or	.⊑		рΗ	rar	nge	Temperature range	
	1	Low temperature		ire	ching P	0.0	00 to	12	.00 pH	-5.0 to 80.0 °C (23.0 to 176.0 °F)		
Y	3	te	Hi mpe	gh eratu	re	Fitanium Matching Pin	0.0	00 to	14	.00 pH	0.0 to 100.0 °C (32.0 to 212.0 °F)	
	4	Fluoride resistant		Titani	0.0	)0 to	10	).00 pH	-5.0 to 60.0 °C (23.0 to 140.0 °F)			

HI2	02	X	X	-	Υ	8	Z	Z		ORP	% Temperature		
ΧХ	04	04 PTFE junction											
۸۸	14	4 Ceramic junction											
		Sensor type					m	V rar	nge	)	Temperature range		
Y	1	PI	Platinum Gold			+ 2000 mV					−5.0 to 100.0 °C		
	2	Go					± 2000 mv			IV	(23.0 to 212.0 °F)		

HI7630 - Y 8 Z				Z	Z		EC & Temperature
γ	2	Two-electrode cell conductivity, SS AISI 316, cell constant k ≈ 0.1/cm				0.0 34	000 μS/cm to 30.00 mS/cm 000 mg/L to 15.00 g/L (TDS factor 0.5) ! Ω • cm to 99.99 MΩ • cm uture 0.0 to 50.0 °C (32.0 to 122.0 °F)
ı		Four-rir conducti platinum cell cons k ≈ 1.0	vity, on gl tant	ass,	TDS RES Seav	0. 1. /ate	0 μS/cm to 999.9 mS/cm 0 mg/L to 400.0 g/L (TDS factor 0.5) 00 Ω • cm to 9.99 MΩ • cm or Salinity 400.0 %NaCl, 42 psu, 80 ppt ture 0.0 to 100.0 °C (32.0 to 212.0 °F)

HI7640 - 1	8	Z	Z	Galvanic DO & Temperature
Galvanic DO ser	nsor	Satu	ration	ion 0.00 to 50.00 mg/L (ppm) 0.0 to 500.0 % re —5.0 to 50.0 °C (23.0 to 122.0 °F)

	remperatore	-5.0 10 50.0 C (25.0 10 122.0 F)
HI7640 - 5 8	ZZ	Optical DO & Temperature
	Concentration	0.00 to 50.00 mg/L (ppm)
Optical DO sensor	Saturation	0.0 to 500.0 %

Temperature −5.0 to 50.0 °C (23.0 to 122.0 °F)

HI7660 - 2 8	ZZ	Low	Range Turbidity
	FNU	range	Temperature range
Turbidity sensor	0.000 to 4. 0.00 to 40. 0.0 to 400.	00 FNU	−5 to 50 °C (23 to 122 °F)

8	Smart probe, with RS-485 connection
ZZ	00 supplied with DIN connector (without cable) 05, 10, 15, 25, 50 fixed cable length (in meters) 02, 05, 10 fixed cable length (in meters) > HI7660-28 TU probe only