

## **UNI-T UT366A Digital Manometer User Manual**

Home » UNI-T » UNI-T UT366A Digital Manometer User Manual



P/N:110401110446X UT366A Digital Manometer UserManual

#### **Contents**

- 1 Introduction
- 2 Accessories
- 3 Specifications
- **4 Product Structure**
- **5 Buttons**
- **6 Operation**
- 7 Probe Indicator Lights
- 8 Maintenance and Repair
- 9 Troubleshooting
- 10 Documents /

Resources

11 Related Posts

#### Introduction

UT366A is an instrument for measuring gauge pressure and differential pressure. UT366A can measure P1/P2 pressure independently with LED indication. It can be widely used in industrial manufacturing, HVAC, plumbing and other industries. Combined with an optional pitot tube, UT366A can also measure wind speed.

#### **Accessories**

1.	Digital manometer	1pcs
2.	Hose	1pcs
3	AAA batteries	3ncs

4. User manual	1pcs
5. Carrying bag	1pcs
6 Magnetic hook	1ncs

#### **Specifications**

• Units: kPa, mbar, bar, psi, mmHg, inH2O, inHg, Ozin2, kgcm2, ftH2O, mmH2O, hPa, m/s, fpm

• Pitot tube coefficient: 1

• Range:

0.00—±15.00 kPa	0.00—±34.80 Ozin2
0.0—±150.0 mbar	0.000-±0.152 kgcm2
0.000—±0.150 bar	0.000— ± 5.026 ftH2O
0.000—±2.175 psi	0.0—±1531 mmH2O
0.0—±112.5 mmHg	0.0—±150.0 hPa
0.00—±60.29 inH2O	0.0-19999.9 m/s
0.000—±4.429 inHg	0-199999 fpm

#### · Resolution:

0.01 kPa	u.01 Ozin2
0.1 mbar	0.001 kgcm2
0.001 bar	0.001 ftH2O
0.001 psi	1mmH20
0.1 mmHg	0.1 hPa
0.01 inH20	0.1 m/s
0.001 inHg	1 fpm

- Accuracy: ±0.5% FS@25°C
- Unit memory: When the product is turned on, its pressure unit defaults to the unit when it was turned off last time.
- Auto power off: When the meter enables this function, it will power off automatically if no button press occurs for 5 minutes.
- Low battery indication: When the battery power is less than 3.7V, a low battery indicator will appear.
- Batteries: AAA 1.5V\* 3pcs
- Power consumption:

Power off: < 10uA;

Power on: < 10mA;

Power on and backlight on: < 15mA;

Power on and one indicator light on: < 15mA;

Power on and two indicator lights on < 20mA; Power on, backlight and one indicator light on:

< 20mA

Power on, backlight and two indicator lights on:

< 25nnA.

#### · Battery life:

Power on: > 50h;

Power on and backlight on: > 30h;

Power on and one indicator light on: > 30h;

Power on and two indicator lights on: > 25h;


Power on, backlight and one indicator light on> 25h;

Power on, backlight, and two indicator lights on> 20h.

#### • Environmental requirements:

Operating: 0-50°C C85%RH; storage: 10-60°C -75(YoRH.

#### **Product Structure**




#### **Buttons**

#### 1. Function

	Long press	Short press	Short press in the menu
HOLD	Power on/off	Data hold	_
UNIT ZERO	Data zero	Unit conversion	+
P1/P2	Tum on/off probe indicator lights	P1/P2 selection	Select
MODE :	Turn on/ off the backlight	Max/Min/Avg	Enter

#### 2. Button combination




### Operation


Turn on/off the meter:
HOLD
Long press Long press
Data hold:
Short press HOLD
Unit conversion:
UNIT
Short press to switch between selectable units: kPa, mbar, bar, psi, mmHg, inH 20, inHg, Ozin2, kgcm2,
ftH2 0, mmH2O, hPa, m/s ,fpm.
Among them, m/s and fpm are wind speed units. To switch between these two units, short press
and zero enter the setting menu, the press is to enter the wind speed unit setting
Unit
mode (as shown in the figure), and then short press to switch between m/s and fpm. Press
HOLD UNIT
and zero again to exit the setting menu. Notes: Wind speed needs to be measured with a pitot tube.
Please purchase it separately if necessary.
Data zero:
The meter can start to operate about 5 seconds after being turned on. Before the hose is connected, if the value
UNIT ZERO to part of the servery is got 0, years good to leave your ZERO to part the date. Did and DO will be present at the
displayed on the screen is not 0, users need to long pres to zero the data. P1 and P2 will be zeroed at the
same time.  Switch channel:
The default channel when turning on the meter is P1-P2 (the difference between P1 and P2 channels). Short
press P1/P2 to step through P1-P2 > P1-P2/P1 > P1-P2/P2 > P1/P2.
Turn on/off probe indicator lights:
Long press P1/P2
Max/Min/Avg selection:
MODE
Short press
Turn on/off the backlight:
Long press
Long press — **
Turn on/off the auto power-off function:

Short press and will show on the screen. The meter will power off automatically if no button press occurs for 5 minutes.

#### Air density setting:



#### **Probe Indicator Lights**




**Note:** P1+ means the air pressure value is positive (the indicator light is green). P1- means the air pressure value is negative (the indicator light is red). Long press the "P1/P2" button to turn on/off the indicator lights. In the P1-P2 channel, the indicator lights are off by default, and cannot be turned on.

#### **Maintenance and Repair**

· Replace batteries:

When the icon is displayed on the screen, follow the steps below to replace the batteries.

- 1. Remove the battery cover.
- 2. Take out the old batteries and put in three new 1.5V AAA batteries. Pay attention to the battery polarity.
- 3. Close the battery cover.



- Clean the housing: Clean the housing with a damp cloth. Please do not use corrosive detergents or solutions for cleaning in that they are corrosive to the housing, especially to the LCD.
- Please take out the batteries if the meter is not used for a long time to prevent battery leakage from seriously damaging the meter.
- Do not disassemble this meter or change the internal.

#### **Troubleshooting**

- "OL or -OL": The reading exceeds the measurement range. Please measure within the specified range
- "Lo": The wind speed reading is too low. Check whether the two ends of the pitot tube are connected reversely.
- "2 flashes when measuring wind speed: The data should be zeroed. Otherwise there will be measurement errors.
- The wind speed unit flashes when pressing the "P1/P2" button: The P1-P2 channel is used for wind speed measurement by default, and cannot be changed.
- "Err:Ambient temperature compensation NTC has errors.



#### UNI-TREND TECHNOLOGY (CHINA) CO., LTD.

No.6, Gong Ye Bei 1st Road, Songshan Lake National High-Tech Industrial Development Zone, Dongguan City, Guangdong Province, China



# UNI-T UT366A Digital Manometer [pdf] User Manual UT366A, Digital Manometer, UT366A Digital Manometer

Manuals+, home

privacy