# TECH TIPS

Subaru Service and Technical Support Line Newsletter

## Article Locator Index

SUBARU

SUBARU SERVICE

TECHTIPS NEWSLETTER LOCATOR INDEX
UPDATED THROUGH AUGUST 2022

***This list is most efficient when searched using CTRL+F***

## TABLE OF CONTENTS

*Click title below to jump to section*


01 - General Information
02 - Engine
03 - Drive Train-Transaxle
04 - Steering
05 - Suspension-Wheels & Tires
06 - Brakes
07 - Electrical
08 - Instrument & Controls
09 - Cooling, Fuel, & Exhaust System
10 - Heating Ventilation & A/C Systems
11 - Emission Systems
12 - Body, Glass, & Upholstery
13 - Paint
14 - Special Tools
15 - Accessories
16 - Automatic Transmission
17 - SRS Air Bag
18 - Service Manual Corrections
19 - Special Edition

## 01-General Information

Legacy Knocking Noise, Rear of Vehicle When Driven Over Bumps ..... 07/91
Justy Fuel Injection System Service Manual Supplement Section 2-7 ..... 08/91
In-transit Spark Plug Fouling Protection ..... 09/91
Kats Wax Transit Coating Remover Precautions ..... 10/91
Lemon Law Responsibilities ..... 11/91
PDI Coolant Check - All Models ..... 11/91
Parts Related Inquiries ..... 02/92
Legacy and Loyale Normal Operating Characteristics ..... 04/92
All SPI Models Throttle Body Gasket Replacement ..... 05/92
Towing a Front Wheel Drive 5-Speed Legacy ..... 06/92
Location of Engine, Transmission, and Production Date Information ..... 11/92
Ordering “D” Check Manuals ..... 02/93
Odometer Labels ..... 02/93
Impreza Side Guard Moldings ..... 03/93
Impreza Key Codes ..... 05/93
Impreza Side Moldings ..... 05/93
1993MY SVX Model Code PKB “LSL” ..... 06/93
All Models with PDI Connector for Storage ..... 06/93
Diagnostic Trouble Codes ..... 07/93
Flat Towing Subaru Vehicles ..... 08/93
All Models Lock Cylinder Key Coding ..... 09/93
Warranty Full History Inspection ..... 09/93
Towing ..... 10/93
Legacy Front Washer Nozzle Clogged ..... 10/93
All Models with All Wheel Drive Systems, Use of the Space Saver Spare Tire or T-Spare Tire ..... 11/93
All Models Equipped with Knock Sensors ..... 11/93
Tool Ordering Procedures ..... 12/93
October Update Revision - Poor Radio Reception AM or FM ..... 12/93
1993MY Legacy and Impreza ECU Operation with Select Monitor ..... 01/94
Diagnosis of Noises Over the Phone ..... 02/94
Justy Diagnostics ..... 03/94
Recall Campaign Announcement – WZG-55 ..... 05/94
Replacement of Ignition Relays ..... 05/94
Repair Information ..... 05/94
Requests to Return Parts for Inspection ..... 05/94
Use of Trouble Code Diagnostic Trees in Service Manuals ..... 05/94
1994MY Impreza Equipment Changes ..... 06/94
Legacy, Impreza, and SVX Service Manual Supplements ..... 06/94
Select Monitor Cartridge-‘95MY Impreza ..... 10/94
1995MY Legacy Outback Wheel Cover Specifications ..... 11/94
1995MY Legacy Service Manual ..... 12/94
1995MY Impreza Select Monitor Update ..... 12/94
Parts Questions ..... 01/95
Legacy Service Manual Supplement ..... 01/95
Oil Leaks ..... 01/95
Obtaining Service Bulletins ..... 03/95
Diagnosing Noises Over the Phone ..... 03/95
Helpline Diagnostic Information ..... 05/95
Physically Damaged Warranty Returned Parts ..... 05/95
Kats Wax Removal Tips ..... 06/95

Thinking, the Service Manual, and the use of Diagnostic Flow Charts....06/95
Vehicle Model Year....09/95
1996MY Subaru Legacy Select Monitor Cartridge....10/95
Select Monitor Information Update....11/95
Cooler Weather and Drivability....11/95
Technical Assistance and the CDS 800 Phone Line....12/95
Part Numbers for Electrical Condition Reports and Quality Monitoring Reports....12/95
Training Test Answers....01/96
Monroney Label Mismatches....01/96
Technical Helpline Updates/Service Bulletins....02/96
Impreza Key Code Location....02/96
1995MY & 1996MY Power Antenna Operation....02/96
Service Bulletin Volume 17/Unlisted Bulletins....04/96
Air Conditioning Reminder....05/96
Technical Service Helpline Efficiency....05/96
1996MY Subaru Legacy VIN Change....06/96
Location of Engine, Transmission and Production Date Information....06/96
Interactive Helpline Updates....07/96
1997MY Subaru Legacy-Retrieval of OBD-II Codes without '97 Select Monitor Cartridge....08/96
Additional 1996MY Subaru Legacy VIN Change Information....09/96
"But, Its New....."....09/96
1997MY Legacy - Information for You....09/96
Returning Your Calls....10/96
Cooler Weather and Driveability....11/96
Towing Vehicles behind Motor Home....02/97
Frozen Wiper Blades....02/97
Technical Helpline Updates/Service Bulletins....03/97
State I/M 240 Emission Testing and Subaru AWD Vehicles....04/97
New Quality Monitoring Report (QMR) Form....05/97
1998 Subaru Forester Facts....07/97
New Subaru Select Monitor....07/97
1997MY Subaru Legacy Service Manual Supplement Volume 7....08/97
1998MY Subaru Forester....09/97
1998MY Subaru Key Codes....09/97
1998MY Forester Flat Towing....10/97
Customer Particulars....10/97
Subaru Forester PDI Connectors....11/97
Holiday Schedule For 1998....01/98
Marking Messages "Urgent" on the Helpline Answering Machine....01/98
Parts Collection Cancellation....01/98
Technical Helpline Update Changes....02/98
New Name.....Same Dedicated Service....02/98
Technical Support Line Changes....02/98
30th Anniversary/WRC Emblems....03/98
1998MY Forester Key Blanks....03/98
State Emission Testing....07/98
Subaru AWD Vehicles Are Exempt from Two Wheel Dynometer Emission Testing....07/98
Subaru Technical Support Line and Independent Repair Shops....07/98
1999MY.... What's New....08/98
We Need to Know....08/98
The Support Line and Parts Questions....08/98
Cooler Weather and Drivability....10/98

We Get Letters ..... 01/99
Magnetic Tip Screwdriver Caution ..... 01/99
Interior Trim Tool ..... 01/99
Other Protection Ideas ..... 01/99
Dash Noise ..... 01/99
Technical Service Support Efficiency ..... 02/99
Location of Data Information for Engine, Trans., and Production Date ..... 03/99
Quality Monitoring Reports (QMRs) and You ..... 03/99
We Get Letters – Continued ..... 04/99
Parts Replacement ..... 04/99
Reference Materials ..... 05/99
Back to Basics – One More Time ..... 05/99
Support Line Case Numbers ..... 07/99
2000MY Key Blanks ..... 07/99
Y2K Subaru Legacy ..... 08/99
Support Line Answering Machine ..... 10/99
New Area Code ..... 11/99
Vehicle Servicing ..... 4/00
Subaru Warranty Coverage Changes for 2001MY ..... 05/00
2001MY Forester Owner's Manual Correction ..... 07/00
Suggested Measuring Device ..... 07/00
Service Bulletin 12-68-00 ..... 08/00
Quality Monitoring Reports ..... 08/00
Required Fluid Use for Warranty Repairs ..... 08/00
Cooler Weather and Drivability ..... 10/00
Impreza 2.5RS Modifications ..... 11/00
Quality Advice Forms for 2001 H6 Outback ..... 11/00
Expanded Support Line Hours ..... 01/01
Parts Collection Center – Additional Location ..... 01/01
AYES Program Participation ..... 02/01
Towing Vehicles behind Motor Homes ..... 02/01
Service Publications New 1-800 Number ..... 02/01
Bulk Fluid Usage ..... 02/01
Ordering Technician Patches ..... 03/01
Answering Machine Reminder ..... 03/01
Key Codes – A Reminder ..... 05/01
2002MY Impreza Sedan Valet Key Function ..... 09/01
Service Manual Applicability ..... 11/01
Special Edition: 2003 Forester Accessory Installation ..... 07/02
Contacting the Technical Support Line ..... 09-10/02
Information Requests ..... 09-10/02
2003 Baja Owners Manual Supplement ..... 03/03
www.Subarunet.com Reminder ..... 03/03
Faded or Ghosted Fluke Original 80 Series Display ..... 04/03
Modifications to Vehicles ..... 07/03
Electronic QMR ..... 07/03
SOA Publication MSA5B0403A ..... 08/03
Clamp-on Racks and Wind Noise ..... 01/04
Calling the Technical Support Line ..... 03/04
Service Manual Correction Labels ..... 05/04
2005MY Legacy/Outback: Updated PDI Check Items and Notes ..... 07/04
Product Improvements ..... 08/04

Subarunet and Service Technicians....10/04
Updated Reprogramming Information....11/04
Cold Weather and Drivability....11/04
Enhanced EQMR....11/04
Premium Ownership Delivery....12/04
Technical Service Bulletins: A Recent List....03/05
Technical Service Bulletins: A Recent List....04/05
Tips from the Techs....04/05
Technical Service Bulletins/Programs....05/05
Technical Service Bulletins, TechTIPS, and Other Publications....06/05
2006MY Mechanism and Function Service Manual....06/05
Recently Published Service Bulletins....06/05
Latest Service Bulletins Released....07/05
STi – Towing Behind Motor Homes....07/05
Latest Service Bulletins Released....08/05
Subaru Warranty Wizard Update....09/05
TechLine Pre-Call Worksheets....09/05
Latest Service Bulletins Released....09/05
Latest Service Bulletins Released....10/05
In Case You Forgot....10/05
Contacting the Technical Support Line....11/05
Come On Guys....11/05
Latest Service Bulletins Released....11/05
2006MY Impreza Indicator Lights....11/05
Technical HelpLine Efficiency....11/05
Latest Service Bulletins Released....12/05
Calling the TechLine…."Can You Hear Me Now?"....12/05
Latest Service Bulletins Released....01/06
Latest Service Bulletins Released....03/06
FYI – Replacement of the Neutral Switch on a 6MT Vehicle....03/06
Service Information Availability on STIS....06/06
Techline Closing....06/06
Techline Pre-Call Worksheets....06/06
Immobilizer Codes & the Techline....06/06
Vehicle Repair Escalation Process....06/06
Calling the Techline….  Can You Hear Me Now???....07/06
2007 Subaru B9 Tribeca Introduction TRB....08/06
Quickie "FYI" TIPS....08/06
Latest SOA Service Documents Released....08/06
Latest SOA Service Documents Released....09/06
Subaru Chemical Information....10/06
Cold Weather- Here We Go Again!....10/06
Latest SOA Service Documents Released....10/06
Rear Differential Oil....11/06
Quick Tip: "No Start" Complaint....11/06
Power Steering Fluid Usage....11/06
New Tech TIPS Editor: Don Bangs....12/06
Quick TIP: Nox Rust....12/06
Clarification of the "Valet Key" and "Master Key" Immobilizer Type....12/06
Automatic Transmission Fluid for All 5EAT and 4EAT Transmissions....12/06
New Techline Representative....01/07
A "Back To Basics" Reminder....01/07

Quick TIPS: Important Items to Note ..... 02/07
From The “Clarifications Department” ..... 03/07
Quick TIP – Forester Spare Tire Cover ..... 03/07
Techline Survey Results ..... 04/07
Gear Oil Specification Differences ..... 06/07
2007 U.S. National Technician Competition ..... 07/07
Latest Service Bulletins Released ..... 07/07
SSM III, Reprogramming & You ..... 08/07
New 2008 M/Y Service Manuals on STIS ..... 11&12/07
U.S National and World Technician Troubleshooting Competitions ..... 12/07
H-6 Engine Smoke from Exhaust on Start-Up ..... 08/08
Sending SSM-III Files ..... 08/08
Oil Filter Wrenches ..... 12/08
Calling the Techline: A Reminder about Cell Phones ..... 12/08
Cold Weather Reminders ..... 12/08
Incentive Program for Technician TIPS Suggestions ..... 01/09
2009 M/Y Forester & Impreza Protective Wheel Film ..... 01/09
2010 M/Y Legacy / Outback Preliminary Information ..... 05/09
Use of Synthetic / Semi-Synthetic Engine Oils ..... 05/09
2008-09 M/Y Impreza, Dim Headlights and / or Erratic Outside Temperature Display ..... 06/09
Help Us to Help You ..... 07/09
2010 M/Y Legacy & Outback Reporting Requirements ..... 07/09
Subarunet & Subaru “SMART” System Login Information ..... 09/09
Cell Phones, Air Tools & the Techline ..... 09/09
SSMIII Error Codes ..... 11/09
EQMR Authorization Requests… A Reminder ..... 01/10
First Annual Subaru / ASE Master Automotive Technician of the Year ..... 02/10
Techline Case Follow-Up and Call-In Tips ..... 04/10
EQMR’s and Photos ..... 05/10
Subaru / ASE Master Automobile Technician of the Year – 2010 ..... 09/10
2nd Annual Subaru / ASE Master Automobile Technician of the Year Awards Announced ..... 10/10
New 2011 MY Forester Quality Reporting Information ..... 11/10
2011 Factory-Fill Synthetic Oil and Maintenance Information ..... 11/10
Does Your Service Department Have A “What’s New” Bulletin Board? ..... 02/11
Troubleshooting Guides - A Reminder ..... 04/11
“D-Check” Connector Locations ..... 05/11
Revised Service Bulletins ..... 06/11
Calling the Techline – Questions You Should Be Ready For ..... 07/11
Use of Silicone Spray Precautions ..... 07/11
2012 Impreza PDI Fuse Procedure ..... 09/11
Is This Clip Important? ..... 10/11
Change to Oil Fill Cap of FB Engine ..... 11/11
2012 M/Y Oil Change Interval Information ..... 11/11
Turning Off Blinking “Check Engine” light on 2012 MY Vehicles ..... 12/11
Valve Clearance Checking Procedures, A Reminder ..... 01/12
Yes, Another Sales Record Year for Subaru ..... 02/12
Techline Case Follow-Up ..... 02/12
Special Automatic Transmission Fluid for the New BRZ ..... 05/12
Calibration Identification Numbers ..... 05/12
Techline Staffing changes ..... 06/12
2013 BRZ PDI Procedure Information ..... 06/12
2013 Legacy, Outback and BRZ Launch-Your Help Is Needed ..... 07/12

Techline Staffing Changes ..... 09/12
Subaru ASE Master Tech Of The Year 2012 ..... 11/12
Addition To PDI Procedure For Impreza And Crosstrek ..... 12/12
Additional Tie Down Plug for 12-13 Impreza Models ..... 01/13
Thanks to You ..... 02/13
QMR Of The Month ..... 02/13
QMR Of The Month Winner ..... 03/13
New Model Launch Activities ..... 03/13
Information You Should Always Have When Calling Tech Line ..... 04/13
QMR Of The Month Winner ..... 04/13
QMR Of The Month Winner ..... 05/13
Recommended Materials Update ..... 05/13
QMR Of The Month Winner ..... 06/13
Authorization Requests ..... 06/13
2013 National Technician Competition ..... 08/13
QMR of the Month ..... 08/13
Quality Monitoring Reports ..... 08/13
QMR of the Month ..... 09/13
Subaru-ASE Master Auto Technician of the year ..... 09/13
Towing Subaru Vehicles-Revisited ..... 09/13
QMR of the Month ..... 10/13
New Tech line Fax Number and Pre-Call Worksheets ..... 10/13
Friday November 29th 2013-Tech line open ..... 10/13
Clarification on Towing ..... 10/13
QMR of the Month ..... 11/13
Don't Forget to check the basics when diagnosing Drivability Complaints ..... 11/13
Troubleshooting Guides on STIS-Reminder ..... 11/13
BUI replacement and Key's ..... 11/13
QMR of the Month ..... 12/13
Fourth Bi-Annual Subaru international tech competition awards ..... 12/13
Subaru/ASE Master Tech of the Year ..... 12/13
2014 XV-Crosstrek Hybrid Launch-Your Help Is needed ..... 12/13
New Tech line hours of operation ..... 12/13
QMR of the Month ..... 01/14
14Crosstrek Hybrid Launch Reminder ..... 01/14
QMR of the Month ..... 02/14
Authorization Request (AR) for Paint and Glass over 500 ..... 02/14
2014 Hybrid Launch-Your Help is Needed ..... 02/14
QMR of the Month ..... 03/14
Tech line new hours of Operation ..... 03/14
2015 WRX and WRX STI Launch-Your help is Needed ..... 03/14
QMR of the Month ..... 04/14
New Tech line Pre-Call Worksheets ..... 04/14
Tech line Case Follow up-Revisited ..... 04/14
Authorization Request Pictures ..... 04/14
QMR of the Month ..... 05/14
Tech line case follow up-Revisited ..... 05/14
QMR of the Month ..... 06/14
15MY Legacy and Outback Transit Fuse Information ..... 06/14
QMR of the Month ..... 07/14
2015 Legacy and Outback Launch Team Activity-Your Help is Needed ..... 07/14
New Subaru Oil Change Reference Cards ..... 07/14

2015 Legacy and Outback Fujitsu 10 Audio and Audio/Navigation Systems ..... 07/14
QMR of the Month ..... 08/14
Change to Spare Tire Retaining Bolt ..... 08/14
QMR of the Month ..... 09/14
Locating Flash write Reprogramming Files for 2015 WRX Models ..... 09/14
Calling the Tech line for Assistance ..... 09/14
QMR of the Month ..... 10/14
5th Annual Subaru Technician Competition ..... 10/14
QMR of the Month ..... 11/14
Interior Rear View Mirror Separation ..... 11/14
QMR of the Month ..... 12/14
Subaru of America's ASE Master Tech of the Year ..... 12/14
QMR of the Month ..... 01/15
Escalation Process What, Why, and How ..... 01/15
QMR Reporting, Do's and Don'ts ..... 01/15
No Crank Condition on Push-Button Start-Equipped Model's ..... 01/15
Techline Case Follow Up ..... 01/15
QMR of the Month ..... 02/15
Reminder: Sending Saved Freeze Frame (FFD) and SSM Data Files ..... 02/15
New Product Announcement (SOA868V9175) Silicone Gasket Remover ..... 02/15
Exciting Update to the "QMR of the Month" Award Program ..... 02/15
QMR of the Month ..... 03/15
Techline Phone System "Courtesy Call Back Feature" ..... 03/15
QMR of the Month ..... 04/15
QMR of the Month Award Presentation ..... 04/15
Calling the Tech line Revisited ..... 04/15
QMR of the Month ..... 05/15
New Required Detail Fields Established for Claims Submission ..... 05/15
Explanation of New Required Fields in Quality Monitoring Report (QMR) ..... 05/15
QMR of the Month Award Presentation ..... 05/15
QMR of the Month ..... 06/15
Authorization Requests/Better Pictures Requested ..... 06/15
Combination Meter and BIU shipments to SOA ..... 06/15
QMR of the Month ..... 07/15
QMR of the Month Award Presentation ..... 07/15
Subaru Oil Consumption ..... 07/15
QMR of the Month ..... 08/15
Technician Submission of the Month ..... 08/15
EyeSight Charts ..... 08/15
2016 Forester Service Manual-The next Generation ..... 08/15
QMR of the Month ..... 09/15
QMR of the Month Award Presentation ..... 09/15
CPO procedure for turbocharged Subaru vehicles ..... 09/15
Understanding DTC's and how to proceed properly with repairs ..... 09/15
QMR of the Month ..... 10/15
QMR of the Month Award Presentation ..... 10/15
Remanufactured Transmission Replacements ..... 10/15
2015 Technician ASCENT Program-Important Enhancements ..... 10/15
QMR of the Month ..... 11/15
QMR of the Month Award Presentation ..... 11/15
QMR of the Month ..... 12/15
QMR of the Month Award Presentation ..... 12/15

Subaru World Technician Competition ..... 12/15
Subaru Technical Training-Gaming Survey ..... 12/15
QMR of the Month ..... 01/16
QMR of the Month Award Presentation ..... 01/16
Pre-cut Keys ..... 01/16
2016 Technical Training Curriculum Planning Workshops ..... 01/16
Fujitsu (F-10) Map Information ..... 01/16
Towing Subaru Vehicles ..... 01/16
The New and Improved QMR of the Month Program ..... 01/16
QMR of the Month ..... 02/16
QMR of the Month Award Presentation ..... 02/16
QMR of the Month ..... 03/16
QMR of the Month Award Presentation ..... 03/16
QMR of the Month ..... 04/16
QMR of the Month Award Presentation ..... 04/16
Subaru-U Announcement ..... 04/16
Saving and Printing Freeze Frame Data ..... 04/16
Changes to Subaru-Net Links ..... 04/16
QMR of the Month ..... 05/16
QMR of the Month Award Presentation ..... 05/16
American National Technician Competition ..... 05/16
Subaru-U ..... 05/16
Stickers on the Windshield ..... 05/16
QMR of the Month ..... 06/16
QMR of the Month Award Presentation ..... 06/16
Subaru-U ..... 06/16
New STIS User's ..... 12/16
Subaru-U ..... 01/17
QMR of the Month ..... 01/17
QMR of the Month Award Presentation ..... 01/17
Subaru-U ..... 02/17
QMR of the Month ..... 02/17
QMR of the Month Award Presentation ..... 02/17
Update to STIS ..... 02/17
QMR of the Month ..... 03/17
Subaru-U ..... 03/17
QMR of the Month ..... 04/17
QMR of the Month Award Presentation ..... 04/17
Subaru-U ..... 04/17
Locating Tech Tips ..... 04/17
CPO Procedure for Turbocharged Subaru Vehicles ..... 04/17
Technicians: What Is Your Role in Product Quality? ..... 04/17
Lost keys? Contact the Subaru Techline ..... 05/17
Application chart for Immobilizer ..... 06/17
DCM and ECM swapping ..... 08/17
Authorization Requests ..... 08/17
CPO Procedure ..... 08/17
Calling the Techline Revisited ..... 08/17
Lost Keys? + Immobilizer Chart ..... 09/17
Understanding DTC's and How to Proceed Properly with Repairs ..... 09/17
Requesting Techline callback's ..... 09/17
The Subaru Parts Collection Center ..... 09/17

The Key to the Highway....11/17
Following the Service Manual for Repairs....11/17
WQK-47 Equipment Cleaning Procedure....11/17
Authorization Requests (AR) for Paint and Glass Over $500....12/17
CPO Procedure for Turbocharged Subaru Vehicles....12/17
Calling TechLine Revisited....12/17
QMR of the Month Program Enhancement....01/18
Reviewing Data Files....01/18
Calling the TechLine Revisited....02/18
Locating TechTIPS....02/18
Understanding Power Supply....02/18
Body Plug Relocation....02/18
Calling Subaru TechLine....04/18
Icy Road Warning Indicator Operation....04/18
Clearing Trouble Codes....05/18
Subaru Diagnostics....05/18
2019MY Ascent Owner's Manual Utilization....SE 05/18
Understanding Readiness Codes....06/18
Why Was That Part Replaced?....06/18
System Owner Manuals....07/18
Understanding DTCs and How to Proceed Properly with Repairs....07/18
Stickers on the Windshield....09/18
Authorization Requests (AR) for Paint and Glass over $500....09/18
QMR of the Month....10/18
2019MY Forester Quality Monitoring Team New Model Launch....10/18
2019MY Forester: Auto Start-Stop and Driver Monitor System Diagnostic Information....10/18
The Importance of Searching for TSBs and TechTips....12/18
QMR of the Month....01/19
Subaru Technicians Honored at ASE Annual Meeting....01/19
TechLine Case Follow Up....01/19
The Radio Keeps Playing and a "Turn Engine Off Before Exiting" Message Appears – Why?....01/19
QMR of the Month....02/19
2019 National Training Competition....02/19
QMR of the Month – Trip Winner Announcement....SE 02/19
QMR of the Month....03/19
7th Annual National Technician Competition Conclusion....SE 03/19
QMR of the Month – Trip Winner Announcement....SE 03/19
QMR of the Month....04/19
Understanding Customer's Concern....04/19
QMR of the Month....05/19
Use of Silicone Spray Precautions....05/19
Brake Lamp Switch Replacement Web Based Training....05/19
QMR of the Month....06/19
Understanding DTCs and How to Proceed Properly with Repairs....06/19
CPO Procedure for Turbocharged Subaru Vehicles....06/19
QMR of the Month....07/19
G Type, H Type, and I Type Immobilizer Registration....07/19
Important Battery Sensor Procedures – 2019MY Crosstrek Plug-In Hybrid (PHEV) Model....07/19
Melting Plastic Parts....07/19
QMR of the Month....08/19
Helpline Diagnostic Information....08/19

QMR of the Month ..... 09/19
Subaru Select Monitor (SM4) Unresponsive When Connecting to Some 2020MY Vehicles ..... 09/19
QMR of the Month ..... 10/19
QMR of the Month ..... 11/19
Authorization Request Pictures ..... 11/19
QMR of the Month ..... 12/19
Calling the Techline Revisited ..... 12/19
Hints for Searching Separate Publications with Online Reference ..... 01/20
Application Chart for Immobilizer System ..... 01/20
Subaru National Technician Competition Selection Announcement ..... 03/20
Disinfecting Vehicles ..... 04/20
CPO Procedure for Turbocharged Subaru Vehicles ..... 04/20
Authorization Requests (AR) for Paint and Glass over $500.00 ..... 04/20
Lost Keys? Contact the Subaru Techline ..... 05/20
Techline Case Follow Up ..... 06/20
New Claims System Coming June 8th – Things to Know for Authorization Requests ..... 06/20
Cell Phones, Air Tools and the Techline ..... 08/20
Calling The Techline Revisited ..... 09/20
Sending email to Techline ..... 09/20
Subaru Express Service – Low-Touch Best Practices for Technicians ..... 10/20
Oil Capacity ..... 10/20
CPO Procedure for Turbocharged Subaru Vehicles ..... 10/20
Techline Staffing Changes ..... 01/21
Special Edition: Escalation Process What, Why, and How ..... 01/21
Combination Meter and BIU shipments to SOA ..... 02/21
Lost Keys? Contact the Subaru Techline ..... 03/21
Dash Camera Etiquette – Behave like you're being watched ..... 04/21
Understand DTCs and How to Proceed Properly with Repairs ..... 05/21
Do Not Print Technical Service Bulletins Reminder ..... 06/21
CPO Procedure for Turbocharged Subaru Vehicles ..... 10/21
Sending Immobilizer Components, Broken on Arrival ..... 11/21
Tech TechShare QMR and You ..... 02/22
Lost Keys? Contact the Subaru Techline. Updated Immobilizer Chart ..... 03/22
Calling the Techline Revisited ..... 04/22
When Diagnostics Don't Diagnose, Checking ALL Power Supplies ..... 04/22
22MY Pre-Delivery Inspection (PDI) Fuse Location Reminder ..... 04/22
Replacing components on the CAN network & Central Gateway Control LAN Registration ..... 05/22
Solterra DTC's Resulting from Service/Maintenance Activities: P0A1B1F, P0A1C1F, U113B87 ..... 08/22
22MY WRX One Touch Turn Signal Operation ..... 08/22

## 02-Engine

1.8 Engine Head Gasket Torque Change/Oil Leakage ..... 05/91
Legacy Throttle Sensor Switch Adjustment ..... 08/91
Noisy Lash Adjusters ..... 09/91
Legacy Exhaust Valves ..... 09/91
Legacy Cylinder Head Resurfacing (Grinding) Specifications Clarification ..... 10/91
Justy Cylinder Head Installation and Retorquing Clarification ..... 11/91
Legacy Turbo Models - Oil In the Coolant ..... 08/92
Oil Leaks ..... 09/92
Correction to Legacy Turbo Oil Leaks in the September Update ..... 10/92
Justy Balancer Chain Replacement ..... 11/92
1991MY–‘1992MY Legacy Turbo and All ‘92MY N.A. M/T “High Idle Complaint” ..... 12/92
1992MY Legacy Turbo Stalls After Start-Up Hot or Cold ..... 12/92
1992MY SVX Trouble Code 56, EGR System ..... 12/92
Loyale “Engine Ping” Complaint SPI ..... 01/93
1992MY SVX Auxiliary Air Valve Disconnection ..... 04/93
All Justy Models Drivability Complaints ..... 08/93
Justy with Multiple Failure Codes Including Code 41 in ECU Memory ..... 09/93
L-Series/Loyale 1.8 Liter OHC Valve Servicing ..... 09/93
Correction to All Justy Models Drivability Complaints, August Update ..... 10/93
1993MY Legacy Models, Electronic Control Unit “Rom” Installation ..... 10/93
Replacement Engine Oil Filters ..... 12/93
Loyale and Legacy HLA Noise ..... 04/94
1995MY Legacy Spark Plugs ..... 10/94
Synthetic Lubricant Usage ..... 10/94
Idle Quality Complaints On ‘95MY Legacy ..... 02/95
Synthetic Engine Oil ..... 02/95
Engine Testing-Back to Basics ..... 04/95
Synthetic Lubricant Usage - Updated Information ..... 07/95
Oil Viscosity Change for 1996MY Subaru Vehicles ..... 10/95
2.5 Liter Motor Engine Knocking or Tapping Noise ..... 01/96
1997MY Engine Noise ..... 09/96
Legacy 2.2L and Impreza 1.8L, 2.2L Engine Oil Filling ..... 09/96
Welcome To Shim City ..... 10/96
New Cambelt Tensioner ..... 04/97
Assembling 1997MY and Newer Engines ..... 08/97
Molybdenum Coating On Pistons ..... 10/97
Engine Noise ..... 11/97
2.5L Engine Cylinder Head Bolt Tightening Sequence ..... 11/97
Legacy Engine Belt Guides ..... 05/98
1996MY 2.5L Exhaust Valves ..... 09/98
2.2L Front Crankshaft Oil Seals ..... 10/98
1999MY Legacy Short Blocks ..... 11/98
Leaking Front Crankshaft Oil Seals ..... 01/99
SIA Installed Engine Oil ..... 03/99
2000MY Spark Plug Application Chart (revised 01-31-00) ..... 04/00
Engine Noise when Cold ..... 08/00
Oil Pumps – Replacement vs. Resealing ..... 01/01
3.0L 6 Cylinder Valve Train Servicing ..... 02/01
Subject: Engine Noise when Cold ..... 02/01
Three Bond 1280B ..... 05/01

2002MY WRX Turbo Cool Down Procedure ..... 06/01
Oil filters: H-4 versus H-6 Engines ..... 03-04/02
2.0L Camshaft Cap Torque Correction ..... 08/02
DOHC Turbo Valve Specification ..... 09-10/02
Subject: Engine Noise when Cold ..... 01-02/03
Radiator Hose Leakage ..... 01-02/03
SOA Replacement Ignition Wire Set ..... 01-02/03
Coolant Seepage from Water Pump ..... 05/03
2004 Baja and Forester Turbo Engine Oil Filters ..... 05/03
Cam Belt Tensioner Replacement ..... 07/03
Vehicle Re-engineering/modifying ..... 07/03
All Turbo Model Oil Filters ..... 07/03
Head Gasket Repairs ..... 11/03
Oil Filter Application Clarification ..... 11/03
Engine Noise – All H6 Vehicles ..... 01/04
H6 Cylinder Head Bolt Torqueing Procedures ..... 02/04
Cylinder Bore Size Location Information ..... 03/04
Cruise Control Cable Retainer Clip: WWQ-01 ..... 04/04
Pressure Washing of Vehicle Engine Compartment – All Models ..... 08/04
Intercooler Spray Tank ..... 03/05
Oil Classification Change for 2006MY Vehicles ..... 07/05
Shortblocks Replaced Under Warranty ..... 08/05
P/N 11063AB120: LH Cylinder Head Assembly ..... 09/05
Engine Testing – Back to the Basics ..... 10/05
Safe Handling of Sodium Filled Valves ..... 10/05
Coolant Seepage from Water Pumps ..... 10/05
Remanufactured SOHC Shortblocks and Bulletin 02-96-05 ..... 11/05
Bank1, Bank 2 ..... 01/06
Valve Stem Oil Seals ..... 02/06
Rubbing Mark on Timing Belt ..... 02/06
Platinum Spark Plug Change Intervals ..... 04/06
Turbo Failures ..... 05/06
H6 Oil Level Explained ..... 06/06
Basics, Basics, Basics ..... 06/06
Turbocharger Oil Supply Filter ..... 03/07
Engine Oil Specification Information ..... 05/07
3.6L H-6 Oil Filter Wrench Information ..... 07/07
Cranks Over But Won't Start? ..... 10/07
2008 M/Y 3.6L Engine Oil Dipstick ..... 11/07
Tribeca Oil Cooler Line Clamps ..... 11/07
Revised Turbocharger Oil Supply Piping ..... 01/08
Subaru Valve Adjustment Information ..... 02/08
More Valve Adjustment Information ..... 04/08
Engine Oil Pan Drain Plug Gaskets:  NOT All the Same! ..... 05/08
Don't Forget To Check Those Banjo Bolt Filters ..... 07/08
WWM-96 Rear Suspension Sub-Frame Corrosion Campaign ..... 11/08
Bank-Specific Misfires & Active Valve Control System (Variable Valve Timing- VVT) ..... 01/09
Oil Filter Replacement Precautions ..... 02/09
Important Short / Long-Block Replacement Reminder ..... 03/09
P0171, Rough Running Condition after Cold Start ..... 04/09
Turbocharged Engines: Oil Supply Reminder ..... 08/09
2010 M/Y Legacy & Outback 3.6L Engine Cover Removal ..... 10/09

Engine Oil Leaks – A Reminder ..... 05/10
Valve Adjustment and Clearance Measurement the Right Way ..... 06/10
4-Cylinder Crankshaft Oil Seal Replacement Procedures ..... 07/10
Don't Forget to Check the EGR Valve ..... 12/10
DTC P0128 Information ..... 12/10
2011 M/Y Forester N/A Revised Oil Filler Cap ..... 02/11
Leaking Engine Oil Seals? Don't Forget to Check the PCV! ..... 02/11
Fluid Leak Detection Made Easier ..... 04/11
Revised Cylinder Head Gasket Diagnostic Procedure ..... 05/11
2010 M/Y and Newer Oil Pan Damage ..... 06/11
2011 M/Y Forester (FB Engine) Cam Position Sensor Information ..... 06/11
2010 M/Y and Later Impreza WRX and STI Turbo Charger and Stay Bracket ..... 06/11
FB25/20 Engine Crankshaft Sensor Reluctor Indexing ..... 10/11
Excessive Noise from the Engine Under Boost ..... 02/12
2010 and Later Legacy and Outback 3.6 Engine Cover Removal ..... 05/12
2007 to 2009 Cylinder Head Identification ..... 06/12
BZR Fuel Injection Operational Characteristics ..... 06/12
Turbo Charges And Piping ..... 08/12
Front Chain Cover Oil Leaks ..... 12/12
Too Much Oil in the Engine ..... 03/13
Understanding The Relationship Between Cam Crank Position Sensors ..... 04/13
2013 Legacy/Outback Spec Change to Engine Under Cover ..... 04/13
2012 WRX and STI Motor Mounts ..... 05/13
Remanufactured Short Blocks ..... 05/13
2.0 and 2.5 FA/FB Chain Driven Engine Timing Information ..... 09/13
Engine oil expansion, Fact or Fiction ..... 12/13
FA and FB Engine Connecting Rod Bolt Removal Tip ..... 02/14
FA and FB Engine Timing ChainTensioner Initial Setting Information ..... 03/14
Piston Ring Installation TIPS ..... 03/14
Discoloration of Cylinder Walls ..... 04/14
Too Much Oil In The Engine Revisited ..... 06/14
Hard Starting, Extended Engine Cranking Concerns Revisited ..... 12/14
FA and FB Engine Crank Sprocket Timing Mark Important Reminder ..... 04/15
2015-16 MY WRX Engine Cover Removal Precaution ..... 09/15
Cam Sprocket Replacement for P000A-P000D A Reminder ..... 10/15
Addressing Accessory Drive Belt Noise ..... 02/16
Timing Chain Cover Installation ..... 04/16
Smoke from Exhaust on DIT Turbo vehicles ..... 12/17
Allowable Repairs to CVT Assemblies ..... 03/18
Engine Oil Pressure Specification Discrepancies ..... 07/18
Fluid Leak Detection Made Easier ..... 11/18
H6 Cylinder Head Replacement Precaution ..... 06/19
P0507 After Engine Service, Abnormal Idle Speed ..... 03/20
Rough Idle with AVCS DTCs ..... 03/20
Improved Diagnosis of Engine Oil Leakage, Leak Trace Powder Revisited ..... 03/21
2019 and up 2.4L Turbo, P0299 ..... 07/21
New and Remanufactured Short Block Replacement Tips & Break-In Procedure ..... 08/21
P0171, Rough Running Conditon After Cold Start ..... 02/22
Diagnosing P0128 on Thermo Control Valve Equipped Vehicles ..... 06/22

## 03-Drive Train-Transaxle

Shifter-Rattle “L” Series 4WD M/T and XT FWD or 4WD M/T ..... 07/91
Legacy Rear Diff ..... 08/91
Manual Transmission Gear Oil ..... 01/92
L-Series and XT Models With Stepped Flywheels ..... 04/92
All Subaru Models Rear Differential Assembly Replacement ..... 05/92
Legacy/SVX Limited-Slip Rear Differential ..... 06/92
1992MY Loyale Shifter Rattle On 4WD 5-Speed Models ..... 08/92
All Four-Wheel Drive Vehicles ..... 11/92
All Subaru Models Wheel Bearing Replacement ..... 06/93
Legacy Axle Repairs ..... 07/93
Justy Drive Axle Installation ..... 09/93
Diagnosing 3SP Automatic Transmissions Starting In Second Gear ..... 11/93
Justy ECVT Transmissions That Won’t Up-Ratio After Rebuild ..... 11/93
Rear Differential Replacement ..... 12/93
3 Speed Automatic Clutch Drum Wear ..... 01/94
Manual Shift Lock Release on ‘94MY SVX ..... 02/94
3-Speed Automatic Differential Rebuilding ..... 05/94
Replacing AWD Rear Wheel Bearings on Legacy, Impreza, and SVX ..... 04/95
Inspection of Clutch Free Play During PDI ..... 07/95
Automatic Impreza Rear Differentials ..... 05/96
Outback Gear Ratios ..... 05/96
Where’s The Hill Holder? ..... 10/96
Inspection of Clutch Free Play During PDI ..... 11/96
Noise from Rear Axle Oil Seal-Legacy Models ..... 01/97
‘97MY Legacy Rear Differential Crossmember Bracket Noise & Vibration ..... 01/97
Rear Differential Modifications ..... 04/97
All Subaru Models with Stepped & Flat Flywheels ..... 07/97
Additional Parts Information on Differential Modifications ..... 07/97
Identifying 1997 Subaru Legacy Propeller Shafts ..... 07/97
1997MY Legacy Rear Differential Crossmember Bracket Noise & Vibration ..... 10/97
Grease Leaking From Inner Axle Joints ..... 02/98
Rear Differential Vent Oil Leakage ..... 04/98
Legacy Engine Belt Guides ..... 05/98
1998MY Vehicles Leaking Axle Grease ..... 09/98
M/T Case Boss Wear ..... 09/98
5MT Popping Out Of First Gear ..... 10/98
Shifter Rattle ..... 02/99
All 1999MY Manual Transmission Vehicle ..... 03/99
Transmission/Rear Differential Gear Ratios ..... 06/99
Popping Out Of Fifth Gear ..... 01/00
1999/2000MY Manual Transmissions Popping Out Of 1st Gear ..... 04/00
2001MY Outback H6-3.0 VDC Precautions ..... 11/00
Variable Torque Distribution ..... 05/01
All Subaru Rear Differentials ..... 10/01
Use of Correct Fluids ..... 08/02
Parts Supersession 2002MY Outback & Impreza 1st Driven Gear ..... 09-10/02
Transmission Popping Out of 3rd Gear ..... 05/03
On The Car Rear Wheel Bearing Replacement Procedure ..... 09/03
Impreza WRX Driveability ..... 04/04
2005MY Manual Transmission Speedometer Gears ..... 06/05

STi Rear Differential Oil ..... 07/05
Impreza STI Characteristics ..... 01/06
Clutch Pedal Squeak ..... 05/06
Manual Transmission Center Differential Damage ..... 10/06
STI / DCCD “Klunking Noise” ..... 02/08
6 M/T “Quick TIPS” ..... 03/08
DTC P1720, DCCD Code in Memory, 2008 STI ..... 09/08
Squeaking Noise When Operating the Clutch Pedal ..... 02/09
2010 M/Y Legacy & Outback Sound at Initial Start-Up ..... 08/09
Tribeca Rear Differential Temp Light Flickering ..... 04/10
Updated M/T Transmission Drain Plug Gasket Information ..... 06/10
2010-11 M/Y Legacy / Outback “Howling” from Under the Vehicle ..... 01/11
2010 M/Y & Later Legacy / Outback 6 M/T Reverse Gear Damage ..... 01/12
BRZ Manual Transmission Sounds ..... 06/12
Color Change To Manual Trans Oil Level Dipstick ..... 10/12
All Manual Transmission Equipped Vehicles ..... 11/12
2015 WRX Short Throw Shifter Precautions ..... 05/14
Transmission Cooler Flushing ..... 08/15
BRZ 6M/T Rattling Sound on Deceleration w/AC On ..... 09/15
Reminder-Cleaning and Lubrication of Clutch Release Components ..... 11/15
P2751 and no CVT Engagement ..... 05/16
AT Learning Control Information ..... 06/16
Transmission Replacement Procedures ..... 06/16
No Movement after Valve Body Replacement on 10-12 Legacy/Outback CVT ..... 08/16
Clutch Release Component Lubrication ..... 10/16
Clutch Release Component Lubrication and Inspection Revisited ..... 11/16
Unnecessary CVT Replacement’s ..... 12/16
HARMAN AUDIO UNITS: Audio Volume Turned To Max When Monitoring Infotainment Data Monitor ..... 03/17
AT Learning Control Information ..... 11/17
Smoke from Exhaust on DIT Vehicles ..... 12/17
P2751 and no CVT Engagement ..... 09/18
Selectable Shift Fork Identification Marks ..... 01/19
Squeak/Chirp Sound from High-Torque CVT When Shifting from P/N to D ..... 04/20
AT Learning Control Information ..... 07/20
Wiring Clarification for Guide Plate B Installation (TSB 16-112-18R) ..... 07/20
P2751, Vehicle does not Move When in Gear ..... 09/20
Front Differential Failure After Transmission R&R ..... 11/20
Binding/Sound While Turning ..... 11/20
Vibration After Transmission or Engine Removal ..... 04/21
Ascent or Legacy/Outback 2.4L Binding When Turning Basic Diagnosis Overview ..... 04/21
Squeak/Chirp Sound from High-Torque CVT When Shifting from P/N to D ..... 01/22
Hub Bearing and Backing Plate Replacement ..... 01/22
Transmission Oil Residue, New Vehicles ..... 06/22

## 04-Steering

Loyale Power Steering Pump Failures....05/91
XT-6 Mps Controller Set....01/92
XT-6 Electronic Controlled Motor Drive Power Steering Service Manual Supplement ....04/92
XT-6 Motor Power Steering “Motor Pump” ....05/92
All Models Power Steering Pumps....06/92
Testing Power Steering Pumps ....06/93
SVX Power Steering Pump Replacement ....02/94
Steering Rack Noise....01/97
Power Steering Pump Replacement ....03/97
2004MY Impreza and Forester Steering Column Cover ....10/03
Parts Ordering Update for VSC Steering Angle Sensor....10/03
Power Steering Rack Repairs ....11/05
2006MY STI Steering Angle Sensor....02/06
Power Steering Pump Noise ....04/07
2005 & Later SIA-Built Steering Rack Rebuilding Tool Info ....10/08
Power Steering Rack Serviceability ....06/11
Electronic Power Steering....10/14

## 05-Suspension-Wheels & Tires

Legacy Rear Stabilizer Link Bushing Seat Change ..... 07/91
Loyale Rear Alignment ..... 10/91
All Models Alignment (Front & Rear) Tips ..... 02/92
Legacy 4WD Noise Coming From Right or Left Rear Area ..... 10/92
Legacy Front End “Pop” Noise ..... 10/92
All Four-Wheel Drive Vehicles ..... 11/92
All Models Wheel Lug Torque ..... 11/92
1993MY Impreza Rear Suspension “Passive Four Wheel Steering” ..... 05/93
All Subaru Models with Air Suspension, Including Legacy (“O” Rings) ..... 06/93
Production Line Installation of Oil Filter and Power Steering Reservoir Filling ..... 06/93
All Subaru Models Front End Alignment ..... 08/93
1992MY SVX Rear Suspension ..... 08/93
Impreza Wheels - 13” vs. 14” ..... 01/94
Impreza Rear Strut Noise Production Change ..... 02/94
1991MY Legacy Complaint of Banging Over Bumps, Especially Prevalent In the Right Rear ..... 03/94
Impreza Rear Strut Noise Production Change ..... 04/94
Impreza Tire Rotation/Maintenance ..... 06/94
Procedures for Yokahama Tire Complaints ..... 02/95
Noisy Impreza Rear Struts ..... 09/95
Front Suspension Noise, 1995/96MY Subaru Legacy ..... 04/96
Impreza Outback Tires ..... 09/96
1996MY & 1997MY 2.2L Manual Transmission Equipped Vehicle ..... 09/96
Additional Tire Information For ‘97MY Impreza Outback ..... 11/96
Axle Shaft Grease ..... 08/99
Recommended Winter Tires for 2000MY Outback ..... 01/00
2000MY Outback Winter (Snow) Tire Information (supplemental) ..... 03/00
Tire Questions and Information Handling Procedures ..... 09/01
WRX and STI Recommended Winter/Snow Tires ..... 11/03
Stick-On Wheel Weights ..... 09/04
2003MY Keyless Entry Control Module Interchangeability ..... 09/04
Tire Pressure Monitoring System ..... 10/04
2005MY Legacy/Outback – Use of Tire Chains ..... 12/04
Tire Pressure Monitoring System (TPMS) Equipped Vehicles ..... 12/04
STi Clunk Noise in Rear ..... 02/05
Rear Stabilizer Link Positioning ..... 10/05
Tire Pressure Monitoring System – A Reminder ..... 11/05
B9 Tribeca Spare Tire Availability ..... 02/06
Tire Pressure Monitoring System (TPMS) – Additional Information ..... 03/06
Tire Valve Stem Caps ..... 03/06
2005~06MY Legacy/Outback Lower Control Arm Bushings ..... 05/06
TPMS Valve Core Tool ..... 06/06
B9 Tribeca Torque Support Plate Revised Torque Specification ..... 08/06
Oil Seepage / Leaking From Struts ..... 01/07
Customer Concern about Tire Conicity & Vehicle Drift ..... 02/07
2008 MY Tire Pressure Monitor (TPMS) Changes ..... 05/07
Emergency Wheel Lock Removal ..... 06/07
Wheel Lug Torque Specs ..... 11/07
Use of Nitrogen in the Tires of Subaru Vehicles ..... 12/08
2010-11 Legacy / Outback Steering Vibration Updates: Helpful Hints ..... 09/10
Tire Pressure Monitor System Reminders ..... 10/10

2011 M/Y Tire Pressure Monitor System “Quick TIP” ..... 11/10
Rear Stabilizer Bar Identification ..... 03/11
Front / Rear Suspension Strut Piston Seal Damage ..... 11/11
Front-End Rattling Noises Over Bumps ..... 11/11
Tribeca Spare Tire Color Change ..... 10/12
2005 And Up Front Lower Control Arm Bushings ..... 05/13
Tire Pressures-Check that Spare ..... 11/13
Wheel Lug Socket Recommendation ..... 03/14
Abnormal Noise Diagnosis ..... 07/16
New Model Alignment Specifications ..... 11/18
Abnormal Noise Diagnosis ..... 12/18
2019 Ascent Noise from Rear Over Rough Roads ..... 10/19
New Model Alignment Specifications ..... 02/20
C2921 and Intermittent TPMS DTC Diagnosis ..... 04/20
Abnormal Noise Diagnosis ..... 01/21
Front Lower Control Arm Bushing Repair Procedure ..... 03/21
AWD light flashing, STI & WRX ..... 05/21
Noises from Strut Area ..... 07/21
TPMS Sensor Installation ..... 12/21
Flat Spots and Road Force Tire Balance ..... 02/22
Ascent Noise from Rear Over Bumps or When Turning ..... 07/22

## 06-Brakes

Legacy ABS Control Unit Code 10 ..... 01/92
ABS Light Illumination Code 16 (G-Sensor) ..... 02/92
Legacy Brake Vibration Complaints ..... 06/92
Legacy Front Disc Brake Pad Wear ..... 11/92
Legacy Right-Hand Drive Vehicles ..... 12/92
Legacy ABS-2E System ..... 02/93
Anti-Lock Brakes For Legacy ..... 03/93
Legacy Brake Pads ..... 10/93
1994MY Impreza Hill Holder “Ghost Cars” ..... 01/94
Legacy Brake Rotors ..... 02/94
Impreza Throttle Position Switch Adjustment ..... 06/94
Non-Approved Adjustments on Legacy, Impreza, &d SVX Throttle Plates and ISC Valves ..... 06/94
Rusty Brake Rotors ..... 07/94
Brake Rotor Machining With Pro-Cut Equipment ..... 08/94
TCS Operation with ‘T-Type’ Spare ..... 10/94
ABS Code 16 - Faulty ABS Control Unit or ‘G’ Sensor (AWD, M/T Model) ..... 10/94
Reading ABS Codes on Early Subaru Legacy Models ..... 07/95
Subaru Legacy - ABS Light on ..... 08/95
Brake Fluid Basics ..... 09/95
ABS And Select Monitor Usage ..... 09/95
ABS/TCS Equipped Legacy Vehicles ..... 10/95
1995MY/1996MY Subaru Legacy with ABS ..... 11/95
1996MY Subaru Legacy Equipped With ABS/5.3 System ..... 11/95
ABS-2E Control Units & ABS Code 23 ..... 12/95
Vehicle Not Complying With Federal & State Regulations ..... 12/95
Intermittent Wheel Sensor Codes in Early Legacy ABS Systems (Non ABS-2E) ..... 12/95
Brake Noise...What Is Normal? ..... 02/96
5.3 ABS System Service Manual ..... 06/96
Component Relocation with 5.3 ABS System ..... 06/96
ABS Equipped Subaru Vehicles System Check ..... 08/96
New 5.3I Type ABS System ..... 02/97
5.3I ABS System Information Update ..... 03/97
ABS 5.3I Service Manual ..... 04/97
Identifying ABS Systems ..... 05/97
ABS 5.3I ABS Warning Light Operation ..... 10/97
ABS/TCS Code 57 ..... 01/98
Use of Non-Approved Brake Additives ..... 05/98
1999MY Forester ABS ..... 02/99
Brake Judder & Noise; All Models ..... 03/99
2002MY Impreza Brake Rotor Scoring ..... 06/01
Bulletin Numbers 03-31-03 & PT 370303 ..... 01/04
Bleeding Brembo Brake System on WRX STI Models ..... 03/04
STI Brake Shim Kit ..... 09/04
Brake Pad Wear Indicator ..... 03/05
B9 Tribeca Brake Servicing ..... 05/05
Preventive Measure for Surface Rust around Disk Brake Pad ..... 05/06
Brake Rotor Concentric Scaring ..... 01/07
VDC Control Module Servicing ..... 09/07
ABS Code C0111- ABS Motor Relay Function ..... 12/07
ABS / VDC Detail Codes and How to Use Them ..... 03/08

New TPMS Transmitter Design Reminders....06/08
Brake Rotor Information....12/08
Tapping or Clicking Noise, 2008-09 Impreza....03/09
Brembo-Equipped Disc Brake Noise....03/09
More C0054 & C0074 Information....04/09
EPB Emergency Manual Release Procedure....11/09
2010 M/Y Legacy & Outback Master Cylinder Removal Precaution....02/10
“Click or Knock” Sound When Releasing the Brake Pedal....05/10
WVY-35 Master Cylinder Installation Precaution....01/12
ABS Brake System Applied Model Information....03/12
Vehicles Equipped with Eyesight....07/12
Important Precautions For Eyesight Equipped Vehicles....08/12
13 BRZ Revised Vehicle Stability Control Diagnostics....11/12
12/13 Impreza Parking Brake Information....11/12
EyeSight System Temporary Stop Information....02/13
Click Or Knock Sound When Releasing The Brake Pedal (Reminder)....02/13
Proper Reporting of Eyesight Related Issues....04/13
Precautions & Diagnostic Tips for Eyesight Equipped Vehicles....04/13
Brake Override System Operation and Hesitation Complaints....11/13
2015 Legacy and Outback Electronic Parking Brake Codes C1956 or C1957....08/14
What’s That Green Stuff under the Master Cylinder Reservoir Cap....05/15
Brake Fluid Color Change....07/15
Hill Holder or Parking Brake (EPB) Won’t Release....11/15
Eyesight Replacement Parts....08/16
2017 Reverse Automatic Braking (RAB), Red Area Appears In Back-Up Camera Display....01/17
Hill Start Assist Light On but No Codes....03/17
2017 Impreza Brake Caliper Oil Residue....11/17
Tap or Click – Type Sound Heard When Coming to a Stop – 2019MY Ascent....01/19
C0271 After Park Brake Actuator Replacement....02/19
Reverse Automatic Braking (RAB)- Important Information....10/19
2017 and Up Impreza Brake Caliper Assembly Oil Residue....12/19
2018+ STI Green Brake Caliper Discoloration....09/20
VDC Control Module Replacement Followed by SRH Warning Light Information....01/21
C1921 – Electronic Parking Brake Inoperative....02/21

## 07-Electrical

Justy ECVT/Ignition Relay ..... 07/91
Legacy Intermittent Hard Or No Start/Ground Shock Tower ..... 07/91
Legacy Ignition Relay ..... 07/91
Justy MPI Codes 11, 13 ..... 07/91
Phantom Code 22, Knock Sensor 87-89MY “L” And XT Series ..... 09/91
A/T Shift Lock System/Loyale ..... 12/91
L-Series OHV Engine-Engine Will Not Shut-Off ..... 01/92
SVX and Legacy Brake Lights Staying On ..... 01/92
Legacy Poor Radio Reception/Low Volume Output ..... 03/92
90MY to Present Justy MPI Distributor Wiring ..... 04/92
Legacy S/W Fuse No.5 Continually Blows-Out ..... 05/92
Legacy Sunvisor Lighted Mirror Wiring #15 Fuse ..... 05/92
Legacy Starters ..... 10/92
1992 MY Legacy & SVX Ignition Relay ..... 10/92
Aftermarket Batteries ..... 11/92
1992MY SIA Legacy S/W Rear Gate Telltale Light Won’t Go Out ..... 11/92
Justy Trouble Code 23: Pressure Sensor ..... 01/93
1993MY Impreza Relays ..... 05/93
Electrical Tips ..... 07/93
Legacy Sunroof Wiring Schematic & Switch Operation ..... 09/93
Electrical Problems? Check the Fuse ..... 10/93
Impreza Headlamp Information ..... 10/93
1990MY Legacy with Code 41 in ECU Memory ..... 11/93
1990MY Legacy Code 42 Throttle Position Switch from ECM ..... 11/93
ROM Application Chart ..... 11/93
1993MY Loyale Intermittent Wiper Wiring Diagram ..... 01/94
Six-Step Troubleshooting Method ..... 02/94
Rear Defogger Wiring & Terminal Repair Kit ..... 02/94
1990MY-Present Loyale Fuel Pump Control Unit Wiring Diagram ..... 03/94
1992MY SVX ROMS ..... 03/94
Battery Charging ..... 03/94
ECVT Trouble Code 31 ..... 04/94
ECVT - Select Monitor Speed Sensor Reading ..... 04/94
Impreza Headlights ..... 04/94
Legacy Fuel System Wiring Diagram ..... 05/94
Impreza Fuel Tank Sending Unit Specifications ..... 05/94
1995MY Legacy Electrical Component Location Quick Reference List ..... 07/94
Legacy Fuel System Wiring Diagram ..... 08/94
SVX Spark Plug Servicing ..... 09/94
Ignition Relays ..... 10/94
Ignition Relays - The Sequel ..... 10/94
1995MY Legacy Speed Limiting Device ..... 11/94
SPI Trouble Code 13 (Crank Angle Sensor) From ECU ..... 11/94
OBD II Check Engine Light ..... 12/94
Speed Sensor 2 ..... 01/95
1994MY Legacy Seat Heaters ..... 01/95
Cold Shift Locks (Impreza Shift Locks That Won’t Unlock When Cold) ..... 02/95
1985MY & Later L-Series MPFI Improper Engine Operation above 2000 RPM ..... 03/95
Battery Replacement ..... 03/95
Electrical Diagnosis, the Helpline, & You ..... 04/95

Battery Charging ..... 05/95
Electrical Condition Reporting ..... 06/95
ROM Installation ..... 08/95
1 Mw Min. ..... 09/95
1996MY Subaru Legacy Outback Fog Lamps ..... 10/95
1995MY Subaru Legacy Outback Rear Power Outlet ..... 11/95
Identification of Cam and Crank Sensors ..... 07/96
1995MY/96MY Subaru Legacy Blows Fuse SBF-2 ..... 07/96
1997MY Legacy Power Door Lock System ..... 09/96
Sticking or Difficult Auto Down P/W Switch Buttons (Mistakenly Printed In Section 11) ..... 10/96
Diagnostic Trouble Code P0341 ..... 10/96
Loose Window Regulators ..... 10/96
Rear Defogger Timer ..... 03/97
Legacy Heater Control Panel Bulbs ..... 03/97
‘98MY Forester Transit Connector Location ..... 08/97
‘98MY Forester Trailer Hitch Wiring Harness ..... 08/97
‘95MY-‘97MY Legacy Moisture Accumulation in the Headlights ..... 04/98
2000MY Legacy Battery ..... 09/99
Wiring Harness Connector I5 ..... 09/99
Electrical Problems? Check The Alternator. ..... 11/99
2000MY Legacy Blows Fuse #5 ..... 01/00
2000MY Subaru Legacy Turn Signal Operation ..... 02/00
2000MY Legacy & Outback Vehicles Fog Light Operation ..... 04/00
Grounds, Grounds, Grounds ..... 07/00
Daytime Running Lights ..... 08/00
Windshield Wiper Deicer System not Working ..... 11/00
Turn Signals Flashing Rapidly ..... 11/00
Blower Motor Resistor Repairs ..... 01/01
In-Dash Cigarette Lighter Usage ..... 06/01
Alternator Supplier Update ..... 08/01
Legacy Transit (D-check plug) Connectors ..... 03-04/02
Fuse 4 Blows-Out ..... 03-04/02
Legacy Rear Wiper Operation ..... 03-04/02
2005MY Legacy/Outback Trailer Hitch Harness Location ..... 07/05
Backup Power Supply Fuse ..... 10/05
2005MY Forester Diagnostic Connector ..... 11/04
2005MY Legacy/Outback Electrical Diagnosis ..... 02/05
Body Integrated Unit (BIU) Replacement ..... 03/05
Fuse Label Correction ..... 03/05
HVAC & Audio Unit Inoperative After Wiring Harness Change ..... 04/05
2005MY Baja with Poor Radio Reception ..... 04/05
HVAC Inoperative After Wiring Harness Change—More Information ..... 05/05
2003MY Forester Fuse Information ..... 08/05
Battery Going Dead or Alarm Going Off ..... 09/05
Information Requested For Harness Repair Kits ..... 11/05
2006MY Legacy/Outback and B9 Tribeca Combination Meter Self Diagnosis ..... 02/06
Change of Seat Heater Relay ..... 02/06
Low Battery Voltage ..... 06/06
2005MY Forester A/F & O2 Sensor Relay Location ..... 06/06
SBF-5 Fuse Blows On 2005 MY / 2006 MY Impreza Vehicles ..... 07/06
“Dark Current” Or Excessive Battery Draw ..... 02/07
Erratic Tail Light Operation ..... 04/07

More “Dark Current” Information ....04/07
Headlight Bulb Replacements –A Reminder ....05/07
New Style 2008 MY Legacy, Outback & Tribeca Keys ....06/07
Midtronics inTELLECT EXP Battery Tester Logic Update ....06/07
Headlight Bulb Socket Repairs ....07/07
2008 MY High Security Keys ....08/07
2008MY Impreza Headlight Switch Operation ....09/07
2008 Impreza Stop Light Switch C0074 and C0054 ....01/08
BIU Replacement and Keys ....05/08
2008 Impreza Data Link Connector Color Change ....06/08
Legacy & Outback Door Switch (Nov 2004 production & after) ....06/08
Wiring Harness Connector Similarities & Cautions ....07/08
Forester Sunroof Reverses When Closing ....12/08
2008-09 Impreza, Erratic Outside Temperature Gauge Operation ....01/09
Door & Ignition Lock Cylinder Replacement Clarification ....02/09
2009 M/Y Forester Power Window Information ....03/09
Power Door Locks Inoperative, 2009 M/Y Forester ....04/09
“Dark Current” ….Revisited ....06/09
2010 M/Y Legacy & Outback Auto Up / Down Feature Operation ....08/09
Speedometer Inoperative? Don’t Overlook the Sunroof Wiring ....08/09
2010 M/Y Legacy & Outback Low-Beam Bulb Replacement ....08/09
2010 M/Y Legacy & Outback Headlight Bulb Replacement Information ....09/09
2010 M/Y Legacy & Outback Power Window Operation ....10/09
Re-Coding Laser-Cut Keys ....01/10
2010 M/Y Legacy & Outback Oil Level Warning Information ....02/10
2010 M/Y Legacy & Outback BIU Interchangeability ....02/10
2010 M/Y Forester “Resonating” Noise When Using the Horn ....03/10
2010 M/Y Forester Dome Light Erratic Operation ....05/10
2010 and 2011 Driver’s AUTO-UP Reset Information ....10/10
2008 – 2011 Impreza Front Turn Signals Blink Too Fast ....01/11
Remote Trunk Release Inoperative After BIU Replacement ....05/11
2008 M/Y and Later Impreza Stop Light Switch Information ....05/11
Sunroof Operation Service Bulletins ....05/11
New DTC’s After Bulkhead Harness Replacement ....06/11
CAN System Diagnostic Information ....07/11
Immobilizer Codes Stored, Engine Starts and Stalls Condition ....08/11
2011 M/Y Impreza High Beams Not Bright Enough? ....10/11
Headlight Aiming Precautions ....11/11
Tom-Tom Equipped Volume Control Information ....12/11
2012 M/Y Impreza No Start, SBF-6 Blown ....01/12
2012 Impreza Key Information ....03/12
Sunroofs and Car Washes ....04/12
Battery Testing, the Importance of Using the Right Standard ....04/12
Re-Programming Information for All 2011-12 M/Y Vehicles ....05/12
2013 BRZ Auto Up/Down Window Feature ....09/12
Hard To Fill Fuel Tank ....09/12
Eyesight Camera Adjustment ....10/12
13 MY Legacy And Outback Accessory Charging ....11/12
Electrical Devices And Air Bag Systems ....12/12
14 MY Forester Turbo Battery Cable Precaution/ DTC P0606 ....02/13
Appearance of Water in BRZ Back Up Light ....03/13
Memory Height Learning Procedure ....04/13

Erratic Digital Fuel Gauge Operation, 2012 My and Later Impreza, BRZ, and 2014 Forester....04/13
Immobilizer/ Key Registration Information....04/13
2014 Forester Information Display Selection Knob( or the Right Side or Other Trip Knob)....04/13
Campaign WQF-42 Information....05/13
Fuel Gauge Diagnostic's....05/13
2014 Forester Turbo, ECM Electrical Testing Reminder....06/13
2014 Forester Power Rear Gate (PRG) Initialization Procedure....06/13
2014 Forester Non-Turbo ECM And BIU Locations....06/13
2014 Forester L/F Power Window auto up/down operation....08/13
HVAC Electrical Connections....09/13
BIU Replacement on all Push-button Start Vehicles....10/13
2014 Forester Seat heater Operation and Switch Functions....11/13
Headlight Adjustment Reminders....11/13
ODS Code 29 or 37, Electrical Devices and Air Bags revisted....12/13
Appearance of Water Droplets in BRZ Exterior Lamps....01/14
Important Hybrid Vehicle Aux Battery Precautions....01/14
Operation of SI-Drive, Sport Sharp(S+) Mode after Cold Start....02/14
Midtronics GR8Use During Control unit Programming....02/14
2010-14 Legacy& Outback Fuse # 16 Failed in the Main Fuse Box....03/14
DTC P0724, Brake Switch Circuit High Input....03/14
Passenger Side Power Window Auto Up/Down Function....08/14
2015 Legacy/Outback Power Window Auto Up/Down Operation Revisited....09/14
2015MY Legacy and Outback Under Hood Main Fuse Box (M/B) Information....09/14
2015 Legacy and Outback Cold Weather Light Operation....10/14
2015 Legacy and Outback Under-Hood Main Fuse Box (M/B) Information....10/14
2015 Legacy and Outback Keyhole Shadow From Projector Beam Headlamp....10/14
Dark Current Draw Revisited....11/14
Bluetooth Pre-Call Worksheet....11/14
2015 Legacy/Outback Unnecessary Power Window Switch Replacements....12/14
Body Integrated Unit (BIU) Replacement/ Interior Lights Flashing....01/15
Identifying Electrical Harness Connectors....04/15
Electrical Diagnosis and Aftermarket Equipment....04/15
DTC Diagnosis and Related Wiring Harness Checks....05/15
2010-2016 Forester TPMS light flashing, Sensor Registration Issues....09/15
Spark Plug Information a Reminder....03/16
Battery Servicing Precautions....03/16
GR-8 1100 EST Battery Diagnostic Station, Power Supply Mode....05/16
No Crank No Start Diagnosis....06/16
Blue-Tooth Pre-call Worksheet....07/16
Ignition Key Cannot Be Removed From Ignition Switch....10/16
Quick Reference Immobilizer Type....10/16
Replacing B-Type BIU....10/16
Fuel Gauge Diagnosis Revisited....11/16
Power Window erratic, cannot program memory....01/17
No Hybrid Auto Start Stop or Ev Travel....01/17
BIU replacement....01/17
Satellite Signal Lost When Traveling South 2014-UP Forester....02/17
PAK file error messages....05/17
B1650 Proper Diagnosis....06/17
Blind Spot Detection Off....01/18
Ground Circuit Identification....03/18
No Hybrid Auto Start Stop or EV Travel....03/18

ECM Reprogramming....05/18
Audio Unit Service/Diagnostic Menu....06/18
Quick Reference Immobilizer Type....08/18
Replacing B-Type BIU....08/18
Ascent Automatic Wiper Rain Sensor Initialization....10/18
2019MY Forester, Driver Monitoring System (DMS) Inoperative....11/18
2019MY Forester, Loose Negative Battery Cable/Terminal Connections....11/18
Performing Variant Work When Replacing Combination Meter....12/18
Automatic Start-Stop System Enable Conditions....12/18
2019MY Forester, Driver Monitoring System (DMS) Inoperative *UPDATE*....01/19
Gen 3 Clock Related Concern....02/19
2018 – 19MY Legacy & Outback – B1650....02/19
2019MY Forester- Rear Seat Heaters Inoperative....03/19
2019MY Forester- Automatic Seat Retraction Feature Operation....03/19
Electrical Diagnosis and Aftermarket Equipment....03/19
2019MY Forester, Driver Monitoring System (DMS) Inoperative B2632 B2642....04/19
Hill Start Assist Lamp Illuminated Without Associated DTCs or Customer's Concern....04/19
2019MY Forester Manual Override for Power Rear Gate....05/19
2019MY WRX, Telematics "i" Button Sticking....05/19
Identical Electrical Connectors....06/19
2019 Forester Door Mirror Reverse Tilt-Down Feature....06/19
2020MY Legacy & Outback, DTCs B2259, B2244, B282C, & B2C22....11/19
Midtronics DSS-5000 and DCA-8000 Tips and Tricks....12/19
Mirror Tilt Inoperative....01/20
Revised Ascent Sunroof Glass (Lid) and Sun Shade Initialization Procedures....01/20
Change of Length of ECM Calibration ID (CID) Numbers....01/20
2019MY and up Forester MFD Displays Incorrect Vehicle Angle....02/20
Ascent Sunroof and Sunshade Motors....02/20
Power Rear Gate (PRG) Inoperative with Ignition ON and / or Engine Running....02/20
Flashing Lights on Rain Sensor Equipped Vehicles....03/20
Heated Seat Operation....03/20
Parasitic Draw (Dark Current) Testing and Telematics DCM....05/20
Replacing B/G-Type BIU....09/20
G and H Type Immobilizer Registration....10/20
Identical Electrical Connectors....10/20
Electrical Connector & Pin Discrepancy....11/20
WRE-21 Ignition Coil Connector Removal and Wire Clip Loss – How to Repair....05/21
Auto Headlight Strategy Logic from My19+ Foresters....07/21
Power door lock inoperative, erratic or rapid operation (All Models)....07/21
Door Lock Battery Back Up Unit....08/21
Infotainment Continues to Play at Key Off and Door Open (All models)....09/21
Diagnosing Network U-Codes....10/21
Parasitic Draw Testing, A Different Approach....10/21
Erratic Digital Fuel Gauge Operation, 2012MY and later Impreza, BRZ and 2014MY Forester....11/21
Fuel Gauge Discrepancy, not reading correctly....11/21
Lane Keep Assist Inoperative, Even When Set To "ON"....12/21
Wiring Harness Ground Bolt Torque Spec....01/22
Check Board Harness Diagnosis....03/22
Headlight appearance "Dark spot in headlight patterns"....04/22
2019MY(+) Hybrid Inverter Cable Installation....08/22

## 08-Instrument & Controls

High Reading Temperature Gauge, Digital Dash 85MY & 86MY “L” Series, Including XT .....08/91
L-Series Speed Sensor Replacement .....02/92
1992MY Legacy FWD Modified Fuel Tank Sender Unit .....09/92
Corrections to Previous Helpline Updates ..... 11/92
Odometer Labels .....02/93
Legacy Knock Sensor Testing .....03/93
Legacy All Wheel Drive Fuel Gauge .....04/93
Impreza Combination Meter Tachometer .....05/93
Legacy Postal Vehicles with Single Action Power Door Locks ..... 11/93
Speedometer Inaccuracies .....01/95
Warning Light Operation .....02/95
Legacy and Impreza Fuel Tank Sending Units .....05/95
Instrument Cluster Circuit Boards .....10/96
Fuel Gauges on “E” .....10/96
1998MY Subaru Forester/Impreza Digital Odometer .....09/97
Odometer Policy.....02/01
Ambient Temperature Sensor .....04/04
SI-Drive Multi-Information Clock Display Characteristics.....04/08
2010 M/Y Legacy & Outback Clock Setting Procedure.....08/09
Adjusting the Clock and Settings of the Multi-Function Display.....05/10
Shift Indicator Light Applicability, 2012M/Y Impreza .....04/12
BRZ Trunk Release Operation..... 07/12
Navigation Screen Displaying The Language Menu ..... 11/12
2014 Forester Multi Function Display Messages.....08/13
2015MY Legacy/Outback, Journey Time Alert on Combination Meter Tell tail Display .....09/15
Resetting Applied Model & Option Codes for Combination Meters ..... 12/19
Combination Meter Settings: Kilometers to Miles.....05/20
Reading and Writing of the ECU Configuration and Odometer Value Clarification.....06/20

## 09-Cooling, Fuel, & Exhaust System

Justy FWD-ECVT Noise from Exhaust Pipe Joint ..... 05/91
Legacy 4EAT Radiators ..... 02/92
Subaru Exhaust Systems ..... 04/92
1992MY SIA Models Production Fuel Filter ..... 05/92
Legacy Exhaust Whistle Turbo & Naturally Aspirated ..... 06/92
1992MY Legacy FWD Modified Fuel Tank Sender Unit ..... 09/92
Corrections to Previous Helpline Updates ..... 11/92
Coolant Recycling ..... 06/93
Summer Low RVP Fuels ..... 06/94
Fuel Quality Check ..... 06/94
Fuel Switching ..... 09/94
Impreza Fuel Tank Sending Unit Assemblies ..... 09/94
Impreza Fuel Tank Capacity ..... 10/94
Replacing Loyale Thermostats ..... 11/94
2.2L Impreza AWD Fuel Senders ..... 04/95
Reformulated Gasoline ..... 05/95
Loyale Water Pump Leaks ..... 07/95
Modified Fuel Injectors ..... 10/96
Cooling Fan Operation ..... 09/97
1999MY Legacy Excessive Crank Time ..... 03/99
Vehicle Won't Take Fuel ..... 03/99
Vehicles That Won't Take Fuel ..... 09/99
Fuel System Quick Connector ..... 10/99
Don't Touch That Screw! ..... 01/00
Sulfur Smell from the Exhaust ..... 05/00
Use of Genuine Air Cleaner Element ..... 11/00
H-6 Extended Crank Time ..... 01-02/02
Forester Fuel Line Noise ..... 09-10/02
WRX STi Driveability ..... 08/03
2004MY Legacy Fuel Filter Replacement ..... 09/03
H6 Drivability ..... 11/03
New Product Orientation for the Cooling System Conditioner ..... 04/04
2004MY Legacy/Outback H-6 and H-4 (NA) Fuel Line Removal ..... 05/04
2005MY Legacy Fuel Line Rattle ..... 11/04
Fuel Order in Cold Weather (Service Bulletin Reminder) ..... 11/04
Fuel Line Tool ..... 12/04
Gas Mileage ..... 03/05
Fuel Hose Retainer Clips ..... 06/05
B9 Tribeca Fuel Line Tool ..... 04/06
Subaru Vehicles and Driveability ..... 09/06
STI Models Fuel Recommendation ..... 11/06
Fuel Odor on Initial Cold Starts ..... 02/07
Engine Cooling System Service & Care Recommendations ..... 06/07
Fuel-Related Driveability Concerns ..... 08/07
Genuine Subaru Cooling System Conditioner Information ..... 10/07
Subaru Super Coolant ..... 11/07
P0171 and "Hard Start" Concerns ..... 12/07
More Subaru Super Coolant Information ..... 03/08
Wynn's Cooling System Equipment Announcement ..... 08/08
"Back To Basics" Rattling Noises From Under the Car ..... 02/09

2009 M/Y Forester Fuel Gauge Inconsistency....02/09
2010 M/Y Impreza, Rattling Noise from Exhaust....10/09
More “Super Coolant” Information....10/09
WVJ-20 (Baja Fuel Pump Outlet Pipe) Revised Product Campaign Bulletin Information....11/09
2011 M/Y Impreza Fuel Door Update....12/10
2011 M/Y Forester Fuel Pressure Testing Information....02/11
Rough Idle Condition Following WVU-31 Reprogramming....06/11
DTC P0453 Diagnostic Information....11/11
FB Engine Fuel Pressure Testing Information....03/12
BRZ High Pressure Fuel Pump....07/12
BRZ Exhaust System Hardware....08/12
Radiator Leaks And Damage....08/12
Locksmith Information....09/12
Use of Dye In AC Systems....09/12
12 Impreza Muffler Appearance Change....10/12
New Fuel With 15% Ethanol....10/12
AF sensor and O2 sensor Removal....01/13
New Fuel 15% Ethanol Reminder....08/13
Hard to Fill Fuel Tank Revisited....12/14
Cooling System Appears to be Overfilled at PDI....06/15
P05A0 and Active Grill Shutter Inspection....01/17
Fuel Tank Cannot be Filled....07/17
Won’t Take Fuel Concerns – Revisited....08/21

## 10-Heating Ventilation & A/C Systems

A/C Service Oil Adjustment ..... 06/91
A/C Diagnostic Aids ..... 08/91
A/C Pulser System Electrical Diagnosis 89MY & 90MY Loyale ..... 08/91
1992MY Legacy A/C Compressor Bracket Discontinuation ..... 11/91
Justy Wynn's Air Conditioning Installation ..... 03/92
The Use of A/C Refrigerants Other Then R-12 ..... 07/92
Justy Air Conditioning Information ..... 07/92
Air Conditioning Evaporator Odor ..... 08/92
SVX Zexel Auto A/C ..... 09/92
Legacy A/C Compressor ..... 10/92
Legacy A/C Kit Supersession ..... 10/92
HFC134a Air Conditioning Refrigerant ..... 02/93
R134a Air Conditioner Refrigerant Service Bulletin ..... 03/93
Legacy Zexel Air Conditioning ..... 04/93
Legacy Compressor Belt Tension ..... 04/93
1993 MY Impreza Air Conditioning Inoperative ..... 07/93
Loyale Factory Installed A/C Does Not Operate ..... 07/93
HFC 134a Air Conditioning Systems ..... 07/93
SVX Auto A/C Display Degrees Celsius to Degrees Fahrenheit ..... 11/93
Bulletin 10-64-92 Heater Vent Door Binding or Leaking Air ..... 12/93
Refrigerant Cross Contamination ..... 01/94
0Z-12: The Facts ..... 02/94
SVX Complaints of No Heat from Dash Vents ..... 04/94
1995MY Impreza Coupe - Bubbles from the Dash Vents ..... 10/94
A/C Reminder ..... 05/95
PAG Oils ..... 05/95
Air Conditioner Hoses ..... 08/95
1995MY RHD Postal Legacy Air Conditioning System ..... 08/95
A/C System Diagnostic Tips ..... 08/95
A/C Testing For System Leakage ..... 08/95
SVX A/C Cutting out When Ambient Temperature Is Hot; SVX Engine Running Hot ..... 09/95
SVX Evaporator Thermo Sensor, Intake Sensor ..... 10/95
A/C Performance-All Models ..... 10/95
Refrigerant Recovery and Recycling Certification ..... 06/96
CFC R-12 Substitute Refrigerants ..... 06/96
Refrigerant Substitutions Warning ..... 08/96
SVX A/C Temperature Control Indicating Centigrade vs. Fahrenheit ..... 10/96
A/C Odors ..... 05/97
1997MY Legacy A/C Seal Ring (Axis Seal) Change ..... 05/97
1998MY Subaru Forester Dash Vent Noise ..... 09/97
1998MY Subaru Forester Squeaking Noise with A/C on ..... 09/97
Dust and Dirt Entering Rear of Vehicle ..... 11/97
Subaru Impreza Center Dash Vent Airflow ..... 07/98
Subaru A/C Retrofit Kits ..... 09/98
Use of A/C Dyes in Subaru Air Conditioning Systems, Manufacturer's Recommendations ..... 09/98
Seasonal Reminder ..... 05/99
A/C Retrofit Kit Information ..... 07/99
A/C Inoperative – Impreza/Forester Vehicles ..... 10/99
2000MY Legacy Heater Control Cables ..... 05/00

2001MY A/C Disconnect Procedure ..... 07/00
Mode Control Panel Change ..... 02/01
2001MY Legacy Evaporator Thermostat Probe Location ..... 07/01
Legacy H6 A/C Compressor Cutting Out ..... 08/01
Valeo/Zexel A/C TXV Fastener Torque Specification ..... 08/01
H6 Climate Control System Information ..... 09/01
Change To 2002MY Legacy/Outback A/C Information ..... 09/01
2001/2002MY Legacy Blower Motor Noise ..... 11/01
Blower Motor Noise ..... 08/02
Blower Motor Noise ..... 01-02/03
Auto. A/C System Aspirator Tubes ..... 07/03
Service Bulletin 10-72-02R – An Update ..... 10/03
B9 Tribeca Air Conditioning Information ..... 09/05
Water Leaking Onto Passenger Floor Board Area ..... 09/05
Water Leaking From A/C Evaporator ..... 10/05
2005MY Legacy/Outback: Water Leaking from A/C Evaporator ..... 11/05
2005~06MY Legacy/Outback Center Dash Vent Temperature ..... 05/06
B9 Tribeca Air Conditioning Information ..... 06/06
H6 A/C Compressors Cutting Off ..... 06/06
06MY Impreza Models: Manual Climate Control System Air Flow Dial “Spring Back” ..... 07/06
Refrigerant Dye Use to Detect Refrigerant Leaks ..... 10/06
A/C Operation Logic Change for 2007MY ..... 11/06
R134-A Recycling Recovery and Recharge Machines: New Manufacturing Standards ..... 12/06
2007 MY Forester A/C Compressor Changes ..... 04/07
A/C Certification –It’s the Law ..... 04/07
Erratic Dash Vent Temperatures ..... 02/08
HVAC Servo Harness Connector Confusion ..... 01/09
2010 – 11 Legacy / Outback Vibration Felt in the Brake Pedal ..... 11/10
Reminder- Use of A/C Leak Detection Dyes ..... 08/11
Center Dash A/C Vents Closing, 2010-12 M/Y Legacy / Outback Models ..... 11/11
2013-14Legacy and Outback Center Console Rear Air Vent Function ..... 03/14
A/C Diagnosis ..... 07/17
Condensation Inside Vehicles ..... 12/17
R-134 A/C Oil Guidelines ..... 07/18
B2242 Set With no Trouble Symptom ..... 02/19
Recovery of Contaminated R-1234yf ..... 08/20
2020+ Legacy/Outback Passenger Air Mix and Intake Air Door Actuators ..... 10/20
20-21MY LGY/OBK, “Setting temperature shift” in A/C CM customization ..... 05/21
2022 WRX AC Condenser, Oil Residue ..... 04/22

## 11-Emission Systems

Justy “Check Engine” Light On/EGR Hose Pulling Off ..... 11/91
ROM Reminder/Legacy A/T Vehicles ..... 12/91
SVX Trouble Code 12 ..... 12/91
SVX Code 37 O2 Sensor (LH) ..... 01/92
L-Series SPI Code 34 (EGR Solenoid) ..... 02/92
All Models False Trouble Codes ..... 04/92
Legacy Turbo Sport Sedan Code 45 (Pressure Sensor, Pressure Exchange Solenoid Valve) ..... 06/92
Legacy Code 32 O2 Sensor ..... 06/92
Justy Code 13 ..... 08/92
ROM Installation Tips ..... 09/92
ECU Memory-All Models ..... 09/92
Justy Trouble Code 23: Pressure Sensor ..... 01/93
O2 Sensors for XT4 and XT6 Vehicles ..... 12/93
Legacy Code 32 O2 Sensor ..... 03/94
Carbureted Vehicles with ID Codes While Engine Is Running ..... 06/94
OBD II - DTC P0441 “Evaporative Emission Control System Incorrect Purge Flow” ..... 11/94
OBD II Test Drives ..... 11/94
Legacy and Impreza Engines with No Injection Pulse #1 Cylinder ..... 03/95
Impreza Air Suction Valve Noise ..... 03/95
1995MY Subaru Legacy DTC P0505 - Idle Control System Malfunction ..... 06/95
1995MY Subaru Legacy DTC P0325 - Knock Sensor Circuit Malfunction ..... 06/95
1995MY Subaru Legacy DTC P0130 - Front O2 Sensor Circuit Malfunction ..... 06/95
Rough Idle on MPFI Vehicles ..... 07/95
1994MY Impreza ROM Sockets ..... 07/95
DTC P0505 Idle Control System When Solenoid Measures 5w or Less ..... 09/95
Extreme Cold Weather Engine Warm Up & OBD II ..... 12/95
Loose Fuel Caps & Trouble Code P0440 ..... 07/96
1997MY Legacy Warranty Claims For Loose Fuel Caps ..... 09/96
Legacy (Non Turbo), SVX, & Impreza ISC Valves ..... 09/96
DTC P0440 & Legacy Fuel Caps ..... 11/96
Blue Vs. Gray Connectors during Diagnosis ..... 11/96
Extreme Cold Weather Engine Warm-Up & OBD-II ..... 11/96
DTC P1500 Radiator Fan Relay One Circuit ..... 03/97
1997MY Subaru Impreza Outback Sport ..... 03/97
Understanding P0440 ..... 04/97
DTC P0507- Idle Control System RPM Higher Than Expected ..... 05/97
DTC P0500 ..... 07/97
Additional Information regarding Code P0440 ..... 07/97
OBD-II Cylinder Misfire Codes ..... 08/97
More P0440 Information ..... 10/97
Exhaust Smell during Cold Start ..... 01/98
Model Year 1998 Changes In P0440 Evap. Operation ..... 1/98 & 05/98
DTC P0440 Revisited ..... 05/98
DTC P0440 Tip ..... 11/98
DTC P1507 ..... 11/98
DTC P0705 Diagnostics ..... 05/99
Freeze Frame Data ..... 08/99
Evaporative System Diagnosis ..... 09/99
OBD Readiness Codes ..... 11/99
DTC P0440 1998/1999MY Forester ..... 1/99

WXV-79 Engine Control Module Service Program ..... 11/00
Freeze Frame Data ..... 05/01
Ignition Coil Service Precaution ..... 01-02/02
2002MY Legacy Atmospheric Pressure Solenoid Valve Operation ..... 03-04/02
DTC P1591 2002MY Impreza WRX M/T ..... 03-04/02
C.I.D. Number for Reprogramming ..... 03-04/02
WWG-90 Campaign Bulletin Correction ..... 08/02
ECM Reflashing Claim Coding ..... 01-02/03
Diagnostic Trouble Codes After WWK-94 ..... 05/03
ECM Calibration Identification Numbers ..... 05/03
ECM Reflashing ..... 05/03
Control Unit Reflashing Information ..... 07/03
Diagnostic Trouble Code (DTC) Detecting Criteria ..... 08/03
Rough Idle/Check Engine Light after Battery Disconnect ..... 09/03
Evaporative Canister Rattle Noise in '04MY Impreza ..... 09/03
ECM Reprogramming – A Reminder ..... 01/04
2004MY Legacy PZEV Vehicles ..... 04/04
DTC P1507 on 1996MY-1999MY Legacy Vehicles ..... 04/04
Updated Reprogramming Sheet ..... 05/04
ECM Reprogramming Fax Forms ..... 09/04
Freeze Frame Data ..... 09/04
Air Fuel Ratio Sensor Kits ..... 12/04
2005MY & Reflashing ..... 12/04
DTC P0171 ..... 04/05
Updated Reprogramming Sheet ..... 08/05
DTC P0171 ..... 09/05
Freeze Frame Data & Calling the TechLine ..... 09/05
ECU Reflashing ..... 10/05
DTC P0715 ..... 10/05
DTC P0171 – 2006MY H4 Legacy/Outback ..... 11/05
Throttle Sensor and Tumble Generator Valve (TGV) Sensors ..... 11/05
DTC P2097 & Reflashing ..... 01/06
3.0L Models: Fuel Requirements Revised ..... 02/06
DTC P0400 Diagnosis ..... 06/06
DTC P1443 ..... 08/06
DTC's & Reflashing ..... 09/06
Clearing DTC's on 2005-2007MY SIA-Built Vehicles ..... 02/07
Diagnostic Help for Evaporative System Codes ..... 04/07
Reprogramming Reminder: Jumper Harness Connectors ..... 05/07
DTC P0457 ..... 09/07
DTC P1443 and the 2008 M/Y Impreza ..... 11/07
Misfire Codes "Don't Forget To Check…" ..... 01/08
Secondary Air Injection System Codes ..... 12/08
WVH-18 & WVI-19 Service Program Information ..... 07/09
"Rusty" Appearance of the Exhaust System ..... 05/10
2010 Legacy GT DTC P0171 ..... 05/10
TIPS on Inspecting DTC P0171 or P0172 ..... 07/10
New 2011 M/Y Forester Evaporative System Testing ..... 12/10
2011 M/Y Forester: Sound From Under the Rear of the Car ..... 04/11
Rust Stains on Stainless Steel Exhaust Systems ..... 06/11
DTC P0457 Information ..... 07/11
2011 M/Y Forester, DTC P2610 ..... 10/11

Troubleshooting DTC P0457 on 08 and Later Model Years....02/13
Getting to the Bottom of Extended Cranking....03/13
WQD-40 A Reminder....04/13
Repeat 420 Codes on High Mileage vehicles....08/13
More Information on Stainless Steel Exhaust System Surface Rust....05/14
Secondary Air Injection DTC's P2441 and P2442....07/15
DTC P0171 Diagnostics....07/16
ELCM (Evaporative Leak Check Control Module) Self Testing for Diagnosis....03/17
DTC P0171 Diagnostics....12/17
DTC P1378- "Pre-Ignition Detected" – 2019MY Ascent....07/18
2019MY Ascent: DTC P0606, Control Module Processor: Diagnostic Hints....10/18
2015MY Legacy/Outback Seat Heater Operation Overview....12/18
Secondary Air Injection Diagnostic Trouble Codes P2441 and P2442....04/19
ELCM Self Testing for Diagnosis....10/19
P04AE Diagnostic Issues for 2019-2020MY Ascent....11/19
DTC P0171 Diagnostics....12/20
EVAP System Smoke testing....12/20
DTC P0171 Diagnostics....02/22

## 12-Body, Glass, & Upholstery


Legacy Glove Box Rattling Noise ..... 05/91
Wiper Blades ..... 08/91
Legacy Sunroof Shade Servicing ..... 10/91
Legacy Wiper Blade Improvements ..... 10/91
Legacy Wind Noise ..... 03/92
Legacy Modified Wiper Arms ..... 03/92
SVX Glass Replacement ..... 04/92
Legacy Upper Windshield Molding Loose ..... 05/92
Door Glass Squeaks Going Up & Down ..... 11/92
Windshield Wiper Maintenance Tips ..... 12/92
1992MY SVX Interior Noise Complaints ..... 08/93
1992MY SVX Sunroof sticking (Difficult to Open) ..... 08/93
Customer Complaints of Whistle Noises ..... 12/93
Seat Belts ..... 01/94
1993MY SIA Built Legacy, Headliner Droop ..... 03/94
1993MY Legacy SIA Built Legacy, Headliner Droop ..... 04/94
Legacy Trim Item Characteristics ..... 04/94
Legacy Door/Ignition Key Code Location ..... 04/94
Sunroof Water Leak Diagnosis ..... 05/94
Keys Plates ..... 10/94
Door Lock/Linkage Inoperative ..... 11/94
1995MY Legacy Wagon Rear Cargo Anchors ..... 12/94
1995MY Legacy Power Door Locks ..... 12/94
Foggy Film on Windows ..... 12/94
1995MY Subaru Legacy “Fluttering” Noise ..... 08/95
Subaru Outback Front License Plate Mounting Kit ..... 10/95
Winter Driving Tip, Interior Window Fogging ..... 01/96
Foggy Film on Windows ..... 01/96
Legacy Wind Noise ..... 02/96
Water in the Rocker Panels ..... 07/96
Loose Bolts on Window Regulators ..... 09/96
Poor Drainage from Rocker Panels: 1995/96MY Legacy Models ..... 09/96
‘97MY Legacy Body Creaking Noise, RH Side Rocker Panel Area ..... 02/97
Proper Operation of Seat Belts, ELR vs. ALR ..... 08/97
New Cup Holder For ’98MY Legacy ..... 11/97
Replacement Wiper Blade Refills ..... 09/98
Improper Driver’s Side Window Operation ..... 10/98
1999MY Impreza Wind Noise ..... 01/99
Bumper Cover Installation Tip ..... 02/99
Front Seat Tracks ..... 04/99
1999MY Forester Radio Antenna ..... 04/99
Tether Anchor Points 1995 – 1999MY Legacy Sedan/SUS ..... 07/99
2000MY Legacy Front License Plate Mounting ..... 09/99
2000MY Wiper Washer System ..... 09/99
Upholstery Items – Repair/Replace ..... 10/99
Forester Tailgate Squeaks/Rattles/Popping ..... 11/99
Metallic Window Tint Films ..... 04/00
Front License Plate Mounting For 2001MY Forester ..... 04/00
Wind Noise/Crossbar Installation ..... 08/00
Inoperative Windshield Washers ..... 02/01
WRX Aluminum Hood Precaution ..... 10/01

2002MY Impreza Sedan Trunk Lock Cylinder ..... 01-02/02
Windshield Wiper Washer Connection ..... 11/02
Sound Dampening Pad ..... 04/03
Adhesive Residue on Painted Surfaces ..... 08/03
Creaking Noise from Door Checker ..... 08/03
2003MY Forester Washer Nozzles ..... 09/03
2003-04MY Front Seatback Cover Reinstallation ..... 11/03
2001-02MY Forester Sunroof Leak ..... 11/03
2004MY Forester Rear Gate Damper Stay ..... 11/03
Striker Color Change ..... 02/04
2003MY Forester: Water Leak from Roof Rail Clip ..... 03/04
Forester Bumper Fastener Bolt Change ..... 03/04
2005MY Legacy Seat Belt Chime Activation ..... 08/04
Seatbelt Reminder System Disablement ..... 08/04
ODS Code 29 ..... 09/04
Frozen Wiper Blades ..... 12/04
Wiper Blades & Winter Weather ..... 01/05
2005MY Legacy/Outback Moon Roof Sunshade Block & Rod Assembly ..... 02/05
B9 Tribeca Front License Plate Mounting ..... 04/05
Wiper Blades & Visibility ..... 06/05
Adhesive Residue On '06MY Forester Rear Tailgate Garnish ..... 07/05
Wind Noise Diagnosis ..... 10/05
VIN Plate Location Change ..... 10/05
Wiper Blades – The Basics ..... 10/05
2006MY Impreza Tool Tray ..... 10/05
Front Washer Nozzle Does Not Spray Properly ..... 01/06
Ashtray Door Paint ..... 04/06
2005MY Legacy Repair Procedure of Overhead Console when the Lid is Hard to Open/Close ..... 04/06
2003~05MY Forester Sunroof Squeaks ..... 05/06
2004-2007MY Forester Sunroof Operation ..... 09/06
Baja Factory Installed "Hard" Bed Cover Replacement Keys ..... 12/06
Forester Rear Gate Handle Binding ..... 01/07
B9 Tribeca Body "Popping-Type" Noise From the Right Front Strut Area ..... 01/07
2007 MY Legacy & Outback Overhead Console Door Binding ..... 04/07
2003-2008 MY Forester Sunroof Squeak ..... 04/08
2009 MY Forester Side View Mirror Torque ..... 05/08
2009 MY Forester Undercoated Wheel Wells ..... 06/08
Rear Wiper Blade Refill ..... 05/07
Impreza, Water in the Trunk ..... 03/07
2008 M/Y Impreza, Rattling Noise from the Right Front ..... 09/08
2009 Forester Buzzing or Rattling Noise from the Front Doors ..... 11/08
Forester Sunroof Not Closing Properly ..... 11/08
Subaru Genuine Wiper Blade Inserts ..... 01/09
2009 M/Y Impreza Rear Seat Updates ..... 02/09
2009 M/Y Forester Rear Combination Lamps ..... 03/09
2009 M/Y Forester Tailgate Grommet Removal ..... 03/09
2009 M/Y Forester Rattling Noise from Rear of Head Liner ..... 04/09
2010 M/Y Legacy & Outback Power Lumbar Support Operation ..... 09/09
2008-09 M/Y Impreza, Rattling or Vibration Noise from Right Front ..... 09/09
2009-10 M/Y Forester Rear Gate Creek ..... 11/09
2010 M/Y Outback Flapping or Fluttering Noise ..... 11/09
2009-10 M/Y Forester Rear Seat Rattle / Squeak ..... 01/10

Buzzing / Vibration Noises from Inside the Doors ..... 12/09
2010 Legacy / Outback Rattle From Overhead Console Area ..... 04/10
Whistling Noise from Windshield Area at Highway Speed ..... 05/10
Slow or Erratic Door Glass Operation ..... 05/10
Stained Rocker Sill Moldings ..... 11/10
Forester and Impreza Rear Quarter Glass Moldings ..... 01/11
Bare Metal Visible in Tie-Down Areas of Undercarriage ..... 04/11
Popping or Creaking Sound from L/Rear, 2010 M/Y Forester ..... 05/11
Buzzing / Vibration Noises Inside the Doors, 2008 and Later Impreza ..... 07/11
Windshield Cracks on the Inside ..... 07/11
2011 M/Y Forester, Rattling Noise from the Rear Roof Area ..... 10/11
Heat-Damaged Plastic Parts ..... 10/11
WVV-32 Campaign, Cowling Clip Removal Tips ..... 10/11
Windshield Cracks on the Inside, A Reminder ..... 11/11
2010-11 M/Y Outback “Popping” or “Tick” Noise from the “B” Pillar Area ..... 11/11
2012 Impreza Glove Box Light ..... 07/12
Cleaning Spotted Window Glass ..... 07/12
BRZ Rear Fold Down Seats ..... 07/12
BRZ Protective Sun Visor Cover ..... 08/12
A-Pillar Trim Tether Clips ..... 08/12
Impreza Rear Package Shelf Rattling Noise ..... 09/12
2010 to 2012 Headliners ..... 09/12
Removal of protective film on side sill plate cover 13 BRZ ..... 10/12
12 MY Tribeca Roof Rail ..... 11/12
09-13 MY Forester Rear Seat Reclining Button ..... 11/12
13 MY BRZ Rear Bumper Removal ..... 11/12
Windshield Cracks on the Inside (Reminder) ..... 01/13
WQA-37 Campaign (Special Pliers) ..... 03/13
Melting Plastic Parts ..... 05/13
BRZ Front Bumper Cover Removal Precautions ..... 01/14
2014 Forester Power Rear Tailgate ..... 04/14
Whitish Discoloration/ Deposits on Front Door Panels, 12MY and Later Impreza and Cross trek ..... 06/14
2015 Legacy and Outback Seat Heater Overview ..... 08/14
2015 Legacy/ Outback Center Console Compartment Door Information ..... 09/14
Design Change to the Zippers Used On Front Seat Backrest Covers ..... 09/14
Rattle Sound from Right Side of Dash Area ..... 01/15
Whitish Discoloration/ Deposits on Front Door Panels, 12MY and Later Impreza and Crosstrek
2015 WRX and STI ..... 01/15
Fuel Door Freeze Up ..... 04/15
Erratic Washer Fluid Level Warning Lamp Illumination ..... 09/15
Glass Authorization Request-Additional photo required ..... 11/15
2015 Legacy/ Outback, Rattling Sound from Front of Vehicle ..... 12/15
Interior Rear View Mirror Separation Reminder ..... 07/16
Water Draining from Body Panels ..... 11/18
Snowflake Type Damage to Glass ..... 01/19
Cleaning Spotted Window Glass ..... 02/19
2019MY Ascent, Spare Tire Hoist Precautions ..... 05/19
Rattle Sound from Steering Wheel Area ..... 02/20
Ascent Wind Rushing Noise ..... 03/20
2019MY and up Forester- Airbag Warning Light Illumination Caused by the Use of Water and / or Glass Cleaner ..... 06/20
Water leaking into cabin from door trim all models and model years ..... 08/20

Ascent Sunroof Frame Assembly....05/21
Rattle sound from driver side dash area....06/21
2022MY BRZ Front and Rear License Plate Installation .... 11/21
Diagnosing Repeat P2762 and P2757....07/22

## 13-Paint

3M Paint Polishing Assistance ..... 03/92
'95MY Legacy Outback Paint ..... 01/95
Correction to Service Bulletin 13-67-95r ..... 11/95
Helpline Update ..... 01/96
Water Spotting On Painted Surfaces ..... 09/96
Paint Procedures for Subaru Bumpers ..... 08/01
Trim and Paint Code Update ..... 04/04
2005MY Forester LL Bean Models Color Code Information Correction ..... 11/04
Paint Discoloration in Wheel Opening Areas ..... 10/09
Finishing Plastic Parts ..... 04/10
XV Crosstrek Paint Schemes/Under Hood Insulator ..... 11/12
Paint Condition on Hood – Moisture Stain ..... 12/18

## 14-Special Tools

Select Monitor Cartridge ..... 10/91
4EAT Valve Body Servicing ..... 12/91
4EAT Band Servo Servicing ..... 12/91
System Check Units for '85MY, '86MY, and '87MY ..... 04/92
SVX Select Monitor Cartridge ..... 04/92
Select Monitor Repair ..... 08/92
Air Conditioning Refrigerant Recycler ..... 08/92
Special Tools for Rear Wheel Bearing Replacement on Legacy All-Wheel Drive Models ..... 09/92
Select Monitor Cartridge Application Chart ..... 11/93
Transmission Pressure Gauge Set ..... 03/94
Select Monitor Repair ..... 11/96
Subaru New Select Monitor Repairs ..... 07/99
2001MY Subaru Forester select monitor cartridge ..... 02/00
New Select Monitor Repairs – An Update ..... 11/00
New Select Monitor Cartridge ..... 01/01
Subaru Fuel Injector Cleaner Tool ..... 05/01
Select Monitor Cables ..... 10/01
Select Monitor Image Loader Software/Hardware ..... 03-04/02
Oxygen Sensor Removing Tool ..... 01-02/03
2003MY Impreza Select Monitor Cartridge Application ..... 01-02/03
Select Monitor Repairs – An Update ..... 10/03
2005MY Legacy/Outback Key Cutter ..... 10/04
Kent-Moore Website ..... 11/04
Select Monitor Repairs: Latest Information ..... 03/05
SDS (Subaru Diagnostic System) & Mode Files ..... 02/06
SDS Kit & Pre-Testing Your Subaru Select Monitor III ..... 03/06
Subaru Select Monitor III & CID Numbers ..... 03/06
Updated Repair Center Phone Number for Kent-Moore ..... 06/06
New Menu Prompts When Calling the SDS Technical Support Helpline ..... 07/06
Mid-Tronics EXP-1000 ..... 08/06
New Special Tool Kit SOA321064 Sent To All Subaru Dealers ..... 10/06
Front Fender Insulator for WRX and STI (Excluding STI Limited) ..... 12/06
Latest SSMIII Software Download Version ..... 03/08
Re-Booting Your SDS Notebook ..... 04/08
Latest SSMIII Software Download Version ..... 06/08
SDS Notebook (CF-18) Helpful Hints ..... 07/08
Latest SSM III Software Version Download ..... 09/08
Legacy / Outback M/T High Idle Re-Flash Clarification ..... 10/08
SSM III Pulse / Analog Kit (Oscilloscope) Information ..... 10/08
Issues with Using SMART (Subaru LMS System) ..... 11/08
Replacement Cables For Subaru Diagnostic System (SDS) ..... 03/09
Fuel Alcohol Tester ..... 04/09
Fuel Pressure Tester Warning from SPX ..... 09/09
Select Monitor (SDS) Issues with Campaign WVM-23 ..... 12/09
Important Engine Support Bracket Return Information ..... 04/10
SDS Printer Problem…. Who You Gonna' Call? ..... 06/10
Techline Pre-Call Worksheets ..... 08/10
CF-U1 Reprogramming Kit Monitor Use ..... 07/11
Flashwrite Error Code 4404 ..... 08/11
Power Steering Rack Service Tool Information ..... 09/11

Using the Service-Techline Reporting Feature on Subarunet ..... 09/11
Body Repair Manual User Information ..... 11/11
2012 Impreza Special Tool Shipments ..... 12/11
New Snap-On Ball Joint Remover Instructions ..... 04/12
Connecting Rod Bolts on FA and FB Engines ..... 09/12
Printing Freeze Frame Data ..... 09/12
Special Tools For The BRZ ..... 09/12
Engine Bridge Replacement Parts ..... 11/12
Test Harness Probes ..... 12/12
Using Your Oscilloscope ..... 12/12
SDI Interface Box and Self Shut Timer ..... 01/13
14MY Forester SSM3 Operation ..... 01/13
SSM3 Unit Of Measurement ..... 08/13
Subaru Special Tools Website URL Update ..... 01/14
GR-8 Battery Testing Information ..... 03/14
New SSM4 software on the C2 Toughbook ..... 06/15
Recommendations for use of the Denso DST-I diagnostic interface ..... 09/15
Stopper Tool for CVT and Automatic Transmissions ..... 11/15
April 2016 SSM4 Changes ..... 04/16
Precautions When Using the DST-I Box ..... 08/16
New Function SSM4 October Version ..... 11/16
SSM3? SSM4? Generic? What Diagnostic Scan Tool Should I Use? ..... 04/17
New Special Tool – Relay Pliers ..... 02/18
WUE-90 Stop Lamp Switch Recall, Special Tool Tip ..... 05/19
False Error Message Displayed When Scanning 2019MY Impreza Sedan with SSM4 ..... 07/19
Errors when Programming with Flashwite® 2 ..... 02/20
Special Tools - Denso USB Cable ..... 04/21
Midtronics DSS-5000 Helpful Hints ..... 04/22
Denso USB Cable & ECM/TCM Reprogramming ..... 07/22

**15-Accessories**

Radio Display Interruption with Brake Pedal Application ..... 05/91
Justy Radio Display Fade ..... 07/91
SVX Security System ..... 10/91
Legacy, Noise Heard Through Speakers When the Illumination Control Is Varied, Clarion Radio ..... 10/91
Quick Cruise Control Check ..... 12/91
SVX Radio Servicing ..... 12/91
SVX Security System ..... 01/92
SVX Compact Disc Player ..... 02/92
SVX Security System Warning ..... 02/92
Legacy Cruise Control Installation ..... 03/92
Loyale Cruise Control for 92MY ..... 03/92
L-Series Poor Radio Reception ..... 03/92
L-Series Clarion 10 Watt ETR and Panasonic Elite LC Cassette Deck Incompatibility ..... 03/92
Radio/Cassette/CD Exchange Or Out Of Warranty Repair Programs ..... 04/92
Accessory Cruise Control Installation in Rural RHD Legacy Postal Models ..... 04/92
Legacy Security System Wiring Information ..... 04/92
1992MY Legacy Cruise Control Installation ..... 06/92
Loyale SOA386C110 Cruise Control Installation Tips ..... 06/92
Legacy Station Wagon “LS” Power Antenna ..... 07/92
Legacy Security System Installation 1991MY to Present Station Wagon Models ..... 07/92
Loyale (SOA386C110) Cruise Control Installation Tips Correction ..... 07/92
Tips for Installing Security System SOA386R100 in A 1992MY Loyale ..... 03/93
Impreza IAC Formerly Called FICD Adjustment ..... 04/93
SVX Audio Assembly Removal ..... 06/93
1993MY SVX New Security System Installation Tips ..... 08/93
Legacy Panasonic 80 Watt Radio Noise in Speakers ..... 08/93
Poor Radio Reception AM or FM ..... 10/93
Legacy & SVX Security System Transmitter Battery Servicing ..... 10/93
SVX New Security System Programming Tips ..... 10/93
SVX Rear Speakers Buzzing ..... 01/94
1995MY Legacy Security System ..... 07/94
1995MY Legacy LSI Security System ..... 09/94
Accessory Block Heaters ..... 10/94
1990MY-1994MY Legacy Security System Operation Q&A ..... 10/94
Installing 1995MY Legacy Roof Racks ..... 11/94
Impreza Accessory ..... 01/95
Hubcaps ..... 01/95
Accessory “Outback” Wheel Covers ..... 03/95
1995MY Subaru Legacy Front End Cover (Bra) ..... 03/95
Installing Impreza Fog Lamp Kits ..... 03/95
Cruise Control & the Use of the Select Monitor ..... 04/95
1995MY Legacy Cruise Control Corrections ..... 04/95
1995MY Legacy LSI Security System Module I/O Chart ..... 04/95
1995MY Legacy S/W Accessory Fork Mount Bike Carrier ..... 05/95
Impreza Foglight Installation ..... 05/95
Radio Noise ..... 06/95
1995MY Subaru Legacy LSI Alarm System ..... 06/95
1995 Subaru Legacy Cruise Control ..... 06/95
Testing Cruise Control Pumps ..... 09/95
Installation of Subaru Impreza ‘LX’ S/W Rear Spoiler ..... 09/95
1995MY Subaru Legacy with Panasonic Radios ..... 11/95

1995MY/1996MY Subaru Impreza & Legacy Cruise Control Applications ..... 11/95
Alloy Wheel Center Caps ..... 12/95
Impreza Fog Lamp Kit P. N. H4510FA100 Fuse Location & Wiring Changes For ’96MY ..... 12/95
Outback Trailer Hitch Part Number L1010AS000 Change In Torque Spec. ..... 12/95
Cruise Control for 2.2 Liter ’96 MY Impreza Manual Trans. Vehicles ..... 12/95
Cruise Control for Newer Legacy Models ..... 12/95
Legacy Remote Keyless Entry System ..... 12/95
Legacy Keyless Entry Diagnosis ..... 01/96
Legacy Accessory Keyless Entry System ..... 01/96
Legacy Roof Rack Installation Information ..... 02/96
Installation Instruction Supplement For ‘96MY Impreza Foglamp Kit #H4510FA100 ..... 04/96
Interior Lights Stay On When Leaving the Car ..... 04/96
1995MY & Up Legacy LSI Keyless Remote System ..... 04/96
Keyless Entry Erratic Transmitter Operation ..... 05/96
Modification to Keyless Entry System Instructions ..... 05/96
Revised 1996 1/2MY and 1997MY Legacy Cruise Control Supplemental Installation Instructions ..... 07/96
1995 & 1996MY Subaru Legacy W/Power Antenna ..... 08/96
1997 Legacy Keyless Entry ..... 08/96
Legacy Outback Trailer Hitch Harness ..... 08/96
Legacy Outback Crossbar Installation Tips ..... 08/96
Legacy LSI Security System ..... 10/96
1996MY Impreza Accessory Keyless Entry Kit H7110FS000 ..... 01/97
1997MY Impreza Accessory Cruise Control ..... 01/97
Outback Roof Rack Crossbar Bolt Part Number Correction ..... 01/97
Legacy Subwoofer/Preamp, P/N H6300AS030 ..... 02/97
Legacy Outback Trailer Hitch Wiring Harness ..... 02/97
Legacy Keyless Entry with Security Upgrade ..... 02/97
Correction to Installation Instructions for Keyless Entry Kits H7110AS000 & H7110AS300 For 1995MY & 1996MY Legacy ..... 02/97
1997MY Impreza Keyless Entry Kit H7110FS000 with Incorrect Wiring Harness ..... 02/97
1997MY Legacy Keyless Entry/ Security System Programming Button Locations ..... 02/97
1997MY Legacy Keyless Entry & Security Upgrade Modifications ..... 03/97
Legacy Keyless Entry/ Security System Upgrade ..... 04/97
1997MY Impreza Foglamp Installation Tips For Kit #H4510FA200 ..... 05/97
1997MY Legacy; Programming Replacement Keyless Entry Control Unit ..... 07/97
New CD Changer Installation Procedures ..... 08/97
Forester Removable Antenna ..... 09/97
1996MY Subaru Legacy Keyless Entry System Not Operating Correctly ..... 09/97
Subaru Keyless Entry Batteries ..... 09/97
Accessory Gauge Pack Information ..... 10/97
1998MY Forester Keyless Entry System Information ..... 10/97
1998MY Impreza Cruise Control Connector ..... 01/98
Keyless Entry System Operation ..... 01/98
Forester Accessory Brush Guard ..... 01/98
1998 Impreza Foglight Kit #H4510FA200 ..... 02/98
1998 Subaru Forester Power Mirror Kit ..... 03/98
Update of Keyless Entry Bulk Head Harness Change ..... 04/98
Keyless Entry/Alarm System Upgrade ..... 04/98
1998MY Impreza Foglight Kit #H4510FA200/220 Correction ..... 04/98
Subaru Keyless Entry/ Security System Reference Guide ..... 04/98
Subaru Accessory Installation Manual ..... 04/98
Programming SVX Alarm Systems ..... 04/98

1998MY Subaru Forester Power Mirror Kit P/N Correction .....05/98
Legacy Station Wagon Audio Harness .....05/98
Accessory Operator Instructions for 1999MY .....07/98
1999MY Legacy Accessory Changes and Corrections .....07/98
Rear Differential Protector .....08/98
Poor AM Radio Reception on Forester Vehicles .....10/98
1999MY Legacy Accessory Cruise Control .....11/98
Keyless Entry/ Security System Transmitter Batteries .....01/99
1999MY Cal. Spec. Impreza Security Kit Availability .....01/99
Shock Sensor Mounting for Forester/Impreza with Security Upgrade .....01/99
Keyless Entry into 1999MY Forester Vehicles with 'All Weather Package' .....01/99
Keyless and Security System Quality Improvements .....01/99
1999MY Forester Radio Noise/Poor Reception .....04/99
1999MY Forester – Clicking Noise from Right Front Speaker .....05/99
Alpine Keyless Entry with Security Upgrade System Operation Reminder .....07/99
Lighted Mirror Sunvisor Replacement Bulbs .....08/99
No Radio Volume – 2000MY Legacy Limited Model Wagons .....08/99
1999MY/2000MY Legacy Alpine Keyless Entry/ Security System Dome Light Operation .....10/99
Trailer Hitch Bike Attachment .....11/99
2000MY Legacy Rear Spoiler .....11/99
Auto Dimming Mirror/Compass.....01/00
Rear Gate Bar P/N E7510lS001 2000MY Legacy Wagons.....05/00
Compass Mirror 2000MY Legacy & 2001MY Forester.....05/00
Electrochromic Compass Mirror .....05/00
Accessory Installation Instructions on Web .....05/00
CD Player/Changer Visual Reference.....05/00
Performance Gauge Pack Operation .....05/00
2000MY Legacy/Outback Hood Deflector 'W' Clips Installation .....07/00
Replacing a Keyless Entry Transmitter Battery.....08/00
2001MY Forester Front Splash Guard Installation (P/N J1010FC000).....08/00
Accessory Block Heaters.....10/00
Internal Trunk Release Handle .....01/01
2002MY Impreza Accessory Application – Compass Mirror .....03/01
2002MY Impreza Trailer Hitch P/N I1010SS000 .....03/01
2002MY WRX/Impreza TechTIPS Special Edition.....03/01
Cross Bar Positioning.....05/01
Short Throw Shifter .....05/01
Accessory Updates.....07/01
Titanium Shift Knob (P/N C1010FA100) Shift Emblem Location .....09/01
WRX Performance Gauge Pack.....10/01
Impreza Sedan Spoiler Installation Tips.....10/01
Forester Splash Guard Installation Tips .....10/01
WRX Steering Column Mounted Boost Gauge.....11/01
2002MY Impreza Subwoofer/Amplifier Compatibility.....11/01
2002MY Impreza Front Under-Spoiler Installation Change.....11-02/02
2002MY WRX Front End Cover.....01-02/02
2002MY Impreza 120 Watt Subwoofer Bracket Change.....01-02/02
EC Compass Mirror Calibration .....03-04/02
BAJA Bed Extender .....09-10/02
Seat Heater Information .....03/03
New Baja & Legacy Hood Deflector Installation .....03/03
Impreza Sedan Spoiler Changes.....05/03

Baja Bed Cover Replacement ..... 05/03
STI Security Module Torque Specifications ..... 07/03
Bumper Beam Plug for Baja Trailer Hitch ..... 07/03
2004MY Forester Hood Deflector/Protector ..... 08/03
Tonneau Cover Replacement Parts For Legacy 00MY~03MY ..... 08/03
2004MY STI Single Turbo Gauge Installation/Intercooler Removal ..... 08/03
Revised Electronic Control Compass Mirror ..... 08/03
2004MY Forester Single Turbo Gauge Installation/Interior Trim Removal ..... 08/03
WRX STI Audio System ..... 08/03
WRX Performance Suspension Kit (STI) ..... 09/03
Baja Sport Activity Lights ..... 09/03
Baja Sport Activity Lights - Relay Location ..... 01/04
Forester Crossbar Design Revision ..... 01/04
Baja Bed Cover Replacement (Reprint from May 2003) ..... 01/04
Poor Radio Reception ..... 02/04
Baja Sport Activity Lights – Relay Location – Correction ..... 02/04
What's That Noise? ..... 04/04
Poor Radio Reminder ..... 04/04
Cruise Control Actutator ..... 04/04
Trailer Hitch Installation ..... 07/04
'05MY Sedan Spoiler Template ..... 07/04
'05MY Splash Guard Tape Area ..... 07/04
'05MY Cargo Net Anchors ..... 07/04
'05MY Legacy & Outback Hood Protector Mounting Points ..... 07/04
2005MY Legacy and Outback Crossbar Positioning ..... 07/04
EC Compass Mirror Mounting ..... 07/04
2005MY Legacy & Outback Ambient Temperature Sensor ..... 07/04
Subwoofer ..... 07/04
Rear Cargo Net Pre-Arranged Drill Marks ..... 07/04
Trailer Hitch Installation ..... 07/04
Impact Sensor (Shock Sensor) Activation ..... 07/04
Impact Sensor (Shock Sensor) Location ..... 07/04
2005MY Legacy/Outback H-4 & H-6 Model Relay Location ..... 07/04
Sedan Spoiler Tether Location ..... 07/04
2005MY Key and Remote Transmitter New Vehicle Check-In Procedure ..... 08/04
Non-Aero Cross Bar Kit ..... 09/04
Sub-Woofer Wiring Harness Re-Routing ..... 11/04
Engine Block Heaters ..... 11/04
Immobilizer Information ..... 12/04
Immobilizer Registration & Cell Phones ..... 12/04
2005MY Legacy Air Filtration Retrofit Kit ..... 04/05
Don't Get Alarmed ..... 05/05
Keyless Remotes ..... 06/05
2005MY Legacy & Outback Air Filter Installation ..... 07/05
Navigation Screen Removal for Subaru B9 Tribeca ..... 07/05
B9 Tribeca Special Edition 2005 (Accessory Information) ..... 07/05
Immobilizer Security Codes ..... 08/05
False Shock Sensor Activation ..... 08/05
B9 Tribeca False Alarm Activation ..... 10/05
2006MY Legacy/Outback Impact Sensor Installation ..... 11/05
EC Mirror Configuration & Application ..... 01/06
Auto-Dimming Compass Mirror (P/N H501SAG100) ..... 03/06

2006MY Forester Impact Sensor Adjustment ..... 03/06
Forester Crossbar Noise ..... 04/06
Keyless Entry Remote Inoperative ..... 05/06
Navigation Display Illumination in Cold Weather ..... 05/06
2006 Immobilizer Component Replacement Guide ..... 07/06
XM Satellite Radio Installation Instructions ..... 08/06
Immobilizer Code Requests ..... 11/06
“Teaching Codes” With an Immobilizer System ..... 11/06
Special 2007MY Issue: B9 Tribeca Accessories ..... 12/06
XM Satellite Radio “Re-Pinging” ..... 01/07
Horn Beeps Erratically When Using RES System ..... 01/07
NAV System Software Update Availability ..... 03/07
Immobilizer Programming & RES Parts Information ..... 03/07
Immobilizer Interface Programming ..... 03/07
Remote Engine Start System- Start Attempt Failure ..... 04/07
OnStar Analog System Phase-Out Information ..... 05/07
2007-08 MY Remote Engine Start Information ..... 07/07
Remote Engine Start Programming Problems ..... 08/07
Sirius Satellite Radio Diagnostic Flow Chart ..... 08/07
2008 MY Impreza Outback Sport & 5-Door Roof Rack Accessory Cross Bars ..... 09/07
NAV / Aftermarket RES System Interference ..... 09/07
Satellite Radio Diagnosis Quick TIP ..... 09/07
Immobilizer “Invalid Teaching Code” Message ..... 10/07
2008 M/Y Impreza Accessory TIPS ..... 10/07
Understanding the Security System Indicator Light ..... 11/07
RES System “Quick TIPS” ..... 12/07
More Immobilizer Helpful Hints ..... 01/08
Tribeca Crossbar Rattling Noise ..... 01/08
Erratic Horn Operation ..... 02/08
Audio System Upgrades: XM / Sirius / iPod Interface ..... 03/08
Important Information Regarding The iPod Interface ..... 03/08
RES Troubleshooting Guides ..... 03/08
Dealer Accessibility to Immobilizer Security and Key Codes ..... 04/08
2009 MY Forester Accessory Installation TIPS ..... 05/08
Impreza Shock Sensor Installation ..... 07/08
Immobilizer Teaching Codes, 2005-09, Breaking the Code ..... 07/08
Remote Engine Start Troubleshooting Guides ..... 08/08
2009 M/Y Forester Wheel Arch Molding Installation Guide ..... 08/08
2009 M/Y Forester Puddle Light Connectors ..... 09/08
Quick Tip: Hands-Free Installation, 2009 M/y Forester & Impreza ..... 09/08
Are You NOT Hearing Voices? ..... 09/08
Reminder: RES Kits Are Not Interchangeable ..... 10/08
2009 M/Y Forester Trailer Hitch / Arch Molding Information ..... 10/08
iPod Interface Information, 2008-09 MY Impreza & 2009 M/Y Forester ..... 11/08
Immobilizer Code / Subaru Lock Info Site (SLIS) Information ..... 11/08
2009 Forester Satellite Radio-Equipped Tuner Clarification ..... 11/08
iPod Interface Charging Information ..... 12/08
Back-Up Sensor False Alarms, 2008-09 Tribeca ..... 12/08
Low Speaker Volume, 2008 M/Y & Later Impreza & Forester ..... 12/08
Accessory Bluetooth “No Caller ID” Message ..... 02/09
Audio / NAV Unit Removal Precautions ..... 03/09
RES Antenna Ring Replacement Information ..... 04/09

2008-09 M/Y Impreza & 2009 M/Y Forester Wind Noise When Using Ski Carrier....04/09
Revised Impreza Roof Rack Crossbar....05/09
2010 M/Y Legacy & Outback Keyless Entry Inoperative....07/09
2010 M/Y Legacy & Outback Denso A/C Compressor Warning....08/09
iPod Charging Information....08/09
2010 M/Y STI Satellite Radio Information....09/09
2010 M/Y Legacy & Outback RES Reminders....09/09
2010 M/Y Tribeca Radio Removal w/ Center Dash Speaker....10/09
2010 M/Y Tribeca Back-Up Sensor Kit Applicability....11/09
2010 M/Y Legacy Sedan Erratic Alarm Activation....11/09
Navigation Discs, There IS A Difference!....12/09
Teaching Codes… A Reminder....01/10
Remote Engine Start Programming....01/10
Remote Keyless Entry Fob Supersession....02/10
2.5L Accessory Block Heater Installation Precaution....03/10
2007 - 09 RES Performance Issues in Cold Weather....03/10
Electrical Problem? Check That Compass Mirror Harness....03/10
2001 – 04H6 A/C Compressor Short-Cycling Reminder....04/10
Keyless Entry Inoperative After Starting Engine with RES....04/10
Decreased Radio Volume in Reverse....05/10
Satellite Radio Artist / Song Information Not Scrolling....05/10
Helpful Bluetooth Information and FAQ's....06/10
2011 M/Y Legacy / Outback Bluetooth Microphone Inoperative....07/10
Excessive A/C Pressures....07/10
Remote Engine Start (RES) Troubleshooting Reminder....07/10
2009 – 10 Forester 6 CD Changer Audio Unit Information....07/10
No or Reduced Sound from Rear Speaker Concerns....08/10
Thule Cargo Box Replacement Keys and Lock Cylinders....08/10
2010 – 11 M/Y Outback Rocker Trim Removal....08/10
RES Service Kit Reminders....09/10
2011 M/Y Impreza Bluetooth / Subwoofer Interference....09/10
Mobile Internet Installation Information....09/10
Media Hub Installation Reminder....09/10
TomTom Navigation System Information....11/10
Deformed Cargo Mats....11/10
2011 M/Y Forester Block Heater Installation Instruction Change....12/10
Navigation "Hard Keys" Flashing / Screen Issues....12/10
RES System Key / Remote Registration Information....12/10
Kenwood Navigation System Troubleshooting Guide Released....12/10
Aftermarket GPS Signal Interference Issues....12/10
2011 Legacy / Outback Revised Dash Speaker Grilles....01/11
Sunroof Motor Replacement Precaution....01/11
Updated RES and TomTom Troubleshooting Guides....01/11
Updated Subwoofer Harness Now Available....02/11
2011 M/Y Outback Compass Mirror "Lock-Up"....02/11
No sound Heard When Using Bluetooth....03/11
No Sound Output from the Audio Unit....04/11
Crackling Sound from the Speakers w/ Key off....04/11
Radio Volume Changes by Itself While Driving....04/11
iPod Scrolling With TomTom Audio System....05/11
Block Heaters and DTC P0126....05/11
Panasonic Audio Unit Exchange Procedure Change....06/11

Tribeca Rear A/C Inoperative or Poor Performance ..... 07/11
Rattling Noise from Right Side of Engine ..... 07/11
Troubleshooting Guides on STIS ..... 07/11
2011 M/Y Impreza, Crank / No Start, Security Light Flashing ..... 08/11
Bluetooth Connection Concern, Can You Hear Me Now? ..... 09/11
Bumper Corner Molding Installation Information ..... 09/11
Blank or “White Screen” Navigation Display ..... 09/11
Use of Aftermarket Engine Under-Covers ..... 11/11
Engine Block Heaters and DTC P0126 (Updated) ..... 11/11
2012 M/Y Impreza Immobilizer Changes ..... 01/12
2010-11 M/Y Legacy / Outback Bluetooth Inoperative ..... 01/12
2012 M/Y Impreza Audio Unit Exchange Information ..... 01/12
2012 M/Y Impreza Remote Engine Start Programming Information ..... 01/12
Rear Seat Entertainment Troubleshooting and User Guides ..... 02/12
2010 and Later (Non-Interface) RES Diagnosis, Don’t Overlook This Step ..... 02/12
2012 M/Y Impreza RES Key Fob Flashing ..... 03/12
Fujitsu-Ten Navigation Units and SD Cards- Important Information ..... 04/12
2010-12 M/Y Outback Cargo Mat Precaution ..... 04/12
Revised Home-Link Mounting Adapter ..... 04/12
Fujitsu-Ten Navigation Screen Display ..... 05/12
2013 BRZ Antitheft Security/Alarm System Activation ..... 07/12
Push Button Start Vehicles Equipped With Remote Engine Start ..... 09/12
Accessories and Eyesight ..... 10/12
2013 Smart Engine Start ..... 10/12
Resources For XM Traffic Inquiries/Concerns ..... 11/12
Bluetooth Information ..... 12/12
13MY Legacy/Outback Navigation Volume Adjustment ..... 01/13
Wheel Locks ..... 01/13
Voice Clarity ..... 03/13
F-10 Diagnostics ..... 03/13
Voice Recognition ..... 03/13
2014 Forester and 2013 Legacy Keyless Access and Keyless Entry ..... 05/13
Navigation Voice Guidance ..... 05/13
2014 Forester Speaker Kit Installation ..... 05/13
F-10 Audio/Navigation Units-No power or Display ..... 08/13
Major RES (Remote Engine Start) Differences 2007 to 2014 ..... 09/13
HomeLink Mirror Programming Information ..... 01/14
2010-14 Outback Rear Bumper Under guard Accessory Reminder ..... 03/14
2015 Legacy and Outback Keyless Entry Audible Signal Feature ..... 08/14
2015 Legacy/Outback XM Reverting to Preview Channel ..... 11/14
2015 Legacy/Outback, Starlink , iHeart Radio Application Information ..... 12/14
Damaged USB Ports ..... 02/15
Selectable Run Time for 2015 Remote Engine Start ..... 03/15
Remote Engine Start (RES) Inoperative, No Response from Remote on Push-Button (Smart) Start Models ..... 05/15
Use of Aftermarket Accessory Engine/Fuel Economy Monitors ..... 07/15
Subaru STARLINK telematics Retailer PDI Process ..... 08/15
Gen 1 F10 Navigation System-Red Light Alert Function ..... 08/15
2015MY Legacy & Outback, GPS Signal Loss w/F10 Navigation System ..... 10/15
Accessory Floor Mat Reminders and Precautions ..... 11/15
Accessory Bumper Cover/Installation Tips and Best Practices ..... 11/15
Identifying Fujitsu-Ten Navigation Units ..... 11/15

New F-10 Gen 2.1 Audio/Navigation System and Siri ..... 11/15
Why Do My Outside Mirror Approach Lights Appear Green..... 01/16
Accessory Door Edge Guard Removal Process ..... 03/16
Bluetooth Operation and Diagnosis ..... 04/16
Clarion Audio Units and Audiobook CD's ..... 04/16
Audio/ Navigation Head Unit Quick Reference Information ..... 04/16
2013 WRX or STI Special Edition Graphics..... 05/16
Door Edge Guards / Installation Tips and Best Practices..... 05/16
Auto Dimming and Home Link Accessory Mirror Wiring Harness Troubleshooting Reminder..... 07/16
Microphone Not Working? Check the Telematics System..... 07/16
2017 Forester Telematics Fuse Change Information ..... 09/16
Keyless Access with Push Button Start Vehicles-Erratic Beeping When Entering the Vehicle ..... 09/16
Long Range Remote Start FAQ..... 09/16
RES Inoperative? Check the RES Antenna ..... 11/16
Display Audio (Non Navigation) Clock Not Synchronized ..... 12/16
No Back Up Camera After Radio Removal ..... 12/16
Clock Settings ..... 12/16
2017 Auto-Dimming Outside Mirror Limited Movement..... 01/17
2017MY Forester Wheel Arch Molding Installation ..... 01/17
2017 MY Impreza, Remote Engine Start (RES) Remote Fob Registration Tips..... 02/17
RES Hood Switch..... 02/17
2017MY Impreza Audio Unit Stays Powered Up After Key Off … Or Does It? ..... 02/17
2017 MY Impreza Remote Engine Start (RES) Time-out Function ..... 02/17
2017MY Impreza- Serial Numbers On Gen 3 Harman Audio Units..... 03/17
2017MY Impreza Key Start RES Tips ..... 03/17
Bluetooth Concerns?..... 05/17
Does this Accessory work with this car? ..... 05/17
LED Lighting ..... 06/17
Combination Meter Replacement ..... 07/17
Eyesight Programming ..... 08/17
Long Range RES Quirks..... 08/17
Eyesight Diagnostic Tips ..... 09/17
Iphone Contact Options ..... 10/17
Navigation and Head Unit Diagnosis ..... 10/17
New Questionnaire for Harman Gen 3 Audio/Navigation concerns..... 11/17
Long Range RES Transmitter Programming ..... 12/17
2017 and Later Impreza, Inoperative Long-Range RES Remotes (Fobs)..... 01/18
Remote Engine Start Hood Switch Installation Review for 2017-2018MY Impreza/2018MY Crosstrek Models.. 02/18
Thule Roof Rack Wind Noise Complaints ..... 03/18
2017MY+ Impreza/Crosstrek (Turn Start) Remote Engine Start Registration ..... 04/18
Remote Start Quick Reference ..... 04/18
2014-2018MY Forester, Rear-View Mirror Removal Helpful Hints ..... 05/18
2014 Keyless Access with Push Button Start Vehicles – Erratic Beeping when Entering the Vehicle..... 05/18
Air Conditioning Season is Here ..... 06/18
Contact Pictures and Head Units..... 06/18
Harman Version 4 Application..... 08/18
DCM Information ..... 08/18
Combination Meter Replacement ..... 09/18
Fujitsu/Denso 10 iPhone Contact Picture Display – Update ..... 10/18
Sirius XM List and Voice Tuning Concerns on Gen 2 & 2.1 Denso (D10) Audio Units..... 10/18
2019MY Impreza/Crosstrek Remote Engine Start (Key Start) – Control Module Installation ..... 10/18
Air Conditioning Leak Revisited ..... 11/18

2019 Forester Remote Engine Start Changes and Precautions ..... 12/18
2019 Impreza Sport Remote Engine Start Climate Control Settings ..... 12/18
Reporting Inaccurate Navigation Map Data ..... 01/19
Unexpected / Abnormal Stop While Operating Remote Engine Start ..... 01/19
19MY Remote Engine Start – Push Button Start ..... 02/19
Use of Aftermarket Accessory Engine / Fuel Economy Monitors ..... 03/19
Basic Diagnostics for Remote Engine Start (RES) Systems ..... 03/19
Testing and Diagnosis of the Telematics Wifi Hotspot and Appointment Scheduler ..... 03/19
How to End Speaker Output Check when Using SSM ..... 04/19
Telematics Operational Concerns Accompanied by DTC B2A15 ..... 05/19
Harman Audio / Navigation System Concerns ..... 05/19
Harman Audio Unit Phonebook Contact Limits ..... 07/19
2015 to Current WRX/STi Popping Sound After Installing Accessory Subwoofer ..... 07/19
Updated Infotainment “Conditions” Information ..... 08/19
Homelink Mirror Programming Information ..... 09/19
Swapping Electrical Components: The Hardest Lessons Learned are Usually the Most Expensive ..... 09/19
Telematics Subscription Error Codes 202 and 204 ..... 09/19
Telematics RES Feature Inoperative and Revised B2A16 Diagnostics ..... 09/19
2020 Legacy & Outback RES Fob Programming Procedure ..... 10/19
2020 Legacy & Outback Immobilizer Registration Process TSB 15-246-19R ..... 10/19
Speed Volume Control ..... 10/19
Updated Infotainment “Conditions” Information ..... 11/19
2020MY Legacy & Outback New Immobilizer Registration Procedures ..... 11/19
2020MY Legacy and Outback, DTC U0254 ..... 12/19
Remote Engine Start (RES) Run Time ..... 03/20
Review of and Additional DTC B2A15 Telematics Information ..... 04/20
Updated Infotainment “Conditions” Information ..... 04/20
Incorrect Operation of Audio Unit After Rockford Fosgate Upgrade Installation ..... 05/20
A/C and Heat Conditions: Use of Recirculation / Recirc Button ..... 05/20
DTC Code B2253 - Damaging a Speaker Coil due to the Electric Current to the Speaker Coil ..... 06/20
Telematics – Attention to the Details Can Insure a Smooth DCM Replacement ..... 07/20
Updated Helpful Infotainment Operational Tips ..... 07/20
Remote Engine Start/ Power Rear Gate Inoperative on Push to Start Vehicles ..... 08/20
Starlink App Soft Key Grayed Out ..... 11/20
STARLINK Update – Retirement of the 3G Cellular Network ..... 12/20
Wireless Phone Charging Accessory ..... 12/20
Remote Engine Start (RES) – No Start After Registration, MY20+ Legacy/Outback or MY19+ Impreza/ Crosstrek (Key Start) ..... 01/21
Homelink Mirror, No Operation with Key Off ..... 02/21
Failed RES: Reference Error Code SER-4357 ..... 02/21
CP1 software version verification ..... 02/21
Blind Spot Detection Disabled, No DTCs found ..... 03/21
CP1 Panel and Steering Switch, Knob Switch Checks ..... 03/21
Gen 4 CP1 Denso – Bookmark Feature ..... 04/21
Roof rail usage/stowing on 2020+ Outbacks ..... 06/21
Gen 2: Denso tech, SXM inoperative after updating ..... 06/21
Gen 4: Denso CP1 Updating and initialization Screen reminder ..... 06/21
Gen 4 Denso CP1 – Volume adjustment is not available, and audio is not playing after reboot ..... 06/21
Gen 3, 3.1 and 3.1 alpha Harmon and Gen 4 Denso CP1 – Prevent Pandora application from automatically launching when connecting phone to vehicle ..... 07/21
Gen 3, 3.1 and 3.1 alpha Harmon and Gen 4 Denso CP1 – Check for conflicting accessories prior ro performing a software update via USB Port ..... 08/21

Gen 3 Bluetooth streaming stuttering issue update AKA BT Skipping with Apple watch paired....08/21
Apple CarPlay Connections....09/21
3G Sunset Video Announcement, STAR-U Training....09/21
Ascent Wireless Charger Installation, White Shifter Lever Rod Orientation....09/21
Auto Start Stop Inoperative or Automatically Disabled at Engine On....10/21
Aftermarket Accessories causing DTCs, Immobilizer concerns and Inoperative Systems....11/21
Harman Bluetooth voice commands and Contact Emojis....11/21
B2255 and B2256 misdiagnosis and Diagnostic changes....11/21
2022 BRA Auto-Dimming Homelink Mirror Inoperative....12/21
DTC P0116 Setting with Engine Block Heater Use....12/21
2022MY Forester, HVAC Gesture Control....01/22
GEOTAB, Fleet Tracking Device....02/22
Keyless entry Inoperative & Turn-Key Immobilizer Programming Inoperative, Similar Connectors....02/22
2022 WRX CID Identification....03/22
Determining a Cockpit Information Display Failure....03/22
Poor Bluetooth Quality Concerns....03/22
Generation 4 Eyesight Camera Removal and Installation....03/22
The Telematics LED: When green does not mean GO....04/22
Charging Cables and Touch Screen Concerns....05/22
CP1 Navigation shows the wrong location....05/22
Harman 3.1 Base & Base+ Only, Ghost Image or Double Image....05/22
Harman Unit, bubble screen condition....05/22
Importance of Inspecting for Aftermakret devices, Check the USB port & LEDs....05/22
Keyless Access Output Volume....06/22
Service Provider Software Information, Infotainment Portal....06/22
Version 4 Eyesight and Immobilizer Registration U1C00....07/22

## 16-Automatic Transmission

Metallic Noise on Light Acceleration- 4EAT Equipped Vehicles .....05/91
3AT Oil Strainer Screen Deterioration .....05/91
4EAT Slow Engagement .....06/91
Legacy Transmission Oil Cooler Flushing .....06/91
ECVT Transfer Cover Gasket/Erratic 4WD Dash Lamp Illumination .....06/91
4EAT Failure After Replacement of Reduction Shaft .....06/91
FT4WD Binding On Corners .....08/91
ECVT Main Drive Shaft Seal Ring .....09/91
Justy ECVT Technical Information Supplement .....10/91
Legacy A/T Oil Pump Cover Bolt Torque Clarification .....11/91
A/T Pressure Checking Tip .....11/91
A/T Thrust Bearing Identification .....01/92
Justy ECVT Cable Adjustments .....01/92
4EAT Parking Pawl Campaign Full Time 4WD .....03/92
4EAT Planetary & High Clutch Parts (L-Series, Legacy, XT, SVX) .....06/92
4EAT Servicing & Repairs .....06/92
3AT Torque Converter Seal Failures .....06/92
4EAT Servicing .....07/92
4EAT Transmission Diagnosis Training Material .....07/92
All Models with 4EAT, Pump Cover Production Change .....07/92
Legacy ATF Filter Replacement .....08/92
ATK-50 4EAT Filter Installation .....08/92
Legacy and SVX 4EAT Torque Bind Complaints .....10/92
Aftermarket Batteries .....11/92
All Four-Wheel Drive Vehicles .....11/92
Automatic Transmission Rebuilding .....12/92
Justy ECVT.....12/92
4EAT All Wheel Drive Complete Unit Exchange .....01/93
4EAT Torque Converter Clutch Always Engaged Causing Engine Stall .....02/93
4EAT Auxiliary ATF Filter .....02/93
3AT (Lock-Up) Torque Converter Engagement on FWD Loyale .....02/93
1990-1993MY All Models With 4EAT Low Temperature Operation .....03/93
Modified 4EAT Pump Gasket .....04/93
1992MY Legacy 4EAT ATK-50 VIN Range Clarification .....04/93
Alternate ECVT Pulley Alignment Formula .....04/93
1990MY-1993MY All Models 4EAT Low Temperature Operation Correction to 03/93 Update .....05/93
Legacy 4EAT Squeaking Noise from Torque Converter .....06/93
Justy ECVT Valve Body Cleaning .....09/93
Speedometer Cable Adapter on 4EAT Transmissions .....10/93
Duty Solenoid “C” Swapping For Testing Purposes .....12/93
3 Speed Automatic Clutch Drum Wear .....01/94
AWD Rear Axle Binding .....02/94
Legacy Torque Converter Bolt Removal .....05/94
High Clutch Seizure/Failure, SVX and Legacy Turbo Service Bulletin 16-58-94 .....05/94
3-Speed Automatic Differential Rebuilding .....05/94
4EAT Gasket and Seal Kit .....06/94
3AT Malfunction .....08/94
4EAT - No Movement in Any Gear .....09/94
‘ATF Temp’ Indicator Light – 1995MY Legacy .....09/94
4EAT Operation – 1995MY Legacy .....09/94
1995 Legacy with Apparently Non-Existent Codes From TCU .....10/94

4EAT Cold Weather Operation ..... 11/94
4EA Shift Problem Diagnostics ..... 12/94
ECVT Loss of Line Pressure ..... 03/95
1995MY 4EAT Vehicle Noise ..... 05/95
1995MY Subaru Legacy/Impreza Shift Lock Diagnosis ..... 09/95
4EAT Low or Erratic Line Pressure ..... 09/95
Repeat ECVT ECU Failures ..... 10/95
Correct Axle Ratios ..... 11/95
Over-Cautious November Update “Correct Axle Ratios” Information ..... 12/95
1996MY Subaru Legacy ATF Cooler Hose Re-Routing ..... 02/96
Change In Configuration of 4EAT Pinion Shaft ..... 04/96
4EAT Delayed Engagement into Drive When Warm ..... 05/96
‘Manual Rom ID...Error 3’ ..... 05/96
4EAT AWD Extension Case Roller Bearing Removal ..... 07/96
4EAT Systems Diagnosis ..... 07/96
4EAT Transmission Binding In Turns ..... 08/96
Late 1995MY & 1996MY Transfer Clutch Chatter ..... 09/96
Limited Slip Additive ..... 11/96
4EAT Cold Weather Operation ..... 11/96
4EAT Speed Sensors ..... 04/97
Checking Tire Pressures At PDI ..... 05/97
Remanufactured Transaxle Program ..... 07/97
Vehicle Engine RPM Goes To Zero When Coming To A Stop ..... 08/97
1998MY Subaru Impreza FWD Fuse Holder ..... 11/97
Rear Axle Binding On Turns - (One More Time) ..... 01/98
1999MY 2.2L 4EAT Subaru Legacy Models Harsh Downshifting ..... 09/98
1999MY 4EAT Transmission Operation ..... 10/98
Transmission Repairs or Replacements ..... 04/99
Transmission Control Units (TCU) Part Numbers ..... 09/99
1999MY and Later (Second Generation 4EAT) Trouble Codes ..... 02/00
4EAT Torque Bind ..... 11/01
Phase 2 4EAT (1999MY to Present) Repairs ..... 03-04/02
4EAT Remanufactured Transaxle Program – A Reminder ..... 08/02
Remanufactured Transmission Paperwork Packets ..... 09-10/02
2003MY 4EAT Differential Drain Plug ..... 11/02
2003MY Legacy 2.5GT Sport Shifter Cold Weather Operation ..... 01-02/03
Slope Control Change for 2003-2004MY Vehicles ..... 04/03
2004 Direct AT Control Valve Body Assembly Collection ..... 09/03
(2004 Baja turbo and Forester turbo) Remanufactured Transmission Installations ..... 10/03
Phase II 4EAT Stud Leak Repair ..... 11/03
Procedures for Handling Returns/Claims – Remanufactured Transmissions ..... 03/04
Phase 2 4EAT Transmission Characteristics – A Reminder ..... 05/04
2005MY Legacy & Outback AT Models Ring Indicator Removal ..... 08/04
Transmission Information Worksheet ..... 08/04
5AT Transmission Removal/Installation Precaution ..... 08/04
2005MY Legacy/Outback AT Models Ring Indicator Removal – Revised ..... 10/04
Inspection and Correction Methods of Connector T4/B11 ..... 12/04
T.S.B. # 16-67-04 ..... 01/05
Remanufactured Automatic Transmission Core Fluid Draining Process ..... 03/05
WWV-06 Campaign ..... 04/05
TCM Code 45 and the SSM III ..... 01/06
Phase 2 4EAT Transmission Characteristics ..... 05/06

2004-2005MY Baja (4AT) Noise on Turns ..... 09/06
Package Changes to Remanufactured Transmissions ..... 10/06
5A/T Remanufactured Transmission and “Learning Control” ..... 12/06
Discontinuation of Spin-On ATF Filter ..... 08/07
Direct Control 4AT Transmission Information ..... 08/07
More ATF HP Fluid Information ..... 09/07
Performing 5 AT “Learning Control” ..... 09/07
5 A/T Turbine Speed Sensor Precaution ..... 11/07
DTC P0741 ..... 12/07
Learning Control Procedure Applicability ..... 03/08
5AT Re-Manufactured Transmission Availability Announcement ..... 04/08
Quick Tip: Don’t Forget To Do The Learning Control! ..... 01/09
Legacy / Outback 3.0L 5 A/T Converter Bolts ..... 03/09
DTC P1714 (4AT) TPS Power Supply Circuit ..... 03/09
DTC P0712, AT Fluid Temperature Sensor Low Input, D4AT ..... 06/09
2010 M/Y Legacy & Outback Lineartronic™ ..... 09/09
5AT Turbine Speed Sensor Reminder ..... 11/09
“Binding on Turns” A Reminder ..... 12/10
4EAT Cold Weather Shift Characteristics Reminder ..... 01/11
Servicing the CVT Front Differential Fluid ..... 02/11
A/T Light Flashing but No DTC Stored (DTC P0712); Erratic Shifting Complaint ..... 03/11
2011 M/Y Tribeca 5A/T, Flywheel Cover ..... 11/11
DTC P0890 “A/T Self-Shut Relay Diagnosis (Low)” ..... 12/11
CVT Replacement Reminder ..... 01/12
2012 M/Y Impreza CVT Valve Body Replacement Information ..... 01/12
A/T Shifting Concerns? Measure Those Tires! ..... 02/12
Generation 1 CVT Transmission Servicing ..... 02/13
CVT Torque Converters ..... 02/14
Cold Weather CVT Operation, Engine RPM, and Cabin Heat ..... 04/14
Automatic Transmission Fluid Usage Chart ..... 04/16
Binding On Turns and Other Transmission Issues ..... 11/16
CVT Fluid ..... 06/17
Damaged Transmission and Front Differential Cases due to over-torque of fill/drain plugs ..... 09/17
Allowable Repairs to CVT Assemblies ..... 10/17
CVT Application and Generation Chart ..... 03/18
Torque Converter Relearn ..... 03/18
CVT Repairs ..... 09/18
Service Manual Correction: Rear Transmission Crossmember/Transmission Mount Removal – Impreza and Crosstrek CVT Models ..... 10/18
Vibration After Transmission or Engine Removal ..... 06/19
2020MY Legacy and Outback New CVT Fluid ..... 09/19
Transmission Control Module (TCM) Freeze Frame Data (FFD) Block 2 ..... 06/20
Automatic Transmission Fluid Types ..... 10/20
Torque Converter Relearn ..... 11/20

## 17-SRS Air Bag

SVX (SRS) Supplemental Restraining System “Air Bag” ..... 01/92
Legacy Models Equipped With Air Bag ..... 06/92
1989MY-92MY Passive Restraint Seatbelt System ..... 03/93
1993MY Legacy “SRS” Airbag Light Stays On ..... 04/93
1993MY Impreza “SRS” Airbag Light Stays On ..... 05/93
Diagnostic Information for Subaru SRS Systems ..... 12/93
Passive Restraints ..... 04/94
Checking Air Bag Harnesses ..... 09/94
Security System in 1994MY SVX with Dual SRS System ..... 10/94
1995MY Subaru Legacy Passenger SRS ..... 06/95
Diagnosing SRS (Air Bag) Codes ..... 07/95
Removal of Passenger’s Air Bag Module ..... 04/96
Deployed SRS Air Bags ..... 06/96
Passenger’s Side Air Bag ..... 11/96
De-Powered Air Bags ..... 02/98
All 1998MY Model Air Bag Applicability ..... 03/98
Availability of Retrofit Air Bag ‘On - Off’ Switches ..... 08/98
Subaru Vehicles Equipped with SRS Side Airbags ..... 08/00
10 Year SRS Inspections ..... 08/00
Diagnosing SRS (Air Bag) Codes ..... 10/00
Subaru Vehicles Equipped with SRS Side Airbags ..... 07/01
2002MY Impreza SRS Harness Change ..... 10/01
2003MY Forester SRS Codes 41 or 42 ..... 07/03
Air Bag Connector ..... 09/03
Service Bulletin 17-09-04 ..... 12/04
SRS Codes 41 & 42 ..... 03/05
ODS DTC Code 28 – Spacer Kit ..... 04/06
2010 Legacy / Outback Seat Belt Twist ..... 03/10
Front Passenger SRS Frontal Airbag (ODS) Indicator Light Information ..... 08/11
WQA-37 Forester Rear Center Seat Belt Recall Supplemental Information ..... 04/12
WUM-98 Supplier and Date Codes ..... 03/20
SRS Air Bag, Rear Seatbelt Chimes ..... 10/21

## 18-Service Manual Corrections

Legacy Knock Sensor ..... 09/91
Service Manual Shuffle ..... 12/91
Diagnosing SVX Trouble Code 37 O2 Sensor LH ..... 03/92
Loyale Passive Restraint and 3-Point Seat Belt Timer Locations ..... 04/92
XT6 Electronic-Controlled Motor Drive Power Steering Service Manual Supplement ..... 04/92
Service Bulletin Manual Supplement Volume 12 Correction ..... 05/92
1992MY Legacy Service Manual Correction ..... 10/92
1995MY Subaru Legacy Service Manual Corrections ..... 03/95
1995MY Legacy Service Manual Revision ..... 07/95
1996MY Legacy Service Manual Supplement ..... 09/95
Impreza Service Manual Supplement ..... 12/95
Service Bulletin Manual & Service Helpline Update Supplement ..... 12/95
1998MY Impreza Service Manual ..... 11/97
Copying Pages from Service Manuals ..... 03/98
Correction to Subaru Forester Service Manual ..... 04/98
Evaporative System Diagnosis T.R.B. Corrections ..... 08/99
2000MY Subaru Legacy & Impreza Service Manuals ..... 01/00
Rear Wheel Alignment Specification Correction ..... 01/00
2000MY Subaru Legacy Service Manual Correction ..... 02/00
Service Bulletin 13-74-00 Correction ..... 08/00
Service Manual Corrections, 2001MY Forester and Legacy ..... 08/00
Service Manual Correction 2001MY Legacy ..... 08/00
Correction to Service Bulletin 10-70-00 ..... 03/01
Updated Service Manual Information ..... 02/11
STIS: Help Us to Help You ..... 05/11
WVX-34 Reminder ..... 01/13
WQA-37 Information ..... 01/13
Errors in Service Manuals, What to Do ..... 12/18
Ascent Sunshade Reinitialization Procedure Clarification ..... 09/19
C1532 Trouble Tree Correction ..... 09/19

## 19-Special Edition

Air Condition Season ..... 07/20
Combination Meter Replacement ..... 09/20
Escalation Process, Contacting Techline ..... 01/21
Updates to Subaru-U ..... 04/21
Transfer Clutch System Diagnostics Consolidated ..... 12/21
Evaporative Diagnostics & Smoke Testing, ELCM Force test ..... 07/22