

Rain Bird SRKCP/CPF

Rain Bird SRKCP/CPF Replacement Solenoid Instruction Manual

Model: **SRKCP/CPF** | Brand: **Rain Bird**

1. INTRODUCTION

This manual provides instructions for the installation, operation, and maintenance of the Rain Bird SRKCP/CPF Replacement Solenoid. This solenoid is designed to restore functionality to compatible Rain Bird irrigation valves, ensuring efficient and reliable water flow control.

The SRKCP/CPF solenoid is an energy-efficient, low-power encapsulated unit featuring a captured plunger for enhanced durability and long-term performance. It is engineered for straightforward removal and installation, often requiring no specialized tools.

2. COMPATIBILITY

The Rain Bird SRKCP/CPF Replacement Solenoid is compatible with the following Rain Bird valve series:

- APAS Series Valves
- ASVF Series Valves
- ECV Series Valves
- CP Series Valves
- CPF Series Valves
- DV Series Valves
- DAS Series Valves
- JTV Series Valves

Important Note:

This replacement solenoid is designed exclusively for newer Rain Bird valves featuring a **hexagon-shaped solenoid**. It is **not compatible** with older Rain Bird valves that utilize round solenoids with ridges.

3. KEY FEATURES

- Direct replacement for specified Rain Bird valve models.
- Energy-efficient, low-power encapsulated design.

- Features a captured plunger for extended life and reliability.
- Designed for quick and easy installation without the need for special tools.
- Helps in efficient troubleshooting and repair of irrigation systems.

4. INSTALLATION

Follow these steps to replace the solenoid on your compatible Rain Bird valve:

1. **Turn off Water Supply:** Before beginning, ensure the main water supply to the irrigation system is completely shut off to prevent water leakage.
2. **Locate the Valve:** Identify the valve requiring solenoid replacement. It is typically located within a valve box in your landscape.
3. **Disconnect Wiring:** Carefully disconnect the two wires connected to the existing solenoid. Note which wire connects to which terminal if applicable, though for a solenoid, polarity is generally not an issue.
4. **Remove Old Solenoid:** Unscrew the old solenoid from the valve body by turning it counter-clockwise. This can usually be done by hand or with minimal force.
5. **Inspect Valve:** Briefly inspect the valve port for any debris or damage before installing the new solenoid.
6. **Install New Solenoid:** Screw the new Rain Bird SRKCP/CPF solenoid into the valve body by turning it clockwise until it is hand-tight. Do not overtighten.
7. **Connect Wiring:** Reconnect the two wires to the new solenoid. Ensure a secure connection. Wire nuts are commonly used for this purpose.
8. **Restore Water Supply:** Slowly turn the main water supply back on. Check for any leaks around the newly installed solenoid.
9. **Test Operation:** Test the valve operation using your irrigation controller to ensure it opens and closes correctly.



Image 1: The Rain Bird SRKCP/CPF Replacement Solenoid. This component is crucial for controlling water flow in irrigation valves.



Image 2: A person's hands installing a new solenoid into an irrigation valve within a valve box. This demonstrates the typical installation environment.



Image 3: A hand holding the solenoid, showing the attached wires ready for connection. This highlights the electrical connection step.



Image 4: Close-up view of the solenoid being screwed into the valve body, illustrating the

clockwise rotation for secure fitting.



Image 5: Detail of the electrical wiring connection to the solenoid, showing the use of wire nuts for a secure and insulated splice.

5. OPERATION

The SRKCP/CPF solenoid primarily operates electronically via your irrigation controller. However, it also features a manual override option:

- **Automatic Operation:** When connected to an irrigation controller, the solenoid will open and close the valve based on the programmed schedule.
- **Manual Operation:** The solenoid body includes markings for "ON" and "OFF" with an arrow indicating "MANUAL 1/4 TURN". To manually open the valve, turn the solenoid 1/4 turn counter-clockwise towards the "ON" position. To close the valve manually, turn it 1/4 turn clockwise towards the "OFF" position. This feature is useful for testing or temporary watering without the controller.

6. MAINTENANCE

The Rain Bird SRKCP/CPF Replacement Solenoid is designed for minimal maintenance. As a replacement part, its primary function is to restore valve operation. Regular maintenance involves:

- **Leak Inspection:** Periodically check the valve area for any signs of water leakage, which could indicate a faulty seal or an issue with the solenoid or valve body.
- **Debris Removal:** Ensure the valve box remains clear of excessive dirt or debris that could interfere with valve or solenoid function.
- **Wiring Integrity:** Occasionally inspect the wiring connections for corrosion or damage, ensuring they remain secure.

7. TROUBLESHOOTING

If your irrigation valve is not functioning correctly after solenoid replacement, consider the following:

- **Valve Not Opening:**
 - Verify the water supply is fully open.
 - Check electrical connections to the solenoid for looseness or corrosion.

- Ensure the irrigation controller is sending power to the correct zone.
- Manually turn the solenoid 1/4 turn to the "ON" position. If the valve opens, the electrical signal or solenoid itself may be faulty.

- **Valve Not Closing:**

- Manually turn the solenoid 1/4 turn to the "OFF" position. If the valve closes, the electrical signal from the controller might be stuck "ON".
- Inspect the valve diaphragm for debris or damage that prevents it from seating properly.
- Ensure the solenoid is fully tightened and not cross-threaded.

- **Incorrect Solenoid Type:** Double-check that the installed solenoid is the correct hexagon-shaped replacement for your valve model. Older round solenoids are not compatible.




8. SPECIFICATIONS


Attribute	Detail
Model Number	SRKCP/CPF
Material	Metal
Item Dimensions (L x W x H)	1.5 x 1.3 x 2.25 inches
Exterior Finish	Black Coated
Number of Ports	2
Item Weight	0.375 ounces
Power Source	Water (controlled electrically)
Included Components	Solenoid
UPC	077985999308

9. WARRANTY AND SUPPORT

The Rain Bird SRKCP/CPF Replacement Solenoid comes with a manufacturer's warranty. For specific warranty details, including coverage period and terms, please refer to the packaging or contact Rain Bird customer support directly.

For technical assistance, troubleshooting beyond this manual, or to inquire about warranty claims, please visit the official Rain Bird website or contact their customer service department. Contact information can typically be found on the product packaging or the Rain Bird website.

 RAIN BIRD ASVF Anti-siphon Valve Operation Manual DAS-075 1/2" ASVF 1" DAS-100 1" ASVF 1"	Rain Bird ASVF Anti-siphon Valve Operation Manual for DAS-075 and DAS-100 Models Comprehensive operation manual for Rain Bird ASVF Anti-siphon Valves (models DAS-075 and DAS-100). Covers installation, assembly, valve operation, troubleshooting, and repair kits for sprinkler systems.
 RAIN BIRD 1" Automatic Sprinkler Valve Operation Manual DAS-100 1" ASVF 1" DAS-100 1" ASVF 1"	Rain Bird DAS-100/ASVF 1" Automatic Sprinkler Valve Operation Manual Comprehensive operation and installation guide for the Rain Bird DAS-100/ASVF 1-inch Automatic Anti-Siphon Sprinkler Valve, covering features, backflow prevention, sizing, assembly, operation, and troubleshooting.
 RAIN BIRD Valves Comprehensive Guide to Irrigation Solutions DAS-075 1/2" ASVF 1" DAS-100 1" ASVF 1"	Rain Bird Valves: Comprehensive Guide to Irrigation Solutions Explore the range of Rain Bird valves, including DV, DVF, ASVF, HV, HVF, PGA, PEB, PESB, PESB-R, EFB-CP, and BPES series. This guide details features, specifications, pressure loss data, and application information for efficient irrigation system design.
 PGA Valve Installation and Operating Instructions Troubleshooting Guide RAIN BIRD	Rain Bird PGA Valve: Installation, Operation, and Troubleshooting Guide Comprehensive guide for installing, operating, and troubleshooting the Rain Bird PGA Valve, including setup instructions, common issues, and solutions.
 RAIN BIRD TRU Series Irrigation Controllers Troubleshooting Guide RAIN BIRD	Rain Bird TRU Series Irrigation Controllers Troubleshooting Guide Comprehensive troubleshooting guide for Rain Bird TRU Series Irrigation Controllers, addressing common watering and electrical issues, and providing instructions for resetting the device to factory defaults.
 RAIN BIRD PEB and PESB Series Valves Technical Specifications RAIN BIRD	Rain Bird PEB and PESB Series Valves: Technical Specifications Detailed technical specifications for Rain Bird PEB and PESB Series solenoid control valves, covering features, performance, pressure loss, dimensions, and model options for irrigation systems.




[\[pdf\]](#) User Manual Installation Guide Instructions Specifications

Installation Instructions High Value In line Valve Cphvvbspff rain bird cp100 1 valve Retailer Rainbird CP 100 Automatic Inch Line by This can be applied Read honest and unbiased product Rain Bird CP100 Without Flow Control LOT OF 2 Zoro Add to Cart en cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 11 |||

ENGLISH EN INSTALLATION INSTRUCTIONS HIGH VALUE IN-LINE VALVE CPHVVBSPPFF CPHVVBSPPMM CPHVVBSPPFF 2 ... wire. Inspect and repair as required. Possible cause 2: Damaged solenoid. Replace solenoid. Kit # **SRKCP/CPF**. Possible cause 3: Damaged diaphragm. Remove bonnet top and replace diaphragm. Kit # DR...

lang:en **score:49** filesize: 398.83 K page_count: 1 document date: 2022-09-12




[\[pdf\]](#) User Manual

el cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 11 |||

EL CPHVVBSPPFF CPHVVBSPPMM 0,056,82 m³/h 0,8 113 l/min 1,0 10,3 bar 15150 psi 24 ... 1: 2: . . . 1: . . 2: . . # **SRKCP/CPF**. 3: . . # DRK-JTV. : , HV . www.rainbird.com Registered tra...

lang:en **score:48** filesize: 413.55 K page_count: 1 document date: 2022-09-12




[\[pdf\]](#) User Manual

ar cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

AR l/min1130,8 m³/h 6,82 0,05 psi 150-15 bar 10,31,0 Hz 60/50 VAC 24 :1 ... :2 ... :1 ... :2 .SRKCP/CPF # . . :3 .DRK-JTV # . . : HV www.rainbird.com Registered trademar...

lang:en **score:48** filesize: 468.82 K page_count: 1 document date: 2024-05-08




[pdf] User Manual

el cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

EL CPHVVBPFF CPHVVBSPMM 0,056,82 m³/h 0,8 113 l/min 1,0 10,3 bar 15150 psi 24 ... 1: 2: . . . 1: . . 2: . . # **SRKCP/CPF**. 3: . . # DRK-JTV. : , HV .
www.rainbird.com Registered tra...

lang:en score:48 filesize: 450.02 K page_count: 1 document date: 2024-05-08




[pdf] User Manual

zh cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 11 |||

ZH 0,056,82 m³/h 0,8 113 l/min 1,0 10,3 bar 15 150 psi 24 VAC 50/60 Hz 1 ... L 1/4 TURN OFF B PTFE PVC C 1 1 2 3 2 1 1 2 3 2 **SRKCP/CPF** 3 DRK-JTV HV RAIN BIRD CORPORATION 6991 East Southpoint Road, Tucson, AZ 85756, USA U...

lang:en score:48 filesize: 503.09 K page_count: 1 document date: 2022-09-12




[pdf] User Manual

zh cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

ZH 0,056,82 m³/h 0,8 113 l/min 1,0 10,3 bar 15 150 psi 24 VAC 50/60 Hz 10,3 ... L 1/4 TURN OFF B PTFE PVC C 1 1 2 3 2 1 1 2 3 2 **SRKCP/CPF** 3 DRK-JTV HV RAIN BIRD CORPORATION 6991 East Southpoint Road, Tucson, AZ 85756, USA U...

lang:en score:48 filesize: 538.06 K page_count: 1 document date: 2024-05-08




[\[pdf\]](#) User Manual

fi cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 12 |||

SUOMI FI ASENNUSOHJEET LAADUKAS PUTKENSISINEN VENTTIILI
CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 26 x 34 ... ista ja korjaa tarvittaessa.
Mahdollinen syy 2: Vaurioitunut solenoidi. Vaihda solenoidi. Pakkaus # **SRKCP/CPF**.
Mahdollinen syy 3: Vaurioitunut kalvo. Irrota suojahattu ylosa ja vaihda kalvo.
Pakkaus...

lang:fi **score:46** filesize: 398.89 K page_count: 1 document date: 2022-09-12




[\[pdf\]](#) User Manual

fi cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

SUOMI FI ASENNUSOHJEET LAADUKAS PUTKENSISINEN VENTTIILI
CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 26 x 34 ... ista ja korjaa tarvittaessa.
Mahdollinen syy 2: Vaurioitunut solenoidi. Vaihda solenoidi. Pakkaus # **SRKCP/CPF**.
Mahdollinen syy 3: Vaurioitunut kalvo. Irrota suojahattu ylosa ja vaihda kalvo.
Pakkaus...

lang:fi **score:46** filesize: 433.12 K page_count: 1 document date: 2024-05-08




[\[pdf\]](#) User Manual

tr cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 11 |||

TRK TU KURULUM TALMATLARI KALITELI DZ VANA TEKNİK ZELLİKLER Aki Basın
Elektrikli 0,056,82 m³/h 0, ... blo. nceleyin ve gereken ekilde onarin. Olasi sebep 2:
Hasarli selenoid. Selenoidi deitirin. Kit # **SRKCP/CPF**. Olasi sebep 3: Hasarli
diyafram. Kaputu st ikarin ve diyaframı deitirin. Kit # DRK-JTV...


lang:id **score:46** filesize: 401.71 K page_count: 1 document date: 2022-09-12



[\[pdf\]](#) User Manual

sv cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||


SVENSKA SV INSTALLATIONSINSTRUKTIONER HGT VRDE INLINE VENTIL CPHVVBSPPFF CPHVVBSPPMM CPHVVBSPPFF 26 ... dning. Inspektera och reparera vid behov. Mjlig orsak 2: Skadad solenoid. Byt ut solenoiden. Kit # **SRKCP/CPF**. Mjlig orsak 3: Skadat diafragma. Ta bort motorhuvn verst och byt ut membranet. Kit # ... lang:no **score:46** filesize: 434.61 K page_count: 1 document date: 2024-05-08



[\[pdf\]](#) User Manual

tr cphvvbspff cphvvbspmm instruction manual 09my24 rainbird sites default files media documents 2024 05 |||


TRK TR KURULUM TALMATLARI KALITELI DZ VANA TEKNK ZELLKLER Aki Basin Elektrikli 0,056,82 m3/h 0, ... blo. nceleyin ve gereken ekilde onarin. Olasi sebep 2: Hasarli selenoid. Selenoidi deitirin. Kit # **SRKCP/CPF**. Olasi sebep 3: Hasarli diyafram. Kaputu st ikarin ve diyaframini deitirin. Kit # **DRK-JTV**... lang:id **score:46** filesize: 402.35 K page_count: 1 document date: 2024-05-09



[\[pdf\]](#) User Manual

it cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 11 |||


ITALIANO IT ISTRUZIONI DI INSTALLAZIONE ELETTROVALVOLA IN LINEA AD ALTE PRESTAZIONI CPHVVBSPPFF CP ... e riparare se necessario. Causa possibile 2: Solenoide danneggiato. Sostituire il solenoide. Kit # **SRKCP/CPF**. Causa possibile 3: Membrana danneggiata. Rimuovere il coperchio in alto e sostituire la... lang:it **score:46** filesize: 399.07 K page_count: 1 document date: 2022-09-12



[\[pdf\]](#) User Manual

it cphvvbsppf cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||


ITALIANO IT ISTRUZIONI DI INSTALLAZIONE ELETTROVALVOLA IN LINEA AD ALTE PRESTAZIONI CPHVVBSPPF CP ... e riparare se necessario. Causa possibile 2: Solenoide danneggiato. Sostituire il solenoide. Kit # **SRKCP/CPF**. Causa possibile 3: Membrana danneggiata. Rimuovere il coperchio in alto e sostituire la...
lang:it **score:46** filesize: 434.08 K page_count: 1 document date: 2024-05-08



[\[pdf\]](#) User Manual

hr cphvvbsppf cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 12 |||


HRVATSKI HR UPUTE ZA UGRADNJU VISOKOKVALITETNI LINIJSKI VENTIL CPHVVBSPPF CPHVVBSPPM CPHVVBSPPF ... Pregledajte i po potrebi popravite. Mogui uzrok 2: Osteen solenoid. Zamijenite solenoid. Komplet # **SRKCP/CPF**. Mogui uzrok 3: Osteena dijafragma. Skinite poklopac gornji i zamijenite dijafragmu. Kom...
lang:hr **score:46** filesize: 166.03 K page_count: 1 document date: 2022-12-14



[\[pdf\]](#) User Manual

hu cphvvbsppf cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 11 |||

MAGYAR HU TELEPTSI UTASTSOK NAGYKAPACITS SOROS SZELEP CPHVVBSPPF CPHVVBSPPM CPHVVBSPPF 26 x 34 m ... ksg szerint javtsa meg. 2. lehetsges ok: A szolenoid megrslt. Cserlje ki a szolenoidot. Kszletszm: **SRKCP/CPF**. 3. lehetsges ok: A membrn megrslt. Tvoltsa el a kupakot fels , majd cserlje ki a membrn...
lang:no **score:46** filesize: 402.12 K page_count: 1 document date: 2022-09-12




[pdf] User Manual

sl cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

SLOVENCINA SL NAVODILA ZA NAMESTITEV LINIJSKI VISOKOTLACNI VENTIL CPHVVBSPPFF CPHVVBSPPMM CPHVVBS ... te. Mozni vzrok 2: Poskodovan elektromagnetni ventil. Zamenjajte elektromagnetni ventil. Komplet # **SRKCP/CPF**. Mozni vzrok 3: Poskodovana diafragma. Odstranite pokrov zgornji in zamenjajte diafragm...

lang:hr score:46 filesize: 433.88 K page_count: 1 document date: 2024-05-08




[pdf] User Manual

hr cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

HRVATSKI HR UPUTE ZA UGRADNJU VISOKOKVALITETNI LINIJSKI VENTIL CPHVVBSPPFF CPHVVBSPPMM CPHVVBSPPFF ... Pregledajte i po potrebi popravite. Mogui uzrok 2: Osteen solenoid. Zamijenite solenoid. Komplet # **SRKCP/CPF**. Mogui uzrok 3: Osteena dijafragma. Skinite poklopac gornji i zamijenite dijafragmu. Kom...

lang:hr score:46 filesize: 433.86 K page_count: 1 document date: 2024-05-08




[pdf] User Manual

sk cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

SLOVENCINA SK POKYNY NA INSTALCIU VYSOKOVKONN ZABUDOVAN VENTIL CPHVVBSPPFF CPHVVBSPPMM CPHVVBSPPFF Skontrolujte a opravte poda potreby. Mozn prcina 2: Poskodov solenoid. Vymete solenoid. Sprava c. **SRKCP/CPF**. Mozn prcina 3: Poskodov membrna. Odoberete kryt vrchn a vymete membrnu. Sprava c. DRK-JT...

lang:hr score:46 filesize: 437.55 K page_count: 1 document date: 2024-05-08



[pdf] User Manual

hu cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||


MAGYAR HU TELEPTSI UTASTSOK NAGYKAPACITS SOROS SZELEP

CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 26 x 34 m ... ksg szerint javtsa meg.

2. lehetsges ok: A szolenoid megsrlt. Cserlje ki a szolenoidot. Kszletszm:

SRKCP/CPF. 3. lehetsges ok: A membrn megsrlt. Tvoltsa el a kupakot fels , majd cserlje ki a membrn...

lang:no **score:46** filesize: 436.46 K page_count: 1 document date: 2024-05-08



[pdf] User Manual

pl cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

POLSKIE PL INSTRUKCJA MONTAU ZAWR RZEDOWY CPHVVBSPFF


CPHVVBSPMM SPECYFIKACJA TECHNICZNA Przeplyw ... Moliwa przyczyna 2:

Uszkodzona cewka elektromagnetyczna. Wymieni cewk elektromagnetyczn. Zestaw

SRKCP/CPF. Moliwa przyczyna 3: Uszkodzona membrana. Zdj pokryw grn i

wymieni membran. Zestaw # DR...

lang:pl **score:46** filesize: 438.84 K page_count: 1 document date: 2024-05-08



[pdf] User Manual Installation Guide Instructions Specifications

en cphvvbspff cphvvbspmm instruction manual 08my24 0 rainbird sites default files media documents 2024 05 |||

ENGLISH EN INSTALLATION INSTRUCTIONS HIGH VALUE IN-LINE VALVE


CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 2 ... wire. Inspect and repair as

required. Possible cause 2: Damaged solenoid. Replace solenoid. Kit # **SRKCP/CPF.**

Possible cause 3: Damaged diaphragm. Remove bonnet top and replace diaphragm.

Kit # DR...

lang:en **score:46** filesize: 433.3 K page_count: 1 document date: 2024-05-08




[\[pdf\]](#) User Manual

cs cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 11 |||

CESTINA CS POKYNY K INSTALACI ADOV VENTIL S VYSOKM PRTOKEM CPHVVbspff CPHVVbspmm CPHVVbspff 26 x ... ntrolujte a opravte podle poteby. Mozn pcina 2: Poskozen elektromagnet. Vymte elektromagnet Sada # **SRKCP/CPF**. Mozn pcina 3: Poskozen membrna. Demontujte kryt nahoe a vymte membrnu. Sada # DRK-JTV....

lang:hr **score:46** filesize: 403.34 K page_count: 1 document date: 2022-09-12




[\[pdf\]](#) User Manual

cs cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

CESTINA CS POKYNY K INSTALACI ADOV VENTIL S VYSOKM PRTOKEM CPHVVbspff CPHVVbspmm CPHVVbspff 26 x ... ntrolujte a opravte podle poteby. Mozn pcina 2: Poskozen elektromagnet. Vymte elektromagnet Sada # **SRKCP/CPF**. Mozn pcina 3: Poskozen membrna. Demontujte kryt nahoe a vymte membrnu. Sada # DRK-JTV....

lang:hr **score:46** filesize: 438 K page_count: 1 document date: 2024-05-08




[\[pdf\]](#) User Manual

pt cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

PORTUGUS PT INSTRUES DE INSTALAO VLVULA DE ALTA QUALIDADE CPHVVbspff CPHVVbspmm CPHVVbspff 26 x ... cione e repare como necessario. Possvel causa 2: Solenoide danificado. Substitua o solenoide. Kit # **SRKCP/CPF**. Possvel causa 3: Diafragma danificado. Substitua a capota superior e substitua o diafr...

lang:pt **score:46** filesize: 436.66 K page_count: 1 document date: 2024-05-08



[\[pdf\]](#) User Manual


de cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022

11 |||

DEUTSCH DE INSTALLATIONSANWEISUNGEN HOCHWERTIGES MAGNETVENTIL CPHVVBSPPFF CPHVVBSPPMM TECHNISCHE S ... und reparieren.

Mögliche Ursache 2: Beschädigtes Magnetventil. Ersetzen Sie das Magnetventil. Kit # **SRKCP/CPF**. Mögliche Ursache 3: Beschädigte Membrane. Entfernen Sie das Ventiloberteil oben und erse...

lang:de **score:46** filesize: 403.3 K page_count: 1 document date: 2022-09-12



[\[pdf\]](#) User Manual


pt cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022

11 |||

PORTUGUS PT INSTRUES DE INSTALAO VLVULA DE ALTA QUALIDADE

CPHVVBSPFF CPHVVBSPPMM CPHVVBSPPFF 26 x ... cione e repare como necessario. Possvel causa 2: Solenoide danificado. Substitua o solenoide. Kit # **SRKCP/CPF**. Possvel causa 3: Diafragma danificado. Substitua a capota superior e substitua o diafr...

lang:pt **score:46** filesize: 401.99 K page_count: 1 document date: 2022-09-12




[\[pdf\]](#) User Manual

nl cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022

11 |||

NEDERLANDS NL INSTRUCTIES VOOR INSTALLATIE HOOGWAARDIGE REGELKLEP CPHVVBSPPFF CPHVVBSPPMM CPHVVBSPP ... cteer en herstel voor zover nodig. Mogelijke oorzaak 2: Beschadigde magneet. Vervang magneet. Kit # **SRKCP/CPF**. Mogelijke oorzaak 3: Beschadigd diafragma. Verwijder kap bovenzijde en vervang diafragma...

lang:nl **score:46** filesize: 398.46 K page_count: 1 document date: 2022-09-12




[pdf] User Manual

de cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

DEUTSCH DE INSTALLATIONSANWEISUNGEN HOCHWERTIGES MAGNETVENTIL CPHVVBSPPFF CPHVVBSPPMM TECHNISCHE S ... und reparieren. Mgliche Ursache 2: Beschdigtes Magnetventil. Ersetzen Sie das Magnetventil. Kit # **SRKCP/CPF**. Mgliche Ursache 3: Beschdigte Membrane. Entfernen Sie das Ventiloberteil oben und erse...


lang:de score:46 filesize: 438.67 K page_count: 1 document date: 2024-05-08



[pdf] User Manual

da cphvvbspff cphvvbspmm instruction manual 08my24 0 rainbird sites default files media documents 2024 05 |||

DANSK DA INSTALLATIONSINSTRUKTIONER IN-LINE-VENTIL AF HJ VRDI CPHVVBSPPFF CPHVVBSPPMM CPHVVBSPPFF 2 ... icer og reparer efter behov. Mulig rsag 2: Beskadiget magnetventil. Udskift magnetventilen. St nr. **SRKCP/CPF**. Mulig rsag 3: Beskadiget membran. Fjern hppen verst og udskift membranen. St nr. DRK-J... lang:da score:46 filesize: 435.74 K page_count: 1 document date: 2024-05-08




[pdf] User Manual

es cphvvbspff cphvvbspmm instruction manual 12se22 rainbird sites default files media documents 2022 11 |||

ESPAOL ES INSTRUCCIONES DE INSTALLACIN VLVULA EN LNEA DE ALTO VALOR CPHVVBSPPFF CPHVVBSPPMM CPHVVB ... ccionar y reparar si es necesario. Causa posible 2: Solenoide daado. Sustituir solenoide n. de kit **SRKCP/CPF** . Causa posible 3: Diafragma daado. Quitar el sombrerete de la vlvula parte superior y s...

lang:es score:46 filesize: 400.33 K page_count: 1 document date: 2022-09-12




[\[pdf\]](#) User Manual

HOOGWAARDIGE REGELKLEP nl cphvvbspff cphvvbspmm instruction manual 08my24 rainbird sites default files media documents 2024 05 |||

NEDERLANDS NL INSTRUCTIES VOOR INSTALLATIE HOOGWAARDIGE REGELKLEP CPHVVBSPFF CPHVVBSPMM CPHVVBSP ... cteer en herstel voor zover nodig. Mogelijke oorzaak 2: Beschadigde magneet. Vervang magneet. Kit # **SRKCP/CPF**. Mogelijke oorzaak 3: Beschadigd diafragma. Verwijder kap bovenzijde en vervang diafragm...

lang:nl **score:45** filesize: 432.42 K page_count: 1 document date: 2024-05-08




[\[pdf\]](#) User Manual Installation Guide Instructions Specifications

HIGH VALUE IN LINE VALVE INSTALLATION INSTRUCTIONS CPHVVBSPMM CPHVVBSPFF MANUAL 1 4 TURN Solenoid PTFE thread seal tape Bleed screw 15915 rainbird media |||

ENGLISH EN INSTALLATION INSTRUCTIONS HIGH VALUE IN LINE VALVE CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 2 ... wire. Inspect and repair as required. Possible cause 2: Damaged solenoid. Replace solenoid. Kit # **SRKCP/CPF**. Possible cause 3: Damaged diaphragm. Remove bonnet top and replace diaphragm. Kit # DR...

lang:en **score:43** filesize: 166.01 K page_count: 1 document date: 2023-05-31




[\[pdf\]](#) User Manual Instructions Declaration of Conformity

183941 02 24MY21 INSTRUCTIONS SUPLI HV indd cphvvbspff cphvvbspmm verbindung Hornbach 2022 21 — MANUAL 1 4 TURN Magnetventil Cewka elektromagnetyczna rainbird 10512111 Doc 01 DE 20220221101807 cdn hornbach at data shop D04 001 780 492 267 095 |||

CPHVVBSPFF, CPHVVBSPMM HV-INSTALLATIONSANWEISUNGEN INSTRUKCJA MONTAU HV CPHVVBSPFF CPHVVBSPFF 26 x ... n und reparieren. Mgliche Ursache 2: Beschdigtes Magnetventil. Ersetzen Sie das Magnetventil. Kit # **SRKCP/CPF**. Mgliche Ursache 3: Beschdigte Membrane. Entfernen Sie das Ventiloberteil oben und erset...

lang:de **score:38** filesize: 903.79 K page_count: 2 document date: 2021-05-24



[\[pdf\]](#) User Manual Installation Guide Instructions Specifications

Rain Bird HV Series Solenoid Valves Manual Rain Irrigation Products Easy Garden Irrigationrb 100hv valve manualcdn shopify s files 1 0298 9049 rb manual v 1681400638 |||

ENGLISH EN INSTALLATION INSTRUCTIONS HIGH VALUE IN-LINE VALVE CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 2 ... ire. Inspect and repair as required. Possible cause 2: Damaged solenoid. Replace solenoid. Kit # **SRKCP/CPF**. Possible cause 3: Damaged diaphragm. Remove bonnet top and replace diaphragm. Kit # ...


lang:en score:38 filesize: 398.83 K page_count: 1 document date: 2022-09-12

[\[pdf\]](#) Instructions Catalog

235536 11 06 08 AntiSiphonValveINSTR indd workstation 8 1 in Jar Top Anti Siphon Valve Instructions Assembly Rain Bird JTVAS100 077985003685 0077985003685 876731 5445f7f2 1f37 4472 8340 f521bd405f4a images thdstatic catalog Images 54 |||

JTV/AS-075, JTV/AS-100, JTV/ASF-075, JTV/ASF-100, DAS/ASVF-075, DAS/ASVF-100 INSTALLATION INSTRUCTIO ... ne y repare como sea necesario. Posible causa 2: Solenoide daado. Reemplace el solenoide. Juego no. **SRKCP/CPF** Posible causa 3: Diafragma daado. Retire la tapa y reemplace Juego de diafragma no. DRK-JT...

lang:en score:36 filesize: 743.62 K page_count: 1 document date: 2008-11-06





[\[pdf\]](#) User Manual Instructions

User Manual Rain Bird SST600IN Simple to Set Indoor Sprinkler Irrigation System Timer Controller 6 Zone Station SRKCP CPF Replacement Solenoid for CP DV ASVF DAS JTV Series Valves Patio Lawn Garden C18LAW0xTnL m media amazon images I |||

User Manual of Product 1: Rain Bird SST600IN Simple-To-Set Indoor Sprinkler/Irrigation System Timer/Controller, 6-Zone/Station this New/Improved Model Replaces SST600I ,Gray/Green Rain Birdt Simple To Set Timer SST Setup Operation Instructions SST user manual EN web.indd 1 10/11/2016 8:17...

lang:en score:31 filesize: 4.32 M page_count: 11 document date: 0000-00-00





[pdf] User Manual

ةينورتكلإلاو ةمئاقلا تاهجلا WEEE لودلا هذه يف ليجستلا لالخ نم Rain Bird صامم مرتفع القيمة داخل خط الأنابيب


rainbird media ||| دحل ةكرش نوكت يتلا رابتخا مت دقو اهيف داريتسالاب 15240

AR l/min1130,8 m3/h 6,82 0,05 psi 150-15 bar 10,31,0 Hz 60/50 VAC 24 :1 ..

SRKCP/CPF # .. :3 .DRK-JTV # .. : HV www.rainbird.com Registered

trademar...

lang:en score:31 filesize: 431.98 K page_count: 1 document date: 2022-09-12



[pdf]

IN LINE VENTIL AF HØJ VÆRDI Rain Bird ELEKTRISK AFFALD OG ELEKTRONISK UDSTYR WEEE

Dette symbol betyder at elektrisk og elektronisk udstyr ikke må 15345 rainbird media |||


DANSK DA INSTALLATIONSINSTRUKTIONER IN-LINE-VENTIL AF HJ VRDI

CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 2 ... icer og reparer efter behov. Mulig

rsag 2: Beskadiget magnetventil. Udskift magnetventilen. St nr. SRKCP/CPF. Mulig

rsag 3: Beskadiget membran. Fjern htten verst og udskift membranen. St nr. DRK-J...

lang:da score:30 filesize: 401.03 K page_count: 1 document date: 2022-09-12



[pdf]

ZAWÓR RZEDOWY Rain Bird Nov 15 2022 — ZUŻYTY SPRZĘT ELEKTRYCZNY I ELEKTRONICZNY

WEEE Symbol ten oznacza że zużytego sprzętu elektrycznego i elektroinstalacyjnego 15248 rainbird

media |||

POLSKIE PL INSTRUKCJA MONTAU ZAWR RZEDOWY CPHVVBSPFF


CPHVVBSPMM SPECYFIKACJA TECHNICZNA Przepływ ... Moliwa przyczyna 2:

Uszkodzona cewka elektromagnetyczna. Wymieni cewk elektromagnetyczn. Zestaw

SRKCP/CPF. Moliwa przyczyna 3: Uszkodzona membrana. Zdj pokryw grn i

wymieni membran. Zestaw # DR...


lang:pl score:30 filesize: 404.01 K page_count: 1 document date: 2022-09-12



[\[pdf\]](#) Accessories Catalog

Irrigation Valves 2017 Product Catalog Rain Bird CP100 1 FPT Inline Automatic Valve 888817 nvuMvF xrefs2 plumbersstock product 8 |||


Irrigation Valves Heavy Duty, Long Lasting Introduction Pop-Up Sprays Nozzles Rotors Impact Sp ... 1 CP100 1 FPT 4.38 x 4.75 x 3 077985610005 1 5 VALVE ACCESSORIES REPLACEMENT PARTS B60599 **SRKCP/CPF** Replacement Solenoid B36330 DRKJTVCP Replacement Diaphragm For JTV Valves B60... lang:en **score:29** filesize: 489.51 K page_count: 6 document date: 2022-04-11



[\[pdf\]](#)

HÖGT VÄRDE INLINE VENTIL AVFALLS ELEKTRISK OCH ELEKTRONISK UTRUSTNING WEEE Denna symbol innebär att uttjänta elektriska och elektroniska produkter inte får blandas med 15252 rainbird media |||


SVENSKA SV INSTALLATIONSINSTRUKTIONER HGT VRDE INLINE VENTIL CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 26 ... dning. Inspektera och reparera vid behov. Mjlig orsak 2: Skadad solenoid. Byt ut solenoiden. Kit # **SRKCP/CPF**. Mjlig orsak 3: Skadat diafragma. Ta bort motorhuvn verst och byt ut membranet. Kit # ... lang:no **score:22** filesize: 400.49 K page_count: 1 document date: 2022-09-12



[\[pdf\]](#)

VYSOKOVÝKONNÝ ZABUDOVANÝ VENTIL ODPAD Z ELEKTRICKÝCH A ELEKTRONICKÝCH ZARIADENÍ OEEZ Symbol znamená že vyradené elektrické a elektronické zariadenia by sa 15349 rainbird media |||

SLOVENCINA SK POKYNY NA INSTALCIU VYSOKOVKONN ZABUDOVAN VENTIL CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF Skontrolujte a opravte poda potreby. Mozn prcina 2: Poskoden solenoid. Vymete solenoid. Sprava c. **SRKCP/CPF**. Mozn prcina 3: Poskoden membrna. Odoberte kryt vrchn a vymete membrnu. Sprava c. DRK-JT... lang:hr **score:22** filesize: 168.81 K page_count: 1 document date: 2022-12-14



[pdf]

NAGYKAPACITÁSÚ SOROS SZELEP Rain BirdMEGJEGYZÉS A téli leállítás során ürítse le a rendszert hogy megóvja HV szelepeket fagytól HUZALOZÁS Külsőmenetes x csúszó adapter

Belsőmenetes 15245rainbird media 15245 |||

MAGYAR HU TELEPTSI UTASTSOK NAGYKAPACITS SOROS SZELEP


CPHVVBSPFF CPHVVBSPMM CPHVVBSPFF 26 x 34 m ... ksg szerint javtsa meg.

2. lehetsges ok: A szolenoid megsrlt. Cserlje ki a szolenoidot. Kszletszm:

SRKCP/CPF. 3. lehetsges ok: A membrn megsrlt. Tvoltsa el a kupakot fels , majd

cserlje ki a membrn...

lang:no score:22 filesize: 436.46 K page_count: 1 document date: 2024-05-08



[pdf]

VÁLVULA EN LÍNEA DE ALTO VALOR 15 mag 2024 — RESIDUOS APARATOS ELÉCTRICOS Y ELECTRÓNICOS RAEE Este símbolo indica que los aparatos eléctricos y electrónicos al final de 15239 rainbird media |||

ESPAOL ES INSTRUCCIONES DE INSTALLACIN VLVULA EN LNEA DE ALTO

VALOR CPHVVBSPFF CPHVVBSPMM CPHVVB ... ccionar y reparar si es

necesario. Causa posible 2: Solenoide daado. Sustituir solenoide n. de kit

SRKCP/CPF . Causa posible 3: Diafragma daado. Quitar el sombrerete de la vlvula

parte superior y s...

lang:es score:22 filesize: 435.39 K page_count: 1 document date: 2024-05-08

[pdf] Instructions Catalog

235535 11 06 08 InlineValveINSTR indd workstation 8 0690c559 bd8e 4512 a00a d8094ef36869 images

thdstatic catalog Images |||

CP-075, CP100, CPF-075, CPF-100, CPJTVF-100 INSTALLATION INSTRUCTIONS


INSTRUCCIONES DE INSTALACIN DI ... ne y repare como sea necesario. Posible

causa 2: Solenoide daado. Reemplace el solenoide. Juego no. **SRKCP/CPF**. Posible

causa 3: Diafragma daado. Retire la tapa y reemplace Juego de diafragma no. DRK-

J...

lang:en score:20 filesize: 711.94 K page_count: 1 document date: 2008-11-06





[\[pdf\]](#) User Manual Catalog

The 1 Brand In Irrigation Manual bleed screw to flush dirt and debris during installation startup Heavy duty solenoid resists power surges Straight through flow prolongs diaphragm life Exclusive RainBirdCPCatalog2017 rainbird sites default files media documents 2018 05 2017 Catalog As part of our 2017 Irrigation Catalog Consumer Products Introduction The #1 Brand In Irrigation Leading the way ... 1 CP100 1 FPT 4.38 x 4.75 x 3 077985610005 1 5 VALVE ACCESSORIES REPLACEMENT PARTS B60599 **SRKCP/CPF** Replacement Solenoid B36330 DRKJTVCP Replacement Diaphragm For JTV Valves B60... lang:en **score:18** filesize: 22.92 M page_count: 112 document date: 2017-06-15



[Rain Bird 2021 Irrigation Catalog: Consumer Products](#)

Explore the Rain Bird 2021 Irrigation Catalog for consumer products, featuring a comprehensive range of sprinklers, timers, valves, drip irrigation systems, and accessories designed for efficient water use in homes and gardens. lang:en **score:11** filesize: 18.67 M page_count: 112 document date: 2021-02-24