

Salter 2724486525731.0

Salter 1066 Bkdr08 Electronic Kitchen Scale User Manual

Model: 2724486525731.0 | Brand: Salter

INTRODUCTION

Thank you for choosing the Salter 1066 Bkdr08 Electronic Kitchen Scale. This manual provides essential information for the proper setup, operation, and maintenance of your new kitchen scale. Please read it thoroughly before use to ensure accurate measurements and prolong the life of your appliance.

This electronic kitchen scale is designed for precise measurement of food ingredients, featuring an 'Add & Weigh' function for convenience, a large LCD display for easy reading, and the ability to switch between metric and imperial units. Its compact design ensures easy storage.

PRODUCT OVERVIEW



Figure 1: Salter 1066 Bkdr08 Electronic Kitchen Scale. This image displays the sleek black design of the scale, with its clear LCD screen showing a measurement and the Salter logo. Two control buttons are visible on the right side of the scale's surface.

The Salter 1066 Bkdr08 scale features a flat weighing surface, a digital LCD display, and two control buttons for operation. Its minimalist design allows it to blend seamlessly into any kitchen environment.

SETUP

1. Unpacking

- Carefully remove the scale from its packaging.
- Inspect the scale for any signs of damage. If damaged, do not use and contact customer support.
- Remove any protective films or stickers from the display or weighing surface.

2. Battery Installation

- Locate the battery compartment on the underside of the scale.
- Open the battery compartment cover.
- Insert the required batteries (type and quantity usually indicated inside the compartment or in quick start guide, typically AAA or CR2032) ensuring correct polarity (+/-).
- Close the battery compartment cover securely.

3. Placement

- Place the scale on a firm, flat, and stable surface. Uneven surfaces can affect accuracy.
- Avoid placing the scale near heat sources, strong electromagnetic fields, or in direct sunlight.

OPERATING INSTRUCTIONS

1. Turning On/Off

- To turn on the scale, press the **ON/OFF** button. The display will show '0' or '0.0' when ready for use.
- The scale will automatically turn off after a period of inactivity to conserve battery life. To manually turn off, press and hold the **ON/OFF** button for a few seconds.

2. Switching Units (Metric/Imperial)

- With the scale turned on, press the **UNIT** button (or similar button, often labeled 'g/oz' or 'kg/lb') to toggle between metric (grams, kilograms) and imperial (pounds, ounces) units.
- The selected unit will be displayed on the LCD screen.

3. Weighing Ingredients

- Place the item to be weighed directly onto the scale's weighing surface.
- Alternatively, place an empty bowl or container on the scale first.
- The weight will be displayed on the LCD screen.

4. Add & Weigh Function (Tare)

The 'Add & Weigh' function allows you to measure multiple ingredients in the same bowl without emptying it, saving on washing up. This is also known as the Tare function.

1. Place your first ingredient (or an empty bowl) on the scale. Note its weight.
2. Press the **ZERO/TARE** button (often labeled 'Z/T' or 'Tare'). The display will reset to '0'.
3. Add the next ingredient to the bowl. The display will show the weight of only the newly added ingredient.
4. Repeat step 2 and 3 for additional ingredients.

MAINTENANCE

1. Cleaning

- Wipe the scale clean with a damp cloth.

- Do not use abrasive cleaners or immerse the scale in water.
- Ensure the scale is completely dry before storing or next use.

2. Storage

- Store the scale in a cool, dry place.
- Avoid placing heavy objects on the scale when not in use, as this can damage the sensors.
- If storing for an extended period, it is recommended to remove the batteries to prevent leakage.

TROUBLESHOOTING

Problem	Possible Cause	Solution
Scale does not turn on.	Dead or incorrectly installed batteries.	Check battery polarity. Replace batteries if necessary.
Inaccurate readings.	Scale not on a flat, stable surface; overload; internal error.	Ensure scale is on a flat surface. Do not exceed maximum capacity. Turn off and on again.
Display shows "Err" or "O-Ld".	Scale is overloaded.	Remove item immediately. Do not exceed the maximum capacity of 3kg / 7lb.
Display shows "Lo".	Low battery power.	Replace batteries.

SPECIFICATIONS

- **Model:** 2724486525731.0 (Bkdr08)
- **Brand:** Salter
- **Capacity:** 3kg / 7lb
- **Display Type:** LCD (Large Display)
- **Material:** Mixed Materials
- **Color:** Black
- **Item Weight:** 416 g
- **Package Dimensions:** 20.3 x 20.2 x 4.7 cm
- **Measurement Type:** Kilograms and Pounds
- **Special Features:** Add & Weigh function, Compact for easy storage

WARRANTY AND SUPPORT

Warranty Information

This product is covered by a standard manufacturer's warranty. For specific details regarding the warranty period and terms, please refer to the warranty card included with your purchase or visit the official Salter website. Extended warranty options may be available from third-party providers.

Customer Support

If you encounter any issues not covered in the troubleshooting section or require further assistance, please contact Salter

customer support. Contact details can typically be found on the official Salter website or on the product packaging. For more information, you may visit the [Salter Official Website](#).

© 2024 Salter. All rights reserved. Information in this manual is subject to change without notice.

ASK A QUESTION ABOUT THIS MANUAL

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page’s manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. [Privacy details](#).

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page
<https://manuals.plus/asin/B006MUNH16>
More documents and user manuals: <https://manuals.plus/>