

[Manuals.plus](#) /

› [Zodiac](#) /

› Zodiac Polaris 9-100-1001 Feed Pipe/Timer Blank Assembly Instruction Manual

Zodiac 9-100-1001

Zodiac Polaris 9-100-1001 Feed Pipe/Timer Blank Assembly Instruction Manual

For Polaris Vac-Sweep 360 Pool Cleaners

1. INTRODUCTION

This manual provides comprehensive instructions for the installation, operation, and maintenance of the Zodiac Polaris 9-100-1001 Feed Pipe/Timer Blank Assembly. This genuine replacement part is specifically designed for use with the Zodiac Polaris Black Max pool cleaner model Vac-Sweep 360.

Please read these instructions carefully before proceeding with installation or maintenance to ensure proper function and longevity of your pool cleaner.

2. PRODUCT OVERVIEW

The 9-100-1001 Feed Pipe/Timer Blank Assembly is a critical component for the efficient operation of your Polaris Vac-Sweep 360 pool cleaner. It facilitates the correct water flow and operational timing within the cleaner's system. This assembly is black in color, matching the aesthetic of the Black Max series.



Image of the Zodiac Polaris 9-100-1001 Feed Pipe/Timer Blank Assembly. This component is essential for maintaining proper water flow and timing in compatible Polaris pool cleaners.

3. SETUP AND INSTALLATION

1. **Preparation:** Before beginning installation, ensure your Polaris Vac-Sweep 360 pool cleaner is disconnected from the water source and removed from the pool.
2. **Locate Existing Assembly:** Identify the current feed pipe/timer blank assembly on your pool cleaner. Observe how it is connected and secured.
3. **Removal:** Carefully detach and remove the old assembly. This may involve unscrewing fasteners or releasing clips, depending on your cleaner's specific design. Refer to your Polaris Vac-Sweep 360's main instruction manual for detailed disassembly steps if needed.
4. **Inspection:** While the assembly is removed, inspect the surrounding areas for any debris or wear. Pay particular attention to the opening where the float rod (if applicable) passes through, ensuring it is clear and free of obstructions. Some users have found that ensuring sufficient clearance in this area can prevent future issues.

5. **Installation of New Assembly:** Position the new Zodiac Polaris 9-100-1001 Feed Pipe/Timer Blank Assembly into place. Secure it using the appropriate fasteners or clips, ensuring all connections are tight and watertight. Avoid overtightening.
6. **Final Check:** Once installed, visually confirm that the assembly is correctly seated and all parts are aligned.

4. OPERATING INSTRUCTIONS

The Zodiac Polaris 9-100-1001 Feed Pipe/Timer Blank Assembly operates automatically as an integral part of your Polaris Vac-Sweep 360 pool cleaner. No manual adjustments are typically required for this specific component after proper installation.

- After installing the assembly, reconnect your pool cleaner to the water source.
- Observe the cleaner's operation to ensure proper water flow and movement.
- If the cleaner does not function as expected, refer to the troubleshooting section of this manual or your main Polaris Vac-Sweep 360 cleaner manual.

5. MAINTENANCE

Regular inspection and maintenance of the feed pipe/timer blank assembly will help ensure the continued efficient operation of your Polaris pool cleaner.

- **Routine Inspection:** Periodically inspect the assembly for any visible signs of wear, cracks, or damage. Check for any blockages caused by debris.
- **Cleaning:** If debris accumulates around the assembly, gently clean it to ensure unobstructed water flow. Use a soft brush or rinse with water.
- **Replacement:** If the assembly shows significant signs of wear, cracking, or damage that could impede its function, it should be replaced with a new genuine Zodiac Polaris 9-100-1001 part to maintain optimal cleaner performance.

6. TROUBLESHOOTING

If your Polaris Vac-Sweep 360 pool cleaner experiences issues after installing the 9-100-1001 Feed Pipe/Timer Blank Assembly, consider the following:

- **No Water Flow or Weak Flow:**
 - Ensure all connections are secure and there are no leaks.
 - Check the feed pipe for any internal obstructions.
 - Verify that the main water supply to the cleaner is adequate and the booster pump (if applicable) is functioning correctly.
- **Cleaner Not Moving or Moving Erratically:**
 - Confirm the assembly is correctly installed and not impeding any moving parts of the cleaner.
 - Refer to the main Polaris Vac-Sweep 360 cleaner manual for broader troubleshooting steps related to cleaner movement and operation.

If problems persist, contact Zodiac customer support or a qualified pool technician.

7. SPECIFICATIONS

Feature	Detail
Product Type	Feed Pipe/Timer Blank Assembly
Model Number	9-100-1001
Compatibility	Polaris Vac-Sweep 360 Pool Cleaner
Color	Black
Product Dimensions	6 x 4 x 6 inches
Item Weight	4.8 ounces
Manufacturer	Zodiac

8. WARRANTY AND SUPPORT

For specific warranty information regarding your Zodiac Polaris 9-100-1001 Feed Pipe/Timer Blank Assembly, please refer to the original product packaging or your purchase documentation. Warranty terms typically vary by region and retailer.

For technical assistance, replacement parts, or further inquiries, please visit the official Zodiac website or contact their customer service department directly. Contact information can usually be found on the Zodiac website or in the documentation accompanying your Polaris pool cleaner.

Zodiac Official Website: www.zodiac.com

ASK A QUESTION ABOUT THIS MANUAL

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page’s manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. [Privacy details](#).

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

<https://manuals.plus/asin/B008EQ706O>

More documents and user manuals: <https://manuals.plus/>