Saved from manuals.plus.
Open the live page for links to other documents and user manuals.

Ford YS4Z-8290-BA

Ford 2.0L Water Pump Inlet Tube Instruction Manual

Model: YS4Z-8290-BA

1. Product Overview

The Ford 2.0L Water Pump Inlet Tube (Part Number YS4Z-8290-BA) is a genuine OEM component designed to ensure proper coolant flow within your vehicle's engine cooling system. This critical part connects the water pump to other cooling system components, facilitating the circulation of coolant to maintain optimal engine temperature.




Figure 1: Exploded view diagram of a typical automotive cooling system, illustrating the placement and connection points of various components including the radiator, hoses, and the water pump inlet tube (represented by a numbered part in the diagram).

Key Features:

- Genuine Ford part that fits your specific vehicle
- Engine Coolant Pipe
- Part Number: YS4Z8290BA
- Manufactured to meet specifications for fit, form, and function

2. Safety Information

Working on automotive cooling systems can be hazardous. Always adhere to the following safety precautions:

- Always ensure the engine is completely cool before attempting any work on the cooling system to prevent burns from hot coolant or engine components.
- Disconnect the vehicle's battery (negative terminal first) before beginning any work to prevent electrical hazards.
- Wear appropriate personal protective equipment, including safety glasses to protect eyes from splashes and gloves to protect hands.
- Coolant is toxic and harmful if ingested. Handle with extreme care and dispose of used coolant properly according to local regulations.
- If you are unsure about any step or lack the necessary tools or experience, consult a qualified automotive technician.

3. Setup (Installation)

Installation of the water pump inlet tube requires specific automotive knowledge and tools. It is highly recommended that this procedure be performed by a certified mechanic.

General Installation Steps (Consult Service Manual for Details):

1. Safely lift and support the vehicle.
2. Drain the engine cooling system completely.
3. Carefully remove any components obstructing access to the old inlet tube.
4. Remove the old water pump inlet tube.
5. Thoroughly clean all mating surfaces to ensure a proper seal with the new tube.
6. Install the new Ford 2.0L Water Pump Inlet Tube, ensuring all new gaskets and seals are correctly seated.
7. Reinstall any removed components.
8. Refill the cooling system with the manufacturer-specified coolant.
9. Bleed any air from the cooling system according to your vehicle's service manual.
10. Check for leaks and test drive the vehicle to ensure proper operation.

Note: *Always refer to your specific vehicle's service manual for detailed, model-specific installation instructions, torque specifications, and coolant bleeding procedures.*

4. Operating (Function)

The water pump inlet tube is a passive component that serves as a conduit for coolant within the engine's cooling system. Its primary function is to provide a sealed pathway for coolant to flow from the radiator or other cooling system components into the water pump. The water pump then circulates this coolant throughout the engine block and cylinder head to absorb and dissipate heat, maintaining optimal engine operating temperature.
Proper functioning of this tube, ensuring no leaks or obstructions, is essential for the efficient operation of the entire cooling system and for preventing engine overheating.

5. Maintenance

While the water pump inlet tube itself requires minimal direct maintenance, its longevity and the overall health of your cooling system depend on regular inspections and proper cooling system care:

- **Regular Inspection:** Periodically inspect all cooling system hoses and connections, including the water pump inlet tube, for any signs of leaks, cracks, swelling, or deterioration. Look for coolant residue or stains around the tube's connection points.

- **Coolant Level:** Ensure coolant levels are maintained between the 'MIN' and 'MAX' marks in the coolant reservoir when the engine is cool. Low coolant levels can indicate a leak.
- **Coolant Condition:** Check the condition of the coolant. It should be clean and free of debris or rust. Replace coolant as per your vehicle manufacturer's recommended service schedule.
- **System Pressure:** A properly functioning cooling system maintains pressure. If you notice a loss of pressure, it could indicate a leak, potentially from the inlet tube or its seals.

6. Troubleshooting

Symptoms of a faulty water pump inlet tube are primarily related to coolant leaks or issues with coolant circulation.

Common Issues and Potential Causes:

- **Coolant Leaks:** If you observe coolant puddles under your vehicle, a sweet smell, or a rapidly decreasing coolant level, inspect the water pump inlet tube and its connection points for the source of the leak. Leaks can occur from damaged tubes, worn-out O-rings, or loose connections.
- **Engine Overheating:** While a faulty inlet tube can contribute to coolant loss leading to overheating, overheating can also be caused by other cooling system issues (e.g., thermostat failure, clogged radiator, faulty water pump, or air in the system). If your engine is overheating, stop driving immediately and have the vehicle inspected.
- **Visible Damage:** Inspect the tube for any visible cracks, corrosion, or deformation that could compromise its integrity.

Recommendation: *If you suspect an issue with the water pump inlet tube or any other cooling system component, it is highly recommended to seek diagnosis and repair from a qualified automotive technician.*

7. Specifications

Specification	Value
Manufacturer	Ford
Part Number	YS4Z-8290-BA
OEM Part Number	YS4Z-8290-BA
Item Weight	13 ounces
Product Dimensions	24 x 4 x 4 inches
Vehicle Service Type	Car

8. Warranty and Support

This genuine Ford part is covered by Ford's standard parts warranty. Please refer to your purchase documentation or contact an authorized Ford dealership for specific warranty terms and conditions, as warranty coverage may vary.
For technical support, installation assistance, or warranty claims, it is recommended to consult a certified Ford service center or a qualified automotive technician. They have the expertise and specialized tools to properly diagnose and address any issues related to your vehicle's cooling system.

© 2024 Ford Motor Company. All rights reserved.

Ask a question about this manual

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. Privacy details.

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

https://manuals.plus/asin/B00AQZBQMA

More documents and user manuals: **https://manuals.plus/**