Saved from manuals.plus.
Open the live page for links to other documents and user manuals.

Power Stop L4300

Power Stop Front Left L4300 Stock Replacement Brake Caliper Instruction Manual

Model: L4300 | Brand: Power Stop

1. Introduction

This manual provides essential information for the installation, maintenance, and safe operation of your Power Stop Front Left L4300 Stock Replacement Brake Caliper. This product is designed as a direct bolt-on replacement for original equipment manufacturer (OEM) brakes in compatible cars, trucks, and SUVs, requiring no modifications.
For optimal performance and safety, it is recommended that installation be performed by a qualified automotive technician.

2. Product Overview

Figure 2.1: Front view of the Power Stop L4300 Stock Replacement Brake Caliper. This image displays the caliper's main body, mounting points, and bleeder screw.

The Power Stop L4300 brake caliper is a remanufactured unit, meticulously inspected and 100% pressure tested to ensure reliable performance. It includes all necessary hardware for installation.



Figure 2.2: Rear view of the Power Stop L4300 Stock Replacement Brake Caliper. This image shows the piston and the internal structure of the caliper.

3. Compatibility

This Power Stop L4300 Front Left Brake Caliper is compatible with a range of vehicles. Always verify fitment using the "Amazon Confirmed Fit" tool or consult a professional before purchase and installation.

Figure 3.1: Example of the "Amazon Confirmed Fit" tool. This tool helps ensure the correct part is selected for your specific vehicle by allowing you to input vehicle type, year, make, and model.

Partial List of Compatible Vehicles:

- Cadillac 60 Special 1993
- Cadillac Commercial Chassis 1990-1993
- Cadillac DeVille 1990-1993, 1997-1999
- Cadillac Escalade 1999-2000
- Cadillac Fleetwood 1991-1993
- Chevrolet Astro 1990-2002
- Chevrolet Blazer 1992-1994
- Chevrolet C1500 1988-1999
- Chevrolet C1500 Suburban 1992-1999
- Chevrolet C2500 1988-1998
- Chevrolet Express 1500 1996-2002
- Chevrolet Express 2500 1996-2002
- Chevrolet K1500 1988-1999
- Chevrolet K1500 Suburban 1992-1999

- Chevrolet K2500 1988-1998
- Chevrolet Tahoe 1995-1999
- Dodge Ram 1500 1994-1999
- GMC C1500 1988-1999
- GMC C1500 Suburban 1992-1999
- GMC C2500 1988-1998
- GMC K1500 1988-1999
- GMC K1500 Suburban 1992-1999
- GMC K2500 1988-1998
- GMC Safari 1990-2002
- GMC Savana 1500 1996-2002
- GMC Savana 2500 1996-2002
- GMC Yukon 1992-1999

4. Package Contents

Upon opening the package, please ensure all the following components are present:

- 1x Power Stop L4300 Front Left Brake Caliper
- All necessary brake caliper hardware, including:
  - Seals
  - Caliper guide pins
  - Dust boots
  - Bleeder screws
  - Brake pad attachment hardware
  - Mounting brackets (if applicable for your vehicle model)

If any components are missing or damaged, do not proceed with installation. Contact Power Stop customer support immediately.

5. Safety Information

Working on vehicle braking systems requires caution and proper tools. Failure to follow safety guidelines can result in serious injury or vehicle damage.

- Always wear appropriate personal protective equipment (PPE), including safety glasses and gloves.
- Ensure the vehicle is securely supported on jack stands on a level surface before beginning any work. Never rely solely on a jack.
- Disconnect the vehicle's battery before working on electrical components, if applicable.
- Brake fluid is corrosive. Avoid contact with skin and painted surfaces. Dispose of used brake fluid responsibly.
- Do not reuse old brake fluid.
- Ensure all fasteners are tightened to the manufacturer's specified torque values.
- If you are unsure about any step, consult a professional mechanic.

6. Installation Guidelines

The Power Stop L4300 brake caliper is designed for direct replacement. However, proper installation is critical for braking system integrity. These are general guidelines; always refer to your vehicle's specific service manual for detailed instructions.

Figure 6.1: Illustration of a brake caliper being installed. This image shows a hand positioning a new caliper over a brake rotor, highlighting the precision required during installation.

Required Tools (Typical):

- Socket/Wrench Set
- Torque Wrench
- Brake Line Wrench
- C-Clamp or Caliper Piston Compressor
- Brake Cleaner
- New Brake Fluid (DOT 3 or DOT 4, as specified by your vehicle manufacturer)
- Bleeder Kit
- Jack and Jack Stands
- Wheel Chocks

Installation Steps (General):

1. **Prepare Vehicle:** Park the vehicle on a level surface, engage the parking brake, and chock the wheels. Loosen the lug nuts on the wheel where the caliper will be replaced.
2. **Lift Vehicle:** Safely lift the vehicle and support it with jack stands. Remove the wheel.
3. **Remove Old Caliper:**
    a. Place a drain pan under the caliper to catch brake fluid.
    b. Using a brake line wrench, carefully disconnect the brake line from the old caliper.
    c. Remove the caliper mounting bolts.
    d. Remove the old caliper from the rotor.
4. **Prepare New Caliper:**
    a. Ensure the new Power Stop caliper matches the old one.
    b. Install any necessary hardware (guide pins, dust boots, etc.) onto the new caliper if not pre-installed.
5. **Install New Caliper:**
    a. Position the new caliper over the brake rotor.

b. Install the caliper mounting bolts and tighten them to your vehicle manufacturer's specifications using a torque wrench.
c. Connect the brake line to the new caliper, ensuring a snug fit. Do not overtighten.

6. **Bleed Brakes:** This is a critical step.
   a. Follow your vehicle's specific bleeding procedure. Typically, this involves opening the bleeder screw while a helper presses the brake pedal, then closing the screw before the pedal is released. Repeat until no air bubbles are visible in the fluid.
   b. Maintain the brake fluid reservoir at the "MAX" level throughout the bleeding process.
7. **Final Checks:**
   a. Inspect all connections for leaks.
   b. Pump the brake pedal several times to ensure a firm pedal feel.
   c. Reinstall the wheel and tighten lug nuts to specifications.
   d. Lower the vehicle.
8. **Test Drive:** Perform a cautious test drive in a safe area, gradually applying brakes to ensure proper function. Avoid hard braking initially.

7. Operation

Once properly installed and bled, the Power Stop L4300 brake caliper will function as an integral part of your vehicle's hydraulic braking system. When the brake pedal is pressed, hydraulic pressure from the master cylinder forces the caliper piston(s) to clamp the brake pads against the rotor, creating friction that slows or stops the vehicle.
After installation, it is normal for the brake pedal to feel slightly soft initially. This should resolve after a few brake applications as the pads seat against the rotor and any residual air is purged from the system. If the pedal remains soft or spongy, re-bleed the brake system.

8. Maintenance

Regular inspection and maintenance of your braking system are crucial for safety and longevity.

- **Routine Inspection:** Periodically inspect the brake caliper, brake lines, and pads for wear, leaks, or damage. This should be done during tire rotations or at least every 12,000 miles (20,000 km).
- **Brake Fluid:** Check brake fluid level regularly and ensure it is within the recommended range. Replace brake fluid according to your vehicle manufacturer's schedule, typically every 2-3 years, as it absorbs moisture over time.
- **Pad Replacement:** When replacing brake pads, inspect the caliper for smooth operation of the piston and guide pins. Lubricate guide pins with appropriate brake grease.
- **Cleaning:** Keep the caliper and surrounding area free of excessive dirt and debris. Use brake cleaner if necessary.

9. Troubleshooting

If you experience issues after installing your new brake caliper, consider the following common problems and solutions:

Symptom	Possible Cause	Solution
Soft or Spongy Brake Pedal	Air in the brake lines; improper bleeding.	Re-bleed the brake system thoroughly. Ensure brake fluid reservoir is full.

Symptom	Possible Cause	Solution
Brake Fluid Leak	Loose brake line connection; damaged brake line or caliper seal.	Inspect all connections and tighten. Check for damage to brake lines or caliper. Replace damaged components.
Brakes Dragging / Wheel Not Spinning Freely	Caliper piston not retracting; seized guide pins; residual pressure in brake line.	Inspect caliper piston and guide pins for smooth movement. Ensure guide pins are lubricated. Check brake hose for internal collapse.
Uneven Braking / Vehicle Pulls to One Side	One caliper not functioning correctly; air in one side of the system; uneven pad wear.	Inspect both front calipers. Re-bleed the system. Check brake pads for even wear.

If troubleshooting steps do not resolve the issue, seek assistance from a certified automotive technician.

10. Specifications

Attribute	Detail
Brand	Power Stop
Model Number	L4300
Item Weight	10.9 pounds
Product Dimensions	6.3 x 6.2 x 10.3 inches
Position	Front Left
Manufacturer Part Number	L4300
OEM Part Number	L4300
ASIN	B01CFL8JWC

11. Warranty and Support

Warranty Information:

Power Stop brake calipers are covered by a**90-day / 3,000 miles warranty**, whichever comes first. This warranty covers defects in materials and workmanship under normal use and service. Please retain your proof of purchase for warranty claims.

Customer Support:

For technical assistance, warranty claims, or questions regarding your Power Stop L4300 brake caliper, please contact Power Stop customer service through their official website or the retailer from whom the product was purchased.
For more information, visit the official Power Stop Store on Amazon.

© 2025 Power Stop. All rights reserved. Information subject to change without notice.

Ask a question about this manual

Ask about setup, troubleshooting, compatibility, parts, safety, or missing instructions. Manuals+ will review the question and use this page's manual context to help answer it.

Name

Anonymous

Email

you@example.com

After a successful submission, we securely hash the supplied account or form email before sending it to Microsoft Advertising for conversion attribution. Privacy details.

Question

Example: How do I reset this device or fix this error?

Details

Model number, symptoms, what you tried, or the section of the manual you are using.

Submit question

Open the live page

https://manuals.plus/asin/B01CFL8JWC

More documents and user manuals: **https://manuals.plus/**