Manuals+
Q & A | Deep Search | Upload

Hairmax LB41

HairMax Laser Band 41 Instruction Manual

Model: LB41

1. Product Overview

The HairMax Laser Band 41 is an FDA-cleared medical device designed to treat hair loss, thinning hair, and promote hair growth. It utilizes low-level laser therapy (LLLT) to stimulate hair follicles and restore the natural hair growth cycle.



Image 1.1: The HairMax Laser Band 41 device shown in its charging cradle, illustrating its curved design and laser diodes.

Key Features:

- **Red Light Therapy:** Employs specific wavelengths of red light to invigorate hair follicles.
- **41 Medical Grade Lasers:** Features 41 individual lasers for targeted treatment.
- **Patented Hair Parting Teeth:** Designed to part hair for optimal laser light delivery to the scalp.
- **Fast Treatment Time:** Requires only 3 minutes per session, three times a week.
- **Flexible Band Design:** Ensures comfortable treatment and ease of movement.
- **FDA Cleared:** Clinically validated for safety and effectiveness in promoting hair growth.

Image 1.2: A detailed diagram highlighting the key features of the Laser Band 41, such as the hair parting teeth and the arrangement of the 41 medical-grade lasers.

Intended Use:

The HairMax Laser Band 41 is indicated for the treatment of hair loss, thinning hair, and balding in individuals with androgenetic alopecia (pattern hair loss).

2. Setup and Charging

Initial Charging:

Before first use, fully charge your HairMax Laser Band 41. The device can be charged either by placing it in its charging cradle or by connecting the charging cable directly to the device.

- Connect the power adapter to a wall outlet and to the charging cradle or directly to the device.
- The indicator light on the device will show charging status. Refer to the device's specific light indicators for full charge notification.
- Ensure the device is fully charged before its first treatment session.

3. Operating Instructions

Follow these steps for effective treatment with your HairMax Laser Band 41:



Image 3.1: A user demonstrating the correct placement of the HairMax Laser Band 41 on the head during a treatment session.

1. **Power On:** Press the power button located on the side of the device once. A white indicator light will illuminate. The lasers will activate only when the device is placed on your head.
2. **Positioning:** Place the device at your hairline (Position 1). The patented hair parting teeth are designed to separate your hair for optimal laser light delivery to the scalp.
3. **Treatment Movement:** When you feel a vibration, slide the HairMax Laser Band 41 backward approximately 2 inches (5 cm) to Position 2. Apply light pressure to ensure the teeth part the hair effectively.
4. **Repeat:** Continue this sliding movement every 30 seconds, moving the device backward until you have covered your entire scalp. The device will vibrate to indicate when to move to the next position.
5. **Full Coverage:** For comprehensive treatment, ensure you cover all areas of the scalp by repeating the process for all 6 designated positions.

Treatment Schedule:

For optimal results, use the HairMax Laser Band 41 for a minimum of 3 minutes per session, three times a week, on non-consecutive days.



Image 3.2: A visual guide detailing the six positions for treating the scalp with the HairMax Laser Band 41.

4. Maintenance

Cleaning the Device:

To maintain the effectiveness and hygiene of your HairMax Laser Band 41, follow these cleaning guidelines:

- Ensure the device is powered off and disconnected from its charging cable before cleaning.
- Gently wipe the surface of the device, including the laser diodes and hair parting teeth, with a soft, damp cloth.
- Do not use abrasive cleaners, solvents, or immerse the device in water.
- Allow the device to air dry completely before storing or recharging.

Storage:

Store the HairMax Laser Band 41 in a cool, dry place, away from direct sunlight and extreme temperatures. Keep it in its original packaging or a protective case when not in use.

5. Troubleshooting

If you encounter any issues with your HairMax Laser Band 41, please refer to the following common solutions:

Problem	Possible Cause	Solution
Device does not power on.	Battery is depleted.	Ensure the device is fully charged. Connect it to the charger and wait for the indicator light to confirm charging.
Lasers do not activate.	Device not properly placed on the head.	The lasers are designed to activate only when in contact with the scalp. Ensure the device is firmly placed on your head.
Device feels too tight or uncomfortable.	Individual head size variation.	While the band has a flexible design, some users may find it snug. Adjust placement slightly or take short breaks if discomfort occurs.

If the issue persists after attempting these solutions, please contact HairMax Customer Support for further

assistance.

6. Product Specifications

Feature	Detail
Model Number	LB41
Dimensions	7 x 2.1 x 4.9 inches
Weight	6.08 ounces
Lasers	41 Medical Grade Lasers
Battery Type	2 Lithium Ion batteries (required)
Treatment Time	3 minutes, 3 times per week
Material Feature	Low Level Laser Therapy With Medical Grade Lasers
UPC	856823006510

Image 6.1: A diagram illustrating the physical dimensions of the HairMax Laser Band 41.

7. Warranty and Support

Manufacturer's Guarantee:

HairMax offers a satisfaction guarantee for its FDA-cleared laser therapy devices. If you are not satisfied with your results within 6 months of purchase, you may be eligible for a refund. Please refer to the official HairMax website or your purchase documentation for full terms and conditions regarding returns and refunds.

Customer Support:

For technical assistance, product inquiries, or warranty claims, please contact HairMax Customer Support. Contact details can typically be found on the product packaging or the official HairMax website.

8. Product Videos

No official product videos from the seller were found that meet the embedding criteria (m3u8 format). Please refer to the manufacturer's website for any available video resources.